

REPAIR ESTIMATE*

VEHICLE NO : SHD 3335Z

DATE 17/11/2017 9:32

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 562.30
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) ?			\$ 24.60
	Front Bumper Retainer Mounting ?			\$ 9.20
	Headlamp (LH) ✓			\$ 1,388.00
	Frt Wheel Hub Cap (LH) ✓			\$ 150.70
	SUB TOTAL			\$ 2,157.20
	LESS 20%			\$ 431.44
	DISCOUNTED TOTAL			\$ 1,725.76
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 350.00 200
	Spray Painting Charge			\$ 400.00 360
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 x
	Frt Wheel Alignment			\$ 80.00 x
	TOTAL LABOUR			\$ 930.00
	ESTIMATE TOTAL			\$ 2,755.76
Kalarickal 17/11/17 1105hr 2012 P.P. Before Paint photo				
LKK Auto Consultants hence notify the Reparer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from insurance Co. Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				