



LIU'S BROTHER AUTO ENGINEERING

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J, Tel: 6741-1730 / 731, Fax: 6744-5746, Email: liusbros@gmail.com

Ref No: GBC7138B171114

P

Estimate

Customer

Name: AXA Insurance Singapore Pte Ltd

Date: 16-11-17

Address: Motor Claims Department

Vehicle No: GBC7138B

8 Shenton Way #27-01

Model/Make: Fiat Doblo Cargo

AXA Tower

Singapore 068811

Maxi 1.6 MJ Diesel (Glazed)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Lh Tailgate <i>Red 5.00</i>	\$ 2,156.30	
2	Tailgate Lock <i>See</i>	\$ 229.90	<i>X</i>
3	Tailgate Weatherstrip <i>70mm</i>	\$ 345.50	<i>X</i>
4	Tailgate Inner Trim Board <i>Delene</i>	\$ 384.90	<i>SN 2</i>
5	Tailgate Outer Garnish <i>ant/cut</i>	\$ 321.80	
6	Tailgate Glass <i>shutland 42888</i>	\$ 841.50	
7	Tailgate Glass Sealant <i>See</i>	\$ 80.00	<i>SN 405.00</i>
8	Tailgate Wiper Motor <i>See</i>	\$ 428.00	<i>2</i>
9	Tailgate Wiper Link <i>11</i>	\$ 165.30	<i>X</i>
10	Tailgate Wiper Rubber <i>11</i>	\$ 98.00	<i>X</i>
11	Tailgate "70 KM/H" Sticker <i>See</i>	\$ 12.00	<i>SN 105.00</i>
12	Tail Lamp <i>See</i>	\$ 388.70	
13	Rear Rh Tailgate <i>See</i>	\$ 1,895.90	<i>X</i>
14	Tailgate Outer Garnish <i>11</i>	\$ 279.00	<i>X</i>
15	Tailgate "FIAT" Emblem <i>See</i>	\$ 87.80	
16	Rear Bumper <i>20/200 601.02</i>	\$ 745.00	
17	Bumper Clips 1 set <i>See</i>	\$ 65.00	<i>SN</i>
18	Bumper Reinforcement <i>See</i>	\$ 475.50	<i>2</i>
19	Bumper Side Bracket 02 pcs (@ \$65.00) <i>MSKed</i>	\$ 130.00	<i>175</i>
20	Bumper Reverse Sensor <i>See</i>	\$ 220.00	<i>SN 2005.00</i>
21	"Corporate" Advertisement Sticker <i>See</i>	\$ 400.00	<i>SN 2805.00</i>
	Remove and refix rear reverse sensor	\$ 80.00	<i>50</i>
	Remove and refix rear Lh & Rh tailgate components & wiper mechanism	\$ 150.00	<i>60</i>
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 1,200.00	<i>900</i>
	To putty & spray painting & including touch up paint on accident affected areas	\$ 1,000.00	<i>800</i>
	Remove & reinstall Lh & Rh Windscreen Glass to facilitate repairs	\$ 240.00	<i>100</i>
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 60.00	<i>50</i>

Total Parts & Labour of estimate for damaged vehicle

\$ 12,480.10

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

\$

SDLS:



M/s Liu's Brother Auto Engrg Wks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Affected
See
2/5 # 6100/2
20/11/17
Thuphooth Other repair
SD 7

P-5683.4
102
5115.06

S.W-595

Labour - 1960

7670.06
6136