

YP1110D
TP-AIG

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/WL

Claim Type: Third Party

Accident Date: 16/11/2017

TP Veh Reg No: GBA4511L

Estimate No: ES1791311/WL

Date: 17 Nov 2017

Policy No: 5076090997-01

Veh Reg No: YP1110D

Make/Model: ISUZU NPR85UH5A

Chassis No: JAANPR85HF7100785

Engine No: 4JJ12E7249

Reg. Date: 25/01/2016

Estimate Repair Cost to Vehicle No : YP1110D

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 TAILGATE LAMPS	134.10	2 PCS	268.20	
			268.20	
		Less 15%	40.23	227.97
Special Net				
2 TAILGATE	1,600.00	1 PC	1,600.00	
3 TAILGATE SPEED STICKER	10.00	2 PCS	20.00	
4 REAR NUMBER PLATE	12.00	1 PCS	12.00	
5 REAR SAFETY BAR ASSY WITH BRACKET	750.00	1 PC	750.00	
6 REAR COY PLATE	250.00	1 PCS	250.00	
7 REAR TRUNK END WOODEN CROSS BAR	480.00	1 PCS	480.00	
8 REAR STEP WOODEN MEMBER	180.00	1 PCS	180.00	
9 REAR TRUCK WOODEN FLOOR BOARD	200.00	8 PCS	1,600.00	
10 REAR WARNING LIGHT	300.00	1 PCS	300.00	
11 REAR TRUCK RH MARN WOODEN CHASSISS	1,200.00	1 PCS	1,200.00	
12 REAR NUMBER PLATE PANEL	120.00	1 PC	120.00	
13 REAR NUMBER PLATE LAMP	45.00	1 PC	45.00	
14 REAR TRUCK CENTRE WOODEN CROSS MEMBER	480.00	1 PCS	480.00	
15 REAR 'U' CRANE WITH NUT	120.00	1 PCS	120.00	
			7,157.00	7,157.00
Labour				
16 TOWING	100.00	1 LA	100.00	
17 REMOVE AND REFIX REAR SAFETY BAR ASSY, TAILGATE, TAIL LAMPS, REAR NUMBER PLATE LAMP PANEL, REAR SPARE TYRE HOLDER, REPAIR RH SIDE GATE, TAILGATE LOCK AND HANDLE, TAIL LAMP PANELS, REAR SPARE TYRE BRACKET, REAR RAILING, REAR RH CHASSISS AND REALIGN THE SAME	1,100.00	1 LA	1,100.00	

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 FAX: 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/WL
Claim Type: Third Party
Accident Date: 16/11/2017
TP Veh Reg No: GBA4511L

Estimate No: ES1791311/WL
Date: 17 Nov 2017
Policy No: 5076090997-01
Veh Reg No: YP1110D
Make/Model: ISUZU NPR85UH5A
Chassis No: JAANPR85HF7100785
Engine No: 4JJ12E7249
Reg. Date: 25/01/2016

Estimate Repair Cost to Vehicle No :YP1110D

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
18 REMOVE AND REFIX REAR EXHAUST, STRAIGHTEN AND CHECK LEAKING	80.00	1 LA	80.00	60
19 REMOVE AND REFIX REAR TRUCK ASSY, CANVAS ASSY, REAR TRUCK FLOOR BOARD PLATE. TO REPLACE REAR TRUCK WOODEN CROSS MEMBER, MAIN CHASSISS, WOODEN FLOOR BOARD AND REALIGN REAR TRUCK POSITION INCLUDING SUPPLY ALL NECESSARY MATERIALS	3,800.00	1 LA	3,800.00	3,111
20 TP PUTTY AND RESPRAY ON TAILGATE, RH SIDE GATE, REAR RAILING, TAILGATE LOWER MEMBER, SIDE GATE LOWER MEMBER, STEP MEMBER, MAIN CHASSISS AND ALL AFFECTED AREA	1,300.00	1 LA	1,300.00	1,000
21 TO REMOVE AND REFIX REAR WARNING LIGHTS, REPAIR WIRE HANESS AND CHECK WARNING LIGHT SYSTEM	120.00	1 LA	120.00	60
			6,500.00	6,500.00
			Total	S\$ 13,884.97
			Add GST @ 7%	971.95
			Total Amount Payable	S\$ 14,856.92

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

張建福 (機件) 拖車服務
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE / WORK ORDER

No. 13892

Date: 15/11/17

寶號

Messrs: 3419

車號

Vehicle No: YP1110 D

車型

Model No: 14 Long

由

From: West Coast Way

到

To: Woodland Drive

時間 (日/夜)

Time (day/night):

其他

Others:

CASH \$: 100 / 2,

CHEQUE:

經手人

Authorised by:

收貨人

Received by:

注意: 本公司對所拖之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.