

15/5/2010

INS. CASE OWNER:

CC 4/AXA1702 2082, T. 10/3/52

LKK:
IDAC:

Surveyor:

m7M

DOI:

ASSIGNMENT

8/11/17

Date / Time :

20/11/17

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No. :

UBD 1478 M

Name of Insured :

Y. WAW CONSTRUCTION P/L

Insured Tel No. :

HP:

Claim No. :

S7M0040M / 18907

Policy No. :

PIK7384

Make / Model :

TOYOTA

Place of Accident :

SLIP RD OF BKE TWOS FIVE

Excess Sec II : S\$

D.O.A. :

16/11/17

Is driver the owner?

(YES / NO)

Nature of Accident :

If NO, Driver Name / Age : MURUGAN

RABINURAN

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No. :

(V/L: YES / NO)

Insured Liability :

%

Final ? Yes / No

SLC 2109A



INSRS:

WSP:

Tel :

Liability :

RMKS:

Hitachi



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

DATE / PIC

21/11/17
12:40pm

SLC 2109A - X

UBD 1478 M

Smart claim

Spoke to OI PIC (Mr Lee) - confirmed accident details, involved in a 4 veh c.c. and 210 is 2nd vehicle. Informed act TP claim, aware of W/O number and agree to settle. Send letter to OI.

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

21/11/17

CH 13/11

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: MTH

Repair Cost:

TP S\$ 10,123.86

(6 days)

Reduction:

29

%

Email

Call

FINAL SETTLEMENT

Date/Time: 04.11.19

Confirm with JAMUNA

Email

Call

Final Liability:

100%

(Agreed / Assessed) BOLA S/N No. : 28

If NO or B 28, Ass. Lia :

Repair Cost:

0/01:

S\$ 10,831.14

Loss of Rental (LOR): 0/01:

S\$ 545.70

(6 days)

x \$85

Loss of Use (LOU):

S\$

(\$

x

days)

Loss of Income (LOI):

S\$

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$ 31.00

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: +350

Total:

S\$ 11,407.84

Global Sum S\$:

FINAL PAYMENT

Date/Time: 04.01.19

Confirm with: JAMUNA

Email

Call

Payee 1:

S\$ 11,407.84

Name 1:

HUAHAI CAPITAL ASIA PACIFIC PTE. LTD.

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

Submarine

Tanpin

REF: AXA

P

ASSIGNMENT

From: Date: 08.12.2017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLC 2109A

at Workshop m/s Hitachi Capital

of No. 8 Fourth Lck Yang Road.

Insured

Policy No.

Claims No.

Sum Insured: Excess:


(Client's Record)

Make of Veh:

(Policy Condition)

3pm
owner waiting

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$100K.

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: - % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLC 2109A Vr Regn: 2616 My.

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Stepwagon. cc 1496

Colour: white IC: Insured / Std / NI / NA

Sp. Reading: 043674 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: RP 31015573.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: 205/60R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. D.O.I. 01/12/17 1530.

Survey held at Hitachi Capital

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/8/17. \$10,122.56, 6 days. Remark: 958,315 confirm with w/s.

(RED: 4,108.98 24%)

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I: / \$

Add Fee: ☐ Site Insp: \$

☐ Interview: \$

☐ Tech. Insp: \$

☐ Weekend: \$

\$ - \$ - \$

Phone:

Other:

TOTAL:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/AXA17022082/pb3		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811		Date : 20-11-2017		
		Code : AXA2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 1778M	Veh. Inspected	SLC 2109A	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	20/11/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/11/2017	Inspection Date		
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Dec 2017)

Parts: M1-MPV HONDA STEPWAGON SPADA 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLC2109A/05/12/2017 18:17

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear Tailgate LH Door <i>by</i> ✓	20.00	0.00 <i>bt</i>	*1,851.20 FL ✓
2	2		*Rear Tailgate LH Door Hinge Top / Lower <i>Ry</i>	20.00	0.00 <i>Ry</i>	*181.00 FL
3	4		*Rear Tailgate LH Door Windscreen Moulding <i>nei</i> ✓	20.00	0.00 <i>nei</i>	*142.00 FL ✓
4	1		*Rear Tailgate LH Door Windscreen Sealant <i>nei</i> ✓	0	0.00 <i>nei</i>	*40.00 FS ✓
5	1		*Rear Tailgate LH Door Lock <i>Ry</i>	20.00	0.00 <i>ry</i>	*307.60 FL
6	1		*Rear Tailgate LH Door Centre Garnish <i>de</i> ✓	20.00	0.00 <i>de</i>	*251.50 FL ✓
7	1		*Rear Tailgate LH Door H Logo <i>nei</i> ✓	20.00	0.00 <i>nei</i>	*65.80 FL ✓
8	1		*Rear Tailgate LH Door STEPWAGON Logo <i>nei</i> ✓	20.00	0.00 <i>nei</i>	*63.50 FL ✓
9	1		*Rear Tailgate LH Door Lower Outer Garnish <i>de</i> ✓	20.00	0.00 <i>de</i>	*641.50 FL ✓
10	1		*Tailgate LH Door Lower Garnish Black Cover <i>wt</i> X	20.00	0.00 <i>wt</i>	*641.50 FL X
11	1	REPAIR	*Tailgate RH Door	20.00	0.00	-
12	1		*Tailgate RH Door Lower Outer Garnish <i>de</i> ✓	20.00	0.00 <i>de</i>	*456.70 FL ✓
13	1		*Tailgate RH Door Lower Garnish Black Cover <i>ry</i> } <i>mm</i>	20.00	0.00 <i>ry</i>	*170.20 FL
14	1		*Reverse Sensor 1set <i>?</i>	0	0.00 <i>mm</i>	*250.00 FS
15	1		*LH Taillamp Lower Garnish Reflector Light <i>?</i>	20.00	0.00 <i>mm</i>	*95.60 FL
16	1		*LH Taillamp Lower Garnish Reflector Light Cover <i>wt</i> ✓	20.00	0.00 <i>wt</i>	*40.50 FL ✓
17	1		*End Panel <i>Ry</i>	20.00	0.00 <i>Ry</i>	*565.50 FL
18	1		*End Panel Garnish <i>X</i> <i>mm</i>	20.00	0.00 <i>mm</i>	*115.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,463.30
- List Item Discount on L Items (S\$)	1,034.66
Total Parts (S\$)	4,428.64

Hitachi Capital Asia Pacific Pte. Ltd/SLC2109A/05/12/2017 18:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align and replace damaged parts of REAR portion	New 1000	2,000.00
2	Spray painting on REAR portion of affected area	New 1000	1,800.00
3	Check Wiring, re-align taillamps and ensure proper function	New 40	80.00
4	Remove & reinstall 2 pieces bumper sensors	New 30	120.00
5	Cavity Treatment on New Parts (2 Panels)	New 60	160.00
6	Remove and Reinstall Reverse Camera	New 60	120.00
7	Remove & re-install Tailgate	New 120	180.00
8	Transfer tailgate lock & mechanism to new tailgate	New 200	200.00
9	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New 60	150.00
10	Remove & replace tailgate spoiler	New 60	150.00
11	Conduct water seepage test	New 40	120.00
Gross Labour Cost (\$\$)			5,080.00

Hitachi Capital Asia Pacific Pte. Ltd/SLC2109A/05/12/2017 18:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N
111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591

0,861.44

14,583.84

Hitachi Capital Asia Pacific Pte. Ltd.
Jun Taiyo Service Centre

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE (SUPPLEMENTARY LIST)

AXA Insurance Pte Ltd

ATTN: MOTOR CLAIMS DEPT

QUOTE NO :
ACCIDENT DATE : 15/11/2017 @ 07.30am
VRN : SLC2109A
MODEL : Honda Stepwagon
TP VRN : GBD1778M

	<u>Qty</u>	<u>S\$ Unit</u>	<u>S\$ Amt</u>	<u>S\$ Labor</u>
<u>PARTS REPLACEMENT</u>				
<u>1. Body Repair</u>				
1 Tailgate handle cover	1	\$ 35.00	\$ 35.00 de ✓	
2 Tailgate RH door top outer garnish	1	\$ 445.00	\$ 445.00 de ✓	
3 Tailgate base assembly	1	\$ 2,850.00	\$ 2,850.00 bt ✓	
4 Tailgate RH door center handle garnish	1	\$ 128.00	\$ 128.00 de ✓	
5 Rear glass LH	1	\$ 1,250.00	\$ 1,250.00 nei ✓	
6 Rear glass RH	1	\$ 1,120.00	\$ 1,120.00 nei ✓	
7 Rear windscreen moulding RH	1	\$ 75.00	\$ 75.00 nei ✓	
8 Discount 20%	1	(\$1,180.60)	\$ (1,180.60) 5903	
TOTAL			\$ 4,722.40	20% ✓

2. Labor Charges

Sub Total : \$ -

Grand Total : \$ 4,722.40
Add 7% GST : \$ 330.57
Nett Total : \$ 5,052.97

No. of repair days: 6

CUSTOMER SIGNATURE

HITACHI CAPITAL ASIA PACIFIC PTE LTD
(MANAGER)

TP INSURER: AXA Insurance Pte Ltd (HQ)
YI WAN CONSTRUCTION PTE LTD
 UNKNOWN
 Singapore UNKNOWN

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	SLC2109A
Policy No:	P1817384	Date of Loss:	15/11/2017
Vehicle Reg. No.:	SLC2109A	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ANG GOON HWEE	Driver (Insured):	MURUGAN RAGUVARAN
Make/Model:	HONDA STEPWAGON SPADA, 1.5 (A)	Vehicle Reg. Date:	05/05/2016
Vehicle Colour:	WHITE		
Engine No:	RP31015573	Chassis No:	L15B3586219
Odometer:	16850 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair 10 (day)			
Description of Accident/Loss	PLEASE REFER TO THE ATTACHMENT.		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

Tan Jiah 97445749
WP
8/12/17 @ 1530
6 days
Resurvey before paint
SVC@lkhaut.com

COST OF CLAIMS

	Amount
Parts	4,428.64
Miscellaneous Items	0.00
Labour	5,080.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$\$)	9,508.64
+ GST 7.00% (\$\$)	665.60
Nett Amount (\$\$)	10,174.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This claim is handled by: SUN ZHU MEI

HITACHI
 Inspire the Next

TP INSURER: AXA Insurance Pte Ltd (HQ)
 YI WAN CONSTRUCTION PTE LTD
 UNKNOWN
 Singapore UNKNOWN

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	SLC2109A
Policy No:	P1817384	Date of Loss:	15/11/2017
Vehicle Reg. No.:	SLC2109A	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	ANG GOON HWEE	Driver (Insured):	MURUGAN RAGUVARAN
Make/Model:	HONDA STEPWAGON SPADA, 1.5 (A)	Vehicle Reg. Date:	05/05/2016
Vehicle Colour:	WHITE		
Engine No:	RP31015573	Chassis No:	L15B3586219
Odometer:	16850 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair 10 (day)			
Description of Accident/Loss	PLEASE REFER TO THE ATTACHMENT.		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

Taughtin 92445744
 WP
 8/12/17 @ 1530
 6 days
 Resuming before paint
 Suv @ 11kmph.com

C T OF CLAIMS

	Amount
Parts	4,428.64
Miscellaneous Items	0.00
Labour	5,080.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,508.64
+ GST 7.00% (S\$)	665.60
Nett Amount (S\$)	10,174.24

This claim is handled by: SUN ZHU MEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Dec 2017)
 Parts: M1-MPV HONDA STEPWAGON SPADA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLC2109A/05/12/2017 18:17
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear Tailgate LH Door <i>ht</i> ✓	20.00	0.00	*1,851.20 FL ✓
2	2		*Rear Tailgate LH Door Hinge Top / Lower <i>Ry</i>	20.00	0.00	*181.00 FL X
3	4		*Rear Tailgate LH Door Windscreen Moulding <i>nei</i> ✓	20.00	0.00	*142.00 FL ✓
4	1		*Rear Tailgate LH Door Windscreen Sealant <i>nei</i> ✓	0	0.00	*40.00 FS ✓
5	1		*Rear Tailgate LH Door Lock ?	20.00	0.00	*307.60 FL X
6	1		*Rear Tailgate LH Door Centre Garnish <i>de</i> ✓	20.00	0.00	*251.50 FL ✓
7	1		*Rear Tailgate LH Door H Logo <i>nei</i> ✓	20.00	0.00	*65.80 FL ✓
8	1		*Rear Tailgate LH Door STEPWAGON Logo <i>nei</i> ✓	20.00	0.00	*63.50 FL ✓
9	1		*Rear Tailgate LH Door Lower Outer Garnish <i>de</i> ✓	20.00	0.00	*225.50 FL ✓
10	1		*Tailgate LH Door Lower Garnish Black Cover <i>ht</i> ✓	20.00	0.00	*641.50 FL X
11	1	REPAIR	*Tailgate RH Door	20.00	0.00	-
12	1		*Tailgate RH Door Lower Outer Garnish <i>de</i> ✓	20.00	0.00	*456.70 FL ✓
13	1		*Tailgate RH Door Lower Garnish Black Cover ?	20.00	0.00	*170.20 FL X
14	1		*Reverse Sensor 1set ?	0	0.00	*250.00 FS X
15	1		*LH Taillamp Lower Garnish Reflector Light ?	20.00	0.00	*95.60 FL X
16	1		*LH Taillamp Lower Garnish Reflector Light Cover <i>ht</i> ✓	20.00	0.00	*40.50 FL ✓
17	1		*End Panel <i>Ry</i>	20.00	0.00	*565.50 FL X
18	1		*End Panel Garnish X	20.00	0.00	*115.20 FL X

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3512.70	5,463.30
- List Item Discount on L Items (\$\$)		1,034.66
Total Parts (\$\$)	2810.16	4,428.64
	SN-40	

Hitachi Capital Asia Pacific Pte. Ltd/SLC2109A/05/12/2017 18:17. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Supplementary \$4722.40 ✓

parts \$3512.70 - 20% = \$2810.16 ✓

S/Nett \$40 ✓

labour \$2550 ✓

* Total P/P \$10122.56 (a) 6 days #

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	Panel beat, cut, weld, re-align and replace damaged parts of REAR portion	New 1000	2,000.00
2	Spray painting on REAR portion of affected area	New 1000	1,800.00
3	Check Wiring, re-align taillamps and ensure proper function	New 40	80.00
4	Remove & reinstall 2 pieces bumper sensors	New 30	120.00
5	Cavity Treatment on New Parts (2 Panels)	New 60	160.00
6	Remove and Reinstall Reverse Camera	New 60	120.00
7	Remove & re-install Tailgate	New 120	180.00
8	Transfer tailgate lock & mechanism to new tailgate	New 200	200.00
9	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New 60	150.00
10	Remove & replace tailgate spoiler	New 60	150.00
11	Conduct water seepage test	New 40	120.00
Gross Labour Cost (S\$)			2550 5,080.00

Hitachi Capital Asia Pacific Pte. Ltd./SLC2109A/05/12/2017 18:17. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

© Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N

111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835

www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)

8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591



MANDATE REQUEST FOR S7M004DM

Type

🔗 Question

Message

Liability: Insured involved in 4 vehicle chain collision insured was the 2nd vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$10,831.14 (w/GST) Loss of Use : \$545.70 (6days x \$85)(w/GST) LTA: \$31.00 Total: \$11,407.84 Immediate Advice with Mandate and revised estimate for your easy reference. Please kindly let us have your approval / instruction if any. Thank you - Asher Sng (19/12/2018)

Reply



Re:MANDATE REQUEST FOR S7M004DM

Type

🔔 Question

Message

Pls proceed

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBD 1778M (Insd veh)	Model:	HONDA STEP WAGON
	SLC 2109A (TP veh)		
Date of Accident:	15/11/2017		

Global Sum Settlement	:	☐ Yes	☒ No	
Repair Estimate	:	\$	15,604.71	
Final Repair Cost	:	\$	10,831.14	
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$	545.70	6 days
LTA / GIA Search Fee	:	\$	31.00	

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	11,407.84

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks

Payment Instruction: Payee's Breakdown			
1)	HITACHI CAPITAL ASIA PACIFIC PTE. LTD.	:	\$ 11,407.84

NUR SHAQILAH BTE ABDOL
WAHAB

30/01/2019
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No. 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM17022082/T1eb3s2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 30-01-2019



ATTN: STACEY NG

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 1778M	Veh. Inspected	SLC 2109A
Policy No.	P1817384	Coverage (\$)	0.00
Claim No.	S7M004DM	Excess (\$)	0.00
Assign From	STACEY NG	Assign Date	20/11/2017

2. Vehicle Particulars & Condition

Make & Model	HONDA STEP WAGON	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RP31015573	Colour	WHITE
Odometer	043674	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60R16	YOKOHAMA	6 mm
L/H Front Tyre	205/60R16	YOKOHAMA	6 mm
R/H Rear Tyre	205/60R16	YOKOHAMA	6 mm
L/H Rear Tyre	205/60R16	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	15/11/2017	Inspection Date	08/12/2017
Survey held at	HITACHI CAPITAL (S) PTE LTD JUN TAIYO SERVICE CENTRE NO. 8 FOURTH LOK YANG ROAD SINGAPORE 629705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	6 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 2109A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR TAILGATE LH DOOR (CONSISTENT)	BENT	1,851.20	1,851.20
2	REAR TAILGATE LH DOOR HINGE TOP / LOWER (CONSISTENT)	TO REPAIR SEE LABOUR	181.00	-
4	REAR TAILGATE LH DOOR WINDSCREEN MOULDING (CONSISTENT)	NECESSARY	142.00	142.00
1	REAR TAILGATE LH DOOR LOCK (CONSISTENT)	NOT NECESSARY	307.60	-
1	REAR TAILGATE LH DOOR CHROME GARNISH (CONSISTENT)	DEFORMED	251.50	251.50
1	REAR TAILGATE LH DOOR H LOGO (CONSISTENT)	NECESSARY	65.80	65.80
1	REAR TAILGATE LH DOOR STEPWAGON LOGO (CONSISTENT)	NECESSARY	63.50	63.50
1	REAR TAILGATE LH DOOR LOWER OUTER GARNISH (CONSISTENT)	DEFORMED	641.50	641.50
1	TAILGATE LH DOOR LOWER GARNISH BLACK COVER (CONSISTENT)	NOT NECESSARY	641.50	-
1	TAILGATE RH DOOR (NPA) (CONSISTENT)	TO REPAIR SEE LABOUR	-	-
1	TAILGATE RH DOOR LOWER OUTER GARNISH (CONSISTENT)	DEFORMED	456.70	456.70
1	TAILGATE RH DOOR LOWER GARNISH BLACK COVER (CONSISTENT)	NOT NECESSARY	170.20	-
1	LH TAILLAMP LOWER GARNISH REFLECTOR LIGHT (CONSISTENT)	NOT NECESSARY	95.60	-
1	LH TAILLAMP LOWER GARNISH REFLECTOR LIGHT COVER (CONSISTENT)	CUT	40.50	40.50
1	END PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	565.50	-
1	END PANEL GARNISH (CONSISTENT)	NOT NECESSARY	115.20	-
1	TAILGATE HANDLE COVER (CONSISTENT) (ADDITIONAL)	DEFORMED	35.00	35.00
1	TAILGATE RH DOOR TOP OUTER GARNISH (CONSISTENT) (ADDITIONAL)	DEFORMED	445.00	445.00
1	TAILGATE BASE ASSEMBLY (CONSISTENT) (ADDITIONAL)	BENT	2,850.00	2,850.00
1	TAILGATE RH DOOR CENTER HANDLE GARNISH (CONSISTENT) (ADDITIONAL)	DEFORMED	128.00	128.00
1	REAR GLASS LH (CONSISTENT) (ADDITIONAL)	NECESSARY	1,250.00	1,250.00

Report Ref No. CC4/ASM17022082/T1eb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR GLASS RH (CONSISTENT) (ADDITIONAL)	NECESSARY	1,120.00	1,120.00
1	REAR WINDSCREEN MOULDING RH (CONSISTENT) (ADDITIONAL)	NECESSARY	75.00	75.00
	LESS 20% DISCOUNT		-2,298.46	-1,883.14
			9,193.84	7,532.56
	SPECIAL NETT ITEMS			
1	REAR TAILGATE LH DOOR WINDSCREEN SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	SET REVERSE SENSOR (SN) (CONSISTENT)	NOT NECESSARY	250.00	-
			290.00	40.00
	LABOUR			
	PANEL BEAT, CUT, WELD, RE-ALIGN AND REPLACE DAMAGED PARTS OF REAR PORTION. INCLUSIVE OF THE REPAIR OF REAR TAILGATE LH DOOR HINGE TOP / LOWER, TAILGATE RH DOOR AND END PANEL.		2,000.00	1,000.00
	SPRAY PAINTING ON REAR PORTION OF AFFECTED AREA.		1,800.00	1,000.00
	CHECK WIRING, RE-ALIGN TAILLAMPS AND ENSURE PROPER FUNCTION.		80.00	40.00
	REMOVE & REINSTALL 2 PIECES BUMPER SENSORS.		120.00	30.00
	CAVITY TREATMENT ON NEW PARTS (2 PANELS)		180.00	60.00
	REMOVE AND REINSTALL REVERSE CAMERA.		120.00	60.00
	REMOVE & RE-INSTALL TAILGATE.		180.00	120.00
	TRANSFER TAILGATE LOCK & MECHANISM TO NEW TAILGATE.		200.00	80.00
	REMOVE & RE-INSTALL REAR TRIM COMPARTMENT TO FACILITATE CUTTING AND REPAIRING WORK.		150.00	60.00
	REMOVE & REPLACE TAILGATE SPOILER.		150.00	60.00
	CONDUCT WATER SEEPAGE TEST.		120.00	40.00
			-	-
			-	-
			-	-
			5,100.00	2,550.00
GRAND TOTAL			14,583.84	10,122.56

Report Ref No. CC4/ASM17022082/T1eb3s2



RECOMMENDED COST OF REPAIRS			10,122.56
-----------------------------	--	--	-----------

Report Ref No. CC4/ASM17022082/T1eb3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.