

TP INSURER: AXA Insurance Pte Ltd (HQ)
 YI WAN CONSTRUCTION PTE LTD
 UNKNOWN
 Singapore UNKNOWN

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	SLC2109A
Policy No:	P1817384	Date of Loss:	15/11/2017
Vehicle Reg. No.:	SLC2109A	Driveable?	
Party At Fault:	UNKNOWN	Driver (Insured):	MURUGAN RAGUVARAN
Driver (TP):	ANG GOON HWEE		
Make/Model:	HONDA STEPWAGON SPADA, 1.5 (A)	Vehicle Reg. Date:	05/05/2016
Vehicle Colour:	WHITE	Chassis No:	L15B3586219
Engine No:	RP31015573		
Odometer:	16850 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair 10 (day)			
Description of Accident/Loss	PLEASE REFER TO THE ATTACHMENT.		
Present Location:	HITACHI CAPITAL ASIA PACIFIC PTE. LTD (HQ)		

Tanpin 97445749
wp
8/12/17 @ 1530
6 days
Resurvey before paint
Surv@kkhant.com

COST OF CLAIMS

	Amount
Parts	4,428.64
Miscellaneous Items	0.00
Labour	5,080.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,508.64
+ GST 7.00% (S\$)	665.60
Nett Amount (S\$)	10,174.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This claim is handled by: SUN ZHU MEI

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Dec 2017)
Parts: M1-MPV HONDA STEPWAGON SPADA 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: Hitachi Capital Asia Pacific Pte. Ltd/SLC2109A/05/12/2017 18:17
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear Tailgate LH Door <i>by</i> ✓	20.00	0.00	/ *1,851.20 FL
2	2		*Rear Tailgate LH Door Hinge Top / Lower <i>Ry</i>	20.00	0.00	1 *181.00 FL
3	4		*Rear Tailgate LH Door Windscreen Moulding <i>nei</i> ✓	20.00	0.00	- *142.00 FL
4	1		*Rear Tailgate LH Door Windscreen Sealant <i>nei</i> ✓	0	0.00	- *40.00 FS
5	1		*Rear Tailgate LH Door Lock ?	20.00	0.00	1 *307.60 FL
6	1		*Rear Tailgate LH Door Centre Garnish <i>de</i> ✓	20.00	0.00	- *251.50 FL
7	1		*Rear Tailgate LH Door H Logo <i>nei</i> ✓	20.00	0.00	- *65.80 FL
8	1		*Rear Tailgate LH Door STEPWAGON Logo <i>nei</i> ✓	20.00	0.00	- *63.50 FL
9	1		*Rear Tailgate LH Door Lower Outer Garnish <i>de</i> ✓	20.00	0.00	- *225.50 FL
10	1		*Tailgate LH Door Lower Garnish Black Cover <i>nei</i> ✓	20.00	0.00	- *641.50 FL
11	1	REPAIR	*Tailgate RH Door	20.00	0.00	-
12	1		*Tailgate RH Door Lower Outer Garnish <i>de</i> ✓	20.00	0.00	- *456.70 FL
13	1		*Tailgate RH Door Lower Garnish Black Cover ?	20.00	0.00	1 *170.20 FL
14	1		*Reverse Sensor 1set ?	0	0.00	1 *250.00 FS
15	1		*LH Taillamp Lower Garnish Reflector Light ?	20.00	0.00	1 *95.60 FL
16	1		*LH Taillamp Lower Garnish Reflector Light Cover <i>nei</i> ✓	20.00	0.00	- *40.50 FL
17	1		*End Panel <i>Ry</i>	20.00	0.00	1 *565.50 FL
18	1		*End Panel Garnish <i>x</i>	20.00	0.00	1 *115.20 FL

F=Franchise part. S=SpcNett. L=ListItemDisc

Sub Total (S\$)	5,463.30
- List Item Discount on L Items (S\$)	1,034.66
Total Parts (S\$)	4,428.64

Hitachi Capital Asia Pacific Pte. Ltd/SLC2109A/05/12/2017 18:17. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	Panel beat, cut, weld, re-align and replace damaged parts of REAR portion	New 1000	2,000.00
2	Spray painting on REAR portion of affected area	New 1000	1,800.00
3	Check Wiring, re-align taillamps and ensure proper function	New 40	80.00
4	Remove & reinstall 2 pieces bumper sensors	New 30	120.00
5	Cavity Treatment on New Parts (2 Panels)	New 60	160.00
6	Remove and Reinstall Reverse Camera	New 60	120.00
7	Remove & re-install Tailgate	New 120	180.00
8	Transfer tailgate lock & mechanism to new tailgate	New 180	200.00
9	Remove & re-install rear trim compartment to facilitate cutting and repairing work	New 60	150.00
10	Remove & replace tailgate spoiler	New 60	150.00
11	Conduct water seepage test	New 40	120.00
Gross Labour Cost (S\$)			5,080.00

Hitachi Capital Asia Pacific Pte. Ltd/SLC2109A/05/12/2017 18:17. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Hitachi Capital Asia Pacific Pte. Ltd. (Main Office) Co. Reg. No. 199400399N
111 Somerset Road #11-05 Singapore 238164 Tel: (65) 6734 1222 Fax : 6734 8835
www.hitachi-capital.com.sg

Jun Taiyo Service Centre (Automobile Leasing & Workshop)
8 Fourth Lok Yang Road Singapore 629705 Tel: (65) 6466 3022 Fax: (65) 6896 6591