

INS CASE OWNER:

CC 4 / ICS170 22083, Ueg3 9

LKK:

IDAC:

Surveyor:

MARCUS

DOI:

ASSIGNMENT

22/1/18

Date / Time:

17/1/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SJS 3643 G

Name of Insured:

Lee Suet Tan

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Strip

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

Gour Hock  
93069289

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Bmpc1700689 H

Policy No.:

WPL17AD0376W1

Make / Model:

Honda Fit

Place of Accident:

PIE &gt; Airport

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

FBO 8294X



INSRS:

WSP:

Tel:

Liability:

RMKS:

Ban Hock

TA 1



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

22/1/18

11/12/17

11/12/17 + 9:40am

13/12/17 + 10:30

26/1/18

FBO 8294X. X;

SJS 3643G - call 11/12/17 10:47am / 11/12/17 10:47am

- call 11/12/17 10:47am / 11/12/17 10:47am

- call 11/12/17 10:47am / 11/12/17 10:47am

CALLED ON NO RESPONSE

CALLED ON/NO NO RESPONSE.

FILE PREP TO TYPST TO PREPARE REPORT.

RECEIVED 28 JAN 2018

RECEIVED 28 MAR 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

22/1/18

Sent By:

Hank

FINALIZATION

Date/Time:

19/1/18

Confirm with: Raymond

Confirm by: Marcus

Repair Cost:

PIP \$56,615.40

( 6 days)

Reduction:

51 %

Email

Call

FINAL SETTLEMENT

Date/Time:

6/3/18

Confirm with: Raymond

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

28 I

If NO or B 28, Ass. Lia.:

100%

Repair Cost:

W/L \$7,018.48

5 VEH CC OLD HIT TP1 AND TP2.

Loss of Rental (LOR):

\$5 -

( days)

Loss of Use (LOU):

\$5 120.00

(\$20 x 6 days)

Loss of Income (LOI):

\$5 -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

\$5 2.00

Medical

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

Total:

\$5 7,200.48

Global Sum \$5:

FINAL PAYMENT

Date/Time:

6/3/18

Confirm with: Raymond

Email

Call

Payee 1:

\$5 7,200.48

Name 1:

BANK HOCK HUN CO. PIE 100.

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

450

REF:

SCIS

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To inspect Vehicle No: F3D8284X  
 at Workshop m/s: 3HM  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 7200k  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 6 days Res: Yes or No  
 Lum Sum: - % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: F3D8284X Regn: 0809  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Yamaha FJR1300 cc 1298  
 Colour: Black A/C: Insured / Std / NI / NA  
 Sp. Reading: 72462 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JYARP13A000005176  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 120/70ZR17  
 R: 180/55ZR17  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal: 6 mm R/Bal: 6 mm  
 L/Bal: \_\_\_\_\_ mm L/Bal: \_\_\_\_\_ mm  
 D.O.A: 5/11/17 D.O.I: 20/11/17  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Rear, L/R, N/S, S/L  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: \_\_\_\_\_ Action / Instruction: LTA 154  
after 7k. 1yrs 9mth. Rep 3500  
maybe TOTAL 1055 after repair Raymond 7k.

PP: +6,615.40 (RED: + 0,661.53 57%)

Date/Time: File Pass to?

☐ : Prel. Report  
☐ : Final Report

1)

Date/Time: File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)☐ : Interview (\$ \_\_\_\_\_)☐ : Tech. Invs (\$ \_\_\_\_\_)☐ : Weekend (\$ \_\_\_\_\_)

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC4/ICS17022083/Uea3

Date: 22.11.2017

The Motor Claims Department  
M/s ECICS LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**FBD 8294X**

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20/11/2017 at the premises of M/s Ban Hock Hin Co. Pte Ltd - Defu Lane have the following to report:-

Workshop Estimate Amount	: S\$	14,277.50
Revised Estimate Amount	: S\$	8,008.50
"Check" Items Amount	: S\$	2,346.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

**Description of Damage:**

The vehicle sustained damages at the  
N/S Body , Front & Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 6.0 day

Yours faithfully,

SEBASTIAN YEANG  
Licensed Appraiser






## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CC4/ICS17022083/Uea3		
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987		Date : 20-11-2017		
		Code : ICS		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJS 3643G	Veh. Inspected	FBD 8294X	
Policy No.	MPC17A00376101	Coverage (\$)	0.00	
Claim No.	DMPC1700689H	Excess (\$)	0.00	
Assign From		Assign Date	20/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	05/11/2017	Inspection Date	20/11/2017	
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



**BAN HOCK HIN**  
Co., Pte Ltd

Co. Reg. No. 197000290K

MOTORCYCLE ACCESSORIES / SERVICE CENTRE  
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL  
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

## QUOTATION

Customer

NO. : 32149

ECICS LIMITED

T TEMASEK BOULEVARD  
#10-01 SUNTEC TOWER ONE  
Singapore 038987

MOTOR CLAIMS DEPT

DATE : 17/11/2017  
CLAIM NO. : 11059  
POLICY NO : MC/00088515/05  
FROM : RAYMOND

VEHICLE NO : FBD8294X  
MAKE/MODEL : YAM / FJR1300 ABS

please check MV & ?

7/12 6615.40 19/1/18 (Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALL BEARING STEERING CONE (BIG) P/N: 13452	REPLACE	1.00	\$1.50	1.50
2	BAR HANDLE LH	REPLACE	1.00	\$218.00	218.00
3	BOX SIDE (LH) P/N: 40574	REPLACE	1.00	\$1,880.00	1,880.00
4	BOX SIDE (RH) P/N: 40575	REPLACE	1.00	\$1,880.00	1,880.00
5	COVER CRANKCASE LH P/N: 55870	REPLACE	1.00	\$182.00	182.00
6	COVER GRIP (GRAB ON) P/N: 56090	REPLACE	1.00	\$75.00	75.00
7	COVER SIDE RH 2	REPLACE	1.00	\$90.00	90.00
8	COVER TAIL 2	REPLACE	1.00	\$165.00	165.00
9	COWLING UPPER ASSY 1 P/N: 40617	REPLACE	1.00	\$283.00	283.00
10	DAMPER COVER SIDE RH 2	REPLACE	1.00	\$8.50	8.50
11	EMBLEM 3D	REPLACE	1.00	\$38.00	38.00
12	FOOTREST REAR RH	REPLACE	1.00	\$21.00	21.00
13	FRAME REAR COMP	REPLACE	1.00	\$1,365.00	1,365.00



S/N	Description	Action	Qty	Unit Price	Amount
14	GASKET CRANKCASE COVER P/N 48868	REPLACE	1.00	\$25.00	25.00
15	GASKET MUFFLER P/N 49863	REPLACE	2.00	\$18.00	36.00
16	LABOUR P/N 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	* Supply/Install	24.00	\$35.00	840.00
17	LOWER FRONT BODY RH P/N 40590	REPLACE	1.00	\$1,190.00	1,190.00 X
18	MIRROR LH P/N 40593	REPLACE	1.00	\$248.00	248.00
19	MIRROR RH P/N 40594	REPLACE	1.00	\$248.00	248.00 X
20	MUFFLER ASSY 1 <i>LH</i> P/N 40595	REPLACE	1.00	\$1,659.00	1,659.00 X
21	MUFFLER ASSY 2 <i>RH</i> P/N 40596	REPLACE	1.00	\$1,659.00	1,659.00 ✓
22	PEDAL GEAR	REPLACE	1.00	\$145.00	145.00
23	PLUG COVER 2 P/N 45266	REPLACE	2.00	\$3.00	6.00 ✓
24	<del>REPAIR FUEL TANK</del>	* Repair	1.00	\$155.00 <i>1205.00</i>	155.00
25	RIVERT P/N 49845	REPLACE	10.00	\$1.50	15.00
26	RUBBER FOOTREST FRONT P/N 34783	REPLACE	1.00	\$25.00	25.00
27	SCREW PAN HEAD P/N 24409	REPLACE	2.00	\$2.50	5.00
28	SEAT ASSY TANDEM	REPLACE	1.00	\$357.00	357.00
29	SLIDER FRAME SET (MOTOVATION) P/N 40764	REPLACE	1.00	\$138.00	138.00
30	SPRAY PAINTING ON FUEL TANK <i>Edoing</i>	Spray *	1.00	\$250.00	250.00
31	SPRING COMPRESSION	REPLACE	1.00	\$1.50	1.50
32	STAY 1 P/N 40613	REPLACE	1.00	\$685.00	685.00 ✓
33	STAY 1 P/N 40612	REPLACE	1.00	\$285.00	285.00 ✓
34	STAY MUFFLER 2	REPLACE	1.00	\$98.00	98.00

SUB TOTAL  
NET TOTAL\$14,277.50  
TOTALP-6406  
5765-4

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
<b>GRAND TOTAL</b>					<b>\$15,276.93</b>

Validity: 30 days

For &amp; on Behalf of

**BAN HOCK HIN CO PTE LTD**

Acknowledge &amp; Accepted By

**RAYMOND**

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

UKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To resurvey damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No repair modification(s) is allowed
- Supplemental item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:





S/N	Description	Action	Qty	Unit Price	Amount
14	MUFFLER ASSY 2 P/N: 40596	REPLACE	1.00	\$1,659.00	1,493.10
				Disc %: 10.00	
15	PEDAL GEAR	REPLACE	1.00	\$145.00	130.50
				Disc %: 10.00	
16	PLUG COVER 2 P/N: 45266	REPLACE	2.00	\$3.00	5.40
				Disc %: 10.00	
17	REPAIR FUEL TANK	Repair	1.00	\$120.00	120.00
18	RIVERT P/N: 49845	REPLACE	10.00	\$1.50	13.50
				Disc %: 10.00	
19	RUBBER FOOTREST FRONT P/N: 34783	REPLACE	1.00	\$25.00	22.50
				Disc %: 10.00	
20	SCREW PAN HEAD P/N: 24409	REPLACE	2.00	\$2.50	4.50
				Disc %: 10.00	
21	SEAT ASSY TANDEM	REPLACE	1.00	\$357.00	321.30
				Disc %: 10.00	
22	SLIDER FRAME SET (MOTOVATION) P/N: 40764	REPLACE	1.00	\$138.00	124.20
				Disc %: 10.00	
23	SPRAY PAINTING ON FUEL TANK	Spray	1.00	\$250.00	250.00
24	SPRING COMPRESSION	REPLACE	1.00	\$1.50	1.35
				Disc %: 10.00	
25	STAY 1 P/N: 40613	REPLACE	1.00	\$685.00	616.50
				Disc %: 10.00	
26	STAY 1 P/N: 40612	REPLACE	1.00	\$285.00	256.50
				Disc %: 10.00	
27	STAY MUFFLER 2	REPLACE	1.00	\$98.00	88.20
				Disc %: 10.00	

SUB TOTAL

\$6,615.40

GST @ 7 %

\$463.08

GRAND TOTAL

\$7,078.48

Validity: 30 days

For &amp; on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge &amp; Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-1-0303  
ISO 9001: 2008





## QUOTATION

Customer :

NO. : 32149

- Rev. 1

ECICS LIMITED  
T TEMASEK BOULEVARD  
#10-01 SUNTEC TOWER ONE  
Singapore 038987

DATE : 17/11/2017  
CLAIM NO. : 11059  
POLICY NO. : MC/00088515/05

MOTOR CLAIMS DEPT

FROM : RAYMOND

VEHICLE NO. : FBD8294X  
MAKE/MODEL : YAM / FJR1300 ABS

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE LH	REPLACE	1.00	\$218.00	196.20
				Disc %: 10.00	
2	BOX SIDE (RH) P/N: 40575	REPLACE	1.00	\$1,880.00	1,692.00
				Disc %: 10.00	
3	COVER CRANKCASE LH P/N: 55870	REPLACE	1.00	\$182.00	163.80
				Disc %: 10.00	
4	COVER GRIP (GRAB ON) P/N: 56090	REPLACE	1.00	\$75.00	67.50
				Disc %: 10.00	
5	COVER SIDE RH 2	REPLACE	1.00	\$90.00	81.00
				Disc %: 10.00	
6	COVER TAIL 2	REPLACE	1.00	\$165.00	148.50
				Disc %: 10.00	
7	DAMPER COVER SIDE RH 2	REPLACE	1.00	\$8.50	7.65
				Disc %: 10.00	
8	EMBLEM 3D	REPLACE	1.00	\$38.00	34.20
				Disc %: 10.00	
9	FOOTREST REAR RH	REPLACE	1.00	\$21.00	18.90
				Disc %: 10.00	
10	GASKET CRANKCASE COVER P/N: 48868	REPLACE	1.00	\$25.00	22.50
				Disc %: 10.00	
11	GASKET MUFFLER P/N: 49863	REPLACE	2.00	\$18.00	32.40
				Disc %: 10.00	
12	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	1.00	\$480.00	480.00
13	MIRROR LH P/N: 40593	REPLACE	1.00	\$248.00	223.20
				Disc %: 10.00	





**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES / SERVICE CENTRE  
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL  
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

## QUOTATION

Customer :

NO. : 32149

ECICS LIMITED  
T TEMASEK BOULEVARD  
#10-01 SUNTEC TOWER ONE  
Singapore 038987

MOTOR CLAIMS DEPT

VEHICLE NO. : FBD8294X  
MAKE/MODEL : YAM / FJR1300 ABS

DATE : 17/11/2017  
CLAIM NO. : 11059  
POLICY NO. : MC/00088515/05  
FROM : RAYMOND

*Not Done yet*  
*maybe TOTAL 1055 ?*  
*20/11/17*  
*TU: 62563561*  
*6 day.*  
*please check MV & ?*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALL BEARING STEERING CONE (BIG) P/N: 13452	REPLACE	1.00	\$1.50	1.50 X
2	BAR HANDLE LH	REPLACE	1.00	\$218.00	218.00
3	BOX SIDE (LH) P/N: 40574	REPLACE	1.00	\$1,880.00	1,880.00 X
4	BOX SIDE (RH) P/N: 40575	REPLACE	1.00	\$1,880.00	1,880.00
5	COVER CRANKCASE LH P/N: 55870	REPLACE	1.00	\$182.00	182.00
6	COVER GRIP (GRAB ON) P/N: 56090	REPLACE	1.00	\$75.00	75.00
7	COVER SIDE RH 2	REPLACE	1.00	\$90.00	90.00
8	COVER TAIL 2	REPLACE	1.00	\$165.00	165.00 X
9	COWLING UPPER ASSY 1 P/N: 40617	REPLACE	1.00	\$283.00	283.00 X
10	DAMPER COVER SIDE RH 2	REPLACE	1.00	\$8.50	8.50 X
11	EMBLEM 3D	REPLACE	1.00	\$38.00	38.00
12	FOOTREST REAR RH	REPLACE	1.00	\$21.00	21.00
13	FRAME REAR COMP	REPLACE	1.00	\$1,365.00	1,365.00 ?



S/N	Description	Action	Qty	Unit Price	Amount
14	GASKET CRANKCASE COVER P/N: 48868	REPLACE	1.00	\$25.00	25.00
15	GASKET MUFFLER P/N: 49863	REPLACE	2.00	\$18.00	36.00
16	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	24.00	\$35.00	840.00
17	LOWER FRONT BODY RH P/N: 40590	REPLACE	1.00	\$1,190.00	1,190.00
18	MIRROR LH P/N: 40593	REPLACE	1.00	\$248.00	248.00
19	MIRROR RH P/N: 40594	REPLACE	1.00	\$248.00	248.00
20	MUFFLER ASSY 1 <i>LH</i> P/N: 40595	REPLACE	1.00	\$1,659.00	1,659.00
21	MUFFLER ASSY 2 <i>RH</i> P/N: 40596	REPLACE	1.00	\$1,659.00	1,659.00
22	PEDAL GEAR	REPLACE	1.00	\$145.00	145.00
23	PLUG COVER 2 P/N: 45266	REPLACE	2.00	\$3.00	6.00
24	REPAIR FUEL TANK	Repair	1.00	\$155.00	155.00
25	RIVERT P/N: 49845	REPLACE	10.00	\$1.50	15.00
26	RUBBER FOOTREST FRONT P/N: 34783	REPLACE	1.00	\$25.00	25.00
27	SCREW PAN HEAD P/N: 24409	REPLACE	2.00	\$2.50	5.00
28	SEAT ASSY TANDEM	REPLACE	1.00	\$357.00	357.00
29	SLIDER FRAME SET (MOTOVATION) P/N: 40764	REPLACE	1.00	\$138.00	138.00
30	SPRAY PAINTING ON FUEL TANK <i>8 hours</i>	Spray	1.00	\$250.00	250.00
31	SPRING COMPRESSION	REPLACE	1.00	\$1.50	1.50
32	STAY 1 P/N: 40613	REPLACE	1.00	\$685.00	685.00
33	STAY 1 P/N: 40612	REPLACE	1.00	\$285.00	285.00
34	STAY MUFFLER 2	REPLACE	1.00	\$98.00	98.00

SUB TOTAL  
GST @ 7%

\$14,277.50  
\$15,277.50



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
<b>GRAND TOTAL</b>					<b>\$15,276.93</b>

Validity: 30 days

For & on Behalf of  
**BAN HOCK HIN CO PTE LTD**

Acknowledge &amp; Accepted By

**RAYMOND**

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:





## Asher Sng (LKKAUTO)

---

**From:** Asher Sng (LKKAUTO)  
**Sent:** Thursday, 23 November, 2017 10:56 AM  
**To:** 'Raymond'  
**Cc:** Vic (LKKAUTO)  
**Subject:** RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Raymond [mailto:[raymond@bhh.com.sg](mailto:raymond@bhh.com.sg)]  
**Sent:** Thursday, 23 November, 2017 10:54 AM  
**To:** Asher Sng (LKKAUTO) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>  
**Cc:** Vic (LKKAUTO) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>  
**Subject:** FW: Accident Involving FBD8294X & SJS3643G on 05/11/2017

Dear Asher,

Sorry we have quoted the wrong third party vehicle, should be SJS3643G instead of SJJ8958M.

We attached the Traffic Police Investigation Result for your perusal.

Appreciate for you to revert with your insured liability for direct settlement.

Thanks

Best Regards,  
Raymond

**Ban Hock Hin Co., Pte Ltd**

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



**No. 6 Defu Lane 4, Singapore 539410**

[www.bhh.com.sg](http://www.bhh.com.sg)

**MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS |**



**From:** Asher Sng (LKKAuto) [<mailto:AsherSng@lkkauto.com>]  
**Sent:** Wednesday, 22 November, 2017 3:51 PM  
**To:** Raymond <[raymond@bhh.com.sg](mailto:raymond@bhh.com.sg)>  
**Cc:** Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>  
**Subject:** RE: Accident Involving FBD8294X & SJJ8958M on 05/11/2017

Hi Raymond,

We refer to the above matter.

Please be informed that we are currently pending for our insured's GIA report.

We shall revert to you upon receiving our insured report from our principal.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Raymond [<mailto:raymond@bhh.com.sg>]  
**Sent:** Wednesday, 22 November, 2017 3:41 PM  
**To:** Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>  
**Subject:** Accident Involving FBD8294X & SJJ8958M on 05/11/2017

Dear Asher,

Mr. Marcus has conducted the pre-repair survey on 21/11/2017.

Please advise your insured liability for direct settlement as soon as possible.

Thanks

Best Regards,  
Raymond

**Ban Hock Hin Co., Pte Ltd**

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



**BAN HOCK HIN**  
Co., Pte Ltd

No. 6 Defu Lane 4, Singapore 539410

[www.bhh.com.sg](http://www.bhh.com.sg)

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS |





**BAN HOCK HIN**  
Co., Pte Ltd

Co. Reg. No: 197000288K

MOTORCYCLE ACCESSORIES / SERVICE CENTRE  
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL  
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

22 JAN 2018

Your Ref : SJS3643G  
Our Ref : TP/11059/FBD8294X/SJS3643G

BY FAX & HAND

ECICS Limited  
Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987

ATTN: Motor Claims Dept

Dear Sir/Madam,

Accident Involving FBD8294X & SJS3643G on 05/11/2017

We refer to the above-mentioned matter.

As instructed by our client, we proceed to quantify our claim as itemized below:

1. Cost of Repair (Inc 7% GST)	\$7,078.48
2. Loss of Use (6 days x \$20)	\$ 120.00
3. GIA Vehicle Insurance Search Fee	\$ 2.00
<b>TOTAL</b>	<b>\$7,200.48</b>

We attached our Tax Invoice and GIA Search Invoice for your perusal.

Please acknowledge receipt.

If you require any further clarification, please do not hesitate to contact Mr Raymond at 6281 6520 ext. 220.

Thank you.

**BAN HOCK HIN CO PTE LTD**

Raymond Tan  
Manager/Insurance Dept







Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

**Our Ref: CC4/ICS17022083/Uea3, CC4/ICS17021606/Ueb3**

14 DEC 2017

**LEE SUET FUN**  
BLK 688C WOODLANDS DRIVE 75  
#15-36  
SINGAPORE 733688

Dear Sir/Madam,

**ACCIDENT INVOLVING SJS 3643G & SJM 4388T & FBD 8294X AT / ALONG  
PIE TOWARDS AIRPORT AFTER CTE EXIT ON 05/11/2017.**

We refer to the above accident, we are the loss adjusters acting on behalf of M/s ECICS Limited, the Motor Insurer of SJS 3643G on the reported accident on 05/11/2017.

Our Principal has received a Third Party property damage claim from the owner of SJM 4388T & FBD 8294X with regards to the above accident.

We will try our best to negotiate for an amicable settlement on best possible terms with Third Party under the terms and conditions of your motor policy. In this respect, the vehicle's premium/NCD may be affected as a result of the above claim.

In the event that you receive any letters/ court documents regards to the above accident matter, please do not reply or respond, you may forward to us directly for further handling and we will reply on your behalf.

Thank you.

Yours faithfully,

Asher  
Case Handler  
DID: 6841 6051  
FAX: 6741 4108  
Email: [Ashersng@lkkauto.com](mailto:Ashersng@lkkauto.com)

c.c. *ECICS Limited*  
(Motor Claims Dept)

## LETTER OF AUTHORISATION

Your Ref : SJS3643G  
Our Ref : TP/11059/FBD8294X/SJS3643G

BY FAX & HAND

ECICS Limited  
Temasek Boulevard  
#10-01 Suntec Tower One  
Singapore 038987

**ATTN: Motor Claims Dept**

Dear Sir/Madam,

**Accident Involving FBD8294X & SJS3643G on 05/11/2017**

### AUTHORIZATION LETTER

I / We refer to the above-mentioned matter.

I, MUHAMMAD SHAFUL ANWAR BIN ABDUL RAZAK hereby irrevocably authorize Ban Hock Hin Co., Pte Ltd to act on our behalf to file a 3<sup>rd</sup> Party Claim against your Insured SJS3643G.

I / We further authorize M/s ECICS Limited to release the claim and payment to M/s Ban Hock Hin Co., Pte Ltd in consideration of their allowing me to take possession of my motorcycle FBD8294X upon completion of repairs.

If you need any verification from us, kindly direct all enquiries and correspondences to M/s Ban Hock Hin Co., Pte Ltd.

Yours faithfully

Witness



.....  
Claimant (Signature & Company Stamp)

.....  
Witness Signature

MUHAMMAD SHAFUL ANWAR BIN ABDUL RAZAK Raymond Tan G7715235R

..... S7621270H

Name & NRIC No

.....  
Name & NRIC No

**DISCHARGE VOUCHER**

CLAIM NO: DMPC1700689H

In consideration of the payment of the sum of **DOLLAR SEVEN THOUSAND TWO HUNDRED AND CENTS FORTY EIGHT ONLY. (S\$7,200.48)**, I/We, hereby accept such sum in full and final settlement of all claims, present or future, that I/We have or may have against ECICS Limited, **LEE SUET FUN** as insurers, owner and driver of Vehicle no. **SJS 3643G** in connection with or in any way arising from the accident involving the said vehicle which occurred on **05/11/2017** at **PIE (CHANGI) AT THE 15KM MARK BEFORE WHAMPOA FLYOVER** with **FBD 8294X**.

I/We further agree that this payment is made without any admission of liability on the part of the said insurers, owner and driver of the vehicle no. **SJS 3643G** and this settlement does not in any way prejudice or prevent any party from making any claim whatsoever which may arise from the damage caused to the vehicle no. **FBD 8294X** in the above mentioned accident. I/We further undertake not to make any reference to the settlement herein mentioned in respect of such claim.

\*I/We authorize you to pay the above settlement sum to **BAN HOCK HIN CO.PTE LTD.**

*DATED THIS <u>11th</u> DAY OF <u>March</u> 20 <u>18</u>	
Signature &/or Co Stamp: <u>[Signature]</u>	Signature &/or Co Stamp: <u>[Signature]</u>
Name of Claimant: <u>Muhammad Shaiful Anwar</u> <u>Bin Abdul Razak</u>	Name of Witness: <u>Tan Chok Loo</u>
Address: <u>Blk 127 Corner Street 1</u> <u>#01-204 S(520127)</u>	Address: <u>6 De Fu Lane 4</u> <u>Singapore 51940</u>
Occupation: <u>Logistic Analyst</u>	Occupation: <u>Manager</u>
NRIC No: <u>S62820838</u>	NRIC No: <u>67715235R</u>

\* Delete if not applicable

\* Please ensure the date is duly filled in

WITHOUT PREJUDICE to:

the insurers' Subrogation Claim and/or

the claimant's third party Claims

except This Notice supersedes any

other notices found in the Discharge

DV TPD (Ver Jan 16)



**BAN HOCK HIN**  
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES / SERVICE CENTRE  
MODIFICATIONS / SPRAY PAINTING AND BODY WORK / METAL  
WORKS / LEASING & RENTALS / FLEET SALES / INSURANCE SALES

## TAX INVOICE

GST Reg No. : M2-0010542-7

Customer :

ECICS LIMITED  
T TEMASEK BOULEVARD  
#10-01 SUNTEC TOWER ONE  
Singapore 038987

MOTOR CLAIMS DEPT

Invoice No. : DLCR40097329-I11059  
Invoice Date : 12/01/2018  
Payment Due Date : 11/02/2018

CLAIM NO. : 11059  
POLICY NO. : MC/00088515/05  
VEHICLE NO. : FBD8294X  
MAKE/MODEL : YAM / FJR1300 ABS

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE LH	REPLACE	1	\$218.00	\$196.20
				Disc %: 10%	
2	STAY 1	REPLACE	1	\$685.00	\$616.50
				Disc %: 10%	
3	STAY MUFFLER 2	REPLACE	1	\$98.00	\$88.20
				Disc %: 10%	
4	REPAIR FUEL TANK	Repair	1	\$120.00	\$120.00
5	SPRAY PAINTING ON FUEL TANK	Spray	1	\$250.00	\$250.00
6	LABOUR	Supply/Install	1	\$480.00	\$480.00
7	BOX SIDE (RH)	REPLACE	1	\$1,880.00	\$1,692.00
				Disc %: 10%	
8	COVER CRANKCASE LH	REPLACE	1	\$182.00	\$163.80
				Disc %: 10%	
9	COVER GRIP (GRAB ON)	REPLACE	1	\$75.00	\$67.50
				Disc %: 10%	
10	COVER SIDE RH 2	REPLACE	1	\$90.00	\$81.00
				Disc %: 10%	
11	COVER TAIL 2	REPLACE	1	\$165.00	\$148.50
				Disc %: 10%	
12	DAMPER COVER SIDE RH 2	REPLACE	1	\$8.50	\$7.65
				Disc %: 10%	
13	EMBLEM 3D	REPLACE	1	\$38.00	\$34.20
				Disc %: 10%	
14	FOOTREST REAR RH	REPLACE	1	\$21.00	\$18.90
				Disc %: 10%	
15	GASKET CRANKCASE COVER	REPLACE	1	\$25.00	\$22.50
				Disc %: 10%	
16	GASKET MUFFLER	REPLACE	2	\$18.00	\$32.40
				Disc %: 10%	
17	MIRROR LH	REPLACE	1	\$248.00	\$223.20
				Disc %: 10%	
18	MUFFLER ASSY 2	REPLACE	1	\$1,659.00	\$1,493.10
				Disc %: 10%	





S/N	Description	Action	Qty	Unit Price	Amount
19	PEDAL GEAR	REPLACE	1	\$145.00	\$130.50
				Disc %: 10%	
20	PLUG COVER 2	REPLACE	2	\$3.00	\$5.40
				Disc %: 10%	
21	RIVERT	REPLACE	10	\$1.50	\$13.50
				Disc %: 10%	
22	RUBBER FOOTREST FRONT	REPLACE	1	\$25.00	\$22.50
				Disc %: 10%	
23	SCREW PAN HEAD	REPLACE	2	\$2.50	\$4.50
				Disc %: 10%	
24	SEAT ASSY TANDEM	REPLACE	1	\$357.00	\$321.30
				Disc %: 10%	
25	SLIDER FRAME SET (MOTOVATION)	REPLACE	1	\$138.00	\$124.20
				Disc %: 10%	
26	SPRING COMPRESSION	REPLACE	1	\$1.50	\$1.35
				Disc %: 10%	
27	STAY 1	REPLACE	1	\$285.00	\$256.50
				Disc %: 10%	
SUB TOTAL					\$6,615.40
GST @ 7 %					\$463.08
GRAND TOTAL					\$7,078.48

Validity: 30 days

For &amp; on Behalf of

BAN HOCK HIN CO PTE LTD



Printed by : RAYMOND





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580

Phone: +65 6224 0010 Fax: +65 6224 0030

Operating Hours: Monday to Friday 9am to 5pm

GST Registration No: M400017735

**Third Party Insurer Enquiry**

Our Ref No: GR-17-166655

Date of Request: 07/11/2017

Your Ref No: Online Purchase

Ban Hock Hin Co. Pte Ltd  
No. 6 Defu Lane 4  
Singapore 539410

Dear Sir/Madam,

Enquiry Date 07/11/2017  
Enquiry By Tan Chok Lok  
TP Vehicle No. SJS3643G  
Accident Date 05/11/2017**Enquiry Result**

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SJS3643G	ECICS Limited	13/08/2017-12/08/2018	63374779 /6303 0178

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE**6 Raffles Quay #18-00, Singapore 048580  
Phone: +65 6224 0010 Fax: +65 6224 0030  
Operating Hours: Monday to Friday 9am to 5pm  
GST Registration No: M400017735**TAX INVOICE**Our Ref No: GR-17-166655  
Date of Request: 07/11/2017

Your Ref No: Online Purchase

Ban Hock Hin Co. Pte Ltd  
No. 6 Defu Lane 4  
Singapore 539410

Dear Sir/Madam,

Enquiry Date: 07/11/2017  
Enquiry By: Tan Chok Lok  
TP Vehicle No: SJS3643G  
Accident Date: 05/11/2017

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

## Asher Sng (LKKAuto)

---

**From:** ECICS Claims <claims@ecics.com.sg>  
**Sent:** Wednesday, 28 February 2018 3:55 PM  
**To:** Asher Sng (LKKAuto)  
**Cc:** ECICS Claims; Shu Pei (LKKAuto); Phoebe Jay Xie (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims); Carrie Tan Chi Hui (ECICS, Claims); Lionel Chua Kok Keong (ECICS, Claims)  
**Subject:** RE: [MANDATE REQUEST] RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017  
**Attachments:** TP LOD.PDF; LKK Survey Photo.pdf; LKK Resurvey Photo.pdf; ACCIDENT SKETCH PLAN.PDF; LKK Adjustment.pdf; LKK Inspection.pdf  
**Follow Up Flag:** Follow up  
**Flag Status:** Completed

Without Prejudice

Our claim no. DMPC1700689H

Dear Asher,

Thank you for your email with the attachment.

Please proceed to settle that fall under BOLA 28i on this claim.

Thank you.

Regards,

Lionel Chua

DID: +65 6303 0167

FAX: +65 6338 9267

**ECICS LIMITED**

Email: [claims@ecics.com.sg](mailto:claims@ecics.com.sg)

follow us on  follow us on  visit our website [ecics.com.sg](http://ecics.com.sg) 

---

**From:** Asher Sng (LKKAuto) [mailto:[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)]

**Sent:** Wednesday, 28 February, 2018 3:38 PM

**To:** ECICS Claims

**Cc:** Shu Pei (LKKAuto); Phoebe Jay Xie (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims); Carrie Tan Chi Hui (ECICS, Claims); Lionel Chua Kok Keong (ECICS, Claims)

**Subject:** RE: [MANDATE REQUEST] RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

Hi Lionel,

We refer to our tele-conversation.



Enclosed the correct attachment for your perusal.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ECICS Claims [<mailto:claims@ecics.com.sg>]

**Sent:** Wednesday, 28 February 2018 3:19 PM

**To:** Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>

**Cc:** ECICS Claims <[claims@ecics.com.sg](mailto:claims@ecics.com.sg)>; Shu Pei (LKKAuto) <[shupe@lkkauto.com](mailto:shupe@lkkauto.com)>; Phoebe Jay Xie (ECICS, Claims) <[PhoebeJay\\_Xie@ecics.com.sg](mailto:PhoebeJay_Xie@ecics.com.sg)>; Janice Goh Siew Geok (ECICS, Claims) <[Janice\\_Goh@ecics.com.sg](mailto:Janice_Goh@ecics.com.sg)>; Carrie Tan Chi Hui (ECICS, Claims) <[Carrie\\_Tan@ecics.com.sg](mailto:Carrie_Tan@ecics.com.sg)>; Lionel Chua Kok Keong (ECICS, Claims) <[Lionel\\_Chua@ecics.com.sg](mailto:Lionel_Chua@ecics.com.sg)>

**Subject:** RE: [MANDATE REQUEST] RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

Without Prejudice

Our claim no. DMPC1700689H

Dear Asher,

Please let us have the front cover page of your survey reported to show the detail of number of days recommended by your surveyor before we could revert to you in due course.

Thank you

Regards,

Lionel Chua

DID: +65 6303 0167

FAX: +65 6338 9267

**ECICS LIMITED**

Email: [claims@ecics.com.sg](mailto:claims@ecics.com.sg)

follow us on  facebook   follow us on  twitter   visit our website [ecics.com.sg](http://ecics.com.sg) 

---

**From:** ECICS Claims

**Sent:** Wednesday, 28 February, 2018 11:21 AM

**To:** Asher Sng (LKKAuto); Lionel Chua Kok Keong (ECICS, Claims)

**Cc:** Phoebe Jay Xie (ECICS, Claims); Carrie Tan Chi Hui (ECICS, Claims); Lionel Chua Kok Keong (ECICS, Claims); ECICS Claims

**Subject:** RE: [MANDATE REQUEST] RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

Dear Asher

Please be informed that this case is handle by my colleague, Lionel Chua and our claim no is DMPC1700689H/JG.

Aside to Lionel

Please look into this case and revert to Asher.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

***\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\****

---

**From:** Asher Sng (LKKAUTO) [<mailto:AsherSng@lkkauto.com>]  
**Sent:** Wednesday, 28 February, 2018 10:32 AM  
**To:** ECICS Claims  
**Cc:** Phoebe Jay Xie (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims); Carrie Tan Chi Hui (ECICS, Claims); Lionel Chua Kok Keong (ECICS, Claims)  
**Subject:** [MANDATE REQUEST] RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017  
**Importance:** High

Hi Sir/Mdm,

We refer to the above matter.

The said chain collision involved 5 vehicles whereby our insured collided into 2 vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We did clarify with insured the nature of the accident and he's aware that NCD (if any) would be affected.

We seek your approval to offer repairer " **BAN HOCK HIN CO.PTE LTD**" at **\$7,200.48 (all-in).**

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repairs (w/GST)	\$ 15,276.93	\$ 7,078.48
2. Loss of Use (6days x \$20)	\$ 120.00	\$ 120.00 (6days x \$20)
3. LTA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 15,398.93	\$ 7,200.48

Our Surveyor recommended 6 days repair.

Enclosed here with all the relevant documents for your perusal.

For your approval please.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

From: Janice Goh Siew Geok (ECICS, Claims) [[mailto:Janice\\_Goh@ecics.com.sg](mailto:Janice_Goh@ecics.com.sg)]

Sent: Thursday, 30 November 2017 3:47 PM

To: Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>

Subject: RE: [URGENT] RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

Dear Asher

Brief Details.

At about 01:25am in the morning of 5th November, I was driving along PIE on lane 1 (the right most lane) passing the CTE underpass when the Toyota in front of me (SJM 4388T) started braking. I braked with about a good 4-5 car distance from the Toyota and midway before my car comes to a complete stop, I felt a bump at the back of my car. Almost immediately after feeling the bump, a white Honda Fit (SJS 3643G) managed to squeeze through the space between my car and the central divider and hit the Toyota (SJM 4388T) on the driver side.

After I got out of the car, I saw a motorbike (FBD 8294X) lying on its left on the road and realized that it was the motorbike (FBD 8294X) that hit my rear. The motorcyclist (Shalfu) was leaning on the central divider, visibly shaken. Upon asking, he told me that the white honda fit (SJS 3642G) hit him, hence why he hit my rear and fell off his bike.

The driver of the Honda (SJS 3643G) did not get out of his car immediately but called his relative for help. He claimed that he applied the brakes but the car did not respond to braking. He also denied hitting the motorbike after hearing my account of the story.

Regards,

Janice Goh

Claims Division

DID: +65 6303 0182

FAX: +65 6338 9267

ECICS Limited

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

***\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\****

---

From: Asher Sng (LKKAuto) [<mailto:AsherSng@lkkauto.com>]

Sent: Wednesday, 29 November, 2017 2:21 PM

To: ECICS Claims

Cc: Carrie Tan Chi Hui (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims); Phoebe Jay Xie (ECICS, Claims); Vic



(LKKAUTO); Admin A; Lionel Chua Kok Keong (ECICS, Claims)

**Subject:** RE: [URGENT] RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

Hi All,

We refer to the above matter.

We had received 2 claims against in on the same day accident.

SJS 3643G (OI) -> FBD 8294X (TP) -> SJJ 8958M

SJS 3643G (OI) -> SJM 4388T (TP) -> SHD 6651R

There was no collision between SJJ 8958M and SJM 4388T.

Enclosed a copy of the accident sketch plan for your easy reference.

In view of above, we are of the opinion that our insured is involved in 2 accident both are 3 vehicle chain collusion our insured last vehicle.

Please kindly let us have your instruction if any.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ECICS Claims [<mailto:claims@ecics.com.sg>]

**Sent:** Wednesday, 29 November, 2017 12:05 PM

**To:** Asher Sng (LKKAUTO) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>

**Cc:** ECICS Claims <[claims@ecics.com.sg](mailto:claims@ecics.com.sg)>; Carrie Tan Chi Hui (ECICS, Claims) <[Carrie\\_Tan@ecics.com.sg](mailto:Carrie_Tan@ecics.com.sg)>; Janice Goh Siew Geok (ECICS, Claims) <[Janice\\_Goh@ecics.com.sg](mailto:Janice_Goh@ecics.com.sg)>; Phoebe Jay Xie (ECICS, Claims) <[PhoebeJay\\_Xie@ecics.com.sg](mailto:PhoebeJay_Xie@ecics.com.sg)>; Vic (LKKAUTO) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Lionel Chua Kok Keong (ECICS, Claims) <[Lionel\\_Chua@ecics.com.sg](mailto:Lionel_Chua@ecics.com.sg)>

**Subject:** RE: [URGENT] RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

Without Prejudice

Our claim no. DMPC1700689H

Dear Asher,

We attached a copy of our insured's GIA report that you have requested for your attention.

Thank you.

Regards,  
Lionel Chua



DID: +65 6303 0167

FAX: +65 6338 9267

**ECICS LIMITED**

Email: [claims@ecics.com.sg](mailto:claims@ecics.com.sg)

follow us on  
**facebook**



follow us on  
**twitter**



visit our website  
**ecics.com.sg**



---

**From:** Asher Sng (LKKAUTO) [<mailto:AsherSng@lkkauto.com>]

**Sent:** Wednesday, 29 November, 2017 10:39 AM

**To:** Carrie Tan Chi Hui (ECICS, Claims); Janice Goh Siew Geok (ECICS, Claims); Phoebe Jay Xie (ECICS, Claims)

**Cc:** ECICS Claims; Vic (LKKAUTO); Admin A; Lionel Chua Kok Keong (ECICS, Claims)

**Subject:** RE: [URGENT] RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Carrie Tan Chi Hui (ECICS, Claims) [[mailto:Carrie\\_Tan@ecics.com.sg](mailto:Carrie_Tan@ecics.com.sg)]

**Sent:** Thursday, 23 November, 2017 9:36 AM

**To:** Asher Sng (LKKAUTO) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>; Janice Goh Siew Geok (ECICS, Claims) <[Janice\\_Goh@ecics.com.sg](mailto:Janice_Goh@ecics.com.sg)>; Phoebe Jay Xie (ECICS, Claims) <[PhoebeJay\\_Xie@ecics.com.sg](mailto:PhoebeJay_Xie@ecics.com.sg)>

**Cc:** ECICS Claims <[claims@ecics.com.sg](mailto:claims@ecics.com.sg)>; Vic (LKKAUTO) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; Lionel Chua Kok Keong (ECICS, Claims) <[Lionel\\_Chua@ecics.com.sg](mailto:Lionel_Chua@ecics.com.sg)>

**Subject:** RE: [URGENT] RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

Hi Asher,

Please see attached GIA report as required.

DMPC1700689H – claim reference

For future assistance on GIA report requests, please forward to Lionel Chua for assistance.

Apologise for the late response.

Thank you.

Regards,  
Carrie Tan  
Claims Division

ECICS Limited  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims.  
Thank you for your kind patience and understanding.\*\**

---

**From:** Asher Sng (LKKAUTO) [<mailto:AsherSng@lkkauto.com>]  
**Sent:** Thursday, 23 November, 2017 9:07 AM  
**To:** Janice Goh Siew Geok (ECICS, Claims); Carrie Tan Chi Hui (ECICS, Claims); Phoebe Jay Xie (ECICS, Claims)  
**Cc:** ECICS Claims; Vic (LKKAUTO); Admin A  
**Subject:** [URGENT] RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017  
**Importance:** High

## URGENT!!!

Hi All,

We refer to the above matter.

Kindly advise if insured reported, if so please kindly let us have a copy of your insured's GIA report for our necessary action.

Third party is chasing for liability.

Thank You.

Best Regards,  
**Asher Sng** | Case Handler  
**LKK Auto Consultants Pte Ltd**  
phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAUTO)  
**Sent:** Wednesday, 22 November, 2017 11:53 AM  
**To:** 'Janice Goh Siew Geok (ECICS, Claims)' <[Janice\\_Goh@ecics.com.sg](mailto:Janice_Goh@ecics.com.sg)>  
**Cc:** Phoebe Jay Xie (ECICS, Claims) <[PhoebeJay\\_Xie@ecics.com.sg](mailto:PhoebeJay_Xie@ecics.com.sg)>; Carrie Tan Chi Hui (ECICS, Claims) <[Carrie\\_Tan@ecics.com.sg](mailto:Carrie_Tan@ecics.com.sg)>; 'ECICS Claims' <[claims@ecics.com.sg](mailto:claims@ecics.com.sg)>; Asher Sng (LKKAUTO) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>; Vic

(LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>  
**Subject:** RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

**Your ref:** TBA  
**LKK ref:** CC4/ICS17022083/Uea3

**WITHOUT PREJUDICE**

Dear Sir/ Madam,

Enclosed revert of vehicle: FBD 8294X

Date of survey: 20.11.2017

Number of days: 6 days

We have not authorized repairs.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP police report

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

*To check availability of the case handler , you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)

**Sent:** Friday, 17 November, 2017 3:50 PM

**To:** 'Janice Goh Siew Geok (ECICS, Claims)' <[Janice\\_Goh@ecics.com.sg](mailto:Janice_Goh@ecics.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

Dear Janice,

Thank you for the assignment.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Janice Goh Siew Geok (ECICS, Claims) [mailto:Janice\_Goh@ecics.com.sg]  
**Sent:** Friday, 17 November, 2017 3:05 PM  
**To:** 'assignments' <assignments@lkkauto.com>  
**Subject:** FW: Accident Involving FBD8294X & SJS3643G on 05/11/2017

Without Prejudice

Dear LKK

Please assist and arrange PRI.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

**WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY**, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

***\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\****

---

**From:** ECICS Claims  
**Sent:** Friday, 17 November, 2017 2:59 PM  
**To:** 'Raymond'; ECICS Claims  
**Subject:** RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

Without Prejudice

Dear Raymond

Thank you for your email.  
We will assign LKK for PRI.

Aside to LKK

Please arrange TP PRI.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987



WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

*\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\**

---

**From:** Raymond [<mailto:raymond@bhh.com.sg>]  
**Sent:** Friday, 17 November, 2017 2:53 PM  
**To:** ECICS Claims  
**Subject:** RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

Dear Janice,

Please assign LKK for the pre-repair survey.

Thanks

Best Regards,

Raymond

Ban Hock Hin Co., Pte Ltd

Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969

Visit us at <http://www.bhh.com.sg>

Facebook: <http://www.facebook.com/bhhsg>



**BAN HOCK HIN**  
Co., Pte Ltd

No. 6 Defu Lane 4, Singapore 539410

[www.bhh.com.sg](http://www.bhh.com.sg)

---

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEA



---

**From:** ECICS Claims [<mailto:claims@ecics.com.sg>]  
**Sent:** Friday, 17 November, 2017 2:30 PM  
**To:** Raymond <[raymond@bhh.com.sg](mailto:raymond@bhh.com.sg)>; ECICS Claims <[claims@ecics.com.sg](mailto:claims@ecics.com.sg)>  
**Subject:** RE: Accident Involving FBD8294X & SJS3643G on 05/11/2017

Without prejudice

Dear Raymond

Thank you for your email.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client's workshop. We propose to use one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert.

1. LKK
2. JP knight
3. Formteam
4. Appraisal Associates
5. Autoprobe
6. Raleigh
7. In-House Surveyor

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

Sorry for the late reply and inconvenience caused.

Thank you.

Regards,  
Janice Goh  
**Claims Division**  
DID: +65 6303 0182  
FAX: +65 6338 9267

**ECICS Limited**  
7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to [motorsurvey@ecics.com.sg](mailto:motorsurvey@ecics.com.sg) directly.

***\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding.\*\****

---

**From:** Raymond [<mailto:raymond@bhh.com.sg>]  
**Sent:** Friday, 17 November, 2017 12:30 PM  
**To:** ECICS Claims  
**Subject:** Accident Involving FBD8294X & SJS3643G on 05/11/2017

Dear Sir/Madam,

We attached the third party claim documents for your perusal.

Appreciate for you to arrange for the pre-repair survey.

Thanks

Best Regards,  
Raymond  
**Ban Hock Hin Co., Pte Ltd**  
Tel: (65) 6281 6520 x 220 | Fax: (65) 6284 2969  
Visit us at <http://www.bhh.com.sg>  
Facebook: <http://www.facebook.com/bhhsg>




**BAN HOCK HIN**  
Co., Pte Ltd

No. 6 Defu Lane 4, Singapore 539410

[www.bhh.com.sg](http://www.bhh.com.sg)

MOTORCYCLE ACCESSORIES | SERVICE CENTRE | MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL WORKS | LEA



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

To : M/s ECICS LTD

Date: 02/04/2018

**THIRD PARTY DIRECT SETTLEMENT**

Vehicle No.	SJS 3643G (Insd Veh)	Your Ref. No. : DMPC1700689H
	FBD 8294X (TP Veh)	Our Ref. No. : CC4/ICS17022083/Uea3q2
Date of Accident	5/11/2017	

Liability	100%	
Final Repair Cost	: \$ 7,078.48	
Loss of Use	: \$ 120.00	6 days
Rental (If any)	: \$	days
Others:	: \$ 2.00	
	: \$	
	7,200.48	
Final Settlement Sum	: \$ 7,200.48	
Remarks	:	

**Payment Instruction: Payee's Breakdown**

1)	BAN HOCK HIN CO.PTE LTD	: \$ 7,200.48
		: \$

JOANNE LEE

LKK Auto Consultants Pte Ltd






# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ECICS LTD		Ref : CC4/ICS17022083/Uea3q2		
7 TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE SINGAPORE 038987		Date : 02-04-2018		
		Code : ICS		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SJS 3643G	Veh. Inspected	FBD 8294X	
Policy No.	MPC17A00376101	Coverage (\$)	0.00	
Claim No.	DMPC1700689H	Excess (\$)	0.00	
Assign From	JANICE	Assign Date	17/11/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	YAMAHA FJR1300	c.c	1298	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	JYARP13A000005176	Colour	BLACK	
Odometer	72462	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	120/70 ZR17	PIRELLI	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	180/55 ZR17	PIRELLI	6 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR,FRONT PORTION AND N/S BODY. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	05/11/2017	Inspection Date	20/11/2017	
Survey held at	BAN HOCK HIN CO.PTE LTD NO 6 DEFU LANE 4 SINGAPORE 539410			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBD 8294X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>REPLACEMENT OF PARTS</b>			
1	BALL BEARING STEERING CONE (BIG)	NOT NECESSARY	1.50	-
1	BAR HANDLE LH	BENT	218.00	218.00
1	BOX SIDE (LH)	TO REPAIR SEE LABOUR	1,880.00	-
1	BOX SIDE (RH)	CRACKED	1,880.00	1,880.00
1	COVER CRANKCASE LH	CUT	182.00	182.00
1	COVER GRIP (GRAB ON)	TORN	75.00	75.00
1	COVER SIDE RH 2	CRACKED	90.00	90.00
1	COVER TAIL 2	CRACKED	165.00	165.00
1	COWLING UPPER ASSY 1	TO REPAIR SEE LABOUR	283.00	-
1	DAMPER COVER SIDE RH 2	NECESSARY	8.50	8.50
1	EMBLEM 3D	NECESSARY	38.00	38.00
1	FOOTREST REAR RH	BROKEN	21.00	21.00
1	FRAME REAR COMP	SERVICEABLE	1,365.00	-
1	GASKET CRANKCASE COVER	NECESSARY	25.00	25.00
2	GASKET MUFFLER @\$18.00	NECESSARY	36.00	36.00
1	LOWER FRONT BODY RH	TO REPAIR SEE LABOUR	1,190.00	-
1	MIRROR LH	BROKEN	248.00	248.00
1	MIRROR RH	NOT NECESSARY	248.00	-
1	MUFFLER ASSY 1 LH	TO REPAIR SEE LABOUR	1,659.00	-
1	MUFFLER ASSY 2 RH	BENT	1,659.00	1,659.00
1	PEDAL GEAR	BENT	145.00	145.00
2	PLUG COVER 2 @\$3.00	NECESSARY	6.00	6.00
10	RIVERT @\$1.50	NECESSARY	15.00	15.00
1	RUBBER FOOTREST FRONT	TORN	25.00	25.00
2	SCREW PAN HEAD @\$2.50	NECESSARY	5.00	5.00
1	SEAT ASSY TANDEM	TO REPAIR SEE LABOUR	357.00	357.00
1	SLIDER FRAME SET (MOTORVATION)	CUT	138.00	138.00

Report Ref No. CC4/ICS17022083/Uea3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SPRING COMPRESSION	NECESSARY	1.50	1.50
1	STAY 1	BENT	685.00	685.00
1	STAY 1	BENT	285.00	285.00
1	STAY MUFFLER 2	BENT	98.00	98.00
	LESS 10% DISCOUNT		-	-640.60
			13,032.50	5,765.40
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FUEL TANK (SN)	DENTED	155.00	120.00
			155.00	120.00
	<b><u>LABOUR</u></b>			
	SPRAY PAINTING ON FUEL TANK & FAIRING.		250.00	250.00
	LABOUR INCLUSIVE OF THE REPAIR OF BOX SIDE (LH), COWLING UPPER ASSY 1, LOWER FRONT BODY RH, MUFFLER ASSY 1 LH AND SEAT ASSY TANDEM.		840.00	480.00
			1,090.00	730.00
	<b>GRAND TOTAL</b>		<b>14,277.50</b>	<b>6,615.40</b>
	<b>RECOMMENDED COST OF REPAIRS</b>			<b>6,615.40</b>

Report Ref No. CC4/ICS17022083/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.