



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 32149

ECICS LIMITED

T TEMASEK BOULEVARD
#10-01 SUNTEC TOWER ONE
Singapore 038987

MOTOR CLAIMS DEPT

VEHICLE NO. : FBD8294X
MAKE/MODEL : YAM / FJR1300 ABS

DATE : 17/11/2017
CLAIM NO. : 11059
POLICY NO. : MC/00088515/05
FROM : RAYMOND

Not Authorised
hlu
maybe TOTAL 1055 ?
20/11/17
tel: 62563561
6dy.
please check MV & ?

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BALL BEARING STEERING CONE (BIG) P/N: 13452	REPLACE	1.00	\$1.50	1.50 X
2	BAR HANDLE LH	REPLACE	1.00	\$218.00	218.00
3	BOX SIDE (LH) P/N: 40574	REPLACE	1.00	\$1,880.00	1,880.00 X
4	BOX SIDE (RH) P/N: 40575	REPLACE	1.00	\$1,880.00	1,880.00
5	COVER CRANKCASE LH P/N: 55870	REPLACE	1.00	\$182.00	182.00
6	COVER GRIP (GRAB ON) P/N: 56090	REPLACE	1.00	\$75.00	75.00
7	COVER SIDE RH 2	REPLACE	1.00	\$90.00	90.00
8	COVER TAIL 2	REPLACE	1.00	\$165.00	165.00 X
9	COWLING UPPER ASSY 1 P/N: 40617	REPLACE	1.00	\$283.00	283.00 X
10	DAMPER COVER SIDE RH 2	REPLACE	1.00	\$8.50	8.50 X
11	EMBLEM 3D	REPLACE	1.00	\$38.00	38.00
12	FOOTREST REAR RH	REPLACE	1.00	\$21.00	21.00
13	FRAME REAR COMP	REPLACE	1.00	\$1,365.00	1,365.00 ?



S/N	Description	Action	Qty	Unit Price	Amount
14	GASKET CRANKCASE COVER P/N: 48868	REPLACE	1.00	\$25.00	25.00
15	GASKET MUFFLER P/N: 49863	REPLACE	2.00	\$18.00	36.00
16	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	24.00	\$35.00	840.00
17	LOWER FRONT BODY RH P/N: 40590	REPLACE	1.00	\$1,190.00	1,190.00
18	MIRROR LH P/N: 40593	REPLACE	1.00	\$248.00	248.00
19	MIRROR RH P/N: 40594	REPLACE	1.00	\$248.00	248.00
20	MUFFLER ASSY 1 <i>LH</i> P/N: 40595	REPLACE	1.00	\$1,659.00	1,659.00
21	MUFFLER ASSY 2 <i>RH</i> P/N: 40596	REPLACE	1.00	\$1,659.00	1,659.00
22	PEDAL GEAR	REPLACE	1.00	\$145.00	145.00
23	PLUG COVER 2 P/N: 45266	REPLACE	2.00	\$3.00	6.00
24	REPAIR FUEL TANK	Repair	1.00	\$155.00	155.00
25	RIVERT P/N: 49845	REPLACE	10.00	\$1.50	15.00
26	RUBBER FOOTREST FRONT P/N: 34783	REPLACE	1.00	\$25.00	25.00
27	SCREW PAN HEAD P/N: 24409	REPLACE	2.00	\$2.50	5.00
28	SEAT ASSY TANDEM	REPLACE	1.00	\$357.00	357.00
29	SLIDER FRAME SET (MOTOVATION) P/N: 40764	REPLACE	1.00	\$138.00	138.00
30	SPRAY PAINTING ON FUEL TANK <i>& Soling</i>	Spray	1.00	\$250.00	250.00
31	SPRING COMPRESSION	REPLACE	1.00	\$1.50	1.50
32	STAY 1 P/N: 40613	REPLACE	1.00	\$685.00	685.00
33	STAY 1 P/N: 40612	REPLACE	1.00	\$285.00	285.00
34	STAY MUFFLER 2	REPLACE	1.00	\$98.00	98.00

SUB TOTAL
GST @ 7 %

\$14,277.50
\$14,277.50



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
GRAND TOTAL					\$15,276.93

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

