

Sulima

CC 4/AIG170

2089, T1 Ta3 9/

LKK:  
IDAC

Inspector:

Tunfelch

DOI:

ASSIGNMENT

21/11/17

Date / Time:

20/11/17

Registered in Merimen:

20/11/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SVT 648 X

Claim No.:

45130017HGA

Name of Insured:

LIM SHENH JIE

Policy No.:

20041341

Insured Tel No.:

62994169

HP:

94750570

Make / Model:

NISSAN SYLPHY

Excess Sec II :S\$

D.O.A.:

21/10/17

Place of Accident:

ORCHARD BOULEVARD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SVT 648 X



INSRS:

WSP:

Tel:

Liability:

RMKS:

SVT 648 X



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

21/11/17  
JW

SVT 648 X - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

9/11/17 @ 5:00 Spoken with Claimant &amp; ask him to send in his car for repair.

9/10/17 @ 5:00 Spoken with Claimant. Sen Yee Hup &amp; Sen Yee Hup will cash claimant for send in the car to proceed with repair.

12/11/17 Pending LOR

Spoke to TP repair, confirmed Claimant do not come back to TP workshop.

Had After update photo X

PRELIMINARY ADVICE

Date/Time:

28/11/2017

Sent By:

HMK

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost: S\$ ( days) Reduction: % Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Final Liability: % 100 (Agreed / Assessed) BOLA S/N No.: 15

Repair Cost: S\$

Loss of Rental (LOR): S\$ ( days)

Loss of Use (LOU): S\$ (\$ x days)

Loss of Income (LOI): S\$ (\$ x days)

LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search S\$

Medical: S\$

Disbursement: S\$ (e.g. Tow/ Independent)

Legal Cost S\$

Total: S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1: S\$

Name 1:

Payee 2: (Strike if N.A.) S\$

Name 2:

Payee 3: (Strike if N.A.) S\$

Name 3:

RECEIVED 13 NOV 2018

2017/11/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format: W/F

3) Survey fee: \$250.00

Tanpik

REF

AIG

# ASSIGNMENT

From: \_\_\_\_\_ Date: 21/11/17

Estimated Cost: \_\_\_\_\_

OD: ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLK7000D

at Workshop/In: Sin Hup Lee

of: Blk1005, Bkt Merah Lane 2 #01-20, 159761

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record): \_\_\_\_\_

Make of Veh: \_\_\_\_\_

After 11am

(Policy Condition): \_\_\_\_\_

Remark: The veh had commenced its repair at the time of inspection.

Sell or Market Value: \_\_\_\_\_

IDAC Accident Report Consistent? Yes or No

GIA / PP Seen Consistent? Yes or No

Est. Papers 2 days Res Yes or No

Lump Sum 20 % 3 Val Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Date / Time Action / Instruction

WFFS: SLK7000D 20/6 Dec.

Type: ☒ Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Vellfire 2.5 2494

Colour: Black

So Reading: 27226

Engine: \_\_\_\_\_

C.No: 3TN6F3DH008007087

Gen Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Mod: Nil / ☒ STD A/Rim or

Tyre Size: F: 235/50R18

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

☒ YOYO / YOKO or

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R.Bal: 6 --- R.Bal: 6 ---

L.Bal: 6 --- L.Bal: 6 ---

D.O.A: \_\_\_\_\_ D.O: 21/11/17 @ 1440

Surveyed at: Sin Hup Lee

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Fvt o/s

The UIC / Chassis frame / Body Structure effected due to collision

L/S: \$1200.00 (Red: \$755.42 / 39%)

Cost Time For Pass: ☐ Preli. Report

Cost Time For Return: ☐ Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Add Fee: ☐ Site Visit \$

☐ Material \$

☐ Techn. Fee \$

☐ Transport \$

Report Format: \_\_\_\_\_

Lump Sum / B.I. / \_\_\_\_\_

新合利服務公司  
Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

16 November 2017

Attn: Motor Claim Department  
AIG Asia Pacific Insurance Pte. Ltd  
AIG Building  
78 Shenton Way #07-16  
Singapore 079120

HAOHUA MARKETING CONSULTING PTE LTD  
c/o Sin Hup Lee Service Co.  
Block 1005 Bukit Merah Lane 2 #01-20  
Singapore 159761

Tanjin 97495745  
up  
21/11/17 @ 1440  
2 days  
Repair after repair  
Sun @ 16hanta form

Dear Sir/Ms,

Re: Road Traffic on 27-10-2017 at Orchard Blvd, involving vehicle SKT648X/SLK7000D

Quotation for Repair Vehicle No: SLK7000D, VELLFIRE 2.5(Third Party Claim)

Quantity	List Item	Price
1	Front Bumper	\$ 1,278.60 <i>de</i>
1	Front Side Bracket	\$ 145.30 <i>X MV</i>
10	Front Clip	\$ 50.00 <i>new</i>
		\$ 1,473.90
	Less 25%	\$ 368.48
		\$ 1,105.42
<b><u>Labour</u></b>		
1	To repair Front Fender. Remove and re-fix Bumper, straighten and realign affected areas.	\$ 400.00 <i>250</i>

1278.60  
+ 50.00  
1328.60  
X 75%  
996.45  
+ 250.00  
+ 250.00  
1,496.45 X 80% = \$1,197.16  
454,200.00

2 To spray Fender & Bumper and affected areas

250  
\$ 450.00

**Total Amount** \$ 1,955.42

Kindly arrange your surveyor to survey my vehicle.

We look forward to hear from you soon.

Thank you.

Yours Faithfully

Mr Wong

81122116

新合利服務公司  
SIN HUP LEE SERVICE CO.,  
Blk 1005, Bukit Merah Lane 2,  
#01-20, Singapore 159751  
Tel: 6276 2482 Fax: 6271 9802

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Poh Kin (LKKAuto)

---

**From:** Poh Kin (LKKAuto)  
**Sent:** Monday, 19 November 2018 1:41 PM  
**To:** 'Syed-Yusoff, Saliha'; CS A Team  
**Cc:** Olivia Lau (LKKAuto); KKLau; Admin A  
**Subject:** RE: AIG ref: 4513001711SG \*DO NOT CALL OI\*

**Importance:** High

Our Ref: CC4/AIG17022089/T1fa3  
Your Ref: 4513001711SG

Dear Ms Saliha,

### ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE NOS. SKT 648X AND SLK 7000D ON 27/10/2017

We refer to the above matter.

Please be informed that we have confirmed with TP Repairer that claimant do not come back to their workshop for repair up to date.

In view of above, we will submit W/P report to your office.

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

 LKK Auto Consultants Pte Ltd *Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** Syed-Yusoff, Saliha [mailto:Saliha.Syed-Yusoff@aig.com]  
**Sent:** Monday, 19 November 2018 12:11 PM  
**To:** CS A Team <cs-a@lkkauto.com>  
**Cc:** Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; KKLau <kklau@lkkauto.com>  
**Subject:** RE: AIG ref: 4513001711SG \*DO NOT CALL OI\*

Dear Team,

May we have update on this matter please.

thank you,

**Poh Kin (LKKAUTO)**

---

**From:** Poh Kin (LKKAUTO)  
**Sent:** Thursday, 12 July 2018 4:39 PM  
**To:** 'sinhuplee@gmail.com'  
**Cc:** Hsiao Tong (LKKAUTO)  
**Subject:** Our Ref: CC4/AIG17022089/T1fa3; Your Ref: SLK 7000D  
**Attachments:** TP\_Estimate\_Marked.pdf  
  
**Importance:** High

**Without Prejudice**

Our Ref: CC4/AIG17022089/T1fa3  
Your Ref: SLK 7000D

Dear Sirs,

**ROAD TRAFFIC ACCIDENT INVOLVING VEHICLE SKT 648X AND SLK 7000D ON 27/10/2017**

We refer to the above matter.

For COR, our surveyor had recommended amount at **L/S \$1,200.00 (before GST) with 2 repair days.**

Please note that: All finalisation is subject to our Principal insurer's approval.

In the meantime, kindly furnish us a copy of after repair photo for our file record.

\*\*\* Kindly forward your LOD with all the relevant documents (ie: final repair bill, authorisation to act, rental receipt) **to us (LKK)** for our necessary action.

Thank you.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement."

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

**Poh Kin, Chong (Mr)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2132 | email: [pohkin@lkkauto.com](mailto:pohkin@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)































Revoked / No settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	31 Oct 2017 <a href="#">Edit Reg</a>		20 Nov 2017 00:00 <a href="#">Edit Adj Rpt</a>	<b>S\$1,200.00</b> <a href="#">Edit Estimates</a>	<b>S\$1,200.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>LIM SHENG JIE (LIN SHENGJIE)</b> , ID: S8400797H								
Main Claimant:	<b>HAOHUA MARKETING CONSULTING PTE. LTD.</b> , Co. Reg. No.: 201630346Z								
Vehicle Reg. No.:	<b>SLK7000D</b>	Date of Loss:	27/10/2017 18:00 - :59 [10 Months and 7 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / 4513001711SG</b>	Policy/Cover Note No.:	2100413411-02000 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKT648X</b>	Policy No. (Claimant):	2100493952						
		Excess:							
Repairer:	<b>Sin Hup Lee Service Co (HQ)</b> Blk 1005 Bukit Merah Lane 2, #01-209 Alexandra Village Industrial Estate, 159761 Bukit Merah - Tel: 6278-2482								
Handling Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Syed-Yusoff, Saliha</b> ] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	<b>AIG Asia Pacific Insurance Pte. Ltd. (SG)</b> - Tel: 65-6419-3000								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 29/11/2017]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLK7000D (4513001711SG)  
[SKT648X]  
TP  
HAOHUA MARKETING CONSULTING PTE. LTD.  
Oct 27 2017 6:25PM  
[LIM SHENG JIE (LIN SHENGJIE)]  
Sin Hup Lee Service Co

<a href="#">Upload Documents</a> <a href="#">Upload Photos</a> <a href="#">Compose New Letter</a> <a href="#">Upload Video</a> <a href="#">Upload Audio</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Video</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/11/17 17:03	OI video - SKT648X	 Load MP4	
<b>Assessment Reports</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/11/17 10:34	<b>Accident Statement</b> <small>From: OD - Reg. No: SKT648X, Claimant: LIM SHENG JIE (LIN SHENGJIE)</small>	 Load HTM	
<b>Photos/Images</b>				
			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/08/18 13:42	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
2	13/08/18 13:42	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
3	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
4	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
5	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
6	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
7	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
8	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
9	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
10	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
11	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
12	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
13	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
14	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
15	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
16	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
17	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
18	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
19	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
20	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
21	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
22	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
23	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
24	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
25	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
26	13/08/18 13:43	General View	 Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				
			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	20/11/17 16:26	EMAIL FORM AIG DD 20.11.2017	 Load PDF	
2	20/11/17 16:26	TP ESTIMATE + TP GIA REPORT	 Load TIF	



Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
			1	
3	21/11/17 12:08	EMAIL FROM AIG DD 20.11.2017	1	Load PDF
4	28/11/17 08:57	TP ESTIMATE - MARKED	1	Load PDF

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b>
<div></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG17022089/T1FA3Q2

Date: 20/11/2018

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100413411-02000

Claimant Vehicle No : SLK7000D

Insured Vehicle No : SKT648X

Date of Loss: 27/10/2017

Nature of Claim: TP

Claim No: 4513001711SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK7000D

Make &amp; Model: TOYOTA VELLFIRE, 2.5 CVT (A)

Engine No: 2ARH791148

Reg. Date: 20/12/2016 (Man. Year: 2016)

Chassis No: JTNGF3DH008007087

Colour: Black

Odometer: 27226 km

Engine Capacity: 2494 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 235/50 R18 Rear Tyre Size: 235/50 R18

Front Left Side: Toyo 6 mm Rear Left Side: Toyo 6 mm

Front Right Side: Toyo 6 mm Rear Right Side: Toyo 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,105.42	996.45	108.97	9.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	850.00	500.00	350.00	41.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,955.42</b>	<b>1,496.45</b>	<b>458.97</b>	<b>23.47</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,200.00</b>		
<b>Nett Amount (S\$)</b>	<b>1,955.42</b>	<b>1,200.00</b>	<b>755.42</b>	<b>38.63</b>
<b>Global Sum Settlement (S\$)</b>		<b>0.00</b>		

### INSPECTION

Date of Assignment: 20/11/2017

Date Inspected: 21/11/2017 Inspected At:

Sin Hup Lee Service Co (HQ)  
Blk 1005 Bukit Merah Lane 2, #01-209  
Alexandra Village Industrial Estate  
Singapore 159761

Estimated Period of Repair: 2.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** Chong Poh Kin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,278.60 FL	*1,278.60 FL
2	1		*FRONT SIDE BRACKET	Not Necessary	145.30 FL	*- FL
3	10		*FRONT CLIP	Necessary	50.00 FL	*50.00 FL
					<b>Sub Total (S\$)</b>	<b>1,473.90</b>
					<b>- List Item Discount on L Items 25.00/25.00% (S\$)</b>	<b>368.48</b>
					<b>Total Parts (S\$)</b>	<b>1,105.42</b>

F=Franchise part. L=ListItemDisc.

**1,328.60**

**332.15**

**996.45**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR FRONT FENDER ,REMOVE AND REFIX BUMPER ,STRAIGHTEN AND REALIGN AFFECTED AREAS	New	400.00	250.00
2	TO SPRAY FENDER & BUMPER AND AFFECTED AREAS	New	450.00	250.00
Gross Labour Cost (S\$)			850.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >