

新合利服務公司
Sin Hup Lee Service Co.

Block 1005 Bukit Merah Lane2 #01-20

Singapore 159761

Tel: 6278 2482 Fax: 6271 9802

Email: sinhuplee@gmail.com

Reg. No. 083995/00E

16 November 2017

Attn: Motor Claim Department
AIG Asia Pacific Insurance Pte. Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120

HAOHUA MARKETING CONSULTING PTE LTD
c/o Sin Hup Lee Service Co.
Block 1005 Bukit Merah Lane 2 #01-20
Singapore 159761

Dear Sir/Ms,

Re: Road Traffic on 27-10-2017 at Orchard Blvd, involving vehicle SKT648X/SLK7000D

Quotation for Repair Vehicle No: SLK7000D, VELLFIRE 2.5(Third Party Claim)

Quantity	List Item	Price
1	Front Bumper	\$ 1,278.60 <i>de</i>
1	Front Side Bracket	\$ 145.30 <i>X</i>
10	Front Clip	\$ 50.00 <i>new</i>
		\$ 1,473.90
	Less 25%	\$ 368.48
		\$ 1,105.42
<u>Labour</u>		
1	To repair Front Fender. Remove and re-fix Bumper, straighten and realign affected areas.	\$ 400.00 <i>250</i>

2	To spray Fender & Bumper and affected areas	\$ 250 450.00
Total Amount		\$ 1,955.42

Kindly arrange your surveyor to survey my vehicle.

We look forward to hear from you soon.


Thank you.

Yours Faithfully

Mr Wong

81122116

新合利服務公司
SIN HUP LEE SERVICE CO.,
Blk 1005, Bukit Merah Lane 2,
#01-20, Singapore 159761
Tel: 6278 2482 Fax: 6271 9802



**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: