

TRANS-CAB AUTO SERVICES PTE LTD

NO2. ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 9285U - AIG**AAD1709-195***Not Authored
1 Sep 8 1830*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 9285U - ROEL

KL1LA69RJB058045

CHEVROLET

CHEVROLET EPICA 2.0

18.09.2017

AIG**PART****LIST**

1	1	Front Bumper	\$	<i>N</i> 1,202.00	<i>X</i>
2	1	Front Bumper Lower Absorber	\$	<i>S</i> 180.00	<i><</i>
3	1	Front Bumper Reinforcement	\$	<i>N</i> 356.00	<i>X</i>
4	1	Front Bumper Retainer RH	\$	<i>D's</i> 102.00	<i>✓</i>
5	1	Front Bumper Retainer LH	\$	<i>S</i> 102.00	<i>X</i>
6	1	Front Bumper Lower Grille	\$	<i>S</i> 78.00	<i>✓</i>
7	1	Front Bumper Lower Stiffener	\$	<i>N</i> 134.37	<i>X</i>
8	1	Bumper Fog Lamp Cover RH	\$	<i>S</i> 32.40	<i>X</i>
9	1	Front Headlamp RH	\$	<i>G</i> 816.00	<i>✓</i>
10	1	Front Fender RH	\$	<i>B</i> 837.60	<i>✓</i>
11	1	Front Fender Liner RH	\$	<i>S</i> 47.00	<i>X</i>
12	1	Windscreen Washer Tank - Filler Neck	\$	<i>S</i> 4.80	
13	1	Windscreen Washer Tank	\$	<i>S</i> 62.00	
14	1	Windscreen Washer Tank Motor	\$	<i>S</i> 51.00	
15	1	Bonnet	\$	<i>N</i> 1,250.00	
16	1	Bonnet Moulding	\$	<i>S</i> 161.97	
17	1	Front Support Panel Assy	\$	<i>N</i> 1,222.32	
18	1	Radiator Grille (Grille A-Rad)	\$	<i>S</i> 367.00	<i>X</i>
19	1	Radiator Grille Top Cover	\$	<i>S</i> 45.02	
20	1	Front Door RH	\$	<i>N</i> 1,133.00	
21	1	Front Side View Mirror RH	\$	<i>S</i> 939.00	

TOTAL	\$	9,123.48
10%	\$	912.35
	\$	8,211.13

Specical Nett

1	1 Set Front Bumper Fastener Clip	\$	<i>N</i> 30.00	<i>X</i>
2	1 Set Front Fender Liner Clip RH	\$	<i>N</i> 30.00	<i>X</i>

TRANS-CAB AUTO SERVICES PTE LTD**AAD1709-195**

NO2. ANG MO KIO ST63 SINGAPORE 569111

TEL.NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 9285U - AIG

3	1	Front Wheel Rim Hub Cap RH	\$	<i>sn</i> 166.30 ✓
4	1	Front Tyre RH	\$	<i>sn</i> 180.00 ✓
5	1	Front Tyre Rim RH	\$	<i>sn</i> 126.00 ✓
6	1	Door Sticker "Trans-cab" RH	\$	<i>nn</i> 80.00 X

TOTAL	\$	612.30
TOTAL PARTS	\$	8,823.43

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,800.00 *30d*

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *30d*

Putty and Spray Painting Of The Affected
Portion.

\$ 3,000.00 *40d*

To Check Electrical Lighting Concerned.

\$ 170.00 *20d*

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X

Towing Fees.

\$ *nn* 120.00 X

To transfer of door fittings, attachment and
perform water seepage test.

\$ *nn* 170.00 X

To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.

\$ *nn* 170.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

TOTAL \$ 7,040.00

Over All Total \$ 15,863.43

LKK Auto Consultant will be advising the Repairer of the following: • To resurvey before/after spray painting • To resurvey part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____	REPAIR DAYS <i>10 DAYS</i> <i>2 days</i>
--	--