

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NQ. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF 577B -**AAD1711-173***Not Notarized*
11 Sep 8 2350h

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHF 577B - CANDY
VF1ABL15AUC278416
RENAULT
LATITUDE
14.11.2017
AIG

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>Bu/m</i> 1,259.42 ✓
2	1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68 X
3	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
4	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75 X
5	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80 X
6	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.22 X
7	1	BUMPER RETAINER FRT LH	\$	<i>D/V</i> 151.41 ✓
8	1	BUMPER BRACKET FRT LH	\$	<i>R</i> 181.75 X
9	1	HEADLAMP LH	\$	<i>SL</i> 1,184.43 X
10	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15 X
11	1	FENDER PANEL FRT LH	\$	<i>Bt/Bu</i> 783.83 ✓
12	1	FENDER INSULATOR LH	\$	<i>SL</i> 130.84
13	1	FENDER BRACKET FRT LH	\$	<i>R</i> 34.14
14	1	WHEELARCH FRT LH	\$	<i>SL</i> 278.84
15	1	RADAITOR GRILLE	\$	<i>SL</i> 1,707.78
16	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 173.36
17	1	RADAITOR GRILLE FRAME	\$	<i>SL</i> 1,353.75
18	1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 615.90
19	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
20	1	BONNET	\$	<i>R</i> 1,941.63
21	1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66
22	1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50
23	1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55
24	1	DOOR MIRROR LH	\$	<i>SL</i> 1,483.40
25	1	DOOR MIRROR GLASS LH	\$	<i>SL</i> 148.20
26	1	DOOR MIRROR BACK COVER LH	\$	<i>SL</i> 218.46
27	1	DOOR WHETHERSTRIP FRT LH	\$	<i>SL</i> 474.21
28	1	DOOR SEAL FRT LH	\$	<i>R</i> 68.67
29	1	ROCKER PANEL OUTER LH	\$	<i>R</i> 987.49
30	1	DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66

TOTAL	\$	21,648.36
10%	\$	2,164.84
	\$	19,483.52

TRANS-CAB AUTO SERVICES PTE LTD

AAD1711-173

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHF 577B -

Specical Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	nn	66.00	X
2	1SET	FRONT BUMPER CLIP	\$	nn	66.00	✓
3	1	RIM LH FRT	\$	nn	385.00	X
4	1	TYRE LH FRT	\$	nn	330.00	X
5	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	X
6	1	DOOR STICKER "Classic"	\$	nn	30.00	X
7	1	DOOR STICKER "6555-3333"	\$	nn	80.00	X

TOTAL	\$	1,037.00
TOTAL PARTS	\$	20,520.52

To Check Electrical Lighting Concerned.	\$	170.00	100
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00	400
Putty and spray painting of the affected portion.	\$	3,000.00	400
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn	170.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00 X
To check steering geometry and computer wheel alignment	\$	nn	220.00 X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	170.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	nn	170.00 X
Towing fees	\$	nn	120.00 X
To rust-proofing of the affected areas.	\$	170.00	300

TOTAL	\$	7,160.00
Over All Total	\$	27,680.52

(PARTS BY PARTS) Repair Days**10 Days**
2 days