

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 204M -**AAD1711-178**

Not Authored
Resony B4 part 81617.11

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 204M - CANDY

VF1ABL15AUC282373

RENAULT

LATITUDE

16.11.2017

*Alt***PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bulldog</i> 1,108.46 ✓
2	1	BUMPER LOWER REAR	\$	<i>Sn</i> 768.84 ✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47 ✓
4	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97 ✓
5	1	BUMEPR RETAINER LH REAR	\$	<i>Di</i> 44.99 ✓
6	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97
8	1	BUMPER RETAINER LH REAR	\$	<i>Sn</i> 44.99
9	1	ROCKER PANEL OUTER LH	\$	<i>R</i> 987.49
10	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13
11	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47
12	1	TAILLAMP LH	\$	<i>Sn</i> 552.55
13	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70
14	1	BOOT REAR	\$	<i>R</i> 2,872.68
15	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35
16	1	BOOT STRUT LH	\$	<i>Sn</i> 276.08
17	1	BOOT HINGE LH	\$	<i>R</i> 367.84
18	1	DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66
19	1	DOOR MOULDING REAR LH	\$	<i>Sn</i> 176.82
20	1	DOOR LOCK REAR LH	\$	<i>R</i> 908.75
21	1	DOOR GRAB HANDLE REAR LH	\$	<i>Sn</i> 210.96
22	1	DOOR HANDLE OUTER REAR LH	\$	<i>Sn</i> 126.49
23	1	DOOR HANDLE CAP REAR LH	\$	<i>Sn</i> 35.52
24	1	DOOR HANDLE SEAL REAR LH	\$	<i>Sn</i> 7.89
25	1	DOOR HANDLE COVER REAR LH	\$	<i>Sn</i> 13.22
26	1	DOOR HANDLE MODULE REAR LH	\$	<i>Sn</i> 133.60

TOTAL	\$	17,233.51
10%	\$	1,723.35
	\$	15,510.16

Specical Nett

1 1SET PARKING AID

\$ *Sn* 700.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-178**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 204M -

2	1SET	REAR BUMPER CLIP	\$	nn	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	—
4	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	nn	10.00	}
5	1SET	BUMEPR RETAINER LH CLIP RR	\$	nn	20.00	
6	1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	
7	1SET	BUMPER LOWER REAR CLIP	\$	nn	66.00	
8	1SET	BOOT FINISHER CLIP	\$	nn	24.20	
9	1	BOOT STICKER "Trans-cab"	\$	nn	30.00	
10	1	BOOT STICKER "6555-3333"	\$	nn	30.00	
11	1	TAILLAMP CLIP LH	\$	nn	5.00	
12	1SET	WHEELARCH CLIP RR LH	\$	nn	66.00	
13	2	REAR WINDSCREEN SELANT	\$	nn	80.00	
14	1	WINDSCREEN MOULDING	\$	nn	100.00	} X
15	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
16	1	CAP HUB LH RR	\$	nn	35.00	
17	1	RIM LH RR	\$	nn	385.00	
18	1	TYRE LH RR	\$	nn	330.00	
19	1	DOOR STICKER "Trans-cab"	\$	nn	80.00	
20	1	DOOR STICKER "Classic"	\$	nn	30.00	
21	1	DOOR STICKER "6555-3333"	\$	nn	80.00	

TOTAL	\$	2,292.20
TOTAL PARTS	\$	17,802.36

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	2201
To reinstall rear bumper parking sensor.	\$	170.00	601
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	2001
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	nn 380.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-178**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 204M -

Towing Fees	\$	<i>120</i> 120.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>170</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>220</i> 220.00 <i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>170</i> 170.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>170</i> 170.00 <i>X</i>

TOTAL	\$	7,710.00
Over All Total	\$	25,512.36

(PARTS BY PARTS)**Repair Days****10 Days***2 days*