

INS. CASE OWNER:

Chee Hong

CC b /AIG1702

2097, 15/11/18

LKK-
IDAC:

Surveyor:

FSC

DOI:

15/11/18

Date / Time:

15/11/18

Registered in Merimen:

20/11/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKW 1572H

Name of Insured:

BEH SIEW GEE TERESA

Insured Tel No.:

HP:

Excess Sec II :\$S

D.O.A.:

10/11/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: Chee Hong

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

20522804434

Policy No.:

20042272-02

Make / Model:

TOYOTA

Place of Accident:

72N FUNG

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SGX 24



INSRS:

WSP:

Tel:

Liability:

RMKS:

OPTIMA



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time		STAGE	DATE / PIC
22/11/18	SGX 24 - X	Non-Reporting ltr (1st):	
22/11/18	SKW 1572H - X	Non-Reporting ltr (2nd):	
22/11/2017		Non-Reporting ltr (Final):	
2:27pm		Notification ltr (if non-pickup):	
		Call OI:	22/11/2017
		After call ltr to OI:	
		Documentation Check List:	Handler Typist
		Notification ltr (if non-pickup)	<input type="checkbox"/>
		After call ltr to OI:	<input checked="" type="checkbox"/>
		Authorisation To Act:	<input checked="" type="checkbox"/>
		Release Voucher:	<input checked="" type="checkbox"/>
		Final Repair Bill:	<input checked="" type="checkbox"/>
		Car Rental Invoice:	<input checked="" type="checkbox"/>
		Towing Invoice:	<input type="checkbox"/>
		LTA / GIA:	<input checked="" type="checkbox"/>
		Medical Bill:	<input type="checkbox"/>
		PIR:	<input type="checkbox"/>
		Mandate/Reject Instruction:	<input checked="" type="checkbox"/>
		LOD:	<input checked="" type="checkbox"/>
		Payment Breakdown Form:	<input type="checkbox"/>
		Post-Repair Photos:	<input type="checkbox"/>
		Others:	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: 22/11/18

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No.:

15

Repair Cost:

\$S 10636.01

Loss of Rental (LOR):

\$S 1286.00

(

8

days)

X150.00 +60

Loss of Use (LOU):

\$S

(\$

x

days)

Loss of Income (LOI):

\$S

(\$

x

days)

LOR only

☐

LOU only

☐

LOR + LOU

☐

LOR + LOI

☐

(Tick only one)

GIA/LTA Search

\$S 2.00

Medical:

\$S

Disbursement:

\$S

Legal Cost

\$S

Total:

\$S 11922.01

Global Sum \$S:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$S 11922.01

Name 1:

OPTIMA WERTZ PTE LTD

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

COPY SENT 8/6/18

ASS. REC. BY:

REF:

AIG/

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or NoLum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGX 7YYr Regn: 02 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mer E200 c.c. 1991Colour: M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading: 32616

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD 2130 422A 102 884Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: 225/55R17BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 4 mmR/Bal. 2 mmL/Bal. 4 mmL/Bal. 2 mmD.O.A. 10/11/17D.O.I. 15/11/17

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

20/11 File pass to Customer7/6/18 Confirm 2-B-2 \$9940.20 with 6 working daysRed. \$5545.20
36/1

Date/Time, File Pass to?



Preli. Report

1)

Date/Time, File Return to?



Final Report

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee

Transportation

) \$ + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG17022097/Kpb3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 20-11-2017	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKW 1572H	Veh. Inspected	SGX 7Y
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	10/11/2017	Inspection Date	15/11/2017
Survey held at	OPTIMA WERKZ PTE LTD 6, KUNG CHONG ROAD SINGAPORE 159143		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Kiza

121

89940-20

Return 84 points

P/P

6 days

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 14 November 2017

Third Party Insurer: AIG

Vehicle No: SGX7Y

Third Party Veh No: SKW1572H

Model: MERCEDES BENZ E200

Date of Accident: 10/11/17

Chassis: WDD2130422A102884

QTY	DESCRIPTION	UNIT \$S	AMOUNT \$S
1	REAR RH DOOR		\$2,118.00
1	REAR RH DOOR RUBBER SEAL		\$135.00
1	REAR RH DOOR WEATHER STRIP		\$274.00
1	REAR RH DOOR POWER WINDOW MOTOR		\$478.00
1	REAR RH DOOR POWER WINDOW REGULATOR		\$702.00
1	REAR RH DOOR POWER WINDOW CHANNEL		\$172.00
1	REAR RH DOOR POWER WINDOW CHANNEL WEATHER STRIP		\$129.00
1	REAR RH DOOR INNER SUPPORT BOARD		\$1,224.00
1	REAR RH DOOR MECHANISM LOCK		\$380.00
14	REAR RH DOOR INNER TRIM BOARD CLIPS	\$9.00	\$126.00
1	ROCKER RH SIDE SKIRTING		\$630.00
1	ROCKER RH SIDE SKIRTING CHROME MOULDING FRONT		\$160.00
1	ROCKER RH SIDE SKIRTING CHROME MOULDING REAR		\$78.00
10	ROCKER RH SIDE SKIRTING CLIPS	\$9.00	\$90.00
1	REAR BUMPER		\$1,872.00
10	REAR BUMPER CLIPS	\$9.00	\$90.00
10	REAR BUMPER RIVET	\$11.50	\$115.00
1	REAR BUMPER RH SIDE RETAINER		\$60.00
1	REAR SUSPENSION RH UPPER ARM		\$178.00
1	REAR SUSPENSION RH KNUCKLE ARM		\$1,592.00
1	REAR SUSPENSION RH KNUCKLE ARM BEARING		\$230.00
1	REAR SUSPENSION RH LOWER ARM		\$242.00
1	REAR SUSPENSION RH TRAILING ARM		\$220.00
1	REAR SUSPENSION RH TORSION ARM		\$210.00
1	REAR RH 17" SPORT RIM ORIGINAL		\$660.00
12	REAR RH FENDER INNER SHIELD CLIPS	\$9.00	\$108.00
	SUB TOTAL		\$12,273.00
	Less 10%		\$1,227.30
	PARTS TOTAL		\$11,045.70

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 14 November 2017

Third Party Insurer:

AIG

Vehicle No: SGX7Y

Third Party Veh No:

SKW1572H

Model: MERCEDES BENZ E200

Date of Accident:

10/11/17

Chassis: WDD2130422A102884

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR RH 225/55 R17 97Y TYRE		5580.00
		S/N TOTAL	5580.00

XX

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,500.00	700
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,250.00	1100
TO TUFF KOTE / ANTI-RUST	\$60.00	300
TO CHECK WIRING, LIGHTING & WATER LEAKAGE	\$60.00	200
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	\$280.00	150
TO DISMANTLE & REPLACED REAR LH UNDER CARRIAGE COMPONENT TO FACILITATE REPAIR	\$350.00	180
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$100.00	60
TO SEND VEHICLE FOR 3D COMPUTERISED WHEEL ALIGNMENT	\$80.00	
TO DISMANTLE & REINSTALL REAR RH DOOR INNER COMPONENT TO FACILITATE REPAIR	\$180.00	80
LABOUR TOTAL	\$3,860.00	
WINSON	TOTAL	\$15,485.70

2740.00

P-8744.40

SL-580.00

L-2740.00

P/P - \$12,044.40

ph: 810/50-20
Remy B4 party
P/P 6 days

QTY	DESCRIPTION	UNIT \$S	AMOUNT \$S
1	REAR RH DOOR		\$2,118.00
1	REAR RH DOOR RUBBER SEAL		\$135.00
1	REAR RH DOOR WEATHER STRIP		\$274.00
1	REAR RH DOOR POWER WINDOW MOTOR		\$478.00
1	REAR RH DOOR POWER WINDOW REGULATOR		\$702.00
1	REAR RH DOOR POWER WINDOW CHANNEL		\$172.00
1	REAR RH DOOR POWER WINDOW CHANNEL WEATHER STRIP		\$129.00
1	REAR RH DOOR INNER SUPPORT BOARD		\$1,224.00
1	REAR RH DOOR MECHANISM LOCK		\$380.00
14	REAR RH DOOR INNER TRIM BOARD CLIPS	\$9.00	\$126.00
1	ROCKER RH SIDE SKIRTING		\$630.00
1	ROCKER RH SIDE SKIRTING CHROME MOULDING FRONT		\$160.00
1	ROCKER RH SIDE SKIRTING CHROME MOULDING REAR		\$78.00
10	ROCKER RH SIDE SKIRTING CLIPS	\$9.00	\$90.00
1	REAR BUMPER		\$1,872.00
10	REAR BUMPER CLIPS	\$9.00	\$90.00
10	REAR BUMPER RIVET	\$11.50	\$115.00
1	REAR BUMPER RH SIDE RETAINER		\$60.00
1	REAR SUSPENSION RH UPPER ARM		\$178.00
1	REAR SUSPENSION RH KNUCKLE ARM		\$1,592.00
1	REAR SUSPENSION RH KNUCKLE ARM BEARING		\$230.00
1	REAR SUSPENSION RH LOWER ARM		\$242.00
1	REAR SUSPENSION RH TRAILING ARM		\$220.00
1	REAR SUSPENSION RH TORSION ARM		\$210.00
1	REAR RH 17" SPORT RIM ORIGINAL		\$660.00
12	REAR RH FENDER INNER SHIELD CLIPS	\$9.00	\$108.00
	SUB TOTAL		\$12,273.00
	Less 10%		\$1,227.30
	PARTS TOTAL		\$11,045.70

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 14 November 2017

Third Party Insurer:

AIG

Vehicle No: SGX7Y

Third Party Veh No:

SKW1572H

Model: MERCEDES BENZ E200

Date of Accident:

10/11/17

Chassis: WDD2130422A102884

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR RH 225/55 R17 97Y TYRE		\$580.00 300
		S/N TOTAL	\$580.00

708.50
'210.50

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION	\$1,500.00	700
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	\$1,250.00	1100
TO TUFF KOTE / ANTI-RUST	\$60.00	300
TO CHECK WIRING, LIGHTING & WATER LEAKAGE	\$60.00	200
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	\$280.00	150
TO DISMANTLE & REPLACED REAR LH UNDER CARRIAGE COMPONENT TO FACILITATE REPAIR	\$350.00	1800
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	\$100.00	600
TO SEND VEHICLE FOR 3D COMPUTERISED WHEEL ALIGNMENT	\$80.00	
TO DISMANTLE & REINSTALL REAR RH DOOR INNER COMPONENT TO FACILITATE REPAIR	\$180.00	800
	LABOUR TOTAL	\$3,860.00
WINSON	TOTAL	\$15,485.70

2740.00

P - 8744.40
S/N - 580.00
L - 2740.00
p/p - \$12,064.40

Phone Number:

Fax Number:

Customer:		Date:	11/25/2017 10:49:16 AM
Company:		VIN	
License No:	SGX7Y	Technician:	WENG
Odometer:		Order No.:	

VEHICLE ALIGNMENT REPORT

MERCEDES-BENZ, 213, 2016-2017, (S) with 4Matic with Code 459/677+L

Primary Angles			Initial	Specifications		Final
				Min	Max	
Front	Caster	Left	-----	9.18°	10.18°	-----
		Right	-----	9.18°	10.18°	-----
	Camber	Left	-0.28°	-1.09°	-0.37°	-0.72°
		Right	-1.44°	-1.09°	-0.37°	-0.94°
	Toe	Left	-5.01°	0.01°	0.18°	0.03°
		Right	4.81°	0.01°	0.18°	0.06°
Total		-0.20°	0.01°	0.35°	0.09°	
Rear	Camber	Left	-1.17°	-1.99°	-0.99°	-1.16°
		Right	-0.94°	-1.99°	-0.99°	-0.61°
	Toe	Left	0.22°	0.09°	0.33°	0.20°
		Right	-1.86°	0.09°	0.33°	0.15°
		Total	-1.64°	0.29°	0.53°	0.35°
	Thrust Angle		-1.04°	-0.13°	0.13°	-0.03°

Secondary Angles		Initial	Specifications		Final
			Min	Max	
SAI	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Included Angle	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Toe Out On Turns	Left	-----	0.94°	1.94°	-----
	Right	-----	0.94°	1.94°	-----
Maximum Turns	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Toe Curve Change	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Sethack	Front	-0.21°	-----	-----	-0.31°
	Rear	-0.32°	-----	-----	-0.52°
Track Width Diff.		-0.19°			-0.16°
Wheel Base Diff.		0.11°			0.21°
Front Ride Height	Left	0.00°	-0.16°	0.63°	0.00°
	Right	0.00°	-0.16°	0.63°	0.00°
Rear Ride Height	Left	0.00°	-0.55°	0.24°	0.00°
	Right	0.00°	-0.55°	0.24°	0.00°
Frame Angle					

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 14 November 2017

Third Party Insurer:

AIG

Vehicle No: SGX7Y

Third Party Veh No:

SKW1572H

Model: MERCEDES BENZ E200

Date of Accident:

10/11/17

Chassis: WDD2130422A102884

Not Authored
1-2-1
Recovery B4 party

6 days

ESTIMATE

QTY	DESCRIPTION	UNIT S\$	AMOUNT S\$	
1	REAR RH DOOR		\$2,118.00	✓
1	REAR RH DOOR RUBBER SEAL		\$135.00	✓
1	REAR RH DOOR WEATHER STRIP		\$274.00	✓
1	REAR RH DOOR POWER WINDOW MOTOR		\$478.00	✓
1	REAR RH DOOR POWER WINDOW REGULATOR		\$702.00	✓
1	REAR RH DOOR POWER WINDOW CHANNEL		\$172.00	✓
1	REAR RH DOOR POWER WINDOW CHANNEL WEATHER STRIP		\$129.00	X
1	REAR RH DOOR INNER SUPPORT BOARD		\$1,224.00	✓
1	REAR RH DOOR MECHANISM LOCK		\$380.00	X
14	REAR RH DOOR INNER TRIM BOARD CLIPS	\$9.00	\$126.00	X
1	ROCKER RH SIDE SKIRTING		\$630.00	X
1	ROCKER RH SIDE SKIRTING CHROME MOULDING FRONT		\$160.00	X
1	ROCKER RH SIDE SKIRTING CHROME MOULDING REAR		\$78.00	✓
10	ROCKER RH SIDE SKIRTING CLIPS	\$9.00	\$90.00	X
1	REAR BUMPER		\$1,872.00	✓
10	REAR BUMPER CLIPS	\$9.00	\$90.00	✓
10	REAR BUMPER RIVET	\$11.50	\$115.00	✓
1	REAR BUMPER RH SIDE RETAINER		\$60.00	X
1	REAR SUSPENSION RH UPPER ARM		\$178.00	✓
1	REAR SUSPENSION RH KNUCKLE ARM		\$1,592.00	✓
1	REAR SUSPENSION RH KNUCKLE ARM BEARING		\$230.00	✓
1	REAR SUSPENSION RH LOWER ARM		\$242.00	✓
1	REAR SUSPENSION RH TRAILING ARM		\$220.00	✓
1	REAR SUSPENSION RH TORSION ARM		\$210.00	✓
1	REAR RH 17" SPORT RIM ORIGINAL		\$660.00	✓
12	REAR RH FENDER INNER SHIELD CLIPS	\$9.00	\$108.00	X
SUB TOTAL			\$12,273.00	
Less 10%			-\$1,227.30	
PARTS TOTAL			\$11,045.70	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OPTIMA WERKZ PTE LTD

Head office : 6 Kung Chong Road Singapore 159143

Tel : +65 6472 1313 Fax : +65 6472 2112

Branch office : 9A Serangoon North Ave 5 Singapore 554500 Tel : +65 6484 9919 Fax : +65 6481 1011

Co. Reg. No. 201212455W

Date: 14 November 2017

Third Party Insurer:

AIG

Vehicle No: SGX7Y

Third Party Veh No:

SKW1572H

Model: MERCEDES BENZ E200

Date of Accident:

10/11/17

Chassis: WDD2130422A102884

ESTIMATE

QTY	SPECIAL NETT	UNIT S\$	AMOUNT S\$
1	REAR RH 225/55 R17 97Y TYRE		\$580.00
		S/N TOTAL	\$580.00

LABOUR CHARGES:

TO REMOVE & REPLACED WITH PANEL BEATING ALL ACCIDENT PORTION \$1,500.00

TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION \$1,250.00

TO TUFF KOTE / ANTI-RUST \$60.00

TO CHECK WIRING, LIGHTING & WATER LEAKAGE \$60.00

TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD \$280.00

TO DISMANTLE & REPLACED REAR LH UNDER CARRIAGE COMPONENT
TO FACILITATE REPAIR \$350.00

TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR \$100.00

TO SEND VEHICLE FOR 3D COMPUTERISED WHEEL ALIGNMENT \$80.00

TO DISMANTLE & REINSTALL REAR RH DOOR INNER COMPONENT TO
FACILITATE REPAIR \$180.00

LABOUR TOTAL \$3,860.00

WINSON TOTAL \$15,485.70

View Received Message

This mail is associated with :

*SGX7Y (2652280443SG)
[SKW1572H]
TP
TAY CHOON HENG DONALD
Nov 10 2017 12:00PM
[Beh Siew Gek Teresa]
Optima Werkz Pte Ltd

Reply Reply All Mark as Unread Print Message Delete Message Forward

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 07/06/2018 13:19 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$11922.01) - SGX7Y - Claim Handler: Loh, Chee-Heng

Approved:11922.01.

DOCUMENTS SUMMARY
There are no documents.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 67414108

Our Ref: CC6/AIG17022097/Kpb3

23 NOVEMBER 2017

BEH SIEW GEK TERESA
BLOCK 714 BEDOK RESERVOIR ROAD
#05-3024
SINGAPORE 470714

Dear Sir/Madam,

ACCIDENT INVOLVING SKW 1572H AND SGX 7Y ON 10.11.2017

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,



Zaini
Case Handler
DID: 6841 2132
FAX: 6741 4108
Email: Zaini@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORISATION TO ACT

I/we, Tay Choon Heng Donald ("the third party claimant") of Blk 106
Lengkong Tiga #08-335 (S) 40106 (address), owner of SGX7Y (vehicle
no.) hereby authorize 6 Kung Chong Rd Singapore 40106 ("the workshop")
to act for me with respect to my claim for repair costs and/or rental and/or loss of use
("claim") for my vehicle no. SGX7Y that was damaged pursuant to the accident which
occurred on 10/11/2017 (date) along Jalan Tunos towards Marine Parade
(location) involving vehicle no/s SKW15724 ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they
deem fit and the workshop is further authorized to receive payment further to settlement of
my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a
without prejudice and without admission of liability basis insofar as the driver/owner/insurers
of the other vehicle/s is concerned.

Dated this 10th (day) of November (month) 20 17 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG ASIA PACIFIC-EXPRESS THIRD PARTY CLAIM)

"We/I, OPTIMA WERKZ PTE LTD (the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 10,636.01 (repair cost), S 1,284.00 (loss of rental/use), S\$ 2.00 (disbursement), for vehicle no. SGX 7Y that was damaged pursuant to the accident which occurred on 10/11/2017 (date) along JLN EUNOS (location) involving vehicle no/s SKW 1572H.

This is pursuant to the inspection conducted on 15/11/2017 (date) at "the workshop".


We/I confirm that we/I are/am authorized by the owner TAY CHOON HENG DONALD (the third party claimant") of vehicle no. SGX 7Y make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".


We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGX 7Y (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 7th (day) of June (month) 2018 (year)

KSC

Signed by AIG appointed surveyor

Wj

Chopped & Signed by "the workshop"

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500

Tel (+65) 6484 9919 Fax: (+65) 6481 1101

Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Tel 6419 1000
Fax: 6835 7416

INV NO. : 121802655
INVOICE DATE : 23/04/2018
REF : TP#572
VEH NO. : SGX7Y
CAR MODEL : E200
CURRENT MILEAGE:
ADVISOR : WINSON
TERMS : COD

DESCRIPTION	QTY	UOM	U.PRICE SGD	AMOUNT SGD
REAR DOOR RH	1	PC	1,906.20	1,906.20
REAR DOOR RUBBER SEAL RH	1	PC	121.50	121.50
REAR DOOR WEATHERSTRIP RH	1	PC	246.60	246.60
REAR DOOR POWER WINDOW MOTOR RH	1	PC	430.20	430.20
ROCKER SIDE SKIRTING CHROME MOULDING RH (REAR)	1	PC	70.20	70.20
REAR BUMPER	1	PC	1,684.80	1,684.80
REAR BUMPER CLIP	10	PCS	8.10	81.00
REAR BUMPER RIVET	10	PCS	10.35	103.50
REAR SUSPENSION UPPER ARM RH	1	PC	160.20	160.20
REAR SUSPENSION KNUCKLE ARM RH	1	PC	1,330.20	1,330.20
REAR SUSPENSION KNUCKLE ARM BEARING RH	1	PC	207.00	207.00
REAR SUSPENSION LOWER ARM RH	1	PC	217.80	217.80
REAR SUSPENSION TRAILING ARM RH	1	PC	198.00	198.00
REAR SUSPENSION TORSION ARM RH	1	PC	189.00	189.00
REAR 17" SPORT RIM ORIGINAL RH	1	PC	594.00	594.00
TO REMOVE & REPLACE WITH PANEL BEATING ALL ACCIDENT PORTION	1	JOB	700.00	700.00
TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	1	JOB	1,100.00	1,100.00
TO TUFF KOTE / ANTI RUST	1	JOB	30.00	30.00
TO CHECK WIRING, LIGHTING & WATER LEAKAGE	1	JOB	20.00	20.00
TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	1	JOB	150.00	150.00
TO DISMANTLE & REPLACE REAR UNER CARRIAGE COMPONENT	1	JOB	180.00	180.00
TO FACILITATE REPAIR LH				
TO DISMANTLE & REPLACE REAR BUMPER REVERSE SENSOR	1	JOB	60.00	60.00
TO SEND VEHICLE FOR 3D COMPUTERISED WHEEL ALIGNMENT	1	JOB	80.00	80.00
TO DISMANTLE & REINSTALL REAR DOOR INNER COMPONENT 1 FACILITATE REPAIR	1	JOB		80.00

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500
Tel (+65) 6484 9919 Fax: (+65) 6481 1101
Co Reg & GST No: 201212455W

TAX INVOICE

To: AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

Tel 6419 1000
Fax: 6835 7416

INV NO. : 121802655
INVOICE DATE : 23/04/2018
REF : TP#572
VEH NO. : SGX7Y
CAR MODEL : E200
CURRENT MILEAGE:
ADVISOR : WINSON
TERMS : COD

DESCRIPTION	QTY	UOM	U.PRICE SGD	AMOUNT SGD
-------------	-----	-----	----------------	---------------

Remarks: DOA: 10/11/17
CLAIMANT NAME: TAY CHOON HENG DONALD
NRIC NO: S1365143D
TP VEHICLE: SKW1572H

Singapore Dollars: Ten Thousand Six Hundred Thirty-Six And Cent One Only

Name: _____

NRIC No.: _____

Signature: _____

SUB TOTAL	SGD	9,940.20
GST 7.00%	SGD	695.81
GRAND TOTAL	SGD	<u>10,636.01</u>

I/We confirm that I/We incurred the repair costs herein and will observe my/our agreement with the repairs.
I/We declare the repairs for above vehicle have been completed to my/our satisfaction.

1) New parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one (1) year or mileage up to 30,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.

2) Recon Parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six (6) months or mileage up to 10,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.

3) Goods sold are not refundable/returnable.

Original Invoice is only valid when the payment is acknowledge receipt by Optima Werkz Pte Ltd. Interest of 2% per month will be charged on any outstanding amount.

for Optima Werkz Pte Ltd

AUTHORISED SIGNATURE(S)

Optima Werkz Pte Ltd

9A Serangoon North Avenue 5, Singapore 554500

Tel (+65) 6484 9919 Fax: (+65) 6481 1011

Co Reg & GST No: 201212455W

TAX INVOICE

To: TAY CHOON HENG DONALD

BLK 106 LENGKONG TIGA
#08-335 SINGAPORE 410106

Tel 9673 0362

Fax:

INV NO. : 120007509
INVOICE DATE : 07/12/2017
REF : TP#572 - CR
VEH NO. : SGX7Y
MAKE : MERCEDES BENZ
MODEL : E200
CURRENT MILEAGE:
ADVISOR :
TERMS : COD

#	DESCRIPTION	QTY	UOM	U/P SGD	AMT SGD
1	CAR RENTAL CHARGES RENTAL AGREEMENT NQ 100800 VEHICLE NO: SJY1947L MODEL: MERCEDES BENZ C180 FROM 10-11-2017 TO 25-11-2017	15	DAYS	240.00	3,600.00

Remarks: DOA: 10/11/17

Singapore Dollars: Three Thousand Eight Hundred Fifty-Two Only

Name: _____

NRIC No.: _____

Signature: _____

SUB TOTAL SGD 3,600.00
GST 7.00% SGD 252.00
TOTAL SGD 3,852.00
Outstanding SGD 3,852.00

/We confirm that iWe incurred the repair costs herein and will observe my/our agreement with the repairs.

/We declare the repairs for above vehicle have been completed to my/our satisfaction

1) New parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of one (1) year or mileage up to 30,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.

2) Recon Parts purchased and installed by Optima Werkz Pte Ltd, will be entitled to warranty period of six (6) months or mileage up to 10,000km, whichever comes first, from the date of invoice, with the exception to wear & tear items.

3) Goods sold are not refundable/returnable.

Original Invoice is only valid when the payment is acknowledge receipt by Optima Werkz Pte Ltd. Interest of 2% per month will be charged on any outstanding amount

For Optima Werkz Pte Ltd

AUTHORISED SIGNATURE(S)

Optima Werkz Pte Ltd

6 Kung Chong Rd Singapore 159143
Tel: +65 6472 1313 Fax: +65 6472 2112 Website: www.ow.sg
9A Serangoon North Ave 5 Singapore 554500
Tel: +65 6484 9919 Fax: +65 6481 1011
CO. REG NO. 201212455W



VEHICLE RENTAL AGREEMENT

TP# 572

DOA: 10/11/2017

No: 100800

HIRER'S PARTICULARS		Rental replacement	
Full Name: <u>Tay Choon Heng Ronald</u>		Vehicle No: <u>SGX77</u>	Vehicle No: <u>SSY947L</u>
Nric/Passport No: <u>S1365143D</u>		Make/Model: <u>M/Benz E200</u>	Make/Model: <u>M/Benz C180</u>
Address: <u>Blk 106 Leng Kong Tien #08-335</u>		Mileage Out: <u>-</u>	<u>117550</u>
			<u>118246</u>
Name & Address Employer: <u>-</u>		DATE OUT: <u>10/11/2017</u>	TIME OUT: <u>4:50</u> AM/PM
		DATE IN: <u>25/11/2017</u>	TIME IN: <u>1:45</u> AM/PM
Occupation: <u>Indoor</u>	Driving Exp: <u>40 Years</u>	Signature: <u>[Signature]</u>	<u>X</u>
Driving Licence No: <u>S1365143D</u>	D/L Type: <u>(Local/Int'l)</u>	CHARGES	
Issue Date: <u>26/07/2004</u>	Date of Birth: <u>29/08/1959</u>	S\$	
Contact no(s): <u>96730362</u>	HP: <u>-</u>	15 Day(s) @ S\$ <u>240.00</u> per day	<u>3600.00</u>
ADDITIONAL DRIVER'S PARTICULARS		Week(s) @ S\$ <u>per day</u>	
Full Name: <u>Tay Kim Noi Evelyn</u>		Month(s) @ S\$ <u>per day</u>	
Nric/Passport No: <u>S171317817</u>		Extension	
Address: <u>AS Above</u>			
Contact no(s): <u>96211179</u>	HP: <u>-</u>	Delivery/Collection Charges	
Driving Licence No: <u>S171317817</u>	Driving Exp: <u>27 Years</u>	Sub-Total	
Issue Date: <u>03/08/2004</u>	D/L Type: <u>(Local/Int'l)</u>	Petrol Level	
Occupation: <u>Indoor</u>	Date of Birth: <u>14/07/1965</u>	Out E 1/4 1/2 3/4 <u>(E)</u>	
REMARKS:		IN E 1/4 1/2 3/4 <u>(E)</u>	
1) Excess I - \$2000.00		MISC	
2) Excess II - \$2000.00		TOTAL CHARGES (Inclusive of GST) <u>3852.00</u>	
<u>[Signature]</u> X		Less Deposit	
		Balance Payable/Refundable	
		Refund received	

*IMPORTANT

- ONLY PERSON ABOVE 24 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE. AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
- ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
- IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
- EXCESS - HIRER IS LIABLE TO PAY INSURANCE EXCESS/ES WHICH IS/ARE APPLICABLE UNDER THE RENTAL CAR INSURANCE POLICY IN ANY EACH ACCIDENT PLUS LOSS OF EARNINGS WHILE DAMAGED VEHICLE IS UNDER REPAIR.
- VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY. OUR INSURANCE DOES NOT COVER IN MALAYSIA.

I HAVE READ THE TERMS AND CONDITIONS ON BOTH SIDE OF THIS RENTAL AGREEMENT AND AGREE THEREOF.
I UNDERTAKE NOT TO USE OR LET OTHERS USE THE RENTAL VEHICLE TO CARRY OUT ANY ILLEGAL OR CRIMINAL ACTS INCLUDING CARRYING OF DUTY UNPAID GOODS.

Hirer's
Signature: [Signature] X
Date:

Driver's Signature
(if different from Hirer) [Signature]
Date:



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-17-168805

Date of Request: 10/11/2017

Your Ref No:

Online Purchase

Optima Werkz Pte Ltd
6 Kung Chong Road
Singapore 159143

Dear Sir/Madam,

Enquiry Date 10/11/2017

Enquiry By Leng leng

TP Vehicle No. SKW1572H

Accident Date 10/11/2017

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

Third Party Insurer Enquiry

Our Ref No: GR-17-168805

Date of Request: 10/11/2017

Your Ref No: Online Purchase

Optima Werkz Pte Ltd
6 Kung Chong Road
Singapore 159143

Dear Sir/Madam,

Enquiry Date 10/11/2017

Enquiry By Leng Ieng

TP Vehicle No. SKW1572H

Accident Date 10/11/2017

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SKW1572H	AIG Asia Pacific Insurance Pte. Ltd.	20/10/2017-19/10/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Nov 2017 Edit Reg		15 Nov 2017 00:00 Edit Adj Rpt	S\$9,940.20 Edit Estimates	S\$9,940.20 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:	Beh Siew Gek Teresa, ID: S1210560F		
Main Claimant:	TAY CHOON HENG DONALD, ID: S1365143D		
Vehicle Reg. No.:	SGX7Y	Date of Loss:	10/11/2017 12:00 - :59 [8 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 2652280443SG	Policy/Cover Note No.:	2100433172 (Comprehensive)
Vehicle Reg. No. (Insured):	SKW1572H	Policy No. (Claimant):	GA163574/1
		Excess:	
Repairer:	Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5, 554500 Serangoon - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 29/11/2017]		
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail	
<ul style="list-style-type: none"> AIG_SG_EXPRESS (07/06/2018): Alert - Adj Mandate Approved (S\$11922.01) - SGX7Y - Claim Handler: Loh, Chee-Hen... 			
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete	
Due Date	Priority	Type	Task Group Subject Handler Assigned By Completed On Created On Done?
No results.			

Claim Documents

***SGX7Y (2652280443SG)
[SKW1572H]**

TP

TAY CHOON HENG DONALD

Nov 10 2017 12:00PM

[Beh Siew Gek Teresa]

Optima Werkz Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit
Assessment Reports				
1 per page <input type="checkbox"/>				
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	21/11/17 10:20	Accident Statement <small>From: SC - Reg. No: SKW1572H, Claimant: BEH SIEW GEK TERESA</small>		Load HTM
Photos/Images				
3 per page <input type="checkbox"/>				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
2	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
3	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
4	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
5	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
6	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
7	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
8	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
9	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
10	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
11	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
12	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
13	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
14	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
15	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
16	06/06/18 17:04	General View		Load JPG <input checked="" type="checkbox"/>
17	06/06/18 17:05	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
18	06/06/18 17:05	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
19	06/06/18 17:05	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
20	06/06/18 17:05	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
21	06/06/18 17:05	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
22	06/06/18 17:05	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
Documentation				
1 per page <input type="checkbox"/>				
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/11/17 08:47	TP ESTIMATE- MARKED		Load PDF
2	21/11/17 08:47	TP GIA REPORT		Load PDF
3	06/06/18 17:04	RENTAL RECEIPT		Load PDF
4	06/06/18 17:04	GIA SEARCH		Load PDF
5	06/06/18 17:04	LETTER TO OI		Load PDF
6	06/06/18 17:14	Email to AIG to seek mandate SGX 7Y 6.6.18		Load PDF

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
7	08/06/18 13:35	WORKSHOP INVOICE		Load PDF
8	08/06/18 13:35	AUTHORISATION TO ACT FORM		Load PDF
9	08/06/18 13:35	Release Voucher		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties:-</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKW1572H (Insd veh)	Model:	MERCEDES-BENZ E200
	SGX7Y (TP veh)		(R17) 2.0 (A)
Date of Accident:	10/11/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$		16,569.70
Final Repair Cost	:	\$		10,636.01
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		1,284.00 8 days
LTA / GIA Search Fee	:	\$		2.00
Others:	:	\$		0.00
	:	\$		
Final Settlement Sum	:	\$		11,922.01

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown				
1)	Optima Werkz Pte Ltd	:	\$	11,922.01
2)		:	\$	
3)		:	\$	

JOANNE LEE KHANG MIN

08 Jun
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG17022097/KWB3Q2

Date: 08/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100433172
Claimant Vehicle No : SGX7Y **Insured Vehicle No :** SKW1572H
 Date of Loss: 10/11/2017 Nature of Claim: TP Claim No: 2652280443SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGX7Y**
 Make & Model: MERCEDES-BENZ E200 (R17), 2.0 (A) Engine No: 27492030812912
 Reg. Date: 13/02/2017 (Man. Year: 2016) Chassis No: WDD2130422A102884
 Colour: Metallic Grey Odometer: 32616 km
 Engine Capacity: 1991 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17
 Front Left Side: Pirelli 4 mm Rear Left Side: Pirelli 2 mm
 Front Right Side: Pirelli 4 mm Rear Right Side: Pirelli 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,625.70	7,540.20	4,085.50	35.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,860.00	2,400.00	1,460.00	37.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,485.70	9,940.20	5,545.50	35.81
+ GST 7.00/7.00% (S\$)	1,084.00	695.81	388.19	35.81
Nett Amount (S\$)	16,569.70	10,636.01	5,933.69	35.81
+ Car Rental (8.0 x S\$150.00/day + 7.00% GST) (S\$)		1,284.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		11,922.01		

INSPECTION

Date of Assignment: 15/11/2017
 Date Inspected: 15/11/2017 Inspected At: Optima Werkz Pte Ltd (HQ)
 9A Serangoon North Ave 5,
 554500 Serangoon

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Bent /Warped	2,118.00 FL	*2,118.00 FL
2	1		*REAR RH DOOR RUBBER SEAL	Necessary	135.00 FL	*135.00 FL
3	1		*REAR RH DOOR WEATHERSTRIP	Necessary	274.00 FL	*274.00 FL
4	1		*REAR RH DOOR POWER WINDOW MOTOR	Jammed	478.00 FL	*478.00 FL
5	1		*REAR RH DOOR POWER WINDOW REGULATOR	Serviceable	702.00 FL	*- FL
6	1		*REAR RH DOOR POWER WINDOW CHANNEL	Serviceable	172.00 FL	*- FL
7	1		*REAR RH DOOR POWER WINDOW CHANNEL WEATHERSTRIP	Serviceable	129.00 FL	*- FL
8	1		*REAR RH DOOR INNER SUPPORT BOARD	Serviceable	1,224.00 FL	*- FL
9	1		*REAR RH DOOR MECHANISM LOCK	Repair	380.00 FL	*- FL
10	14		*REAR RH DOOR INNER TRIM BOARD CLIPS	Not Necessary	126.00 FL	*- FL
11	1		*ROCKER RH SIDE SKIRTING	Repair	630.00 FL	*- FL
12	1		*ROCKER RH SIDE SKIRTING CHROME MOULDING FRONT	Serviceable	160.00 FL	*- FL
13	1		*ROCKER RH SIDE SKIRTING CHROME MOULDING REAR	Dented	78.00 FL	*78.00 FL
14	10		*ROCKER RH SIDE SKIRTING CLIPS	Not Necessary	90.00 FL	*- FL
15	1		*REAR BUMPER	Buckled / Dented	1,872.00 FL	*1,872.00 FL
16	10		*REAR BUMPER CLIPS	Necessary	90.00 FL	*90.00 FL
17	10		*REAR BUMPER RIVET	Necessary	115.00 FL	*115.00 FL
18	1		*REAR BUMPER RH SIDE RETAINER	Serviceable	60.00 FL	*- FL
19	1		*REAR SUSPENSION RH UPPER ARM	Distorted	178.00 FL	*178.00 FL
20	1		*REAR SUSPENSION RH KNUCKLE ARM	Bent	1,592.00 FL	*1,478.00 FL
21	1		*REAR SUSPENSION RH KNUCKLE ARM BEARING	Bent	230.00 FL	*230.00 FL
22	1		*REAR SUSPENSION RH LOWER ARM	Distorted	242.00 FL	*242.00 FL
23	1		*REAR SUSPENSION RH TRAILING ARM	Distorted	220.00 FL	*220.00 FL
24	1		*REAR SUSPENSION RH RH TORSION ARM	Distorted	210.00 FL	*210.00 FL
25	1		*REAR RH 17 SPORT RIM ORIGINAL	Dented	660.00 FL	*660.00 FL
26	12		*REAR RH FENDER INNER SHIELD CLIPS	Not Necessary	108.00 FL	*- FL
27	1		*REAR RH 225/55 R17 97Y TYRE	Serviceable	580.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **12,853.00** **8,378.00**
 - List Item Discount on L Items 10.00/10.00% (\$\$) 1,227.30 837.80

Total Parts (\$\$) **11,625.70** **7,540.20**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REPLACE WITH PANEL BEATING ALL ACCIDENT PORTION	New	1,500.00	700.00
2	TO PUTTY & SPRAY PAINTING WITH SEALANT ALL ACCIDENT PORTION	New	1,250.00	1,100.00
3	TO TUFF KOTE/ANTI-RUST	New	60.00	30.00
4	TO CHECK WIRING ,LIGHTING & WATER LEAKAGE	New	60.00	20.00
5	TO DIAGNOSTIC CHECK & RESET MEMORY TO IDENTIFICATION STANDARD	New	280.00	150.00
6	TO DISMANTLE & REPLACED REAR LH UNDER CARRIAGE COMPONENT TO FACILITATE REPAIR	New	350.00	180.00
7	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR	New	100.00	60.00
8	TO SEND VEHICLE FOR 3D COMPUTERISED WHEEL ALIGNMENT	New	80.00	80.00
9	TO DISMANTLE & REINSTALL REAR RH DOOR INNER COMPONENT TO FACILITATE REPAIR	New	180.00	80.00
Gross Labour Cost (\$\$)			3,860.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >