

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5652A -**AAD1711-182***Not Authoish*
11 Sep 8 ?

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5652A - CANDY

VF1ABL15AUC279748

RENAULT

LATITUDE

16.11.2017

⑨**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Bu</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
3	1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
4	1	BUMPER RETAINER FRT LH	\$	<i>Dis</i> 151.41 ✓
5	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
6	1	BUMPER RETAINER FRT RH	\$	<i>Sn</i> 150.77 X
7	1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
8	1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
9	1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>Sn</i> 207.21 X
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
12	1	BUMPER BEAM FRT	\$	<i>n</i> 914.08 X
13	1	TOW COVER FRT	\$	<i>Sn</i> 28.61 X
14	1	RADAIOR GRILLE	\$	<i>mycm</i> 1,707.78 ✓
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>ru</i> 225.36 ✓
16	1	RADAIOR GRILLE FRAME	\$	<i>cm</i> 1,353.75 ✓
17	1	FRAME FULL SUPPORT PANEL	\$	<i>cm</i> 615.90 ✓
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>n</i> 89.79 X
19	1	FRONT BRACE PANEL	\$	<i>n</i> 177.22 X
20	1	HEADLALMP LH	\$	<i>nd/lt</i> 1,184.43 ✓
21	1	HEADLALMP RH	\$	<i>Sn</i> 1,184.43 X
22	1	HEADLAMP PANEL FRT LH	\$	<i>n</i> 152.15 ✓
23	1	HEADLAMP PANEL FRT RH	\$	<i>n</i> 152.15 X
24	1	BONNET	\$	<i>n</i> 1,941.63 } X
25	1	BONNET INSULATOR	\$	<i>Sn</i> 405.73 }
26	1	BONNET STRUT LH	\$	<i>Sn</i> 88.61 }
27	1	BONNET STRUT RH	\$	<i>Sn</i> 88.61 }
28	1	BONNET HINGE LH	\$	<i>n</i> 348.31 }
29	1	BONNET HINGE RH	\$	<i>n</i> 348.31 }
30	1	BONNET LOCK	\$	<i>n</i> 305.48 }
31	1	BONNET CABLE	\$	<i>Sn</i> 119.19 }
32	1	BONNET CABLE COVER	\$	<i>Sn</i> 161.03 }
33	1	BONNET SEAL OUTER	\$	<i>Sn</i> 92.36 }
34	1	FENDER PANEL FRT LH	\$	<i>n</i> 783.83 }

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-182**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5652A -

35	1	FENDER PANEL FRT RH	\$	R	783.83	
36	1	WHEELARCH FRT RH	\$	Sn	278.84	
37	1	FENDER BRACKET LOWER RH	\$	R	15.79	
38	1	FENDER INSULATOR RH	\$	Sn	130.84	
39	1	AIR CLEANER LOWER	\$	Sn	271.26	
40	1	AIR CLEANER HOSE	\$	Sn	76.14	
41	1	A/C CONDENSER	\$	Sn	2,020.37	
42	1	AIR COOLER	\$	Sn	792.60	
43	1	AIR INTERCOOLER HOSE (LONG)	\$	Sn	1,014.13	
44	1	AIR INTERCOOLER HOSE (Short)	\$	Sn	375.14	
45	1	TRANSMISSION COOLER	\$	Sn	1,219.30	
46	1	TRANSMISSION COOLER PAD	\$	Sn	17.96	
47	1	RADIATOR	\$	Sn	1,202.20	
48	1	RADAIOR FAN COWLING	\$	Sn	820.54	
49	1	RADIATOR FAN MOTOR LH	\$	Sn	967.36	
50	1	RADIATOR FAN MOTOR RH	\$	Sn	1,479.46	
51	1	RADIATOR TANK	\$	Sn	324.62	
52	1	WINDSCREEN FRT	\$	Sn	1,364.06	
53	1	BUMPER COVER REAR	\$	B	1,108.46	✓
54	1	BUMPER LOWER REAR	\$	B	768.84	✓
55	1	BUMPER BRACKET CTR REAR	\$	Sn	113.47	X
56	1	BUMEPR BRACKET SIDE LH REAR	\$	Sn	135.97	<
57	1	BUMEPR BRACKET CTR LH REAR	\$	Sn	44.99	X
58	1	BUMEPR BRACKET SIDE RH REAR	\$	Dir	135.97	✓
59	1	BUMEPR BRACKET CTR RH REAR	\$	CM	44.99	✓
60	1	BUMPER BEAM REAR	\$	B	777.52	✓
61	1	BUMPER BEAM BRACKET LH REAR	\$	R	225.95	X
62	1	BUMPER BEAM BRACKET RH REAR	\$	B	225.95	✓
63	1	BUMPER REFLECTOR RH	\$	B	43.61	✓
64	1	BOOT REAR	\$	B	2,872.68	✓
65	2	BOOT RUBBER PLUG	\$	Sn	221.81	
66	1	BOOT FINISHER	\$	Sn	470.06	
67	1	BOOT SWITCH	\$	Sn	168.13	
68	1	BOOT TRIM BOARD	\$	Sn	914.87	
69	1	BOOT LOCK	\$	R	202.67	
70	1	BOOT LOCK CATCH	\$	R	74.40	
71	1	BOOT LOCK LINKAGE	\$	Sn	34.53	
72	1	BOOT LOCK LINKAGE HOLDER	\$	Sn	154.52	
73	1	BOOT LOCK CATCH TRIM BOARD	\$	Sn	249.24	
74	1	BOOT WHEATERSTRIP	\$	Dir/L	323.05	✓
75	1	BOOT REFLECTOR LAMP LH	\$	Sn	493.35	X
76	1	BOOT REFLECTOR LAMP RH	\$	CM	493.35	✓

TRANS-CAB AUTO SERVICES PTE LTD
AAD1711-182

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5652A -

77	1	BOOT BADGE 'RENAULT'	\$	<i>M</i>	225.36	—
78	1	BOOT BADGE	\$	<i>M</i>	225.36	—
79	1	BOOT STRUT LH	\$	<i>S</i>	276.08	} X
80	1	BOOT STRUT RH	\$	<i>S</i>	276.08	
81	1	BOOT HINGE LH	\$	<i>R</i>	367.84	
82	1	BOOT HINGE RH	\$	<i>R</i>	367.84	
83	2	LICENCE PLATE LAMP	\$	<i>P</i>	50.52	
84	1	WINDSCREEN REAR	\$	<i>S</i>	1,463.28	
85	1	WINDSCREEN GARNISH INNER LH	\$	<i>S</i>	263.74	
86	1	WINDSCREEN GARNISH INNER RH	\$	<i>S</i>	263.74	}
87	1	TAILLAMP LH	\$	<i>S</i>	552.55	
88	1	TAILLAMP PANEL LH	\$	<i>R</i>	986.70	
89	1	TAILLAMP RH	\$	<i>B</i>	552.55	—
90	1	TAILLAMP PANEL RH	\$	<i>B</i>	986.70	—
91	1	CHASSIS PANEL REAR RH	\$	<i>R</i>	3,766.43	X
92	1	FENDER PANEL REAR LH	\$	<i>R</i>	3,299.13	X
93	1	FENDER PANEL REAR RH	\$	<i>B</i>	3,299.13	—
94	1	WHEELARCH REAR RH	\$	<i>S</i>	543.47	X
95	1	FENDER PANEL INNER TRIM REAR RH	\$	<i>Ref</i>	671.45	—
96	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	<i>R</i>	3,039.04	X
97	1	LOWER ARM REAR RH	\$		905.99	?
98	1	KUCKLE ARM REAR RH	\$		736.67	?
99	1	ABSORBER RH REAR	\$		389.75	?
100	1	ABSORBER DUST COVER REAR RH	\$	<i>S</i>	92.16	X
101	1	ABSORBER MOUNTING REAR RH	\$	<i>S</i>	92.16	X
102	1	AIR VENT RH	\$	<i>P</i>	97.28	X
103	1	REAR AXLE	\$		4,167.03	?
104	1	AXLE ARM ROD	\$	<i>S</i>	117.22	X
105	1	AXLE ARM LH	\$	<i>S</i>	117.22	X
106	1	AXLE ARM RH	\$		117.22	?
107	1	AXLE ARM SHIELD LH	\$	<i>S</i>	9.08	X
108	1	AXLE ARM SHIELD RH	\$	<i>S</i>	9.08	X
109	1	AXLE SPRING ARM LH	\$	<i>S</i>	376.92	X
110	1	AXLE SPRING ARM RH	\$	<i>S</i>	376.92	X
111	1	STABILIZER BAR REAR	\$	<i>S</i>	604.65	X
112	1	STABILIZER LINK REAR LH	\$	<i>P</i>	92.36	X
113	1	STABILIZER LINK REAR RH	\$		92.36	?
114	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i>	2,189.88	X
115	1	SPARE WHEEL PANEL TRIM (Luggage Floor Panel)	\$	<i>S</i>	612.21	X
116	1	SPARE WHEEL PANEL BRACKET RH	\$	<i>R</i>	121.36	X
117	1	OUTER PANEL REAR (End Panel)	\$	<i>B</i>	1,471.77	—
118	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>CM</i>	401.02	—

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-182**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5652A -

119	1	EXHAUST REAR	\$	7,489.05 ✓
120	1	EXHAUST CAP REAR	\$	230.49 ✓
121	1	EXHAUST MOUNTING REAR	\$	31.97 ✓
122	1	EXHAUST BRACKET REAR	\$	39.86 X
123	1	EXHAUST HEAT SHIELD REAR	\$	99.06 ✓
124	1	SHIELD - HEAT - TUNNEL	\$	225.16 ✓
125	1	DOOR PANEL REAR RH	\$	2,844.66 X
126	1	DOOR SEAL REAR RH	\$	162.02 X

TOTAL	\$	85,251.00
10%	\$	8,525.10
	\$	76,725.90

Specical Nett

1	1SET	RADAITOR GRILLE FRAME CLIP	\$	52.00 ✓
2	1SET	BUMPER CLIP FRT	\$	66.00 ✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	12.00
4	1	BUMPER SUPPORT CLIP FRT LH	\$	10.50
5	1	BUMPER BRACKET CLIP FRT RH	\$	12.00
6	1	BUMPER SUPPORT CLIP FRT RH	\$	10.50
7	1	TOW COVER FRT	\$	14.50
8	1SET	RADAITOR GRILLE SCREW	\$	16.00
9	1SET	BUMPER GRILLE LOWER CLIP	\$	69.00
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	70.00
11	2	FRAME FULL SUPPORT PANEL NUT	\$	20.00
12	2	FRAME FULL SUPPORT PANEL STUD	\$	30.00
13	1SET	WHEELARCH CLIP FRT RH	\$	29.40
14	1	CAP HUB RH FRT	\$	35.00
15	1	RIM RH FRT	\$	385.00
16	1	TYRE RH FRT	\$	330.00
17	1SET	BUMPER RR CLIP	\$	66.00 ✓
18	1SET	BUMPER BEAM BOLT	\$	22.22 X
19	1SET	PARKING AID	\$	600.00 ✓
20	1	BUMPER BRACKET CLIP CTR REAR	\$	15.00
21	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	12.00
22	1	BUMEPR RETAINER CLIP LH REAR	\$	10.40
23	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	12.00
24	1	BUMEPR RETAINER CLIP RH REAR	\$	10.40
25	1	CAP HUB LH RR	\$	35.00
26	1	RIM LH RR	\$	385.00
27	1	TYRE LH RR	\$	330.00
28	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-182**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5652A -

29	1	SPARE TYRE	\$	Sn 330.00 X
30	1SET	BOOT FINISHER CLIP	\$	nn 25.10 X
31	1	Rear boots sticker "trans-cab"	\$	nn 30.00 ✓
32	1	Rear boots sticker "6555-3333"	\$	nn 30.00 —
33	1	FENDER PANEL INNER TRIM CLIP REAR RH	\$	nn 22.00 X
34	1SET	WHEELARCH CLIP RH RR	\$	nn 32.34 X
35	2	Rear windscreen sealant	\$	nn 80.00 40sn
36	1	Windscreen moulding	\$	nn 100.00 ✓
37	1	Rear Windscreen Inner Sponge Seal	\$	nn 100.00 30sn
38	1	EXHAUST MOUNTING REAR	\$	Perimeter 65.50 X
39	1	EXHAUST BRACKET REAR	\$	n 22.22 X
40	1SET	Front licence plate with holder	\$	nn 80.00 45sn
41	1SET	Rear licence plate with holder	\$	Sn 80.00 X
42	1	DOOR STICKER "6555-3333" LH	\$	nn 80.00 X
43	1	DOOR STICKER "6555-3333" RH	\$	nn 80.00 X

TOTAL	\$	4,202.08
TOTAL PARTS	\$	80,927.98

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	5,600.00 1800
Towing Fees.	\$	nn 120.00 X
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00 X
Putty and spray painting of the affected portion.	\$	6,000.00 1320
To rust-proofing of the affected areas.	\$	170.00 90
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00 100
To check steering geometry and computer wheel alignment	\$	220.00 60
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00 X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00 250

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-182**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5652A -

To Check Electrical Lighting Concerned.	\$	170.00	4d
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	<i>Reported</i> 380.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>NA</i> 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>NA</i> 170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>NA</i> 380.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	6d
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>Reported</i> 380.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$	170.00	6d
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	380.00	12d
To reinstall rear bumper parking sensor.	\$	170.00	6d
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00	} 8d
To repair and realign rear exhaust pipe.	\$	170.00	
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	?
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	<i>Reported</i> 380.00	X
To drop rear axle assy, remove and renewal of the necessary parts	\$	<i>NA</i> 380.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1711-182**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC 5652A -

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>nn</i> 440.00	X
To vacuum, replace, refix and recharge air condenser	\$	380.00	<i>10d</i>
To replace, refix and top up coolant for radiator	\$	170.00	<i>5d</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	170.00	<i>5d</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00	X
TOTAL	\$	18,880.00	
Over All Total	\$	99,807.98	

< parts by parts > Repair Days

~~20 DAYS~~*14 days*