

ASS. REC BY

REF CS/MSG17022107/R 1 tbe2

Branch/Location

Surveyor
Meinren

Rasul

ASSIGNMENT (Office)

From (Person)

Christina Wong

of

MSG

Date/Time

20/11/17 @ 1:34 pm

Estimated Cost:

Bill to:

OD (TP+WS/TP RES / OD RES / EVA / INV / MV7 CS

To Inspect Vehicle No:

BMQ 1521

Insured:

FBG 287D

at Workshop m/s

SG 98 Motor

Tel:

6452 4898

of Blk 4001 AMK Ind Park 1 # 01-21, 569622

Policy No:

MSD/VMS/17-360187

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

30/10/2017

CA / REV / REP. / REV 24 HRS

(wp)

21/11/17

H.O.D. Endorsement:

Date/Time

3:50pm @ 20/11/17

Person Contacted:

Rose

Vehicle IN/OUT

Date/Time

Action/Instruction (→ Estimate

BMQ 1521-X

FBG 287D-X

Lump Sum \$2100/- (Red: 2753.60 : 56%) Agree

ASSIGNMENT

210

20/8/2018




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17022107/R1tb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 20-11-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	FBG 287D	Veh. Inspected	BMQ 1521
Policy No.	MSD/VMS/17-360187	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (CHRISTINA WONG)	Assign Date	20/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	30/10/2017	Inspection Date	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Nov 2017		20 Nov 2017 13:34 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SUBRAMANIAM S/O RAJAGOPAL, ID: S1601991G		
Main Claimant:	LOGENTHARAN NOOKARAJOO, ID: G2845553X		
Vehicle Reg. No.:	BMQ1521	Date of Loss:	30/10/2017 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	MSD/VMS/17-360187
Vehicle Reg. No. (Insured):	FBG287D	Policy No. (Claimant):	Coverage: 09/03/2017 - 08/03/2018
		Excess:	
Repairer:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/11/2017]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.



**SINGAPORE
POLICE FORCE**



T/20171116/2045

1 of 3

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

Report No. T/20171116/2045

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 16/11/2017 12:23		Vide Report No.:		Station Diary No.: 25	
Informant's Particulars					
Name of Informant: LOGENTHARAN NOOKARAJOO			Address:		
ID Type / ID No.: FIN NO / G2845553X			Contact No.: Home/Office: 002454957 Mobile: 91352571		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 21	Date of Birth: 24/02/1996	Type of Informant: Rider		
Race: Indian			Language:		Institution / School Name:
Occupation: SECURITY GUARD			Driving Licence Information: Class: 2B Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 30/10/2017 08:45	Type of Location: Straight Road
Location: Along Road 1 TELOK BLANGAH ROAD near SPC				
Weather: Cloudy		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Traffic Light - Working		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
BMQ1521	Motorcycle			Red	Seriously Damaged	1
FBG287D	Motorcycle			Black	Slightly Damaged	0

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20171116/2045

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

2 of 3

Report No. T/20171116/2045

CONTINUATION OF REPORT

Rider			
Name	LOGENTHARAN NOOKARAJOO	ID No.	G2845553X
Related Vehicle	BMQ1521 (Motorcycle)	Contact No.	002454957
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 2B Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	31/10/2017
No. of Days granted Medical Leave	21	Degree of Injury	Serious
Pillion			
Name	SILEMARASAN MUNIANDY	ID No.	G2261775W
Related Vehicle	BMQ1521 (Motorcycle)	Contact No.	0172404436
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	30/10/2017	Date Discharge	NIL
No. of Days granted Medical Leave	03	Degree of Injury	Slight

Brief Details.

On 30/10/17 at about 0845hrs, I was riding to work with my friend Silembarasan Muniandy along Telok Blangah Rd on the most left lane. Suddenly, a motorcycle from the middle lane cut into my lane. The front of my bike then hit the side of the motorcycle. I was then conveyed to Singapore General Hospital. I suffered broken bones on my face and also broke my teeth. Both my arms and legs also have abrasions. My bike has damages on the front and side, however I have no idea how bad the front is damaged. My friend has sent me photos that can see the side is damaged and a little bit of the front of the motorcycle. My pillion also has MC for 3 Days, I am hospitalized for a day in Singapore General Hospital and subsequently transferred to hospital in KL for four days. I am given 21 days MC by Singapore General Hospital. I was conveyed by ambulance on the spot and police were at scene too. I am lodging this report now as I have just recovered slightly and also am lodging this report for insurance purposes.



**SINGAPORE
POLICE FORCE**



T/20171116/2045

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

3 of 3

Report No. T/20171116/2045

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

D /

Sgt 2 LEE JIA YAN

Signature Of Interpreter:

Not applicable

Officer In Charge Of Case:

TP / GIT /

Sgt 2 LIM HONG LEE

Contact No.: 65476438

Signature Of Informant:

Date/Time:

16/11/2017 12:23

Classification Of Case:

Authentication Stamp

NP168

POLICE FORCE

SN 46

SIGNATURE

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 27 November 2017

To : LKK

By Fax: 6256-4315

Attn : Rasul

Tel : 90010068

VEHICLE NO : BMQ 1521

Yamaha LC 135 Jupiter

ACCIDENT DATE: 30 October 2017

<u>Description</u>	<u>Qty</u>	<u>Quotation \$</u>
1 Handle Bar	1	135.00 X SVL
2 Handle Bar Bracket	1	105.00 X SVL
3 U Clip	1	265.00 X SVL
4 Head Lamp Cover	1	80 150.00 SVL
5 Mirror	1 set	50 120.00 SVL
6 Brake Lever	1	40 79.00 SVL
7 Front Panel	1	100 150.00 CRN
8 Front Panel Garnish	1	100 150.00 CRN
9 Fork Tube	1 set	380 480.00 CRN
10 Fork Underbracket	1	85 125.00 CRN
11 Wheel Rim	1 set	180 300.00 SVL
12 Front Mudguard	1	90 135.00 SVL
13 Front Brake Disc	1	195.00 X SVL
14 Front Side Panel RH	1	150 185.00 SVL
15 Side Panel Inner Garnish RH	1	100 155.00 SVL
16 Air Intake	1	85 155.00 CRN
17 Rear RH Side Panel	1	155.00 repair
18 Footrest	1	65 95.00 SVL
19 Footrest Rubber	1	45.00 CRN
20 Exhaust Pipe	1	400 550.00 SVL
21 Exhaust Guard	1	80 125.00 SVL
Sub-Total		3,854.00 2030
Less 10%		385.40 10%
Sub-Total		3,468.60 1827

VEHICLE NO : BMQ 1521

Yamaha LC 135 Jupiter

Nett items

- 1 Towing fee
- 2 Front box
- 3 Rear box
- 4 Remove & replace fork assy, fork oil seal - top up fork oil
- 5 Remove & replace rim & brake disc
- 6 Re-align body frame
- 7 Remove & replace new parts, align & etc
- 8 Check electrical harness wiring
- 9 Supply body decal sticker

40.00 ✓
80 135.00 cut ✓
150 280.00 sub ✓
150.00 80
80.00 40
250.00 180
280.00 150
50.00 20
120.00 60

Sub-Total 1,385.00

Nett Total 4,853.60

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion
Thank you

SG 98 MOTOR PTE LTD

:LG

Rasm
Ap 90010068
4 days
L/S
22/11/17 @ 1840

1827
800
2627
20%
2101.60
43-2,100
4 days

OK Acceptance - 20/8/2018
 Race/SG motor

VEHICLE NO : BMQ 1521

Yamaha LC 135 Jupiter

Nett items

- 1 Towing fee
- 2 Front box
- 3 Rear box
- 4 Remove & replace fork assy, fork oil seal - top up fork oil
- 5 Remove & replace rim & brake disc
- 6 Re-align body frame
- 7 Remove & replace new parts, align & etc
- 8 Check electrical harness wiring
- 9 Supply body decal sticker

40.00
 80 135.00 cut
 150 280.00 sub
 150.00 80
 80.00 40
 250.00 180
 280.00 150
 50.00 20
 120.00 60


Sub-Total 1,385.00

Nett Total 4,853.60

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion

Thank you



SG 98 MOTOR PTE LTD

:LG

Race
 Ap 90010068
 4 days
 4/3
 22/11/17 @ 1840

1827
 800
 2627
 20%
 2101.60
 43.2, 100
 4 days






































...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Nov 2017		20 Nov 2017 13:34 Edit Adj Rpt	S\$2,100.00 Edit Estimates	S\$2,100.00 View Rpt		Pending for Survey Report Cancel Case














Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: SUBRAMANIAM S/O RAJAGOPAL , ID: S1601991G									
Main Claimant: LOGENTHARAN NOOKARAJOO , ID: G2845553X									
Vehicle Reg. No.: BMQ1521		Date of Loss:	30/10/2017 00:00 - :59						
Claim Type: TP / MSC/V/17-001795		Policy/Cover Note No.:	MSD/VMS/17-360187 Coverage: 09/03/2017 - 08/03/2018						
Vehicle Reg. No. (Insured): FBG287D		Policy No. (Claimant):							
		Excess:							
Repairer: Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21, 569622 Ang Mo Kio - Tel: 64524898									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Christina Wong - 6643 1311]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 21/11/2017]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*BMQ1521 (MSC/V/17-001795)
[FBG287D]
TP
LOGENTHARAN NOOKARAJOO
Oct 30 2017 12:00AM
[SUBRAMANIAM S/O RAJAGOPAL]
Sg 98 Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page	<input type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print
1	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
2	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
3	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
4	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
5	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
6	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
7	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
8	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
9	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
10	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
11	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
12	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
13	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
14	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
15	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
16	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
17	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
18	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
19	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
20	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
21	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
22	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
23	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
24	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
25	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
26	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
27	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
28	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
29	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
30	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
31	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
32	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
33	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
34	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
35	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
36	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>
37	20/08/18 16:59	General View						Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
39	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
40	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
41	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
42	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
43	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
44	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
45	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
46	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
47	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
48	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
49	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
50	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
51	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
52	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
53	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
54	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
55	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
56	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
57	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
58	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
59	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
60	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
61	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
62	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
63	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
64	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
65	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
66	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
67	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
68	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
69	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
70	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
71	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
72	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
73	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
74	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
75	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
76	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
77	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
78	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
79	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
80	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
81	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
82	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
83	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
84	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
85	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
86	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
87	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/ Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
89	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
90	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
91	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
92	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
93	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
94	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
95	20/08/18 16:59	General View	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/11/17 13:36	Police Report Part 1	 Load PDF	
2	20/11/17 13:36	Police Report Part 2	 Load PDF	
3	20/11/17 13:36	PRI	 Load PDF	
4	01/12/17 14:28	email to AJAX and ask for our OI's police report, OI said he gave AJAX.	 Load PDF	
5	05/12/17 12:28	email from AJAX attached OI police report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022107/R1TBE2

Date: 24/08/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMS/17-360187		
Claimant Vehicle No :	BMQ1521	Insured Vehicle No :	FBG287D		
Date of Loss:	30/10/2017	Nature of Claim:	TP	Claim No:	MSC/V/17-001795

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	BMQ1521	Engine No:	HIDDEN
Make & Model:	YAMAHA FZ150, 150cc	Chassis No:	HIDDEN
Reg. Date:	(Man. Year:)	Odometer:	75573 km
Colour:	Red		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90-17	Rear Tyre Size:	80/90-17
Front Left Side:	Maxxis 3 mm	Rear Left Side:	Maxxis 3 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,883.60	2,057.00	1,826.60	47.03
Miscellaneous Items	0.00	0.00	0.00	
Labour	970.00	570.00	400.00	41.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	4,853.60	2,627.00	2,226.60	45.88
Approved Total (Overridden) (\$\$)		2,100.00		
Nett Amount (\$\$)	4,853.60	2,100.00	2,753.60	56.73

INSPECTION

Date of Assignment:	20/11/2017	
Date Inspected:	22/11/2017 Inspected At:	Sg 98 Motor Pte Ltd (HQ) BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 Singapore 569622
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Aug 2018)

Parts: N/A YAMAHA FZ150 150cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for BMQ1521)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HANDLE BAR	Serviceable	135.00 FL	*- FL
2	1		*HANDLE BAR BRACKET	Serviceable	105.00 FL	*- FL
3	1		*U CLIP	Serviceable	265.00 FL	*- FL
4	1		*HEAD LAMP COVER	Scratched	150.00 FL	*80.00 FL
5	1		*SET MIRROR	Broken	120.00 FL	*50.00 FL
6	1		*BRAKE LEVER	Scratched	79.00 FL	*40.00 FL
7	1		*FRONT PANEL	Cracked	150.00 FL	*100.00 FL
8	1		*FRONT PANEL GARNISH	Cracked	150.00 FL	*100.00 FL
9	1		*SET FORK TUBE	Cut	480.00 FL	*380.00 FL
10	1		*FORK UNDERBRACKET	Bent	125.00 FL	*85.00 FL
11	1		*SET WHEEL RIM	Scratched	300.00 FL	*180.00 FL
12	1		*FRONT MUDGUARD	Scratched	135.00 FL	*90.00 FL
13	1		*FRONT BRAKE DISC	Serviceable	195.00 FL	*- FL
14	1		*FRONT SIDE PANEL RH	Missing	185.00 FL	*150.00 FL
15	1		*SIDE PANEL INNER GARNISH RH	Scratched	155.00 FL	*100.00 FL
16	1		*AIR INTAKE	Cracked	155.00 FL	*85.00 FL
17	1		*REAR RH SIDE PANEL	Repair	155.00 FL	*- FL
18	1		*FOOTREST	Scratched	95.00 FL	*65.00 FL
19	1		*FOOTREST RUBBER	Cut	45.00 FL	*45.00 FL
20	1		*EXHAUST PIPE	Scratched	550.00 FL	*400.00 FL
21	1		*EXHAUST GUARD	Scratched	125.00 FL	*80.00 FL
22	1		*FRONT BOX	Cut	135.00 FS	*80.00 FS
23	1		*REAR BOX	Scratched	280.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,269.00	2,260.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	385.40	203.00
Total Parts (\$\$)	3,883.60	2,057.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING FEE	New	40.00	40.00
2	REMOVE & REPLACE FORK ASSY, FORK OIL SEAL - TOP UP FORK OIL	New	150.00	80.00
3	REMOVE & REPLACE RIM & BRAKE DISC	New	80.00	40.00
4	RE-ALIGN BODY FRAME	New	250.00	180.00
5	REMOVE & REPLACE NEW PARTS, ALIGN & ETC	New	280.00	150.00
6	CHECK ELECTRICAL HARNESS WIRING	New	50.00	20.00
7	SUPPLY BODY DECAL STICKER	New	120.00	60.00
Gross Labour Cost (\$\$)			970.00	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >