



KAH MOTOR CO. SDN. BHD.
 (A Member of the Oriental Holdings Berhad)
 Service and Body Repair
 Tel: +65 6841 3838 Website: www.honda.com.sg
 For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
 Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
Registration No : SJD150K
Chassis No : JHMRC1890HC203721
Model : ODYSSEY 2.4 EXV-S 17YM (EURO 6)
Owner's Name : HARRY PURWADINATA
Ins Policy No. :
Date of Accident : 12/11/2017

Document No. : SQT17004654 Page 1
Date : 14. Nov 2017
Customer No. : WZA006
Svc Advisor :
Engine No : K24W72041366
Date | Time : 14. Nov 2017 8:16:27 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER:HARRY PURWADINATA OWNER INSURER:AVIVA LTD ACC DATE:12/11/2017 SURVEYED BY: DATE: REF NO: TP INSURER:AXA INSURANCE S'PORE PTE LTD TP VEH:SGW3535A						
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR	1	320.00 ?		320.00	22.40	342.40
04715-T6A-900ZZ	FACERR.BUMPER	1	557.20 <i>DX</i>	35	362.18	25.35	387.53
71507-T6A-003ZD	FACEL.RR.BUMPER GARNISH	1	75.30 <i>SCA</i>	35	48.94	3.43	52.37
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	18.70 <i>ne</i>	35	12.15	0.85	13.00
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	18.70 <i>ne</i>	35	12.15	0.85	13.00
91505-TM8-003	CLIPBUMPER	7	2.00 <i>ne</i>	35	9.10	0.64	9.74
	Sum Item				764.52	53.52	818.04
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	50.00 <i>X</i>		50.00	3.50	53.50
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	100.00 <i>✓</i>		100.00	7.00	107.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	450.00 <i>X</i>		450.00	31.50	481.50
BKBU02R	REPLACE RR BUMPER, L RR BUMPER FACE GARNISH,	1	1000.00 <i>560</i>		1000.00	70.00	1070.00
BP04R	SPRAY PAINTING ON, RR BUMPER, L RR BUMPE	1	1000.00 <i>450</i>		1000.00	70.00	1070.00
	Sum Labor				2600.00	182.00	2,782.00

Survey By: Rahou - 49 90010068
 Date & Time: 11/12/17 @ 1550
 Excess: _____
 Status: 3 days

Revisy b4 print

Total Amount	3,364.52	235.52	3,600.04
Total (Inclusive of GST)	3,600.04		

LKK Auto Consultants hence notify the Repairer Total (Inclusive of GST)

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Document No. : SQT17004654 **Page** 2
Date : 14. Nov 2017
Customer No. : WZA006
Svc Advisor :
Engine No : K24W72041366
Date | Time : 14. Nov 2017 8:16:27 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Registration No : SJD150K
Chassis No : JHMRC1890HC203721
Model : ODYSSEY 2.4 EXV-S 17YM (EURO 6)
Owner's Name : HARRY PURWADINATA
Ins Policy No. :
Date of Accident : 12/11/2017

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
------	-------------	-----	------------	--------	--------	---------	------------------

Signature

Printed on 15/11/2017 10:22:46 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)