

Premium Automobiles

88 Jln Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLR 7725 J.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>deformed</i>	\$ 982.00	✓ 785.60
2	REAR BUMPER MID PORTION <i>deformed</i>	\$ 792.00	✓ 633.20
3	REAR BUMPER LOWER SPOILER TRIM <i>deformed</i>	\$ 378.00	✓ 151.20
4	REAR BUMPER LOWER SPOILER <i>deformed</i>	\$ 549.00	✓
5	REAR BUMPER REFLECTOR - LHS <i>crushed</i>	\$ 24.00	✓ 20.48
6	REAR WHEEL ARCH TRIM - LHS/RHS <i>ru</i>	\$ 776.00	✓ 620.8
7	REAR PARKING AID <i>ru</i>	\$ 208.00	✓
8	SUNDRIES <i>ru</i>	\$ 300.00	X
TOTAL SPARE PARTS		\$ 4,009.00	
TOTAL LABOUR CHARGES		\$ 3,472.00	
GRAND TOTAL		\$ 7,481.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Telefax

Estimated Labour Charges for Accident Vehicle SLR 7725 J.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00 500	
3	To respray rear bumper, lower spoiler and both wheel arch trims.	\$ 2,100.00 1300.	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		\$ 3,472.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved
S/N are Special Nett.