

ASS. RES. BY

CS/MSGH022127/MIV Doc

merimen

MA

ASSIGNMENT OFFICE

From (Person):

Ong chin Kiat

MSIG

20/11/17 @ 2.54 pm

Estimated Cost

Bill to

OD

TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No.

SJC 4188G

Insured

at Workshop in:

K. Kim Hin Auto

Tel: 64527018 | 9717 6881

or 160 Sin Ming Drive # 02-20, 575722

Policy No.

A6043953QMX

Claim No.

536931

Sum Insured

Excess:

\$50000

Make of Veh:

(Client's Record)

D.O.A. 13/11/2017

CA / REV

REP. / REV 24 HRS

Date/Time:

3:37pm @ 20/11/17

Version Contested

Shuman

H.O.D. Endorsement

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SJC 4188G - NBA/AIG 13015413 / 54-D O/A 26/28/2013	
21/11/17	Revert by merimen	
21/11/17	Rece approved from Chen How by merimen	
21/11/17	@ 1149am Informal Shuman c/A on IB1 ex \$500	
14/5/18	@ 257pm Meng Huat will finalise with us	

REF:

Surveyor

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s KK HIN.
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.


N/S	O/S

Bal. or Market Value: \$39k.
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SJC 488G. Yr Regn: AUG 2009.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: AUDI A4 c.c. 1792
 Colour: WHITE A/C: Insured / Std / NI / NA
 Sp. Reading: 243967 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAU2ZZ8K2AA01411.
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 245/35/19
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or MAXEN
 Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. 7 mm L/Bal. 7 mm
 D.O.A. Blueberry D.O.T. 20/1/2017
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
22/5/18	Final fg \$ 6261.50 confirmed by email (Ref 5785, 4890) (No LS)
	RECEIVED 2 JUN 2018
	 23/5/2018

Date/Time, File Pass to? ☐ : Preli. Report1) ☐ : Final Report

Date/Time, File Return to?

2) 23/5 - typistDays Of Repair: 4Resurvey No. of Trip: 1Survey Fee: 300

Transportation: _____

) S + RS. SI

) Photos

) Others

TOTAL

Report Format: merimanLump Sum / I.B.I: (\$) 6261.50Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)310

Survey Department Check List (Case Handler)

Reference No. : CS/MSG 170 22127/ Mlvb

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)	✓			
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess	✓			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases	✓			
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 22/5/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17022127/M1vb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 20-11-2017		
		Code : MSG		
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected		SJC 4188G
Policy No. A8043953QMX		Coverage (\$)		0.00
Claim No. 536931		Excess (\$)		500.00
Assign From MERIMEN (ONG CHIN KIAT)		Assign Date		20/11/2017
2. Vehicle Particulars & Condition				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer		Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
Accident Date 13/11/2017		Inspection Date 20/11/2017		
Survey held at 160 SIN MING DRIVE # 02-20,575722				
Repairer K KIM HIN AUTOMOTIVE PTE LTD				
5a. Remarks				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Nov 2017 Sendback Est	17 Nov 2017 16:22 \$11,997.00	20 Nov 2017 14:54 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	NG BOON KHIM, ID: S1731103D, Tel: +6594773369		
Vehicle Reg. No.:	SJC4188G	Date of Loss:	13/11/2017 16:00 - :59
Claim Type:	OD / 536931	Policy/Cover Note No.:	A80439535QMX (Comprehensive) Coverage: 11/08/2017 - 10/08/2018
		Excess:	\$4500.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Ong Chin Kiat - 6594 2558]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/11/2017]		
Driver/Custodian:	ONG JUN DA (28 / Male), NRIC: S8904072H, Tel: +6597972726		
Adj Asg. Remarks:	Car is in Please revert. Thank you		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

...CLAIM SUBFOLDER...(Pending for Approval)

(12)

CLAIM SUBFOLDER TRACKING

Case	Date	Estimate	Date Received	App Assigned	CA Date	Status
Main	14 Nov 2017		17 Nov 2017 16:22 S\$11,997.00			Pending for Approval

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	NG BOON KHIM , ID: S1731103D, Tel: +6594773369		
Vehicle Reg. No.:	SJC4188G	Date of Loss:	13/11/2017 16:00 - :59
Claim Type:	OD / 536931	Policy/Cover Note No.:	A80439535QMX (Comprehensive) Coverage: 11/08/2017 - 10/08/2018
		Excess:	S\$500.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) PROFILE 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Ong Chin Kiat - 6594 2558]		
Driver/Custodian:	ONG JUN DA (28 / Male), NRIC: S8904072H, Tel: +6597972726		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

View Received Message

This mail is associated with :

SJC4188G (536931)
OD
Nov 13 2017 4:00PM
[NG BOON KHIM]
K Kim Hin Auto Pte Ltd

Reply

Reply All

Mark as Unread

Print Message

Delete Message

Forward

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 22/05/2018 16:44 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$6261.50) - SJC4188G - Claim Handler: Ong Chin Kiat

Approved:6261.50.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 21 May 2018

Preliminary Advice

Vehicle No	: SJC4188G	Accident Date	: 13/11/2017
Make	: AUDI A4	Policy No.	: A80439535QMX
Assignment Date	: 20/11/2017	Excess	: S\$500.00
Date of Inspection	: 20/11/2017	Est. Duration of Repair	: 4.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,046.50 (incl.supplementary \$49.50)
Revised Amount	:S\$	6,261.50 (incl.supplementary \$49.50)
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,261.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	39,000.00
COE / PARF Rebate	:S\$	23,055.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,945.00

Remarks

(X) The vehicle is economical for repair.

() The above survey was conducted on a 'without prejudice' basis.

View Received Message

This mail is associated with :

SJC4188G (536931)

OD

Nov 13 2017 4:00PM

[NG BOON KHIM]

K Kim Hin Auto Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 21/11/2017 11:22 AM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$5486.00) - SJC4188G - Claim Handler: Ong Chin Kiat

Approved:5486.00.

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Ong Chin Kiat

Date: 21 Nov 2017

Preliminary Advice

Vehicle No	: SJC4188G	Accident Date	: 13/11/2017
Make	: AUDI A4	Policy No.	: A80439535QMX
Assignment Date	: 20/11/2017	Excess	: S\$500.00
Date of Inspection	: 20/11/2017	Est. Duration of Repair	: 4.00
Inspection At	: K KIM HIN AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-20, SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,997.00
Revised Amount	:S\$	5,486.00
Check Items (Estimated)	:S\$	2,040.50
Total	:S\$	7,526.50

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	39,000.00
COE / PARF Rebate	:S\$	23,055.00
Salvage Value	:S\$	
Margin for Repair	:S\$	15,945.00

Remarks

(X) The vehicle is economical for repair. Kindly let us have your approval please.

() The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	1103D

Vehicle Details

Vehicle No.	SJC4188G
Vehicle to be Exported	No
Intended De-registration Date	14 Nov 2017
Vehicle Make	AUDI
Vehicle Model	A4 1.8T FSI MU CVT ABS D/AB 2WD 4DR
Primary Colour	White
Manufacturing Year	2009
Engine No.	CDH056667
Chassis No.	WAUZZZ8K2AA014711
Maximum Power Output	118.0 kW (158 bhp)
Open Market Value	\$35,947.00
Original Registration Date	11 Aug 2009
First Registration Date	11 Aug 2009
Transfer Count	2
Actual ARF Paid	\$35,947.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	10 Aug 2019
PARF Rebate Amount	\$19,770.00

Intended COE Rebate Details

COE Expiry Date	10 Aug 2019
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$18,890.00
COE Rebate Amount	\$3,285.00
Total Rebate Amount	\$23,055.00

The information contained herein is correct as at 14 Nov 2017

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	14/11/2017 18:16
Date Of Accident	13/11/2017 16:15
Exact Location Of Accident	JALAN DATO SULAIMAN
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJC4188G
Insured/Policyholder	
Name Of Registered Owner	NG BOON KHIM
NRIC No	S1731103D
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-94773369
Alternative Phone No	OFFICE-94773369

Vehicle Particulars

Manufacturer	AUDI
Model	A4-1.8 TFSI (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A80439535QMX
Cover Note Number	

Driver

Name of Driver	ONG JUN DA
NRIC No	S8904072H
Date Of Birth	15/01/1989
Occupation	INDOOR
Date Of Driving Pass	15/03/2011
Driving Experience	6 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97972726
Fax Number	
Contact Number	
EMail Address	JUNDA15@HOTMAIL.COM

Email Address

DETAILS OF INJURED PERSON 1

Name RIDER

Approximate Age

Injuries Sustain

Injured person in which vehicle? MAA3202


Were seat belts worn?

Was injured conveyed to hospital by ambulance? NO

Address

Postcode

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I am inching out my car to check for approaching vehicle towards me. A Malaysia registered motorbike dash towards my car at high speed and knock onto the front of my car.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:
(Company chop if applicable)

Driver's Signature

(If driver is not the policyholder)

Date & Time: 1.17 pm

14 11 17

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



CO. REG. NO: 199402370D

GST NO: M2-0123250-3

AUTO PTE LTD**金興(龔)汽車私人有限公司**

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkimhin.com.sg

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A80439535QMX	Date of Loss:	13/11/2017
Vehicle Reg. No.:	SJC4188G	Driveable?	
Driver Age/Info:	28 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	NG BOON KHIM	Contact No:	+6594773369
Driver:	ONG JUN DA		

Make/Model:	AUDI A4, 1.8 TFSI (A)	Vehicle Reg. Date:	11/08/2009
Vehicle Colour:	WHITE		
Engine No:	CDH056667	Chassis No:	WAUZZZ8K2AA014711
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	5

Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.
Remarks:	VEHICLE IS IN, KINDLY ARRANGE FOR SURVEY. THANK YOU.
Present Location:	K KIM HIN AUTO PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	9,917.00
Miscellaneous Items	0.00
Labour	2,080.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	11,997.00
- Excess (S\$)	500.00
(S\$)	11,497.00
+ GST 7.00% (S\$)	804.79
Nett Amount (S\$)	12,301.79

This claim is handled by: SHUMAN

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 17 Nov 2017)

Parts: 143 **AUDI A4 1.8 TFSI (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: (Unsubmitted, no print-code for SJC4188G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*FRONT BUMPER	0.00	0.00	*990.00 F	✓
2	2		*FRONT BUMPER SIDE RETAINER (LH/RH) <i>os dte N S one</i>	40.00	0.00	*60.00 F	30
3	2		*FRONT BUMPER SIDE BRACKET (LH/RH) <i>os dte N S one</i>	40.00	0.00	*70.00 F	35
4	1		*FRONT BUMPER LOWER BRACKET <i>dis</i>	0.00	0.00	*50.00 F	✓
5	1		*FRONT BUMPER SPOILER <i>dis</i>	0.00	0.00	*290.00 F	✓
6	2		*FRONT BUMPER FOGLAMP ASSY (LH/RH) <i>os dte N S one</i>	40.00	0.00	*280.00 F	140
7	2		*FRONT BUMPER FOGLAMP COVER (LH/RH) <i>wig</i>	0.00	0.00	*140.00 F	✓
8	1		*FRONT BUMPER TOWING COVER	X 0.00	0.00	*35.00 F	X SV
9	1		*FRONT BUMPER UNDER COVER	? 0.00	0.00	*95.00 F	✓
10	1		*FRONT BUMPER REINFORCEMENT <i>dis</i>	40.00	0.00	*350.00 F	X H
11	2		*FRONT BUMPER REINFORCEMENT BRACKET (LH/RH) ?	X 0.00	0.00	*190.00 F	X H
12	2		*FRONT BUMPER REINFORCEMENT TOP HOLDER (LH/RH) ?	0.00	0.00	*50.00 F	X H
13	1		*FRONT BUMPER SPONGE <i>wig</i>	0.00	0.00	*70.00 F	✓
14	1		*FRONT GRILLE	0.00	0.00	*850.00 F	✓
15	1		*FRONT GRILLE INNER COVER <i>dis</i>	X 0.00	0.00	*65.00 F	X H
16	1		*O/S FRONT FENDER	0.00	0.00	*360.00 F	✓
17	1		*O/S FRONT FENDER TOP BRACKET-FRONT <i>dis</i>	X 0.00	0.00	*40.00 F	X
18	1		*O/S FRONT FENDER TOP BRACKET-REAR <i>dis</i>	X 0.00	0.00	*40.00 F	X
19	1		*O/S FRONT FENDER INNER BRACKET <i>dis</i>	X 0.00	0.00	*50.00 F	X
20	10		*O/S FRONT FENDER TOP BRACKET RIVET <i>dis</i>	0.00	0.00	*30.00 F	✓
21	2		*FRONT SUPPORT PANEL AIR GUIDE (LH/RH) <i>os dte N S one</i>	X 0.00	0.00	*70.00 F	35
22	1		*FRONT SUPPORT PANEL <i>a</i>	? 0.00	0.00	*390.00 F	X H
23	2		*FRONT SUPPORT PANEL LOWER BRACKET (LH/RH)	? 0.00	0.00	*80.00 F	X H
24	2		*RADIATOR LOWER BRACKET	? 0.00	0.00	*70.00 F	X H
25	1		*RADIATOR LOWER BUSH	X 0.00	0.00	*10.00 F	X H
26	2		*HEADLAMP ASSY (LH/RH) <i>os dte N S one</i>	40.00	0.00	*1,600.00 F	800
27	2		*HEADLAMP LOWER BRACKET (LH/RH)	? 0.00	0.00	*130.00 F	X H
28	2		*HEADLAMP LOWER BASE (LH/RH) <i>dis</i>	? 0.00	0.00	*120.00 F	60
29	1		*BONNET	X 0.00	0.00	*600.00 F	X
30	1		*BONNET LOCK	0.00	0.00	*90.00 F	X
31	1		*BONNET SAFETY LOCK	X 0.00	0.00	*80.00 F	X
32	1		*BONNET PULL LOCK CABLE	X 0.00	0.00	*40.00 F	X
33	1		*O/S FRONT FENDER INNER SHIELD	X 0.00	0.00	*115.00 F	X
34	1		*TURBO INTERCOOLER <i>production</i>	? 0.00	0.00	*190.00 F	X H
35	1		*AIRCON CONDENSER	? 0.00	0.00	*430.00 F	X H
36	1		*O/S HORN	? 0.00	0.00	*110.00 F	X H
37	1		*RADIATOR	X 0.00	0.00	*360.00 F	✓
38	1		*FRONT NUMBER PLATE	X 0	0.00	*40.00 FS	X
39	1		*O/S FRONT BUMPER FOGLAMP WIREHARNESS (LOCAL REPAIR)	X 0	0.00	*380.00 FS	X
40	1		*RADIATOR COOLANT	40	0.00	*48.00 FS	X

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	9,058.00
+ Margin on L,N Items 10.00% (\$\$)	859.00
Total Parts (\$\$)	9,917.00

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
-----	-----	----------	-------------	-------	-------	--------

Report was unsubmitted during this print-out.
Generated using **Merimen e-Claims IEAS**

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	✓ 502 750.00
2	TO FOCUS HEADLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	✓ 80 50.00
3	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	✓ 600 900.00
4	TO REWIRING AND ONLINE PROGRAMMING.	New	✓ 380.00
Gross Labour Cost (\$\$)			2,080.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

✓ for Antenna
PPR Repair
Before Paint Plate
20/11/2017
4w/1day
LHK Antenna

EXCESS 0.00

23/11/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants
Repairer of the
damaged part
is subject to
survey is on a
"Without Prejudice"
basis is a
confirmation(s) is
must be
approval from Insurance Company

CO. REG. NO: 199402370D

GST NO: M2-0123250-3

K. Kim Hin AUTO PTE LTD**金興(興)汽車私人有限公司**

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkimhin.com.sg

(SUPPLEMENTARY)INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	A80439535QMX	Date of Loss:	13/11/2017
Vehicle Reg. No.:	SJC4188G	Driveable?	
Driver Age/Info:	28 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	NG BOON KHIM	Contact No:	+6594773369
Driver:	ONG JUN DA		

Make/Model:	AUDI A4, 1.8 TFSI (A)	Vehicle Reg. Date:	11/08/2009
Vehicle Colour:	WHITE		
Engine No:	CDH056667	Chassis No:	WAUZZZ8K2AA014711
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	5

Description of Accident/Loss	PLEASE REFER TO SKETCH PLAN.
------------------------------	------------------------------

Remarks:	SUPPLEMENTARY
----------	---------------

Present Location:	K KIM HIN AUTO PTE LTD (HQ)
-------------------	-----------------------------

COST OF CLAIMS	Amount
Parts	49.50
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	49.50
+ GST 7.00% (\$)	3.47
Nett Amount (\$)	52.97
+ Previous Estimates (\$)	12,301.79

5/21/2018

Repairer Estimates Suppl. #1

Claim Total (\$)

12,354.76

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference**

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 21 May 2018)

Parts: 143 **AUDI A4 1.8 TFSI (A) (Catalogue:Merimen Singapore 1.0)**

Labour: Repairer's **(Price-denominated Standard List)**

Print Code: K Kim Hin Auto Pte Ltd/SJC4188G/21/05/2018 12:14

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT SUPPORT PANEL TOP GARNISH <i>Def</i>	0.00	0.00	*45.00 F
						Sub Total (S\$)
						45.00
						+ Margin on L,N Items 10.00% (S\$)
						4.50
						Total Parts (S\$)
						49.50

F=Franchise part.

K Kim Hin Auto Pte Ltd/SJC4188G/21/05/2018 12:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

K Kim Hin Auto Pte Ltd/SJC4188G/21/05/2018 12:14. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 22 May 2018 5:45 PM
To: 'survey@kkimhin.com.sg'; Ma C.F (LKKAUTO)
Cc: SUR
Subject: RE: SJC4188G OD-MSIG FINALISATION

Dear Meng Huat,

Confirmed P/P \$6,261.50 before excess \$500 @ 4 working days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, 21 May 2018 11:28 AM
To: 'survey@kkimhin.com.sg' <survey@kkimhin.com.sg>; Ma C.F (LKKAUTO) <MaCF@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: SJC4188G OD-MSIG FINALISATION

Dear Meng Huat,

Please submit supplementary in merimen.

Front support panel top garnish-\$45/-

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: survey@kkimhin.com.sg [<mailto:survey@kkimhin.com.sg>]
Sent: Thursday, 17 May 2018 4:47 PM
To: Ma C.F (LKKAUTO) <MaCF@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: SJC4188G OD-MSIG FINALISATION

Hi Mr Ma,

Enclosed you attention.

P/P=\$6,261.50

Please confirm.

Thank you.

Regard

Meng Huat

K.Kim Hin Auto

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Nov 2017)
Parts:	143	AUDI A4 1.8 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJC4188G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BUMPER	0.00	0.00	*990.00F ✓
2	2		*FRONT BUMPER SIDE RETAINER (LH/RH) <i>as dr NGW</i>	0.00	0.00	*68.00F 30 ✓
3	2		*FRONT BUMPER SIDE BRACKET (LH/RH) <i>as dr NGW</i>	0.00	0.00	*70.00F ✓
4	1		*FRONT BUMPER LOWER BRACKET <i>as</i>	0.00	0.00	*50.00F ✓
5	1		*FRONT BUMPER SPOILER <i>as</i>	0.00	0.00	*290.00F ✓
6	2		*FRONT BUMPER FOGLAMP ASSY (LH/RH) <i>as dr NGW</i>	0.00	0.00	*280.00F 40 ✓
7	2		*FRONT BUMPER FOGLAMP COVER (LH/RH) <i>as</i>	0.00	0.00	*140.00F ✓
8	1		*FRONT BUMPER TOWING COVER	0.00	0.00	*35.00F ✓
9	1		*FRONT BUMPER UNDER COVER ✓	0.00	0.00	*95.00F ✓
10	1		*FRONT BUMPER REINFORCEMENT <i>as</i>	0.00	0.00	*350.00F ✓
11	2		*FRONT BUMPER REINFORCEMENT BRACKET (LH/RH) ?	0.00	0.00	*190.00F ✓
12	2		*FRONT BUMPER REINFORCEMENT TOP HOLDER (LH/RH) ?	0.00	0.00	*50.00F ✓
13	1		*FRONT BUMPER SPONGE <i>as</i>	0.00	0.00	*70.00F ✓
14	1		*FRONT GRILLE	0.00	0.00	*850.00F ✓
15	1		*FRONT GRILLE INNER COVER <i>as</i>	0.00	0.00	*65.00F ✓
16	1		*O/S FRONT FENDER <i>as</i>	0.00	0.00	*360.00F ✓
17	1		*O/S FRONT FENDER TOP BRACKET-FRONT <i>as</i>	0.00	0.00	*40.00F ✓
18	1		*O/S FRONT FENDER TOP BRACKET-REAR <i>as</i>	0.00	0.00	*48.00F ✓
19	1		*O/S FRONT FENDER INNER BRACKET <i>as</i>	0.00	0.00	*50.00F ✓
20	10		*O/S FRONT FENDER TOP BRACKET RIVET	0.00	0.00	*30.00F ✓
21	2		*FRONT SUPPORT PANEL AIR GUIDE (LH/RH) <i>as</i>	0.00	0.00	*70.00F 35 ✓
22	1		*FRONT SUPPORT PANEL <i>as</i>	0.00	0.00	*300.00F ✓
23	2		*FRONT SUPPORT PANEL LOWER BRACKET (LH/RH)	0.00	0.00	*80.00F ✓
24	2		*RADIATOR LOWER BRACKET	0.00	0.00	*70.00F ✓
25	1		*RADIATOR LOWER BUSH	0.00	0.00	*10.00F ✓
26	2		*HEADLAMP ASSY (LH/RH) <i>as</i>	0.00	0.00	*1,600.00F 200 ✓
27	2		*HEADLAMP LOWER BRACKET (LH/RH) ✓	0.00	0.00	*130.00F ✓
28	2		*HEADLAMP LOWER BASE (LH/RH) <i>as</i>	0.00	0.00	*120.00F 60 ✓
29	1		*BONNET <i>as</i>	0.00	0.00	*600.00F ✓
30	1		*BONNET LOCK <i>as</i>	0.00	0.00	*90.00F ✓
31	1		*BONNET SAFETY LOCK <i>as</i>	0.00	0.00	*80.00F ✓
32	1		*BONNET PULL LOCK CABLE <i>as</i>	0.00	0.00	*40.00F ✓
33	1		*O/S FRONT FENDER INNER SHIELD <i>as</i>	0.00	0.00	*115.00F ✓
34	1		*TURBO INTERCOOLER ✓	0.00	0.00	*190.00F ✓
35	1		*AIRCON CONDENSER	0.00	0.00	*430.00F ✓
36	1		*O/S HORN	0.00	0.00	*110.00F ✓
37	1		*RADIATOR ✓ <i>as</i>	0.00	0.00	*360.00F ✓
38	1		*FRONT NUMBER PLATE <i>as</i>	0.00	0.00	*40.00F ✓
39	1		*O/S FRONT BUMPER FOGLAMP WIREHARNES (LOCAL REPAIR) <i>as</i>	0.00	0.00	*380.00F ✓
40	1		*RADIATOR COOLANT	0.00	0.00	*48.00F ✓

F=Franchise part. S=Spclt.

Sub Total (\$)	9,058.00
+ Margin on L,N Items 10.00% (\$)	859.00
Total Parts (\$)	9,917.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	500 250.00
2	TO FOCUS HEADLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	80 50.00
3	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	600 900.00
4	TO REWIRING AND ONLINE PROGRAMMING.	New	380.00
Gross Labour Cost (S\$)			2,080.00

Report was unsubmitted during this print-out.
Generated using Merlimen e-Claims IEAS

< END OF ESTIMATES >

Not Antikam
PPR Repw
Before Fina Pldr
20/11/2017
4w/days

EXCESS 300

Sup

lp Fnt Support Panel Top Graciel

Let Antikam

\$ 45.00 / day

\$ 4620.00 - Put

\$ 45.00 - Sup

\$ 4665.00

+102

\$ 5,131.50

\$ 1130.00 - Labor

\$ 6,261.50



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 8936



Dept Direct: 6305 9610



Dept Direct: 6417 9794



TOYOTA
Dept Direct: 6305 9611

LEAPUS
Dept Direct: 6417 9792

DAIHATSU
Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTO CITY

SINGAPORE 575722
TEL: 64527018 MENG FAX: 64583895
ALIN: MENG HUAT

WAUZZZ8K2AA014711

TAX INVOICE : AR201711-12338
DATE : 21/11/2017
CUSTOMER ID : KKJ001
VEH REG. NO. : SJC4188G
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR : SGD

SQ	STOCKID	DESCRIPTION	Std Loc	QTY	U/PRICE	AMOUNT
1.	8K0807284	FRT BUMPER S/RETAINER RH (21)	CC	1	30.00	30.00
			CC5-F-06AA			
2.	8T0941700B	FOG LAMP RH (03)	CC	1	140.00	140.00
			CC5-H-04AB			
3.	8K0807681C 01C	FOG LAMP COVER LH (01)	CC	1	70.00	70.00
			CC5-C-07AB			
4.	8K0807682C 01C	FOG LAMP COVER RH (01)	CC	1	70.00	70.00
			CC5-C-06AB			
5.	8K0807233	FRT BUMPER UNDER COVER	CC	1	95.00	95.00
			CC5-H-07A			
6.	8K0807550	FRT BUMPER SPONGE (52)	CC	1	70.00	70.00
			CC5-H-07D			
7.	8K0853651D 1RR	RADIATOR GRILLE (052)	CC	1	850.00	850.00
			CC5-B-09AC			

CONTINUE NEXT PAGE

[P] 21/11/2017 4:13:43PM

[E] 21/11/2017 3:46:12PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per-month will be imposed on OverDue Account(s).

ORIGINAL



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9781 / 6745 9538



Dept Direct: 6305 9810



Dept Direct: 6417 9784



Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

Arrange By

Driver

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTO CITY
SINGAPORE 575722
TEL: 64527018 MENG FAX: 64583895
ATTN: MENG HUAT
WAUZZZ8K2AA014711

TAX INVOICE : AR201711-12338
DATE : 21/11/2017
CUSTOMER ID : KK1001
VEH REG. NO. : SJC4188G
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8. 8K0821106A	FRT FENDER RH (02)	CC CC5-B-07C	1	360.00	360.00
9. 8K0121284G	AIR GUIDE RH (51)	CC CC5-E-07BB	1	35.00	35.00
10. 8K0941454	HEADLAMP INNER BRACKET RH (01)	CC CC5-H-05A	1	60.00	60.00
11. 8K0145805G/P	TURBO INTERCOOLER (03)	CC CC5-C-02B	1	190.00	190.00
12. 8K0121251T/AJ	RADIATOR (02)	CC CC5-C-01B	1	360.00	360.00

SUB-TOTAL: 2,330.00
ADD GST 7.00% 163.10

E. & OE

TOTAL AMOUNT SGD: 2,493.10

[P] 21/11/2017 4:13:43PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 21/11/2017 3:46:12PM

JAE Auto Pte. Ltd.

Sales Executive: ANN

This is computer generated document.

No signature is required.



ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9909

Arrange By

Driver

MLC



Dept Direct: 6306 8010



TOYOTA
DEPT DIRECT: 6417 9792



Dept Direct: 6417 9794



Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY

SINGAPORE 575722
TEL: 64527018 MENG FAX: 64583895
ATTN: MENG HUAT

WAUZZZ8K2AA014711

TAX INVOICE : AR201711-12346
DATE : 21/11/2017
CUSTOMER ID : KK1001
VEH REG. NO. : SJC4188G
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1. 8K0807899	FRONT BUMPER LOWER BRACKET	KH	1	50.00	50.00
		KH2-I-05B			
2. 8K0805607C	HEADLAMP LOWER BRACKET LH (02)	KH	1	65.00	65.00
		KH2-I-06G			
3. 8K0805608C	HEADLAMP LOWER BRACKET RH (02)	KH	1	65.00	65.00
		KH2-II-04D			

SUB-TOTAL: 180.00
ADD GST 7.00% 12.60

E & OE TOTAL AMOUNT SGD: 192.60

[P] 21/11/2017 4:13:22PM

[E] 21/11/2017 3:49:40PM

Goods Sold are not refundable for Cash

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte Ltd.

Sales Executive: ANN

This is computer generated document.

No signature is required.



* A R 2 0 1 7 1 1 1 2 3 4 6 *

ORIGINAL

Good Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司 JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9626



Dept Direct: 6305 9810

Dept Direct: 6305 9811

Dept Direct: 6417 9782



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY
SINGAPORE 575722
TEL: 64527018 MENG FAX: 64583895
ATTN: MENG HUAT
WAUZZZ8K2AA014711

TAX INVOICE : AR201711-12805
DATE : 22/11/2017
CUSTOMER ID : KK1001
VEH REG. NO. : SJC4188G
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	Stk Loo	QTY	U/PRICE	AMOUNT
SK0807081	SUPPORT PANEL TOP GARNISH CCS-H-08A		1	45.00	45.00

SUB-TOTAL: 45.00
ADD GST 7.00 % 3.15

E & OE TOTAL AMOUNT SGD: 48.15

[P] 22/11/2017 11:41:35AM

[E] 22/11/2017 11:39:02AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte Ltd.

Sales Executive: ANN

This is computer generated document.

No signature is required.



* AR 2017 11 - 12805 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL



日美汽車和人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN BLADE
Dept Direct: 6417 9791 / 6745 9898



Dept Direct: 6305 9610



Dept Direct: 6305 9611



Dept Direct: 6417 9792



Dept Direct: 6417 9794



Dept Direct: 6417 9795



Dept Direct: 6417 9796



Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

K KIM HIN AUTO PTE LTD
160 SIN MING DRIVE #02-18/19/20/21
SIN MING AUTOCITY

SINGAPORE 575722
TEL : 64527018 MENG FAX : 64583895
ATTN : MENG HUAT
WAUZZZ8K2AA014711

TAX INVOICE : AR201711-12309
DATE : 21/11/2017
CUSTOMER ID : KKI001
VEH REG. NO. : SJC4188G
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 8K0807105D GRU	FRONT BUMPER (09)	U1 2J4	1	990.00	990.00
2. 8K0807110 IRR	FRT BUMPER SPOILER (061)	U1	1	290.00	290.00
3. N 0161857	FENDER RIVET	SUPPLIER U1	10	3.00	30.00
4. 8K0941030D/AK	HEADLAMP RH	SUPPLIER U1	1	800.00	800.00

SUB-TOTAL : 2,110.00
ADD GST 7.00 % 147.70

E. & O.E TOTAL AMOUNT SGD: 2,257.70

[P] 21/11/2017 5:14:39PM

[E] 21/11/2017 3:28:03PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : ANN



* A R 2 0 1 7 1 1 - 1 2 3 0 9 *

Goods Received in Good Order

This is computer generated document.
No signature is required.

Signature / Co Stamp / Date

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	14 Nov 2017 Sendback Est	17 Nov 2017 16:22 \$11,997.00	20 Nov 2017 14:54 Edit Adj Rpt	\$6,261.50 Edit Estimates	\$6,261.50 View Rpt		Pending for Survey Report Cancel Case
Supp #1	21 May 2018 12:13	21 May 2018 12:14 \$49.50	21 May 2018 12:14			(Combined)	Combined with Main Uncombine Suppl.

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS

Insured:	NG BOON KHIM, ID: S1731103D, Tel: +6594773369		
Vehicle Reg. No.:	SJC4188G	Date of Loss:	13/11/2017 16:00 - :59 [99 Months and 2 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / 536931	Policy/Cover Note No.:	A80439535QMX (Comprehensive) Coverage: 11/08/2017 - 10/08/2018
		Excess:	S\$500.00
Repairer:	K Kim Hin Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-20, Sin Ming AutoCity, 575722 Sin Ming - Tel: 64527018		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Ong Chin Kiat - 6594 2558]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 20/12/2017]		
Driver/Custodian:	ONG JUN DA (28 / Male), NRIC: S8904072H, Tel: +6597972726		
Adj Asg. Remarks:	Car is in Please revert. Thank you		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

- MSIG_SG (22/05/2018): Alert - Adj Mandate Approved (\$6261.50) - SJC4188G - Claim Handler: Ong Chin Ki...
- MSIG_SG (21/11/2017): Alert - Adj Mandate Approved (\$5486.00) - SJC4188G - Claim Handler: Ong Chin Ki...

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SJC4188G (536931)
OD
Nov 13 2017 4:00PM
[NG BOON KHIM]
K Kim Hin Auto Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video				
			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	14/11/17 19:20	Video - Accident [Linked Accident Report Documents]	Load MP4	
Assessment Reports				
			1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	14/11/17 19:23	Accident Statement	Load HTM	
2	17/11/17 16:22	Repairer Estimates	Load HTM	
3	21/05/18 12:14	Repairer Estimates Suppl. #1	Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/11/17 09:55	Adjuster Immediate Advice	Load HTM	
2	21/05/18 12:28	Adjuster Immediate Advice	Load HTM	
Photos/Images				
			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/11/17 09:49	General View	Load JPG	☒
2	21/11/17 09:49	General View	Load JPG	☒
3	21/11/17 09:49	General View	Load JPG	☒
4	21/11/17 09:49	General View	Load JPG	☒
5	21/11/17 09:49	General View	Load JPG	☒
6	21/11/17 09:49	General View	Load JPG	☒
7	21/11/17 09:49	General View	Load JPG	☒
8	21/11/17 09:49	General View	Load JPG	☒
9	21/11/17 09:49	General View	Load JPG	☒
10	21/11/17 09:49	General View	Load JPG	☒
11	21/11/17 09:49	General View	Load JPG	☒
12	21/11/17 09:49	General View	Load JPG	☒
13	21/11/17 09:49	General View	Load JPG	☒
14	21/11/17 09:49	General View	Load JPG	☒
15	21/11/17 09:49	General View	Load JPG	☒
16	21/11/17 09:49	General View	Load JPG	☒
17	21/11/17 09:49	General View	Load JPG	☒
18	21/11/17 09:49	General View	Load JPG	☒
19	21/11/17 09:49	General View	Load JPG	☒
20	21/11/17 09:49	General View	Load JPG	☒
21	21/11/17 09:49	General View	Load JPG	☒
22	21/05/18 11:17	Reinspection Photo	Load JPG	☒
23	21/05/18 11:17	Reinspection Photo	Load JPG	☒
24	21/05/18 11:17	Reinspection Photo	Load JPG	☒
25	21/05/18 11:17	Reinspection Photo	Load JPG	☒
26	21/05/18 11:17	Reinspection Photo	Load JPG	☒
27	21/05/18 11:17	Reinspection Photo	Load JPG	☒

Video			1 per page	
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
28	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
29	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
30	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
31	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
32	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
33	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
34	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
35	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
36	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
37	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
38	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
39	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
40	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
41	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
42	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
43	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
44	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
45	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
46	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
47	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
48	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
49	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
50	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
51	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
52	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
53	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
54	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
55	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
56	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
57	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
58	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
59	21/05/18 11:17	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	16/11/17 13:15	PARF COE	 Load PDF	
2	08/12/17 15:31	OI & TP malaysia police report & PIR - OI charged for Inconsiderate driving & Maphlindo bill	 Load PDF	
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)	Thumbnail	Print
1	17/11/17 16:12	Certificate of Insurance	 Load PDF	
2	17/11/17 16:12	Log card (if available)	 Load PDF	
3	17/11/17 16:12	Driver's NRIC	 Load PDF	
4	17/11/17 16:12	Insured's NRIC	 Load PDF	
5	17/11/17 16:12	TRANSFER FEE	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	21/11/17 10:42	SURVEYOR MARKING	 Load PDF	
2	21/05/18 11:38	1ST MARKING	 Load PDF	
3	21/05/18 12:22	SUPPLEMENTARY	 Load PDF	
4	28/05/18 12:09	Parts Invoice	 Load PDF	

Linked Accident Report Documents

View

Video				1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	14/11/17 19:20	Video - Accident	1	Load MP4	

Assessment Reports				1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	14/11/17 19:23	Accident Statement	1	Load HTM	

Photos/Images				3 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	14/11/17 19:20	Accident Photo	1	Load JPG	☒
2	14/11/17 19:20	Accident Photo	1	Load JPG	☒
3	14/11/17 19:20	Accident Photo	1	Load JPG	☒
4	14/11/17 19:20	Accident Photo	1	Load JPG	☒
5	14/11/17 19:20	Accident Photo	1	Load JPG	☒
6	14/11/17 19:20	Accident Photo	1	Load JPG	☒
7	14/11/17 19:21	Accident Photo	1	Load JPG	☒
8	14/11/17 19:21	Accident Photo	1	Load JPG	☒
9	14/11/17 19:21	Accident Photo	1	Load JPG	☒

Documentation				1 per page	☒
No	Finalized On	K Kim Hin Auto Pte Ltd (HQ)		Thumbnail	Print
1	14/11/17 19:20	Sketch Plan	1	Load TIF	
2	14/11/17 19:20	Sketch Plan #2	1	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Repairer ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG17022127/M1VBE2

Date: 28/05/2018

REFERENCE

Insured/Claimant:	NG BOON KHIM	Policy No:	A80439535QMX	
Date of Loss:	13/11/2017	Nature of Claim:	OD	Claim No: 536931

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC4188G		Engine No:	CDH056667
Make & Model:	AUDI A4, 1.8 TFSI (A)		Chassis No:	WAUZZZ8K2AA014711
Reg. Date:	11/08/2009 (Man. Year: 2009)		Odometer:	243967 km
Colour:	White			
Engine Capacity:	1798 cc			
Market Value/New Car Price:	S\$39,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35 R19	Rear Tyre Size:	245/35 R19
Front Left Side:	Nexen 7 mm	Rear Left Side:	Nexen 7 mm
Front Right Side:	Nexen 7 mm	Rear Right Side:	Nexen 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,966.50	5,131.50	4,835.00	48.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,080.00	1,130.00	950.00	45.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,046.50	6,261.50	5,785.00	48.02
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	11,546.50	5,761.50	5,785.00	50.10
+ GST 7.00/7.00% (S\$)	808.26	403.31	404.95	50.10
Nett Amount (S\$)	12,354.76	6,164.81	6,189.95	50.10

INSPECTION

Date of Assignment:	20/11/2017 Present Location:	K Kim Hin Auto Pte Ltd (HQ)
Date Inspected:	20/11/2017 Inspected At:	160 Sin Ming Drive #02-20, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: MA CHIN FOOK

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 May 2018)
Parts: 143 AUDI A4 1.8 TFSI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJC4188G)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Deformed	990.00 F	*990.00 F
2	1		*FRONT BUMPER SIDE RETAINER (LH/RH) (WCP)	O/S Distorted/N/S Serviceable	60.00 F	*30.00 F
3	1		*FRONT BUMPER SIDE BRACKET (LH/RH) (WCP)	Serviceable	70.00 F	*- F
4	1		*FRONT BUMPER LOWER BRACKET (WCP)	Distorted	50.00 F	*50.00 F
5	1		*FRONT BUMPER SPOILER (WCP)	Distorted	290.00 F	*290.00 F
6	1		*FRONT BUMPER FOGLAMP ASSY (LH/RH) (WCP)	O/S Missing/N/S Serviceable	280.00 F	*140.00 F
7	2		*FRONT BUMPER FOGLAMP COVER (LH/RH) (WCP)	Missing	140.00 F	*140.00 F
8	1		*FRONT BUMPER TOWING COVER (WCP)	Serviceable	35.00 F	*- F
9	1		*FRONT BUMPER UNDER COVER (WCP)	Damaged	95.00 F	*95.00 F
10	1		*FRONT BUMPER REINFORCEMENT (WCP)	Not Necessary	350.00 F	*- F
11	2		*FRONT BUMPER REINFORCEMENT BRACKET (LH/RH) (WCP)	Not Necessary	190.00 F	*- F
12	2		*FRONT BUMPER REINFORCEMENT TOP HOLDER (LH/RH) (WCP)	Not Necessary	50.00 F	*- F
13	1		*FRONT BUMPER SPONGE (WCP)	Missing / Torn	70.00 F	*70.00 F
14	1		*FRONT GRILLE (WCP)	Distorted / Cracked	850.00 F	*850.00 F
15	1		*FRONT GRILLE INNER COVER (WCP)	No such part	65.00 F	*- F
16	1		*O/S FRONT FENDER (WCP)	Dented	360.00 F	*360.00 F
17	1		*O/S FRONT FENDER TOP BRACKET-FRONT (WCP)	Serviceable	40.00 F	*- F
18	1		*O/S FRONT FENDER TOP BRACKET-REAR (WCP)	Serviceable	40.00 F	*- F
19	1		*O/S FRONT FENDER INNER BRACKET (WCP)	Repair	50.00 F	*- F
20	10		*O/S FRONT FENDER TOP BRACKET RIVET (WCP)	Necessary	30.00 F	*30.00 F
21	1		*FRONT SUPPORT PANEL AIR GUIDE (LH/RH) (WCP)	N/S Serviceable/O/S Distorted	70.00 F	*35.00 F
22	1			Not Necessary	390.00 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
			*FRONT SUPPORT PANEL (WCP)			
23	2		*FRONT SUPPORT PANEL LOWER BRACKET (LH/RH) (WCP)	Not Necessary	80.00 F	*- F
24	2		*RADIATOR LOWER BRACKET (WCP)	Not Necessary	70.00 F	*- F
25	1		*RADIATOR LOWER BUSH (WCP)	Not Necessary	10.00 F	*- F
26	1		*HEADLAMP ASSY (LH/RH) (WCP)	O/S Cracked / N/S Serviceable	1,600.00 F	*800.00 F
27	2		*HEADLAMP LOWER BRACKET (LH/RH) (WCP)	Necessary	130.00 F	*130.00 F
28	1		*HEADLAMP LOWER BASE (LH/RH) (WCP)	O/S Cracked	120.00 F	*60.00 F
29	1		*BONNET (WCP)	Repair	600.00 F	*- F
30	1		*BONNET LOCK (WCP)	Serviceable	90.00 F	*- F
31	1		*BONNET SAFETY LOCK (WCP)	Serviceable	80.00 F	*- F
32	1		*BONNET PULL LOCK CABLE (WCP)	Serviceable	40.00 F	*- F
33	1		*O/S FRONT FENDER INNER SHIELD (WCP)	Serviceable	115.00 F	*- F
34	1		*TURBO INTERCOOLER (WCP)	Punctured	190.00 F	*190.00 F
35	1		*AIRCON CONDENSER (WCP)	Not Necessary	430.00 F	*- F
36	1		*O/S HORN (WCP)	Not Necessary	110.00 F	*- F
37	1		*RADIATOR (WCP)	Bent	360.00 F	*360.00 F
38	1		*FRONT NUMBER PLATE	Serviceable	40.00 FS	*- FS
39	1		*O/S FRONT BUMPER FOGLAMP WIREHARNES (LOCAL REPAIR)	Serviceable	380.00 FS	*- FS
40	1		*RADIATOR COOLANT	Serviceable	48.00 FS	*- FS
Supplementary #1						
41	1		*FRONT SUPPORT PANEL TOP GARNISH (WCP)	Deformed	45.00 F	*45.00 F

F=Franchise part. S=SpcNett.

Sub Total (\$\$)	9,103.00	4,665.00
+ Margin on L,N Items 10.00/10.00% (\$\$)	863.50	466.50
Total Parts (\$\$)	9,966.50	5,131.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIT AND TO RENEW AFFECTED PARTS.	New	750.00	500.00
2	TO FOCUS HEADLAMPS. TO CHECK WIRING AND LIGHTING OPERATION.	New	50.00	30.00
3	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.	New	900.00	600.00
4	TO REWIRING AND ONLINE PROGRAMMING.	New	380.00	0.00
Gross Labour Cost (S\$)			2,080.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >