

INS. CASE OWNER:

Natalie

CC 4/III170

2137, Kwa352

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

24/11/17

Date / Time:

20/11/17

Registered in Merimen:

21/11/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SH 9564M

Name of Insured:

CPR

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

11-11-17

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

ABDUL HANIF BIN ABDUL RAHMAN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

mcom001

H-140

LKG - checkpoint

SLJ 8531L



INSRS:

WSP:

Tel:

Liability:

RMKS:

PH Auto



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time	STAGE	DATE / PIC
28/11/17	Non-Reporting ltr (1st):	
	Non-Reporting ltr (2nd):	
	Non-Reporting ltr (Final):	
	Notification ltr (if non-pickup):	
	Call OI:	
	After call ltr to OI:	
28/11/17	Documentation Check List:	Handler Typist
	Notification ltr (if non-pickup)	
	After call ltr to OI:	
	Authorisation To Act:	
	Release Voucher:	
	Final Repair Bill:	
	Car Rental Invoice:	
	Towing Invoice:	
	LTA / GIA:	
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD:	
	Payment Breakdown Form:	
	Post-Repair Photos:	
	Others:	
PRELIMINARY ADVICE	Date/Time:	Sent By:
FINALIZATION	Date/Time:	Confirm with:
Repair Cost:	SS	(days) Reduction: %
FINAL SETTLEMENT	Date/Time:	Confirm with:
Final Liability:	%	(Agreed / Assessed) BOLA S/N No.:
Repair Cost:	SS	
Loss of Rental (LOR):	SS	(days)
Loss of Use (LOU):	SS	(\$ x days)
Loss of Income (LOI):	SS	(\$ x days)
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>		[Tick only one]
GIA/LTA Search	SS	
Medical:	SS	
Disbursement:	SS	(e.g. Tow/ Independent)
Legal Cost	SS	
Total:	SS	Global Sum SS:
FINAL PAYMENT	Date/Time:	Confirm with:
Payee 1:	SS	Name 1:
Payee 2: (Strike if N.A.)	SS	Name 2:
Payee 3: (Strike if N.A.)	SS	Name 3:

RECEIVED 30 NOV 2017

Reject Case
By (Stamp): VivianCOPY SENT
31/11/17


- 1) Claim status: Normal/Reject/Private Settle
- 2) Report Format: reject
- 3) Survey fee: A 350.00

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC4/III17022137/Kwa3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 21-11-2017	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SH 9564M	Veh. Inspected	SLJ 8531L
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/11/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	11/11/2017	Inspection Date	24/11/2017
Survey held at	BII AUTO SERVICES PTE LTD BLK 1 SIN MING INDUSTRIAL ESTATE SECTOR C #01-115 SINGAPORE 575636		
5a. Remarks			
INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street
#04-05 IOB Building
Singapore 049711
ATTN: MOTOR CLAIM DEPARTMENT
Tel : 63476100 Fax : 62244174

Dear Sir/Madam,

Accident Repair On : SLJ8531L
Model : CHERVOLET
Policy No : VPA/P1885097
Chassis No : KL1YA7589HK609215
Year Of Make : 2016
Date / Time Of Accident : 11/11/2017 at 2310Hrs
Location : BKE heading towards Woodlands Checkpoint

Date: 20/11/2017

Page : 1 of 2

Not Authored
Recovery After Party

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount
S/N			SS		SS
1	Front Fender RH	1	722.00		722.00 X
2	Front Fender Shield RH	1	138.00		138.00 ✓
3	Front Fender Clips	10	4.50		45.00 ✓
4	Front Fender Wheel Arch RH	1	120.00		120.00 ✓
5	Front Door RH	1	1,360.00		1,360.00 X
6	Front Door Upper Hinge RH	1	50.00		50.00 X
7	Front Door Lower Hinge RH	1	50.00		50.00 X
8	Front Wheel Rim RH	1	665.00		665.00 X
Sub-Total:					3,150.00
Less : 10% discount					630.00
Total Parts :					2,520.00 2835

Special Nett Items

- | | | | |
|---|-------------------|-------|---------|
| 1 | Anti-rust coating | 80.00 | 80.00 X |
|---|-------------------|-------|---------|

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total Nett Items: 80.00

Acknowledged by Repairer

Signature:

Date:

Labour Charges For Front RH Portion

- | | | | |
|---|--|--------|------|
| 1 | Provide skill labour to remove all damaged & necessary parts, to panel beat, cut & weld if necessary, to realign all panels and reinstall all replacement parts. | 500.00 | 1500 |
| 2 | Provide skill labour & material to putty all replaced & repaired parts, to respray using 2K paint with oven spray booth facilities | 750.00 | 2000 |
| 3 | Provide skill labour to disconnect & check electrical wiring, harness, wyre sockets, etc. test & rectify for proper functioning | 80.00 | X |
| 4 | Provide skill labour to check and re-adjust front wheel alignment. | 80.00 | 600 |

5

Provide skill labour to dismantle and transfer door fitting and facilitate repair

n ~ 100.00 X

Total Labour:	1,510.00
Total Parts:	2,520.00
Total Nett Items:	80.00
	4,110.00
GST 7%	287.70
Grand Total:	4,397.70

4425

Estimate Repair Duration (include 1 day for re-survey & 1 day for parts ordering)7 days

2 days

Accident Vehicle Of : SLJ8531L

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

Survey attended by:

Name :

Kenneth

Company :

CKK

Date :

24/11/17

Time :

2:05pm

Contact No :

96810663

Email :

Estimator : Anthony

Nivitha (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 20 November, 2017 3:22 PM
To: 'sur@lkkauto.com'
Cc: BHAS - Jacelyn Loh; BHAS - Janice Koh; BHAS - Kelvin Lim; BHAS - Bernard Kee; BHAS - Moo Wen Zheng; BHAS - Anthony Lau; Natalie Lee; Catherine Chong (LKK Auto)
Subject: FW: PRE REPAIR INSPECTION OUR VEHICLE - SLJ8531L/ YOUR VEHICLE - SH9564M
Attachments: SAS2310576.pdf; PRIJPG

3.52 pm @ 20/11/17
Vehicle Not In
Person @ jacelyn.

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SLJ8531L and let us have your report urgently.

This claim will be handled by Ms Natalie.

*Kindly upload this survey request email to merimen.

Thank You.

Best Regards,

ANDREW LIM

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 227

S&P 'A-' (stable) rated Company

From: BHAS - Jacelyn Loh [mailto:jacelyn.loh@bhauto.com.sg]

Sent: Monday, 20 November, 2017 2:49 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: BHAS - Janice Koh <janice.koh@bhauto.com.sg>; BHAS - Kelvin Lim <kelvin.lim@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>; BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>

Subject: RE: PRE REPAIR INSPECTION OUR VEHICLE - SLJ8531L/ YOUR VEHICLE - SH9564M

To: the officer in charge

Dear sir, mdm,

We choose below surveyor: **LKK Auto**

Ps- vehicle currently **NOT IN** our workshop

Thank You & Best Regards,

Jacelyn Loh

BH AUTO SERVICES PTE LTD

Address: Blk 1, Sector C, Sin Ming Industrial Estate
#01-111/113/115/117 Singaopre:575636
(T) +65-6559 2098 /8944 (F) +65-6515 3144 / +65-6269 2404
Email: jacelyn.loh@bhauto.com.sg
Website: <http://www.bhauto.com.sg>

From: Motor Claim - III [<mailto:motorclaim@iii.com.sg>]

Sent: Monday, 20 November 2017 11:16 AM

To: BHAS - Anthony Lau <anthony.lau@bhauto.com.sg>

Cc: BHAS - Janice Koh <janice.koh@bhauto.com.sg>; BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>; BHAS - Kelvin Lim <kelvin.lim@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>

Subject: RE: PRE REPAIR INSPECTION OUR VEHICLE - SLJ8531L/ YOUR VEHICLE - SH9564M

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

ANDREW LIM

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 227

S&P 'A-' (stable) rated Company

From: BHAS - Anthony Lau [<mailto:anthony.lau@bhauto.com.sg>]

Sent: Saturday, 18 November, 2017 5:28 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Cc: BHAS - Janice Koh <janice.koh@bhauto.com.sg>; BHAS - Jacelyn Loh <jacelyn.loh@bhauto.com.sg>; BHAS - Kelvin Lim <kelvin.lim@bhauto.com.sg>; BHAS - Bernard Kee <bernard.kee@bhauto.com.sg>; BHAS - Moo Wen Zheng <wenzheng.moo@bhauto.com.sg>

Subject: PRE REPAIR INSPECTION OUR VEHICLE - SLJ8531L/ YOUR VEHICLE - SH9564M

Dear Sir / Ma'am,

We would like to arrange to survey for the above mentioned vehicle for **SLJ8531L**.

Please assist to contact us to arrange for survey.

Ps: Car not in workshop

Thank you

Best Regards,

Anthony Lau

(W) 6559 8940 (F) 6269 2404

(Add) Blk 1 Sin Ming Industrail Estate Sector C #01-111-113-115-117 Singapore 575636

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Nov 2017 Edit Reg		20 Nov 2017 00:00 Edit Adj Rpt	S\$518.00 Edit Estimates	S\$518.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R									
Main Claimant: YAP BAOQI, ID: S82190603									
Vehicle Reg. No.: SLJ8531L		Date of Loss: 11/11/2017 23:00 - :59							
Claim Type: TP / MCT17110476		Policy/Cover Note No.: MCOM0016							
Vehicle Reg. No. (Insured): SH9564M		Policy No. (Claimant): VPA/P1885097							
Excess:									
Repairer: BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117, 575636 Sin Ming - Tel: 6559 8944									
Handling Insurer: India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by NATALIE LEE - 63476100 ext 243]									
Claimant's Insurer: AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/11/2017]									
Driver/Custodian (Insured): ABDUL HANI BIN ABDUL RAHIM (), NRIC: S1457976A									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> III_SG (29/11/2017): Alert - Adj Mandate Approved (S\$0.00) - SLJ8531L - Claim Handler: NATALIE LEE III_SG (28/11/2017): Alert - Adj Mandate Approved (S\$0.00) - SLJ8531L - Claim Handler: NATALIE LEE 									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLJ8531L (MCT17110476)
[SH9564M]
TP
YAP BAOQI
Nov 11 2017 11:00PM
[COMFORT TRANSPORTATION PTE LTD]
BH Auto Services Pte Ltd

Upload Documents Upload Photos Compose New Letter		View Use Viewer ▼
Video		1 per page ▼ <input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)
1	28/11/17 17:14	Video - Accident
		<div style="display: flex; justify-content: space-between;"> Thumbnail Print </div> <div style="display: flex; justify-content: space-between;"> 1 Load MP4 </div>
Photos/Images		3 per page ▼ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	28/11/17 17:34	General View
2	28/11/17 17:34	General View
3	28/11/17 17:34	General View
4	28/11/17 17:34	General View
5	28/11/17 17:34	General View
6	28/11/17 17:34	General View
7	28/11/17 17:34	General View
8	28/11/17 17:34	General View
9	28/11/17 17:34	General View
10	28/11/17 17:34	Odometer Reading
11	28/11/17 17:34	Chassis Number
		<div style="display: flex; justify-content: space-between;"> Thumbnail Print </div> <div style="display: flex; justify-content: space-between;"> 1 Load JPG </div>
Documentation		1 per page ▼ <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)
1	21/11/17 09:05	TP GIA REPORT
2	21/11/17 09:05	ACKNOWLEDGEMENT EMAIL TO III DD 21.11.2017
3	21/11/17 09:05	NOTIFICATION FROM WORKSHOP
4	28/11/17 09:40	TP ESTIMATE - MARKED
5	28/11/17 17:44	Email to III to reject claim 28.11.17
6	30/11/17 10:38	Email to wkshop reject claim 30.11.17
No	Finalized On	India International Insurance Pte Ltd (HQ)
1	22/11/17 09:05	Singapore Accident Statement
		<div style="display: flex; justify-content: space-between;"> Thumbnail Print </div> <div style="display: flex; justify-content: space-between;"> 1 Load PDF </div>

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
<div style="border: 1px solid #ccc; padding: 5px; margin-bottom: 5px;"> Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) </div> <div style="border: 1px solid #ccc; height: 100px; width: 100%;"></div>	
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III17022137/KWA3S2

Date: 19/12/2017

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0016
Claimant Vehicle No :	SLJ8531L	Insured Vehicle No :	SH9564M
Date of Loss:	11/11/2017	Nature of Claim:	TP
		Claim No:	MCT17110476

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ8531L	Engine No:	A14NET162850013
Make & Model:	CHEVROLET ORLANDO, 1.4 Turbo (A)	Chassis No:	KL1YA7589HK609215
Reg. Date:	28/12/2016 (Man. Year: 2016)	Odometer:	14982 km
Colour:	White		
Engine Capacity:	1362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Michelin 9 mm	Rear Left Side:	Michelin 9 mm
Front Right Side:	Michelin 9 mm	Rear Right Side:	Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,835.00	108.00	2,727.00	96.19
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,590.00	410.00	1,180.00	74.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,425.00	518.00	3,907.00	88.29
+ GST 7.00/7.00% (S\$)	309.75	36.26	273.49	88.29
Nett Amount (S\$)	4,734.75	554.26	4,180.49	88.29
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	20/11/2017	
Date Inspected:	24/11/2017 Inspected At:	BH Auto Services Pte Ltd (Sin Ming) Blk 1 Sin Ming Industrial Estate Sector C, #01/111/113/115/117 Singapore 575636
Estimated Period of Repair:	2.0 days	

Adjuster: KENNETH KONG

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Dec 2017)
Parts:	M1-MPV	CHEVROLET ORLANDO 1.4 Turbo (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ8531L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Repair	722.00 FL	*- FL
2	1		*FRONT FENDER SHIELD RH	Serviceable	138.00 FL	*- FL
3	10		*FRONT FENDER CLIPS	Not Necessary	45.00 FL	*- FL
4	1		*FRONT FENDER WHEEL ARCH RH	Cut	120.00 FL	*120.00 FL
5	1		*FRONT DOOR RH	Repair	1,360.00 FL	*- FL
6	1		*FRONT DOOR UPPER HINGE RH	Repair	50.00 FL	*- FL
7	1		*FRONT DOOR LOWER HINGE RH	Repair	50.00 FL	*- FL
8	1		*FRONT WHEEL RIM RH	Repair	665.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	3,150.00	120.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	315.00	12.00
Total Parts (\$\$)	2,835.00	108.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	ANTI-RUST COATING.	New	80.00	0.00
2	PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED & NECESSARY PARTS, TO PANEL BEAT, CUT & WELD IF NECESSARY, TO REALIGN ALL PANELS AND REINSTALL ALL REPLACEMENT PARTS.	New	500.00	150.00
3	PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL REPLACED & REPAIRED PARTS, TO RESPRAY USING 2K PAINT WITH OVEN SPRAY BOTH FACILITIES.	New	750.00	200.00
4	PROVIDE SKILL LABOUR TO DISCONNECT & CHECK ELECTRICAL WIRING, HARNESS, WIRE SOCKETS, ETC. TEST & RECTIFY FOR PROPER FUNCTIONING.	New	80.00	0.00
5	PROVIDE SKILL LABOUR TO CHECK AND RE-ADJUST FRONT WHEEL ALIGNMENT.	New	80.00	60.00
6	PROVIDE SKILL LABOUR TO DISMANTLE AND TRANSFER DOOR FITTING AND FACILITATE REPAIR.	New	100.00	0.00
Gross Labour Cost (\$\$)			1,590.00	410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >