

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636

Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street

#04-05 IOB Building

Singapore 049711

ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

Not Withheld
Resurvey After Repair

Dear Sir/Madam,

Accident Repair On : SLJ8531L

Model : **CHEROULET**

Policy No : **VPA/P1885097**

Chassis No : **KL1YA7589HK609215**

Year Of Make : **2016**

Date / Time Of Accident : **11/11/2017 at 2310Hrs**

Location : **BKE heading towards Woodlands Checkpoint**

Date: 20/11/2017

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replacement Of Parts

S/N	Quantity	Unit Price	Condition	Amount
		S\$		S\$
1 Front Fender RH	1	722.00		722.00 X
2 Front Fender Shield RH	1	138.00		138.00 ✓
3 Front Fender Clips	10	4.50		45.00 X
4 Front Fender Wheel Arch RH	1	120.00		120.00 ✓
5 Front Door RH	1	1,360.00		1,360.00 X
6 Front Door Upper Hinge RH	1	50.00		50.00 X
7 Front Door Lower Hinge RH	1	50.00		50.00 X
8 Front Wheel Rim RH	1	665.00		665.00 X
Sub-Total:				3,150.00
Less : 10% discount				630.00
Total Parts :				2,520.00

Special Nett Items

- 1 Anti-rust coating

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

80.00 80.00

Total Nett Items: 80.00

Labour Charges For Front RH Portion

- | | | | |
|---|--|--------|-----|
| 1 | Provide skill labour to remove all damaged & necessary parts, to panel beat, cut & weld if necessary, to realign all panels and reinstall all replacement parts. | 500.00 | 150 |
| 2 | Provide skill labour & material to putty all replaced & repaired parts, to respray using 2K paint with oven spray booth facilities | 750.00 | 200 |
| 3 | Provide skill labour to disconnect & check electrical wiring, harness, wyre sockets, etc. test & rectify for proper functioning | 80.00 | X |
| 4 | Provide skill labour to check and re-adjust front wheel alignment. | 80.00 | 60 |

5 Provide skill labour to dismantle and transfer door fitting and facilitate repair

100.00 X

Total Labour:	1,510.00
Total Parts:	2,520.00
Total Nett Items:	80.00
	4,110.00
GST 7%	287.70
Grand Total:	4,397.70

Estimate Repair Duration (include 1 day for re-survey & 1 day for parts ordering) 7 days

2 days

Accident Vehicle Of : SLJ8531L

Page : 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

Survey attended by:

Name : Kenneth

Company : CLC

Date : 24/1/17

Time : 2:05pm

Contact No : 96810663

Email : _____

Estimator : Anthony