

REPAIR ESTIMATE

20/11/2017 11:08

VEHIC : SHC 1062D

AIG

Jy

MODEL: TOYOTA PRIUS

QTY	PARTS DESCRIPTION	TYPE	UNIT PRICE	AMOUNT
	REAR TRUNK LID COVER <i>X repair</i>			\$ 922.50
	REAR TRUNK LID LOCK <i>X</i>			\$ 447.70
	REAR TRUNK LID RUBBER <i>X</i>			\$ 357.00
	REAR TRUNK LID GLASS (BLACK COLOR) <i>X</i>			\$ 995.00
	REAR TRUNK LID LOGO(PRIUS) <i>✓</i>			\$ 60.80
	REAR TRUNK LID LOGO(HYBRID) <i>✓</i>			\$ 52.40
	REAR TRUNK LID LOGO(TOYOTA STAR) <i>✓</i>			\$ 45.90
	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE <i>✓</i>			\$ 889.70
	REAR BUMPER <i>✓</i>			\$ 458.60
	REAR BUMPER RE-INFORCEMENT <i>?</i>			\$ 318.80
	REAR BUMPER UNDER COVER <i>✓</i>			\$ 552.60
	REAR BUMPER SIDE RETAINER <i>?</i>			\$ 112.70
	REAR BUMPER SPONGE <i>X</i>			\$ 143.40
	REAR BUMPER UNDER SIDE COVER (LH) <i>✓</i>			\$ 232.00
	REAR BUMPER UNDER SIDE CENTRE COVER <i>?</i>			\$ 220.60
	REAR BUMPER CLIPS <i>✓</i>			\$ 22.00
	REAR BUMPER TOWING COVER <i>X</i>			\$ 82.70
	SEAL, REAR BUMPER SIDE, LH <i>?</i>			\$ 148.40
	TAIL LAMP ASSY (UPPER), LH <i>✓</i>			\$ 557.90
	TAIL LAMP ASSY (LOWER), LH <i>✓</i>			\$ 548.40
	REAR END PANEL <i>X repair</i>			\$ 602.10
	REAR END PANEL GARNISH <i>?</i>			\$ 121.60
	REAR SPARE TYRE PANEL <i>?</i>			\$ 667.70
	REAR WINDSCREEN GLASS <i>X</i>			\$ 1,555.80
	REAR WINDSCREEN GLASS MOULDING <i>X</i>			\$ 60.00
	SUB TOTAL			\$ 10,176.30
	LESS 25% DISCOUNT			\$ 2,544.08
	DISCOUNTED TOTAL			\$ 7,632.23
	REAR TRUNK LID APPS STICKER <i>✓</i>			\$ 40.00
	REAR TRUNK LID COMFORT & TEL NO. STICKER <i>✓</i>			\$ 60.00
	REAR BUMPER REVERSE SENSOR <i>✓</i>			\$ 135.70
	REAR BUMPER RUBBER MAT <i>X</i>			\$ 50.00
	REAR WINDSCREEN SEALANT <i>X</i>			\$ 46.00
	Labour Charge			\$ 331.70
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Towing Charge			\$ 50.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,990.00
	ESTIMATE TOTAL			\$ 9,953.93

SUB TOTAL

LESS 25%

DISCOUNTED TOTAL

REAR TRUNK LID APPS STICKER ✓

REAR TRUNK LID COMFORT & TEL NO. STICKER ✓

REAR BUMPER REVERSE SENSOR ✓

REAR BUMPER RUBBER MAT X

REAR WINDSCREEN SEALANT X

Labour Charge

Panel Beating

Spray Painting Charge

Wiring Charge

Tuff Kote

Towing Charge

Remove/Refix Rear Windscreen Glass

Remove/Refix Reverse Sensor

TOTAL LABOUR

ESTIMATE TOTAL

LKK Auto Co
 Repair
 • To resurvey the
 • To display damage
 • Parts prices
 • Third party
 • No illegal
 • Supplemental
 is subject to
 Acknowledged
 Signature
 Date

Kalaia 11/11/17

20/11/17 11:25

4 days

381P

Before paint photo

NETT

NETT

NETT

NETT

NETT

600

580

20

X

/

X

20




JOB REQUISITION FOR BREAKDOWN / TOWING SERVICE

Job Requisition

1. Date: <u>18-11-17</u> Time Received: <u>0441</u>		3. Vehicle Type: ☐ Private ☒ Taxi (CTPL/CCPL) ☐ Fleet ☐ STK (Boon Lay)	4. Type of Towing: ☒ Normal Tow ☐ King Dolly ☐ Flat Bed ☐ Crane-up
2. ☐ New ☐ SPARK Kakis Name of Customer : <u>MR CHUA</u> Contact No. : <u>91772515</u> Vehicle No. : <u>SHC 1062D</u> Make / Model / Colour : <u>PRIVUS</u> Email : _____		5. Nature of Service: ☐ Jumpstart ☒ Recovery ☐ Change Tyre / Battery	6. Parts Replaced/Remarks: _____ _____
7. Location: <u>270 BANGKIT RD</u>		8. Vehicle Tow - In Workshop: ☐ Smoky Exhaust ☐ Wheel Jammed ☐ Overheating ☐ Steering Faulty ☐ Brake Faulty ☐ Alternator Faulty ☐ Starting Problem ☐ Loss Power ☒ Accident ☐ Engine Stalled ☐ Return Taxi	
9. Preferred Workshop: ☐ Braddell ☒ Loyang ☐ Pandan ☐ Sin Ming ☐ Sungei Kadut ☐ Ubi ☐ Senoko ☐ Komoco (UBI / Leng Kee) ☐ Cycle & Carriage (PD) ☐ Others: _____			

10. Odometer Reading : _____
Fuel Level : ☐ F ☐ 1/4 ☐ 1/2 ☐ 3/4 ☐ E

11. Radio / CD Player
☐ OK
☐ Faulty
☐ Not tested



: Cracked X : Dented
/ : Scratched O : Missing

[Signature]
Signature of Customer

Job Attended

12. Tow Truck / Recovery Van : ☐ VRS ☐ QA ☐ STD ☒ TZ ☐ IRS ☐ OTHERS
Name of Driver : T. ROWE Get Up
Vehicle No. : YN 4055A
Time Dispatch : 0441
Time of Arrival : 0615
Time Completed : 0715

Cash Invoice Details (if applicable)

13. Cash Invoice No. : _____

Customer Acknowledgement

- a. I have been advised to remove all valuable items in my vehicle, including Global Positioning System (GPS), audio compact disk, thumbdrive, carpark coupons, cash cards, spectacles, pen, etc.
b. I understand that any items left behind are at my own risk and SPARK Car Care™ will not be held liable for such losses.
c. Surcharge: Towing fee will be levied if the customer decides neither to tow nor proceed with the repairs in SPARK Car Care™.

18-11-17
Date

0615
Time

[Signature]
Signature of Customer

14. WORKSHOP

Name of Attending Staff/Guard

Date & Time of Arrival

Signature of Attending Staff/Guard

CUSTOMER'S COPY