

ASS. REC. BY:

REF:

TMI / CC3/TML17022149/Kdgnz

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: SLL 40615

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

02

days

Res.: Yes or No

Lum Sum: _____

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: SHD 27514

Yr Regn: 07 12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Chevrolet

c.c. 1991

Colour: White / Red

A/C: Insured / Std / NI / NA

Sp. Reading: 427637

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KL1LA69RTBB

099411

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R.15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or King Kong

Front

Rear

R/Bal. J mm

R/Bal. J mm

L/Bal. J mm

L/Bal. J mm

D.O.A. 16/11/17

D.O.I. 20/11/17

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rec

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/11/17

File pass to Corbyne

L1R 8 145d (Red: 13758.51, 90%).

SHD 27514 - CC3/AXA 13017870/Kv/m3w2

009 = 230913

SLL 40615 - X

21/11/17

email GIA & Est to Shirley.

RECEIVED 05 DEC 2017

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I. (\$) 1450

250

10

260



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD Ref : CC3/TMI17022149/Kgb

20 MCCALLUM STREET #09-01
TOKIO MARINE CENTRESINGAPORE 069046

Date : 21-11-2017



Code : TMI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 4061S	Veh. Inspected	SHD 275H
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/11/2017	Inspection Date	20/11/2017
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Ai Phing (LKKAuto)

From: Ai Phing (LKKAuto)
Sent: Tuesday, 21 November, 2017 3:36 PM
To: Too Joon Hwa
Cc: Priscilla Tan; SUR
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - TRANS-CAB AUTO SERVICES PTE LTD - DOA: 16-11-2017, SHD 275H (TP), SLL 4061S (OI)
Attachments: GIA.pdf, ESTIMATE.pdf

Dear Shirley,

Please be informed that we had inspected the vehicle SHD 275H on 20-11-2017 at M/s: Trans-Cab Auto Services Pte Ltd.

Enclosed herewith a copy of TP's GIA report and workshop Estimate.

Meanwhile, kindly create claims in Merimen for our necessary action.

Best Regards,

Ai Phing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #01-25 | S(408933)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	3878K

Vehicle Details

Vehicle No.	SHD275H
Vehicle to be Exported	Yes
Intended De-registration Date	17 Nov 2017
Vehicle Make	CHEVROLET
Vehicle Model	EPICA 2.0DSL AT ABS D/AB 2WD 4DR TURBO
Primary Colour	Red
Manufacturing Year	2011
Engine No.	Z20S1456001K
Chassis No.	KL1LA69RJBB099411
Maximum Power Output	110.0 kW (147 bhp)
Open Market Value	\$14,384.00
Original Registration Date	27 Jul 2012
First Registration Date	27 Jul 2012
Transfer Count	0
Actual ARF Paid	\$14,384.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	26 Jul 2020
PARF Rebate Amount	\$10,068.00

Intended COE Rebate Details

COE Expiry Date	26 Jul 2020
COE Category	A - Car (1600cc & below)
COE Period(Years)	8
PQP Paid	\$48,176.00
COE Rebate Amount	\$16,204.00
Total Rebate Amount	\$26,272.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 17 Nov 2017

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/11/2017 09:52
Date Of Accident	16/11/2017 15:45
Exact Location Of Accident	ORCHARD BOULEVARD X TOMLINSON ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD275H
Insured/Policyholder	
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD
Co Reg No	200303878K
Email Address	CLAIMS@TRANSCAB.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-62866666

Vehicle Particulars

Manufacturer	CHEVROLET
Model	EPICA-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	VPX/P1680520
Cover Note Number	

Driver

Name of Driver	KOH KAH THIAM
NRIC No	S0642455D
Date Of Birth	14/08/1951
Occupation	OUTDOOR
Date Of Driving Pass	06/08/1971
Driving Experience	46 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97967211
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	38 MAR THOMA ROAD #10-05
Postcode	328712
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 16.11.2017 at about 1545hours, I was travelling straight on the third lane along Orchard Boulevard x Tomlinson Road. While crossing the junction, suddenly I felt an impact. Vehicle B (SLL4061S) which was travelling on my right had hit onto my taxi's right side rear portion.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO BIG
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL4061S
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	SALENAH
NRIC/Passport Number	
Contact Number	96262256
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

pls see attach G.A Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHD 275H -

AAD1711-193

Not Authorised
11 Sep @ 1450h

Vehicle No.:
 Chassis No.:
 Date of Accident :
 Vehicle Make:
 Vehicle Model:
 Third Party Insurer :

SHD 275H - CANDY
KL1LA69RJBB099411
16.11.2017
CHEVROLET
CHEVROLET EPICA 2.0
TOC10

PART		LIST	
1	1	Front Fender RH	\$ 837.60
2	1	Front Fender Liner RH	\$ 47.00
3	1	Front Door RH	\$ 1,133.00
4	1	Front Door Outer Moulding RH	\$ 220.00
5	1	Front Door Outer Handle RH	\$ 125.00
6	1	Front Side View Mirror RH	\$ 939.00
7	1	Side Rocker Panel Garnish RH	\$ 236.40
8	1	Rear Door RH	\$ 1,133.00
9	1	Rear Door inner lock RH	\$ 425.00
10	1	Rear Door outer weatherstrip moulding RH	\$ 85.00
11	1	Rear Door outer handle RH	\$ 60.00
12	1	Rear Fender RH	\$ 1,145.00
13	1	Rear Fender Inner Cowling RH	\$ 76.60
14	1	Rear Tail Lamp RH	\$ 479.30
15	1	Rear Bumper	\$ 1,202.00

TOTAL	\$	8,143.90
10%	\$	814.39
	\$	7,329.51

Specical Nett

1	1 Set	Front Fender Liner Clip	\$ 30.00	X
2	1Set	Rear Bumper Parking Sensor	\$ 300.00	X
3	1 Set	Rear Bumper Fastener Clip	\$ 30.00	✓
4	1 Set	Rear Fender Liner Clip	\$ 30.00	X
5	1	Door Sticker "Trans-cab"	\$ 80.00	X
6	1	Door Sticker "6555-3333"	\$ 80.00	X
7	1set	Side Rocker Panel Garnish Clip RH	\$ 60.00	X
8	1	Rear Tyre RH	\$ 360.00	X
9	1	Rear Wheel Rim RH	\$ 254.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD 275H -

10 1 Hub Cup Rim RR RH \$ *35.00* X

TOTAL	\$	1,259.00
TOTAL PARTS	\$	8,588.51

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,700.00 *3000*

To Rust-Proofing Of The Affected Areas.

\$ *220.00* X

To transfer of tire, rim and on wheel balancing.

\$ *170.00* X

Putty and Spray Painting Of The Affected
Portion.

\$ 2,800.00 *4000*

To Check Electrical Lighting Concerned.

\$ *170.00* X

To check steering geometry and computer wheel
alignment

\$ *220.00* X

To transfer of door fittings, attachment and
perform water seepage test.

\$ *170.00* X

To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.

\$ *170.00* X

TOTAL	\$	6,620.00
Over All Total	\$	15,208.51

REPAIR DAYS**10 DAYS***2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TMI17022149/KGBN2
Date: 13/12/2017

REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MU002037
Claimant Vehicle No :	SHD275H	Insured Vehicle No :	SLL4061S
Date of Loss:	16/11/2017	Nature of Claim:	TP
		Claim No:	M1705871

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD275H	Engine No:	Z20S1456001K
Make & Model:	CHEVROLET EPICA, 2.0 2.0DSL AT ABS D/AB 2WD 4DR TUR (A)	Chassis No:	KL1LA69RJBB099411
Reg. Date:	27/07/2012 (Man. Year: 2011)	Odometer:	427637 km
Colour:	Red/White		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Linglong 8 mm	Rear Left Side:	Linglong 8 mm
Front Right Side:	Linglong 8 mm	Rear Right Side:	Linglong 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	8,588.51	1,111.80	7,476.71	87.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,620.00	700.00	5,920.00	89.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,208.51	1,811.80	13,396.71	88.09
Approved Total (Overridden) (\$\$)		1,450.00		
(\$\$)	15,208.51	1,450.00	13,758.51	90.47
+ GST 7.00/7.00% (\$\$)	1,064.60	101.50	963.10	90.47
Nett Amount (\$\$)	16,273.11	1,551.50	14,721.61	90.47

INSPECTION

Date of Assignment: 22/11/2017

Date Inspected: 20/11/2017 Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: LOW AI PHING

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Dec 2017)
 Parts: 143 CHEVROLET EPICA 2.0 2.0DSL AT ABS D/AB 2WD 4DR TUR (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SHD275H)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER RH	Serviceable	837.60 FL	*-FL
2	1		*FRONT FENDER LINER RH	Serviceable	47.00 FL	*-FL
3	1		*FRONT DOOR RH	Repair	1,133.00 FL	*-FL
4	1		*FRONT DOOR OUTER MOULDING RH	Serviceable	220.00 FL	*-FL
5	1		*FRONT DOOR OUTER HANDLE RH	Serviceable	125.00 FL	*-FL
6	1		*FRONT SIDE VIEW MIRROR RH	Serviceable	939.00 FL	*-FL
7	1		*SIDE ROCKER PANEL GARNISH RH	Serviceable	236.40 FL	*-FL
8	1		*REAR DOOR RH	Repair	1,133.00 FL	*-FL
9	1		*REAR DOOR INNER LOCK RH	Repair	425.00 FL	*-FL
10	1		*REAR DOOR OUTER WEATHERSTRIP MOULDING RH	Serviceable	85.00 FL	*-FL
11	1		*REAR DOOR OUTER HANDLE RH	Serviceable	60.00 FL	*-FL
12	1		*REAR FENDER RH	Repair	1,145.00 FL	*-FL
13	1		*REAR FENDER INNER COWLING RH	Serviceable	76.60 FL	*-FL
14	1		*REAR TAIL LAMP RH	Serviceable	479.30 FL	*-FL
15	1		*REAR BUMPER	Buckled/Dented	1,202.00 FL	*1,202.00 FL
16	1		*SET FRONT FENDER LINER CLIP	Not Necessary	30.00 FS	*-FS
17	1		*SET REAR BUMPER PARKING SENSOR	Serviceable	300.00 FS	*-FS
18	1		*SET REAR BUMPER FASTENER CLIP	Necessary	30.00 FS	*30.00 FS
19	1		*SET REAR FENDER LINER CLIP	Not Necessary	30.00 FS	*-FS
20	1		*DOOR STICKER TRANS-CAB	Not Necessary	80.00 FS	*-FS
21	1		*DOOR STICKER 6555-3333	Not Necessary	80.00 FS	*-FS
22	1		*SET SIDE ROCKER PANEL GARNISH CLIP RH	Not Necessary	60.00 FS	*-FS
23	1		*REAR TYRE RH	Serviceable	360.00 FS	*-FS
24	1		*REAR WHEEL RIM RH	Serviceable	254.00 FS	*-FS
25	1		*HUB CUP RIM RR RH	Serviceable	35.00 FS	*-FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	9,402.90	1,232.00
- List Item Discount on L Items 10.00/10.00% (S\$)	814.39	120.20
Total Parts (S\$)	8,588.51	1,111.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	2,700.00	300.00
2	TO RUST-PROOFING OF THE AFFECTED AREAS	New	220.00	-
3	TO TRANSFER OF TIRE,RIM AND ON WHEEL BALANCING	New	170.00	-
4	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,800.00	400.00
5	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	-
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	-
7	TO TRANSFER OF DOOR FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	-
8	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	-
Gross Labour Cost (\$\$)			6,620.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >