

ASS. REC. BY:

REF:

CS/ms(17022165 / Krbe2

Special Instruction:

SURVIVOR:

Kenneth

ASSIGNMENT (Office)

From (Person):

Trene Tan

of

MSLH

Date/Time:

20-11-2017 3:53pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBB 9947A

Insured:

SKZ 3532U

at Workshop m/s

Mega Auto

Tel:

9758 2843

of

160 Sin Ming Jie # 02-01

Policy No:

B2S8 71928QMY

Claim No:

536403

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09-11-2017

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time:

21-11-2017 9:37am

Person Contacted:

An. Meng

Vehicle IN/OUT

Date/Time

Action/Instruction ( ✓ ) Estimate

GBB 9947A - X

SKZ 3532U - X

Sent preli through menimen

Confirm LIS \$ 2,900.00, 5 days

kol: \$2199.35, 437.





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17022165/Krb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 21-11-2017	
Code : MSG			
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SKZ 3532U	Veh. Inspected	GBB 9947A
Policy No.	B28871928QMY	Coverage (\$)	0.00
Claim No.	536403	Excess (\$)	0.00
Assign From	MERIMEN (IRENE TAN)	Assign Date	20/11/2017
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
Accident Date	09/11/2017	Inspection Date	21/11/2017
Survey held at	160 SIN MING DRIVE #02-01		
Repairer	MEGA AUTO PTE LTD		
<b>5a. Remarks</b>			

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Nov 2017		20 Nov 2017 15:53 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

<b>Insured:</b>	LIM BOON THONG, ID: S6818461D		
<b>Main Claimant:</b>	FEDERAL EXPRESS (SINGAPORE) PTE LTD, Co. Reg. No.: 198402740W		
<b>Vehicle Reg. No.:</b>	GBB9947A	<b>Date of Loss:</b>	09/11/2017 15:00 - :59
<b>Claim Type:</b>	TP / 536403	<b>Policy/Cover Note No.:</b>	B28871928QMY (Comprehensive) Coverage: 20/01/2017 - 19/01/2018
<b>Vehicle Reg. No. (Insured):</b>	SKZ3532U	<b>Policy No. (Claimant):</b>	
		<b>Excess:</b>	S\$700.00
<b>Repairer:</b>	Mega Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-01 Auto City, 575645 Sin Ming - Tel: 91068227		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/11/2017]		
<b>Driver/Custodian (Insured):</b>	LIM BOON THONG ( / Male), NRIC: S6818461D		

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.



## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 01 Dec 2017

**Preliminary Advice**

Insured Vehicle No	: SKZ3532U	Accident Date	: 09/11/2017
TP Vehicle No	: GBB9947A	Assignment Date	: 20/11/2017
Make	: TOYOTA REGIUS ACE	Est. Duration of Repair	: 4.50
Date of Inspection	: 21/11/2017		
Inspection At	: MEGA AUTO PTE LTD (HQ) 160 SIN MING DRIVE #02-01 AUTO CITY SINGAPORE 575645		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,099.35
Revised Amount	:S\$	3,012.22
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,012.22

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.

### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date Of Report	17/11/2017 09:39
Date Of Accident	09/11/2017 15:35
Exact Location Of Accident	ALONG PIONEER CRESCENT TWDS TANJONG KLING RD
Country/State of Loss	SINGAPORE

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBB9947A
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FEDERAL EXPRESS (SINGAPORE) PTE LTD
Co Reg No	198402740W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-69222929

#### Vehicle Particulars

Manufacturer	TOYOTA
Model	REGIUS ACE-3.0 D DX (A)
Exact Purpose for which vehicle was being used at time of accident	DELIVERY AND PICK-UP
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

#### Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	100774093
Cover Note Number	

#### Driver

Name of Driver	PRABU S/O BALAKRISHNAN
NRIC No	S8430763G
Date Of Birth	26/09/1984
Occupation	OUTDOOR
Date Of Driving Pass	19/06/2008
Driving Experience	9 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address BLK 661A EDGEDALE PLAINS  
#04-606 SINGAPORE

Postcode 821661

Was driver an employee of the Insured's Company YES

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions JUST STARTED DRIZZLING

Road Surface ROAD SURFACE NOT SO WET

#### Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

On 09/11/2017 at 15:36hrs while driving along Pioneer Crescent towards Tanjong Kling Road, I came to a complete stop behind a truck when vehicle SKZ3532U rear-ended my vehicle. No injuries to either party.

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKZ3532U

Vehicle Make/Model/Colour SUBARU/RED

Details Of Properties FRONT BUMPER AND BONNET

Name of Driver LIM BOON THONG

NRIC/Passport Number S6818461D

Contact Number 83337228

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Details of Witness

Name

Phone Number


Email Address

Sketch Plan #2

SKETCH PLAN

Vehicle A : GBB 7947A

Vehicle B : SKZ 3532U



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 09/10/2017 at 15:36hrs while driving along Pioneer Crescent towards Tanjong Kling Road, I came to a complete stop behind a truck when vehicle SKZ 3532U rear-ended my vehicle. No injuries to either party.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Federal Express (S) Pte Ltd  
 22-01 P.A. Intur  
 5-083, Lorong 4 G17, #01  
 Policyholder's Signature  
 Date & Title:

(Driver's Signature  
 (if driver is not the policyholder)  
 Date & Time:

Reporting Centre Personnel's Signature  
 Name:  
 NRIC/YPN No.:

Quotation Details - Quotation No SN-002012-17-20039

Date Created: 18/11/2017  
12/4/2011

Customer Details:

Fedex  
Federal Express (s) Pte Ltd  
90 Alps Ave  
Singapore 498746  
Fax: 69222550



[View Photo](#) [Accident Photo](#)

Vehicle Details

Vehicle No : GBB 9947  
A  
Vehicle Make : Toyota  
Vehicle Model : Hiace 2008  
Vehicle Engine No :  
Engine No :  
Chasis No :  
Mileage :

Owner's Accident Details

Job No : SN-002012-17-20039  
JobCategory : TP - Lump Sum  
Date of Accident :  
Owner's Insurer :  
Location of Accident :

Surveyor's Details

Surveyor Name :  
Surveyor Company :  
Surveyor ContactNo :  
Surveyor FaxNo :  
Quotation Submission Date :  
Surveyor Approve Date :  
Supplementary Date :  
Supplementary Approve Date :

*Not Authored  
11 Sep @ 2900  
Resurvey After Paint  
5 days*

*HennerthKang@IKKauto.com*

Item No	Ref No	Description	QTY	Unit List Price	Mark Up / Discount %	Mark Up / Discount Price	Total Price	Rev Qty	Rev Price	Unit Price	Remarks	Final Total Price	Surveyor Approval
<u>Materials</u>													
1	1	Tailgate	1	\$1,601.00	-25.00	\$1,200.75	\$1,200.75	0	0		By	\$0.00	✓
2	2	Rear Bumper	1	\$354.60	-25.00	\$265.95	\$265.95	0	0		Rev/WM	\$0.00	✓
3	3	Rear Bumper Retainer RH	1	\$21.10	-25.00	\$15.83	\$15.83	0	0		Dis	\$0.00	✓
4	4	Rear Bumper Retainer LH	1	\$21.10	-25.00	\$15.83	\$15.83	0	0		Sm	\$0.00	X
5	5	Rear Bumper Clips	10	\$3.80	-25.00	\$2.85	\$28.50	0	0		Rev	\$0.00	✓
6	6	Rear Corner Panel RH	1	\$84.10	-25.00	\$63.08	\$63.08	0	0		R	\$0.00	✓
7	7	Rear Corner Panel LH	1	\$84.10	-25.00	\$63.08	\$63.08	0	0		R	\$0.00	X
8	8	Tail Lamp RH	1	\$256.20	-25.00	\$192.15	\$192.15	0	0		e 101	\$0.00	✓
9	9	Tail Lamp LH	1	\$256.20	-25.00	\$192.15	\$192.15	0	0		Sm	\$0.00	X
10	10	Rear End Panel	1	\$309.40	-25.00	\$232.05	\$232.05	0	0		By	\$0.00	✓

Material Total: \$2,269.35 Final Sub-Total : \$0.00

Special Nett Items

1	11	Tailgate Glass Sealant	1	\$40.00	0.00	\$40.00	\$40.00	0	0	Net	\$0.00	✓
2	12	Rear End Panel Sealant	1	\$50.00	0.00	\$50.00	\$50.00	0	0	Net	\$0.00	30.50
3	13	Reverse Sensor	1	\$220.00	0.00	\$220.00	\$220.00	0	0	NSP	\$0.00	X
4	14	Tailgate Sticker	1	\$200.00	0.00	\$200.00	\$200.00	0	0	Net	\$0.00	150.50

**Special Nett Items Total: \$510.00 Final Sub-Total : \$0.00**

Labour

1	15	Labour for Tailgate Sticker	1	\$80.00	0.00	\$80.00	\$80.00	0	0		\$0.00	60.00
2	16	Labour for facilitate repair	1	\$1,000.00	0.00	\$1,000.00	\$1,000.00	0	0		\$0.00	600.00
3	17	Check & Reconnet Wiring	1	\$60.00	0.00	\$60.00	\$60.00	0	0		\$0.00	20.00
4	18	R&R Reverse Sensor	1	\$60.00	0.00	\$60.00	\$60.00	0	0	nn	\$0.00	X
5	19	Rust Proof	1	\$80.00	0.00	\$80.00	\$80.00	0	0		\$0.00	60.00
6	20	R&R Tailgate Glass	1	\$120.00	0.00	\$120.00	\$120.00	0	0		\$0.00	✓
7	21	R&R Tailgate Components	1	\$120.00	0.00	\$120.00	\$120.00	0	0		\$0.00	60.00
8	22	Respray Accident damaged area	1	\$800.00	0.00	\$800.00	\$800.00	0	0		\$0.00	500.00

**Labour Total: \$2,320.00 Final Sub-Total : \$0.00**

Others

**Others Total: \$0.00 Final Sub-Total : \$0.00**

**Total Price: \$5,099.35 Final Total Price : \$0.00**



Quotation Details - Quotation No SN-002012-17-20039

Date Created: 18/11/2017  
12/1/2011

**Customer Details:**

Fedex  
Federal Express (s) Pte Ltd  
90 Alps Ave  
Singapore 498746  
Fax: 69222550



[View Photo](#) [Accident Photo](#)

**Vehicle Details**

Vehicle No : GBB 9947 A  
Vehicle Make : Toyota  
Vehicle Model : Hiace 2008  
Vehicle Engine No :  
Engine No :  
Chassis No :  
Mileage :

**Owner's Accident Details**

Job No :  
JobCategory : TP - Lump Sum  
Date of Accident :  
Owner's Insurer :  
Location of Accident :

**Surveyor's Details**

Surveyor Name :  
Surveyor Company :  
Surveyor ContactNo :  
Surveyor FaxNo :  
Quotation Submission Date :  
Surveyor Approve Date :  
Supplementary Date :  
Supplementary Approve Date :

*Not Authorized  
By B?  
Presony After Paint  
4-5 days  
kennethkeng@1kkauto.com*

Item No	Ref No	Description	QTY	Unit List Price	Mark Up / Discount %	Mark Up / Discount Price	Total Price	Rev Qty	Rev Price	Unit Price	Remarks	Final Total Price	Surveyor Approval
<b>Materials</b>													
1	1	Tailgate	1	\$1,601.00	-25.00	\$1,200.75	\$1,200.75	0	0	0	<i>B?</i>	\$0.00	<input checked="" type="checkbox"/>
2	2	Rear Bumper	1	\$354.60	-25.00	\$265.95	\$265.95	0	0	0	<i>Rev/UM</i>	\$0.00	<input checked="" type="checkbox"/>
3	3	Rear Bumper Retainer RH	1	\$21.10	-25.00	\$15.83	\$15.83	0	0	0	<i>D/S</i>	\$0.00	<input checked="" type="checkbox"/>
4	4	Rear Bumper Retainer LH	1	\$21.10	-25.00	\$15.83	\$15.83	0	0	0	<i>S</i>	\$0.00	<input checked="" type="checkbox"/>
5	5	Rear Bumper Clips	10	\$3.80	-25.00	\$2.85	\$28.50	0	0	0	<i>Rev</i>	\$0.00	<input checked="" type="checkbox"/>
6	6	Rear Corner Panel RH	1	\$84.10	-25.00	\$63.08	\$63.08	0	0	0	<i>R</i>	\$0.00	<input checked="" type="checkbox"/>
7	7	Rear Corner Panel LH	1	\$84.10	-25.00	\$63.08	\$63.08	0	0	0	<i>R</i>	\$0.00	<input checked="" type="checkbox"/>
8	8	Tail Lamp RH	1	\$256.20	-25.00	\$192.15	\$192.15	0	0	0	<i>C/S</i>	\$0.00	<input checked="" type="checkbox"/>
9	9	Tail Lamp LH	1	\$256.20	-25.00	\$192.15	\$192.15	0	0	0	<i>S</i>	\$0.00	<input checked="" type="checkbox"/>
10	10	Rear End Panel	1	\$309.40	-25.00	\$232.05	\$232.05	0	0	0		\$0.00	<input checked="" type="checkbox"/>

Material Total: \$2,269.35 Final Sub-Total : \$0.00

Special Nett Items

1	11	Tailgate Glass Sealant	1	\$40.00	0.00	\$40.00	\$40.00	0	0	me	\$0.00	✓
2	12	Rear End Panel Sealant	1	\$50.00	0.00	\$50.00	\$50.00	0	0		\$0.00	?
3	13	Reverse Sensor	1	\$220.00	0.00	\$220.00	\$220.00	0	0	nsp	\$0.00	x
4	14	Tailgate Sticker	1	\$200.00	0.00	\$200.00	\$200.00	0	0	me	\$0.00	150.00

**Special Nett Items Total: \$510.00 Final Sub-Total : \$0.00**

Labour

1	15	Labour for Tailgate Sticker	1	\$80.00	0.00	\$80.00	\$80.00	0	0		\$0.00	600
2	16	Labour for facilitate repair	1	\$1,000.00	0.00	\$1,000.00	\$1,000.00	0	0		\$0.00	6000
3	17	Check & Reconnet Wiring	1	\$60.00	0.00	\$60.00	\$60.00	0	0		\$0.00	200
4	18	R&R Reverse Sensor	1	\$60.00	0.00	\$60.00	\$60.00	0	0	nn	\$0.00	x
5	19	Rust Proof	1	\$80.00	0.00	\$80.00	\$80.00	0	0		\$0.00	?
6	20	R&R Tailgate Glass	1	\$120.00	0.00	\$120.00	\$120.00	0	0		\$0.00	✓
7	21	R&R Tailgate Components	1	\$120.00	0.00	\$120.00	\$120.00	0	0		\$0.00	600
8	22	Respray Accident damaged area	1	\$800.00	0.00	\$800.00	\$800.00	0	0		\$0.00	5000

**Labour Total: \$2,320.00 Final Sub-Total : \$0.00**

Others

**Others Total: \$0.00 Final Sub-Total : \$0.00**

**Total Price: \$5,099.35 Final Total Price : \$0.00**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey/bater/deteriorary painting
- To display damaged vehicle during resurvey
- Parts prices are subject to confirmation
- Third copy will be sent on "Without Prejudice" basis
- No illegal modification are allowed
- Supplemental repairs will be resurveyed and is subject to the claim from insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

**...CLAIM SUBFOLDER...(Pending for Survey Report)**

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Nov 2017		20 Nov 2017 15:53 <a href="#">Edit Adj Rpt</a>	<b>S\$2,900.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,900.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<a href="#">Main</a>	<a href="#">Reference</a>	<a href="#">Claim Details</a>	<a href="#">Documents</a>	<a href="#">Show All</a>
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]	
<b>Insured:</b>	LIM BOON THONG, ID: S6818461D		
<b>Main Claimant:</b>	FEDERAL EXPRESS (SINGAPORE) PTE LTD, Co. Reg. No.: 198402740W		
<b>Vehicle Reg. No.:</b>	GBB9947A	<b>Date of Loss:</b>	09/11/2017 15:00 - :59
<b>Claim Type:</b>	TP / 536403	<b>Policy/Cover Note No.:</b>	B28871928QMY (Comprehensive) Coverage: 20/01/2017 - 19/01/2018
<b>Vehicle Reg. No. (Insured):</b>	SKZ3532U	<b>Policy No. (Claimant):</b>	
		<b>Excess:</b>	S\$700.00
<b>Repairer:</b>	Mega Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-01 Auto City, 575645 Sin Ming - Tel: 91068227		
<b>Handling Insurer:</b>	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
<b>Adjuster:</b>	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 20/12/2017]		
<b>Driver/Custodian (Insured):</b>	LIM BOON THONG ( / Male), NRIC: S6818461D		

ASSOCIATED MAIL RECEIVED	<a href="#">View All</a>	<a href="#">Compose Case Mail</a>
--------------------------	--------------------------	-----------------------------------

There are no mail for this case.

ALL ASSOCIATED TASKS										
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?	
No results.										

## Claim Documents

\*GBB9947A (536403)  
[SKZ3532U]  
TP  
FEDERAL EXPRESS (SINGAPORE) PTE LTD  
Nov 9 2017 3:00PM  
[LIM BOON THONG]  
Mega Auto Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		View Use Viewer <span style="font-size: small;">▼</span>	
<b>Assessment Reports</b>						1 per page <span style="font-size: small;">▼</span>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print	
1	20/11/17 11:49	<b>Accident Statement</b> <small>From: SC - Reg. No: SKZ3532U, Claimant: LIM BOON THONG</small>		<b>i</b>	Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	01/12/17 16:01	<b>Adjuster Immediate Advice</b>		<b>i</b>	Load HTM		
<b>Photos/Images</b>						3 per page <span style="font-size: small;">▼</span>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
2	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
3	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
4	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
5	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
6	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
7	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
8	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
9	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
10	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
11	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
12	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
13	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
14	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
15	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
16	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
17	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
18	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
19	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
20	05/12/17 15:03	<b>General View</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
21	05/12/17 15:03	<b>Reinspection Photo</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
22	05/12/17 15:03	<b>Reinspection Photo</b>		<b>i</b>	Load JPG	<input checked="" type="checkbox"/>	
<b>Documentation</b>						1 per page <span style="font-size: small;">▼</span>	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)			Thumbnail	Print	
1	20/11/17 11:50	<b>Email from TP for survey</b>		<b>i</b>	Load PDF		
2	20/11/17 11:50	<b>TP estimate</b>		<b>i</b>	Load PDF		
3	20/11/17 11:50	<b>TP GIA REPORT</b>		<b>i</b>	Load PDF		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print	
1	05/12/17 14:46	<b>Supplementary</b>		<b>i</b>	Load PDF		

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>			Reset	Save	Print
There are no document checklists configured.					

**Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**

**Show Remarks To:**  Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17022165/KRBE2

Date: 05/12/2017

#### REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	B28871928QMY
Claimant Vehicle No :	GBB9947A	Insured Vehicle No :	SKZ3532U
Date of Loss:	09/11/2017	Nature of Claim:	TP
			Claim No: 536403

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBB9947A	Engine No:	1KD2051788
Make & Model:	TOYOTA REGIUS ACE, 3.0 D DX (A)	Chassis No:	KDH2210007199
Reg. Date:	14/12/2010 (Man. Year: 2010)	Odometer:	227116 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	195 R15X8
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 4 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 4 mm

*The above values represent the remaining tyre treads depth*

#### COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,032.74	2,281.92	750.82	24.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,420.00	900.00	38.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>5,352.74</b>	<b>3,701.92</b>	<b>1,650.82</b>	<b>30.84</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,900.00</b>		
	(S\$) 5,352.74	2,900.00	2,452.74	45.82
	+ GST 7.00/7.00% (S\$) 374.69	203.00	171.69	45.82
<b>Nett Amount (S\$)</b>	<b>5,727.43</b>	<b>3,103.00</b>	<b>2,624.43</b>	<b>45.82</b>

#### INSPECTION

Date of Assignment:	20/11/2017	
Date Inspected:	21/11/2017	Inspected At: Mega Auto Pte Ltd (HQ) 160 Sin Ming Drive #02-01 Auto City Singapore 575645
Estimated Period of Repair:	5.0 days	

**Adjuster:** KENNETH KONG

**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

Part Source:	(Last Synchronised: 05 Dec 2017)	
Parts:	N/A	TOYOTA REGIUS ACE 3.0 D DX (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBB9947A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Bent	1,601.00 FL	*1,601.00 FL
2	1		*REAR BUMPER	Buckled / Cracked	354.60 FL	*354.60 FL
3	1		*REAR BUMPER RETAINER RH	Distorted	21.10 FL	*21.10 FL
4	1		*REAR BUMPER RETAINER LH	Serviceable	21.10 FL	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	38.00 FL	*38.00 FL
6	1		*REAR CORNER PANEL RH	Repair	84.10 FL	*- FL
7	1		*REAR CORNER PANEL LH	Repair	84.10 FL	*- FL
8	1		*TAIL LAMP RH	Cracked	256.20 FL	*256.20 FL
9	1		*TAIL LAMP LH	Serviceable	256.20 FL	*- FL
10	1		*REAR END PANEL	Bent	309.40 FL	*309.40 FL
11	1		*TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS
12	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*30.00 FS
13	1		*REVERSE SENSOR	No such part	220.00 FS	*- FS
14	1		*TAILGATE STICKER	Necessary	200.00 FS	*150.00 FS
15	1		*TAILGATE WEATHERSTRIP	Cut	253.39 FS	*126.70 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,789.19	2,927.00
- List Item Discount on L Items 25.00/25.00% (S\$)	756.45	645.08
<b>Total Parts (S\$)</b>	<b>3,032.74</b>	<b>2,281.92</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR FOR TAILGATE STICKER	New	80.00	60.00
2	LABOUR FOR FACILITATE REPAIR	New	1,000.00	600.00
3	CHECK & RECONNECT WIRING	New	60.00	20.00
4	R&R REVERSE SENSOR	New	60.00	0.00
5	RUST PROOF	New	80.00	60.00
6	R&R TAILGATE GLASS	New	120.00	120.00
7	R&R TAILGATE COMPONENTS	New	120.00	60.00
8	RESPRAY ACCIDENT DAMAGED AREA	New	800.00	500.00
<b>Gross Labour Cost (S\$)</b>			<b>2,320.00</b>	<b>1,420.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >