

REC.BY:

REF:

CS/MSH17022166 / Rmb2

Special Instruction:

SURVEYOR:
Mullmen

Rasul

ASSIGNMENT (Office)

From (Person):

Elaine Ngu

of

MSH

Date/Time:

20-11-2017 3:57pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL 5985U

Insured:

SJY 7070B

at Workshop m/s

World Auto

Tel:

9758 8347

of

1 Kranji Loop

Policy No:

28968249 Amy

Claim No:

537006

Sum Insured:

Excess:

\$ 600.00

Make of Veh:

D.O.A.

14-11-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS (WPI)

H.O.D. Endorsement:

Date/Time:

21-11-2017 9:32am

Person Contacted:


Mr. Sim

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SL 5985U x
	SJY 7070B - 06 / AXF 12018450 / U11321
22/11/2018	Confirmed part by part \$8218-32 - repair 8 days
	(Red. \$5386.40, 40%)

Date: 200912

KIV to finalised



NRIC No. S7834672H



Date of issue

19-12-2008

APT BLK 56 TEBAN GARDENS ROAD #03-457
SINGAPORE 800055

NRIC No. S7834672H

Date 07/07/2018

4824690

member

Faru

MSLH

4597K

From: 21-11-2017 Date: 21-11-2017 SLL 59854 Policy No: 2017 mark

Estimated Cost: 1000 Type: C (C) Cycle Bus Van Utility Taxi Prime Mover

OD: 17 WS TR RES CD: RES/ EVA WY: MM Truck Trailer

To inspect vehicle No: SLL 59854 Name: Honda Vezel Hybrid 1.5X 1496

at: World Auto Colour: Red H.O. Insured: Std. N. N/A

of: 1 Krunji Loop St. Parking: 040691 T.Rand Insured: Std. N. N/A

Insured: Eng No: Ru31213284


Policy No: Gen. Cond: Good (G) / Poor / Burnt

Claims No: Steering: (G) Jammed / Leaked / Burnt or

Sum Insured: Excess: Brake: (G) Jammed / Leaked / Burnt or

Client's Record: Mod: NI / SR / STD Air/In or

Make of veh: Tyre Size: 215/60R16

Policy Condition:  Front: BS (G) EXNOVA GY: FS / LIZA MIO / HTSU: PR: SUMI

Remark: The veh had commenced its repair at the time of inspection. TOYO YOKO or Don

Ball or Market Value: Front: 6 Rear: 6

DAC Accident Report: Consistent? : Yes or No R.Ba: 6 L.Ba: 6

DAC Rep Seen: Consistent? : Yes or No D.O.A: 14/11/17 D.O.: 21/11/17

Est. Repairs: days: Res: Yes or No Surveyed at: World Auto

Sum Sum: Rs: 3 Yrs: Yes or No Des. of Damages: Fr: (G) / O/S / N/S / U/O / Roof top or

QA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle IN / OUT

The L.O. Chassis/frame Body Structure affected due to collision

Date: 22/11/17 Time: REV Action: preli Instruction: in member.

One Time Fee Pass: ☒ Preli. Report

22/11/2018 ☐ Final Report

Days Of Repair: 300

Resurvey No. of Told: 10

Survey Fee: 310

Add Fee: ☐ Grease: \$

☐ Tire: \$

☐ Wash: \$

☐ Detail: \$

Receipt For: T/P

Claim Sum: \$

Signature: 310

From: ADMIN SAT [mailto:admin@sngahtee.com]
Sent: Monday, October 16, 2017 10:33 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: ACCIDENT INVOLVING OUR CLIENT VEHICLE SLG7912T AND YOUR INSURED SHD3584X 12/10/2017

Dear All,

Have your insured reported the accident?
 Is liability in our favour?
 Hope to hear from you.
 Thanks you

Best Regards

Joyce Tan | admin@sngahtee.com

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
 TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of internet transmission or any modification. Print this email only if it is absolutely necessary and help in preservation of environment. India International Insurance Pte Ltd. Registration No. 198703792-K



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17022166/R1gb		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 21-11-2017		
Code : MSG				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJY 7070B	Veh. Inspected	SLL 5985U	
Policy No.	28968249QMY	Coverage (\$)	0.00	
Claim No.	537006	Excess (\$)	0.00	
Assign From	MERIMEN (ELAINE NGU)	Assign Date	20/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	14/11/2017	Inspection Date	21/11/2017	
Survey held at	1 KRANJI LOOP			
Repairer	WORLD AUTO PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Survey Department Check List (Case Handler)

Reference No.: CS / MS617022166 / R / nb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	/			
C	Customer Code	/			
N	Assign From	/			
C	Assign Date	/			
C	Veh No (Inspected)	/			
C	Veh No (Insured)	/			
C	D.O.A	/			
C	Policy No	/			
C	Claim No	/			
C	Insurance Authorisation (CA / REV / REP)	/			
C	Report Type	/			
C	Weekend Charges	/			
N	Survey held at/Repairer	/			
C	Excess	/			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	/			
C	Regn Month/Year	/			
N	Vehicle Type	/			
N	Make & Model	/			
C	Engine Capacity. (C.C)	/			
N	Colour	/			
C	Odometer. (Sp. Reading)	/			
C	Chassis No	/			
N	General Condition	/			
N	Steering	/			
N	Brake	/			
N	Modification (Modi)	/			
C	Tyre Size	/			
N	Tyre Make	/			
C	Tyre Balance	/			
C	Date of Inspection	/			
N	Survey held	/			
N	Des. of Damages	/			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded				
---	--------------------------------------	--	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				


(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: Rita 22/1/2018
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2018



Accident Photo

Norrita (LKKAUTO)

From: sim@worldauto.com.sg
Sent: Monday, 22 January 2018 12:45 PM
To: Norrita (LKKAUTO)
Subject: RE: Final Bill SLL 5985U

Without Prejudice

Dear sir

Ok confirm \$8,218.32

Regards

From: Norrita (LKKAUTO) [mailto:norrita@lkkauto.com]
Sent: Monday, January 22, 2018 12:43 PM
To: sim@worldauto.com.sg
Cc: SUR <sur@lkkauto.com>; Rasul (LKKAUTO) <Rasul@lkkauto.com>
Subject: RE: Final Bill SLL 5985U

Dear Mr Sim

Thank you for your email .

Confirm part by part amount nett \$8,218.32 - Repair 8 days.

Best Regards,

Rita AB |

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 email: sur@lkkauto.com | Fax: 6256-4315

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rasul (LKKAUTO)
Sent: Monday, 22 January 2018 12:34 PM
To: SUR <sur@lkkauto.com>
Subject: FW: Final Bill SLL 5985U

Dear Rita

fyi

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

STV #639C

CHIA MOTOR

1301 Bedok North Avenue 4 #03-04A Singapore 48945
Tel: (65) 6243 1373 Fax: (65) 6243 1376

VHA No. 00117

VEHICLE RENTAL AGREEMENT

ROC No. 53165298W

HIRER'S PARTICULAR		ADDITIONAL DRIVER'S PARTICULARS		VEHICLE CHECK LIST		ACCESSORIES CHECK	
Name: (as in I/C) TAN SOOK LENG		Name: (as in I/C) AS REV		INDICATE: A - ACCIDENTS D - DENTS S - SCRATCHES		☐ Radio / Class ☐ STD Tools ☐ Ashtray ☐ Cig Lighter ☐ S/Tyre ☐ Jack ☐ Hub Caps ☐ Cartridges	
NRIC/PASSPORT No: S7305510E		NRIC/PASSPORT No: BK422 PASIR RIS DR. G.		RIGHT FRONT TOP LEFT REAR			
Address (Res) #10-147 S. B10422		Address (Res):		Occupation:			
Tel: (O) _____ (H) _____ HP/Pg _____		Issue Date: _____		Driving Licence No: _____			
Date of Birth: _____		D/L Type: Local / International		Issue Date: _____			
Occupation: _____		Driving Exp: _____		Occupation: _____			
Name & Address of Employer: _____		Driving Exp: _____		Occupation: _____			
Vehicle No: SGA4274L		Mileage Out: _____		Mileage Out: _____			
Make & Model: _____		Auto / Manual		Group: _____			
OUT: Date 17/11/2012 Time: 1800		HIRE/PERIOD EXPIRY		COLLISION DAMAGE WAIVER		YES / NO	
PERSONAL ACCIDENT INSURANCE		YES / NO		CHARGES			
Daily 6 @ 100 per day		Weekly 600.00 per week		Monthly 1800 per month		Hours 1800 per hour	
Others 1800 per hour		CDW 1800 per day/month		PAI 1800 per day/month		Delivery Service	
SUB-TOTAL \$		PETROL LEVEL		Out 1/4 E 1/4 F 1/2		In 1/4 E 1/4 F 1/2	
EXTENSION		Collection Service		Misc.		TOTAL CHARGES \$ 600.00	
Rented out by:		Hirer's Signature		Addition Driver's Signature			

I have read and agree to the terms and condition on both sides of this agreement. If I have presented a charge/ credit card for payment, I agree that all amount payable under this agreement and for parking and traffic infringements may be billed to that account and my signature above will be considered to have been made on the charge/credit card voucher. All information I have given CHIA MOTOR in connection with this agreement is true.

IMPORTANT

1. ONLY PERSON ABOVE 23 YEARS OF AGE WITH MORE THAN 2 YEARS DRIVING EXPERIENCE, AUTHORISED, LICENSED AND SIGNING THIS AGREEMENT MAY DRIVE THE VEHICLE.
 2. ALL PARKING AND TRAFFIC VIOLATIONS ARE THE RESPONSIBILITY OF THE HIRER. AN ADMINISTRATIVE CHARGE WILL BE LEVIED ON ANY TRAFFIC VIOLATIONS REDIRECTED.
 3. THE HIRER SHALL BE LIABLE FOR EXCESS CHARGES FOR ANY LATE RETURN AT THE RATE SHOWN PER HOUR OR PER DAY, INCLUSIVE OF CDW AND FOR PAI WHERE APPLICABLE.
 4. IN CASE OF ACCIDENT, THE HIRER SHALL REPORT TO RENTAL OFFICE IMMEDIATELY. IF THERE IS BODILY INJURIES, A POLICE REPORT MUST BE MADE WITHIN 24 HOURS.
 5. VEHICLE IS STRICTLY FOR SINGAPORE USE ONLY AND MAY NOT BE DRIVEN OUT OF SINGAPORE WITHOUT PRIOR CONSENT OF THE COMPANY CHIA MOTOR RENTAL.
- RETURN OF VEHICLE - THE HIRER / DRIVER IS REQUIRED TO SIGN IN THE COLUMN "SIGNATURE OF HIRER / DRIVER" FAILING WHICH THE DAY AND TIME INSERTED BELOW SHALL BE DEEMED TO BE THE DAY AND TIME THE VEHICLE IS RETURNED TO CHIA MOTOR AND THE SAME SHALL BE ACCEPTED AS CONCLUSIVE EVIDENCE OF THE SAME AND SHALL NOT BE CHALLENGED OR QUESTIONED ON ANY ACCOUNT WHATSOEVER.

DATE IN	TIME IN	MILEAGE	CHECKED BY	REMARKS	SIGNATURE OF HIRER/DRIVER
02/11/12	1800				

From: sim@worldauto.com.sg [<mailto:sim@worldauto.com.sg>]
Sent: Wednesday, 17 January, 2018 11:53 AM
To: Rasul (LKKAuto)
Subject: Re: Final Bill SLL 5985U

Dear sir

Attached final bill SLL 5985U for your reference

Please revert to us soon

Regards

S.T.Sim

World Auto Pte Ltd

No 1 Kranji Loop

Singapore 739535

Mobile: 97588347

Print Date/Time : 17 Jan 2012 / 14:51:54
 Receipt Date/Time : 17 Jan 2012 / 14:51:54

Tax Invoice/Receipt

Receipt No.: ITNET-00000-120117-000754
 Previous Receipt No.:

S/N Item Description/
 Business Transaction Reference No.

As at 17 Jan 2012/11:05:00
 INSURANCE CO:AXA INSURANCE SINGAPORE PTE LTD
 1 Insurance Enquiry - SGZ3282M
 Enquiry Fee
 20120117145030892897

5.35	5.00	0.35	Sub-Total
5.35	5.00	0.35	Total Before Rounding
5.35	5.00	0.35	Rounding Difference
0.00			Total Amount Payable
5.35			Paid By
5.35			20120117145045878
5.35			Direct Debit: eNETS
5.35			Debit (Internet Banking)
5.35			Total
0.00			Cash Change
5.35			Tendered Amount
0.00			Excess Refundable Amount

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

TP (In) MSIG

MWA117151846 / World Auto Pte Ltd - HQ
ENTRY DATE & TIME: 16/11/2017 11:34

Your NCD will be affected due to late reporting
Actual e-Filing Submission Date & Time: 16/11/2017 11:46

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/11/2017 11:34
Date Of Accident	14/11/2017 16:30
Exact Location Of Accident	KIM SENG ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLL5985U
Insured/Policyholder	
Name Of Registered Owner	LCRF PTE LTD
Co Reg No	201624597K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62414992

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL HYBRID-1.5 Z (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	999995174
Cover Note Number	

Driver

Name of Driver	TAM CHEE MOON
NRIC No	S6971863I
Date Of Birth	28/05/1969
Occupation	OUTDOOR
Date Of Driving Pass	22/02/1991
Driving Experience	26 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured PAID DRIVER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Remarks/ Reasons: NO VIDEO TO SHOW
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJY7070B
 Vehicle Make/Model/Colour
 Details Of Properties
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number
 Email Address

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Nov 2017		20 Nov 2017 15:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
[Created by insurer]									
Insured:	ONG BOON HIAN, ID: S7031380D, Tel: +6596720267, Email: po7070@gmail.com								
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Vehicle Reg. No.:	SLL5985U	Date of Loss:	14/11/2017 16:00 - :59						
Claim Type:	TP / 537006	Policy/Cover Note No.:	28968249QMY (Comprehensive) Coverage: 14/06/2017 - 13/06/2018						
Vehicle Reg. No. (Insured):	SJY70708	Policy No. (Claimant):							
		Excess:	S\$600.00						
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 97588347								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 21/11/2017]								
Driver/Custodian (Insured):	ONG BOON HIAN (47 / Male), NRIC: S7031380D, Tel: +6596720267								
ASSOCIATED MAIL RECEIVED									
View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 22 Nov 2017

Preliminary Advice

Insured Vehicle No : SJY7070B

TP Vehicle No : SLL5985U

Accident Date : 14/11/2017

Make : HONDA VEZEL

Assignment Date : 20/11/2017

Date of Inspection : 21/11/2017

Est. Duration of Repair : 8.00

Inspection At : WORLD AUTO PTE LTD - KRANJI (HQ)
NO 1 KRANJI LOOP
SINGAPORE 739535

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,604.72
Revised Amount	:S\$	6,550.72
Check Items (Estimated)	:S\$	2,744.00
Total	:S\$	9,294.72

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

Michelin Engineering Pte Ltd

52 Joo Chiat Road Singapore 427374

Tel : 64404428 Fax : 83458516

Name : Atlantis Car & Truck Rental Pte Ltd
Address : c/o 52 Joo Chiat Road
Singapore 427374

Date : 26-Oct

FINAL REPAIR BILL FOR MITSUBISHI L300 NO. GZ 2179 K

Lump Sum Repair Cost

: \$ 3,100.00

Singapore Dollars : Three Thousand One Hundred Only

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA):
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquires by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date & Time


Driver's Signature (if driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan

Kim Seng Road

14-11-17

A SLL5985U

B SJY 2020B

Bus stop

B

A



Sketch Plan #2

Describe Circumstances of the Accident


On 14-11-17 at 1636hrs when I was waiting for a traffic light at Kim Seng Road in front of me had 2 cars then suddenly S1P 7070B from behind knock to my car.

Declaration

We declare the foregoing particulars are true in every respect



Policyholder's Signature / Date & Time

 14-11-17

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD**Estimate : ES00543**

Date : 16/11/2017

Vehicle Num. : SLL 5985U (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 14/11/2017

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :

- | | | |
|-----|---|---|
| 1. | 1 | REAR TAILGATE (VEZEL) |
| 2. | 1 | REAR TAILGATE HYBRID EMBLEM (VEZEL) |
| 3. | 1 | REAR TAILGATE HONDA EMBLEM(VEZEL) |
| 4. | 1 | REAR TAILGATE VEZEL EMBLEM(VEZEL) |
| 5. | 1 | REAR WINDSCREEN GLASS MOULDING(VEZEL) |
| 6. | 1 | REAR TAILGATE WEATHERSTRIP (VEZEL) |
| 7. | 1 | REAR TAILGATE NUMBER PLATE HOLDER (VEZEL) ? |
| 8. | 1 | REAR TAILGATE INNER TRIM COVER (VEZEL) |
| 9. | 1 | REAR TAILGATE LOCK ASY (VEZEL) |
| 10. | 1 | REAR TAILGATE LOCK CATCH (VEZEL) |
| 11. | 1 | REAR TAILGATE INNER TRIM HOLDER COVER (VEZEL) |
| 12. | 1 | REAR TAILGATE RH REFLECTOR (VEZEL) |
| 13. | 1 | REAR TAILGATE LH REFLECTOR (VEZEL) |
| 14. | 1 | REAR RH TAILLAMP ASSY (VEZEL) |
| 15. | 1 | REAR RH SIDE BUMPER (VEZEL) |
| 16. | 1 | REAR END PANEL TOP GARNISH (VEZEL) ✓ |
| 17. | 1 | REAR END PANEL (VEZEL) |
| 18. | 1 | REAR SPARE TYRE COMPARTMENT PANEL (VEZEL) |
| 19. | 1 | REAR SPARE TYRE COMPARTMENT BOX (VEZEL) |
| 20. | 1 | REAR BUMPER ASSY (VEZEL) |

List TotalS\$:

20.00% Discount S\$:


10,007.90

2,001.58

8,006.32

1,450.00 *Price*
 86.80 *Price*
 81.30 *Price*
 86.80 *Price*
 195.00 *Price*
 155.00 *Price*
 600.00 *Price*
 680.00 *Price*
 550.00 *Price*
 180.00 *Price*
 85.00 *Price*
 480.00 *Price*
 480.00 *Price*
 780.00 *Price*
 258.00 *Price*
 155.00 *Price*
 830.00 *Price*
 1,500.00 *Price*
 420.00 *Price*
 955.00 *Price*

CONTINUE / ...



WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

MSIG INSURANCE (S) PTE LTD**Estimate : ES00543**

Date : 16/11/2017

Vehicle Num. : SLL 5985U (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 14/11/2017

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

SPECIAL NETT ITEMS :

- | | | | | |
|----|---|---|--|--|
| 1. | 1 | REVERSE SENSOR (VEZEL) | | |
| 2. | 1 | REAR WINDSCREEN SEALANT | | |
| 3. | 8 | REAR END PANEL TOP GARNISH (VEZEL) <i>clips</i> | | |
| 4. | 8 | REAR BUMPER CLIPS (VEZEL) | | |

~~280.00~~ 220.00 ✓
~~160.00~~ 80.00 ✓
~~1,240.00~~ 78.40 ✓
 9.80

Special Nett Total S\$:

1,758.40

LABOUR :

TRANSFER TAILGATE DOOR MECHANISM (VEZEL)
 REMOVE AND INSTALL REAR WINDSCREEN (VEZEL)
 To labour charge for removing rear bumper, rear
 tailgate, rear end panel, spare tyre panel out
 to facilitate repairs and replacement of damaged parts
 To respray rear tailgate, rear bumper, end panel
 spare tyre panel, R/R side bumper
 To deactivate and activate high voltage hybrid
 battery as a safety precautions requirements
 To conduct a standard of operating procedure
 post repairs diagnostic scan test as a requirement
 for hybrid cars upon completion of collision repairs

120.00 60
~~160.00~~ 120
 1,600.00 800
 1,200.00 700
 380.00 200
 380.00 200

Labour Total S\$:

3,840.00

E. & O.E.

Total S\$:

13,604.72

for WORLD AUTO PTE LTD

Paul
HP 90010068

8 days
45 9/P

21/11/17 @ 1430

Resy after repair
by part

23/11/17

WORLD AUTO PTE LTD

47 Jalan Pemimpin #01-02/03

Halcyon 2, S'pore 577200

Tel No. : 6451 3933 Fax No. : 6455 7576

E-Mail : worldaut@singnet.com.sg

Website : www.worldauto.com.sg

Tax Reg. No. : 200006765-H Buss. Reg. No. : 200006765H

Page 1/2

Before Paint Survey

Signature

28/11/2017

MSIG INSURANCE (S) PTE LTD

Estimate : ES00543

Attention : Motor Claim Department

Date : 16/11/2017

Vehicle Num. : SLL 5985U (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 14/11/2017

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1	REAR TAILGATE (VEZEL) ✓	✓ 1,450.00	Free
2.	1	REAR TAILGATE HYBRID EMBLEM (VEZEL)	86.80	Ree
3.	1	REAR TAILGATE HONDA EMBLEM(VEZEL)	81.30	Ree
4.	1	REAR TAILGATE VEZEL EMBLEM(VEZEL)	86.80	Ree
5.	1	REAR WINDSCREEN GLASS MOULDING(VEZEL)	195.00	Ree
6.	1	REAR TAILGATE WEATHERSTRIP (VEZEL)	155.00	Ree
7.	1	REAR TAILGATE NUMBER PLATE HOLDER (VEZEL)	600.00	cut
8.	1	REAR TAILGATE INNER TRIM COVER (VEZEL)	680.00	Ree
9.	1	REAR TAILGATE LOCK ASY (VEZEL)	550.00	Ree
10.	1	REAR TAILGATE LOCK CATCH (VEZEL)	180.00	Ree
11.	1	REAR TAILGATE INNER TRIM HOLDER COVER (VEZEL)	86.80	Ree
12.	1	REAR TAILGATE RH REFLECTOR (VEZEL)	480.00	Ree
13.	1	REAR TAILGATE LH REFLECTOR (VEZEL)	480.00	Ree
14.	1	REAR RH TAILLAMP ASSY (VEZEL)	780.00	Ree
15.	1	REAR RH SIDE BUMPER (VEZEL)	258.00	Ree
16.	1	REAR END PANEL TOP GARNISH (VEZEL) ✓	155.00	Ree
17.	1	REAR END PANEL (VEZEL)	830.00	Ree
18.	1	REAR SPARE TYRE COMPARTMENT PANEL (VEZEL)	1,500.00	Ree
19.	1	REAR SPARE TYRE COMPARTMENT BOX (VEZEL)	420.00	Ree
20.	1	REAR BUMPER ASSY (VEZEL)	955.00	Ree
List TotalS\$:			10,007.90	
20.00% Discount S\$:			2,001.58	
			8,006.32	

CONTINUE / ...

JTO PTE LTD

#01-02/03

577200

33 Fax No. : 6455 7576

ut@singnet.com.sg

w.worldauto.com.sg

S. : 200006765-H Buss. Reg. No. : 200006765H

Page 2 / 2

INSURANCE (S) PTE LTD

Estimate : ES00543

Date : 16/11/2017

Vehicle Num. : SLL 5985U (LCR)

Make/Model : HONDA VEZEL HYBRID

Chassis/Eng# :

Accident Date : 14/11/2017

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

SPECIAL NETT ITEMS :

- | | | | | |
|----|---|------------------------------------|--|--|
| 1. | 1 | REVERSE SENSOR (VEZEL) | | |
| 2. | 1 | REAR WINDSCREEN SEALANT | | |
| 3. | 8 | REAR END PANEL TOP GARNISH (VEZEL) | | |
| 4. | 8 | REAR BUMPER CLIPS (VEZEL) | | |

Special Nett Total S\$:

LABOUR :

- TRANSFER TAILGATE DOOR MECHANISM (VEZEL)
- REMOVE AND INSTALL REAR WINDSCREEN (VEZEL)
- To labour charge for removing rear bumper, rear tailgate, rear end panel, spare tyre panel out to facilitate repairs and replacement of damaged parts
- To respray rear tailgate, rear bumper, end panel spare tyre panel, R/R side bumper
- To deactivate and activate high voltage hybrid battery as a safety precautions requirements
- To conduct a standard of operating procedure post repairs diagnostic scan test as a requirement for hybrid cars upon completion of collision repairs

Labour Total S\$:

280.00 220 net
150.00 80 net
1,240.00 1,240.00
9.80 78.40 net
30 30
1,758.40

120.00 60
150.00 120
1,600.00 800
1,200.00 700
380.00 200
380.00 200
2080

3,840.00

E. & O.E.

Total S\$: 13,604.72

WORLD AUTO PTE LTD

Paint 7220-90
1er 200 1400 50

SN 5 1718-32
360 W
2080 W
over 828-32

8 days

Paint
HP 90010068

8 days
4/5 P/P

24/11/17 @ 1430

Repy after repair
by paint

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	15 Nov 2017		20 Nov 2017 15:57 Edit Adj Rpt	S\$8,218.32 Edit Estimates	S\$8,218.32 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	ONG BOON HIAN, ID: S7031380D, Tel: +6596720267, Email: po7070@gmail.com		
Main Claimant:	LCRF PTE LTD, Co. Reg. No.: 201624597K		
Vehicle Reg. No.:	SLL5985U	Date of Loss:	14/11/2017 16:00 - :59
Claim Type:	TP / 537006	Policy/Cover Note No.:	28968249QMY (Comprehensive) Coverage: 14/06/2017 - 13/06/2018
Vehicle Reg. No. (Insured):	SJY7070B	Policy No. (Claimant):	
		Excess:	S\$600.00
Repairer:	World Auto Pte Ltd - Kranji (HQ) No 1 Kranji Loop, 739535 Kranji - Tel: 97588347		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 20/12/2017]		
Driver/Custodian (Insured):	ONG BOON HIAN (47 / Male), NRIC: S7031380D, Tel: +6596720267		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLL5985U (537006)**
[SJY7070B]
TP
LCRF PTE LTD
Nov 14 2017 4:00PM
[ONG BOON HIAN]
World Auto Pte Ltd - Kranji

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/11/17 15:56	Accident Statement From:OD - Reg. No: SJY7070B, Claimant: ONG BOON HIAN	 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/11/17 16:19	Adjuster Immediate Advice	 Load HTM	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/11/17 16:12	General View	 Load JPG	☒
2	22/11/17 16:12	General View	 Load JPG	☒
3	22/11/17 16:12	General View	 Load JPG	☒
4	22/11/17 16:12	General View	 Load JPG	☒
5	22/11/17 16:12	General View	 Load JPG	☒
6	22/11/17 16:12	General View	 Load JPG	☒
7	22/11/17 16:12	General View	 Load JPG	☒
8	22/11/17 16:12	General View	 Load JPG	☒
9	22/11/17 16:12	General View	 Load JPG	☒
10	22/11/17 16:12	General View	 Load JPG	☒
11	22/11/17 16:12	General View	 Load JPG	☒
12	22/11/17 16:12	General View	 Load JPG	☒
13	22/11/17 16:13	General View	 Load JPG	☒
14	22/11/17 16:13	General View	 Load JPG	☒
15	22/11/17 16:13	General View	 Load JPG	☒
16	22/11/17 16:13	General View	 Load JPG	☒
17	22/11/17 16:13	General View	 Load JPG	☒
18	22/11/17 16:13	General View	 Load JPG	☒
19	22/11/17 16:13	General View	 Load JPG	☒
20	22/11/17 16:13	General View	 Load JPG	☒
21	22/11/17 16:13	General View	 Load JPG	☒
22	22/11/17 16:13	General View	 Load JPG	☒
23	22/11/17 16:13	General View	 Load JPG	☒
24	22/11/17 16:13	General View	 Load JPG	☒
25	22/11/17 16:13	General View	 Load JPG	☒
26	22/11/17 16:13	General View	 Load JPG	☒
27	22/11/17 16:13	General View	 Load JPG	☒
28	22/11/17 16:13	General View	 Load JPG	☒
29	22/11/17 16:13	General View	 Load JPG	☒
30	22/11/17 16:13	General View	 Load JPG	

					☒
31	22/11/17 16:13	General View	1	Load JPG	☒
32	22/11/17 16:13	General View	1	Load JPG	☒
33	22/11/17 16:13	General View	1	Load JPG	☒
34	22/11/17 16:13	General View	1	Load JPG	☒
35	22/11/17 16:13	General View	1	Load JPG	☒
36	22/11/17 16:13	General View	1	Load JPG	☒
37	22/11/17 16:13	General View	1	Load JPG	☒
38	22/11/17 16:13	General View	1	Load JPG	☒
39	22/11/17 16:13	General View	1	Load JPG	☒
40	22/11/17 16:13	General View	1	Load JPG	☒
41	22/11/17 16:13	General View	1	Load JPG	☒
42	22/11/17 16:13	General View	1	Load JPG	☒
43	22/11/17 16:13	General View	1	Load JPG	☒
44	22/11/17 16:13	General View	1	Load JPG	☒
Documentation				1 per page v	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	20/11/17 15:56	TPD SLL5985U GIA REPORT	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG170221668/R1NBE2

Date: 24/01/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28968249QMY

Claimant Vehicle No : SLL5985U

Insured Vehicle No : SJY7070B

Date of Loss: 14/11/2017

Nature of Claim: TP

Claim No: 537006

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL5985U

Make & Model: HONDA VEZEL, 1.5 HYBRID X (A)

Engine No: LEB5913265

Reg. Date: 02/03/2017 (Man. Year: 2016)

Chassis No: RU31213254

Colour: Red

Odometer: 40691 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size: 215/60 R16

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,764.72	6,138.32	3,626.40	37.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,840.00	2,080.00	1,760.00	45.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	13,604.72	8,218.32	5,386.40	39.59
+ GST 7.00/7.00% (S\$)	952.33	575.28	377.05	39.59
Nett Amount (S\$)	14,557.05	8,793.60	5,763.45	39.59

INSPECTION

Date of Assignment: 20/11/2017

Date Inspected: 21/11/2017

Inspected At: World Auto Pte Ltd - Kranji (HQ)
No 1 Kranji Loop
Singapore 739535

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: LOW AI PHING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 24 Jan 2018)

Parts: M1-SUV **HONDA VEZEL 1.5 HYBRID X (A)** (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLL5985U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE (VEZEL)	Buckled	1,450.00 FL	*1,450.00 FL
2	1		*REAR TAILGATE HYBRID EMBLEM (VEZEL)	Necessary	86.80 FL	*86.80 FL
3	1		*REAR TAILGATE HONDA EMBLEM (VEZEL)	Necessary	81.30 FL	*81.30 FL
4	1		*REAR TAILGATE VEZEL EMBLEM (VEZEL)	Necessary	86.80 FL	*86.80 FL
5	1		*REAR WINDSCREEN GLASS MOULDING (VEZEL)	Necessary	195.00 FL	*195.00 FL
6	1		*REAR TAILGATE WEATHERSTRIP (VEZEL)	Necessary	155.00 FL	*155.00 FL
7	1		*REAR TAILGATE NUMBER PLATE HOLDER (VEZEL)	Serviceable	600.00 FL	*- FL
8	1		*REAR TAILGATE INNER TRIM COVER (VEZEL)	Deformed	680.00 FL	*680.00 FL
9	1		*REAR TAILGATE LOCK ASY (VEZEL)	Jammed	550.00 FL	*550.00 FL
10	1		*REAR TAILGATE LOCK CATCH (VEZEL)	Serviceable	180.00 FL	*- FL
11	1		*REAR TAILGATE INNER TRIM HOLDER COVER (VEZEL)	Serviceable	85.00 FL	*- FL
12	1		*REAR TAILGATE RH REFLECTOR (VEZEL)	Cracked	480.00 FL	*480.00 FL
13	1		*REAR TAILGATE LH REFLECTOR (VEZEL)	Broken	480.00 FL	*480.00 FL
14	1		*REAR RH TAILLAMP ASSY (VEZEL)	Broken	780.00 FL	*780.00 FL
15	1		*REAR RH SIDE BUMPER (VEZEL)	Deformed	258.00 FL	*258.00 FL
16	1		*REAR END PANEL TOP GARNISH (VEZEL)	Bent	155.00 FL	*155.00 FL
17	1		*REAR END PANEL (VEZEL)	Bent	830.00 FL	*830.00 FL
18	1		*REAR SPARE TYRE COMPARTMENT PANEL (VEZEL)	Serviceable	1,500.00 FL	*- FL
19	1		*REAR SPARE TYRE COMPARTMENT BOX (VEZEL)	Serviceable	420.00 FL	*- FL
20	1		*REAR BUMPER ASSY (VEZEL)	Deformed	955.00 FL	*955.00 FL
21	1		*REVERSE SENSOR (VEZEL)	Not Working	280.00 FS	*220.00 FS
22	1		*REAR WINDSCREEN SEALANT	Necessary	160.00 FS	*80.00 FS
23	8		*REAR END PANEL TOP CLIPS	Necessary	1,240.00 FS	*30.00 FS
24	8		*REAR BUMPER CLIPS (VEZEL)	Necessary	78.40 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,766.30	7,582.90
- List Item Discount on L Items 20.00/20.00% (S\$)	2,001.58	1,444.58
Total Parts (S\$)	9,764.72	6,138.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER TAILGATE DOOR MECHANISM (VEZEL)	New	120.00	60.00
2	REMOVE AND INSTALL REAR WINDSCREEN (VEZEL)	New	160.00	120.00
3	TO LABOUR CHARGE FOR REMOVING REAR BUMPER, REAR TAILGATE, REAR END PANEL, SPARE TYRE PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,600.00	800.00
4	TO RESPRAY REAR TAILGATE, REAR BUMPER, END PANEL SPARE TYRE PANEL, R/R SIDE BUMPER	New	1,200.00	700.00
5	TO DEACTIVATE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A SAFETY PRECAUTIONS REQUIREMENTS	New	380.00	200.00
6	TO CONDUCT A STANDARD OF OPEARTING PROCEDURE POST REPAIRS DIAGNOSTIC SCAN TEST AS A REQUIREMENT FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS	New	380.00	200.00
Gross Labour Cost (S\$)			3,840.00	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

