

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: FWD Singapore Pte. Ltd.
6 Temasek Boulevard
#18-01 Suntec Tower 4
Singapore 038986

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Clara Li Zi Rong

Date: 23 Nov 2017

Preliminary Advice

Vehicle No	: SDX2929J	Accident Date	: 17/11/2017
Make	: HONDA CIVIC	Policy No.	: PNPV2017-00000521
Assignment Date	: 21/11/2017	Excess	: S\$600.00
Date of Inspection	: 21/11/2017	Est. Duration of Repair	: 0.00
Inspection At	: TORQUE 5 PTE LTD (KAKI BUKIT) NO. 8 KAKI BUKIT AVE 4,, #01-50 SINGAPORE 415875		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,567.50
Revised Amount	:S\$	6,132.50
Check Items (Estimated)	:S\$	983.00
Total	:S\$	7,115.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	13,500.00
COE / PARF Rebate	:S\$	11,742.00
Salvage Value	:S\$	
Margin for Repair	:S\$	1,758.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :