



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT

EQ INSURANCE COMPANY LTD

Ref: CS3/EQ117022170/Gbe2

5 MAXWELL ROAD M#17-00 TOWER BLOCK MND
COMPLEXSINGAPORE 069110

Date: 29-03-2018



Code: EQI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBC 2608U	Veh. Inspected	SKX 9352T
Policy No.		Coverage (\$)	0.00
Claim No.	DM17HO02604/JT	Excess (\$)	0.00
Assign From	BAZLIN AHMAD	Assign Date	21/11/2017

2. Vehicle Particulars & Condition


Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11105757	Colour	BLACK
Odometer	20932 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.



5. General Information

Accident Date	18/11/2017	Inspect Date / Time	22/11/2017 (12:30 PM)
Survey held at	RYDER AUTO WORKSHOP LLP 1 KAKI BUKIT AVE 6 #01-56 SINGAPORE 417883		

5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
 B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
 THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
 C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
 D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$8,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **8 Working Days**

Report Ref No. CS3/EQ117022170/Gbe2

Inspected By

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.