

INS. CASE OWNER:

CC 6/CTI1702

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE

Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES/ NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

Confirm by:

REALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

SS

%

(Agreed / Assessed) BOLA S/N No.:

15

Repair Cost:

SS

(

days) Reduction:

%

Loss of Rental (LOR):

SS

(

days) Reduction:

%

Loss of Use (LOU):

SS

(\$30.00 x 11 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only

LOU only

SS

LOR + LOU

LOR + LOI

(Tick only one)

GIA LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

Total:

SS

\$8,883.85

Global Sum SS:

\$8,880.00

L PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

\$8,880.00

Name 1:

Lee Brothers Automotive Pte. Ltd.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

If NO or B 28, Ass. Lia:

OZO changed lane and collided

with TP.

COP 178

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP.

3) Survey fee: \$400.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI17022172/Upb3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 21-11-2017



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 2944C	Veh. Inspected	PLU 1588
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	18/11/2017	Inspection Date	21/11/2017
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/CTI17022172/Upb3

Date: 22.11.2017

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.


PLU1588

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 21.11.2017 at the premises of M/s LEE BROTHERS AUTOMOTIVE PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$	13,714.90
Revised Estimate Amount	: S\$	7,155.50
"Check" Items Amount	: S\$	2,587.50
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
O/S Body



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 8 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

XE 2944C

ESTIMATE

DATE : 20/11/2017

VEHICLE NO : PLU 1588

MAKE/MODEL : MIT. ATTRAGE

ACC DATE : 18/11/2017

p Not Adult
nu
1/s H7850h
Sty.
take, W. Alhage
21/11/17

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
	<u>LIST PRICE</u>		
1	1 REAR BUMPER	Deepcut 659.00	659.00 ✓
2	2 REAR BUPER SIDE RETAINER RH/LH	O/S Bay 32.00	64.00 1p c
3	1 REAR FENDER RH	2.1/20/Ref 725.00	725.00 ✓
4	1 REAR FENDER LOWER SHIELD RH	1.1 46.00	46.00 X
5	1 REAR SPORT RIM RH	C-17 645.00	645.00 3005.2
6	1 REAR SHOCK ABSORBER RH	Tur 225.00	225.00 ✓
7	1 REAR AXLE	1.1 939.00	939.00 X
8	1 REAR AXLE WHEEL BEARING RH	2.1/20 110.00	110.00 ✓
9	1 REAR DOOR RH	Body 845.00	845.00 ✓
10	1 REAR DOOR TOP HINGE RH	Ref 49.00	49.00 ✓
11	1 REAR DOOR BOTTOM HINGE RH	Ref 49.00	49.00 ✓
12	1 REAR DOOR CHECKER RH	Tur 52.00	52.00 ✓
13	1 REAR DOOR RUBBER RH	To.1 129.00	129.00 ✓
14	1 REAR DOOR LOCK RH	4.1/5.1/6.1 290.00	290.00 ?
15	1 REAR DOOR INNER SPEAKER RH	Cue 155.00	155.00 ?
16	1 REAR DOOR INNER TRIM BOARD RH	2.1/20 472.00	472.00 ?
17	1 REAR DOOR GLASS CHANNEL RH	1.1 101.00	101.00 X
18	1 REAR DOOR GLASS REGULATOR RH	Ref 119.00	119.00 ?
19	1 REAR DOOR GLASS REGULATOR MOTOR RH	Shut 352.00	352.00 ✓
20	1 REAR DOOR BLACK TAPE RH	ner 27.00	27.00 ✓
21	1 REAR DOOR OUTER HANDLE RH	n 92.00	92.00 X
22	1 DOOR CENTRE PILLAR RH	n 982.00	982.00 ✓
23	1 FRONT DOOR RH	10/12/14 752.00	752.00 ✓
24	1 FRONT DOOR RUBBER RH	ner 168.00	168.00 ✓
25	1 FRONT DOOR INNER SPEAKER RH	1.1 155.00	155.00 X
26	1 FRONT DOOR LOCK RH	Tur 290.00	290.00 ?
27	1 FRONT DOOR INNER TRIM BOARD RH	Ref 495.00	495.00 ?
28	1 FRONT DOOR GLASS RH	1.1 375.00	375.00 X
29	1 FRONT DOOR GLASS CHANNEL RH	1.1 113.00	113.00 X
30	1 FRONT DOOR GLASS REGULATOR RH	Ref 125.00	125.00 ✓
31	1 FRONT DOOR GLASS REGULATOR MOTOR RH	Shut 352.00	352.00 ✓
32	1 FRONT DOOR BLACK TAPE RH	ner 27.00	27.00 ✓

LEE BROTHERS AUTOMOTIVE PTE. LTD.

33	1	FRONT DOOR OUTER HANDLE RH	92.00	CU7	92.00	✓
34	1	FRONT DOOR VIEW MIRROR RH	604.00	SW	604.00	✓
35	1	FRONT DOOR VIEW MIRROR COVER RH	103.00	CU7	103.00	✓
36	1	FRONT DOOR VIEW MIRROR SIGNAL LAMP RH	151.00	17	151.00	✓
	1	FRONT FENDER QUARTER GARNISH RH	32.00	garnish	32.00	✓
					10,961.00	
			LESS 10%		1,096.10	
					9,864.90	

7330

6597

SPECIAL NETT ITEMS

1	1	REAR WINDSCREEN SPONGE TAPE	20.00	neu	20.00	✓
2	1	(SET) FRT WINDSCREEN SEALANT	80.00	neu	80.00	40
3	1	(SET) REAR BOOT INNER TRIM CLIPS	45.00	17	45.00	✓
4	1	(SET) REAR BUMPER CLIP	35.00	neu	35.00	✓
5	1	REAR TYRE RH	200.00	gms	200.00	60% 120
6	1	FRONT FENDER EMBLEM RH	50.00	neu	50.00	✓
			BALANCE B/F		430.00	

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT/WELD REAR FENDER RH AND REPAIR FENDER INNER PANEL AND REPLACE ACCIDENT PARTS	1000	1,200.00	
2	TO SPRAY PAINTING ON ACCIDENT PARTS	1000	1,200.00	
3	TO REMOVE, REFIX REAR WINDSCREEN		120.00	✓
4	TO REMOVE, REFIX CUSHION AND INNER TRIM	80	120.00	
5	TO REMOVE, REPLACE REVERSE SENSOR	50	80.00	
6	TO REMOVE, REPLACE REAR UNDERCARRIGE	120	300.00	
7	4 WHEEL ALIGNMENT	60	80.00	
8	TO TRANSFER 2 DOOR PARTS	120	160.00	
9	TO TUFF KOTE		100.00	✓
10	TOWING		60.00	✓
			3,420.00	

9572

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 13,714.90

4872

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

XE 2944C

ESTIMATE

DATE : 20/11/2017

VEHICLE NO : PLU 1588

MAKE/MODEL : MIT. ATTRAGE

ACC DATE : 18/11/2017

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
	<u>LIST PRICE</u>		
1	1 REAR BUMPER	659.00	659.00 ✓
2	2 REAR BUPER SIDE RETAINER RH/LH	32.00	64.00 ✓
3	1 REAR FENDER RH	725.00	725.00 ✓
4	1 REAR FENDER LOWER SHIELD RH	46.00	46.00 X
5	1 REAR SPORT RIM RH	645.00	645.00 3005.00
6	1 REAR SHOCK ABSORBER RH	225.00	225.00 ?
7	1 REAR AXLE	939.00	939.00 X
8	1 REAR AXLE WHEEL BEARING RH	110.00	110.00 ?
9	1 REAR DOOR RH	845.00	845.00 ✓
10	1 REAR DOOR TOP HINGE RH	49.00	49.00 ✓
11	1 REAR DOOR BOTTOM HINGE RH	49.00	49.00 ✓
12	1 RAER DOOR CHECKER RH	52.00	52.00 ✓
13	1 REAR DOOR RUBBER RH	129.00	129.00 ✓
14	1 REAR DOOR LOCK RH	290.00	290.00 ?
15	1 REAR DOOR INNER SPEAKER RH	155.00	155.00 ?
16	1 REAR DOOR INNER TRIM BOARD RH	472.00	472.00 ?
17	1 REAR DOOR GLASS CHANNEL RH	101.00	101.00 X
18	1 RAER DOOR GLASS REGULATOR RH	119.00	119.00 ?
19	1 REAR DOOR GLASS REGULATOR MOTOR RH	352.00	352.00 ?
20	1 REAR DOOR BLACK TAPE RH	27.00	27.00 ✓
21	1 REAR DOOR OUTER HANDLE RH	92.00	92.00 X
22	1 DOOR CENTRE PILLAR RH	982.00	982.00 ✓
23	1 FRONT DOOR RH	752.00	752.00 ✓
24	1 FRONT DOOR RUBBER RH	168.00	168.00 ✓
25	1 FRONT DOOR INNER SPEAKER RH	155.00	155.00 X
26	1 FONT DOOR LOCK RH	290.00	290.00 ?
27	1 FRONT DOOR INNER TRIM BOARD RH	495.00	495.00 ?
28	1 FRONT DOOR GLASS RH	375.00	375.00 X
29	1 FRONT DOOR GLASS CHANNEL RH	113.00	113.00 X
30	1 FRONT DOOR GLASS REGULATOR RH	125.00	125.00 ?
31	1 FRONT DOOR GLASS REGULATOR MOTOR RH	352.00	352.00 ?
32	1 FRONT DOOR BLACK TAPE RH	27.00	27.00 ✓

Not Submit
1/5
21/11/17

LEE BROTHERS AUTOMOTIVE PTE. LTD.

33	1	FRONT DOOR OUTER HANDLE RH	92.00	<i>cut</i>	92.00	✓
34	1	FRONT DOOR VIEW MIRROR RH	604.00	<i>310</i>	604.00	✓
35	1	FRONT DOOR VIEW MIRROR COVER RH	103.00	<i>cut</i>	103.00	✓
36	1	FRONT DOOR VIEW MIRROR SIGNAL LAMP RH	151.00	<i>17</i>	151.00	✓
	1	FRONT FENDER QUARTER GARNISH RH	32.00	<i>garnish</i>	32.00	✓
					10,961.00	
			LESS 10%		1,096.10	
					9,864.90	

SPECIAL NETT ITEMS

1	1	REAR WINDSCREEN SPONGE TAPE	20.00	<i>new</i>	20.00	✓
2	1	(SET) FRT WINDSCREEN SEALANT	80.00	<i>new</i>	80.00	✓
3	1	(SET) REAR BOOT INNER TRIM CLIPS	45.00	<i>17</i>	45.00	✓
4	1	(SET) REAR BUMPER CLIP	35.00	<i>new</i>	35.00	✓
5	1	REAR TYRE RH	200.00	<i>gumb</i>	200.00	✓
6	1	FRONT FENDER EMBLEM RH	50.00	<i>new</i>	50.00	✓
			BALANCE B/F		430.00	

LABOUR CHARGES :

1	TO KNOCK OUT DENT, CUT/WELD REAR FENDER RH AND REPAIR FENDER INNER PANEL AND REPLACE ACCIDENT PARTS	<i>1000</i>	1,200.00	
2	TO SPRAY PAINTING ON ACCIDENT PARTS	<i>1000</i>	1,200.00	
3	TO REMOVE, REFIX REAR WINDSCREEN		120.00	✓
4	TO REMOVE, REFIX CUSHION AND INNER TRIM	<i>80</i>	120.00	
5	TO REMOVE, REPLACE REVERSE SENSOR	<i>50</i>	80.00	
6	TO REMOVE, REPLACE REAR UNDERCARRIGE	<i>120</i>	300.00	
7	4 WHEEL ALIGNMENT	<i>60</i>	80.00	
8	TO TRANSFER 2 DOOR PARTS	<i>120</i>	160.00	
9	TO TUFF KOTE		100.00	✓
10	TOWING		60.00	✓
				3,420.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$ 13,714.90

Shu Pei (LKKAUTO)

From: Irene Tay <irene.tay@sg.cntaiping.com>
Sent: Tuesday, 28 November, 2017 4:21 PM
To: Shu Pei (LKKAUTO)
Subject: CTP REF NO. SNM17D06693C02 LKK REF NO. CC6/CT117022172/UPB3 - ACCIDENT INVOLVING XB2944C AND PLU1588 ON 18 NOVEMBER 2017
Attachments: GIA REPORT XE2944C.pdf; TayHp_CLCR95.782.pdf

WITHOUT PREJUDICE

Dear Sir/Mdm,

We refer to the above matter and your email dated 27 November 2017.

We enclosed herewith a copy of our Insured GIA Report & Letter to our Insured for your attention.

Regards,

Irene Tay

Claims Department
China Taiping Insurance (Singapore) Pte. Ltd.
3, Anson Road, #16-00
Springleaf Tower,
Singapore 079909
Co. Reg. No. 200208384E
DID: 6389-6192
Fax: 6224 7175
Email: claimsdept@sg.cntaiping.com
Email: irene.tay@sg.cntaiping.com
Website: www.sg.cntaiping.com

Zaini (LKK Auto)

From: Zaini (LKK Auto)
Sent: Wednesday, 28 February 2018 12:18 PM
To: 'Karen'
Cc: Hsiao Tong (LKKAuto)
Subject: RE: Your Ref: LB1117-2351_ACCIDENT INVOLVING XE 2944C & PLU 1588 ON 18/11/2017
Attachments: CTI RV PLU1588 18112017.pdf

WITHOUT PREJUDICE

Dear Karen,

We refer to our previous tele-conversation.

We confirmed global settlement at **\$8,880.00(all in)** for the above matter.

Thank you for acceptance.

Kindly refer to the attached DV above and forward your signed DV and Rental invoice in **ORIGINAL HARDCOPY** via post for our necessary action.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Karen [mailto:karen@leebrothers.com.sg]
Sent: Tuesday, 20 February 2018 3:20 PM
To: Zaini (LKK Auto) <Zaini@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: Your Ref: LB1117-2351_ACCIDENT INVOLVING XE 2944C & PLU 1588 ON 18/11/2017
Importance: High

Dear Zaini,

We would like to counter propose \$ 8950/- all in.

Thanks & Best Regards

Ms Karen
Lee Brothers Automotive Pte Ltd

1 Kaki Bukit Ave 6
#02-47 Autobay
Singapore 417883
Tel: 6509 5521
Fax: 6509 5523

From: Zaini (LKK Auto) [<mailto:Zaini@lkkauto.com>]
Sent: Wednesday, 14 February, 2018 10:58 AM
To: Karen
Cc: Hsiao Tong (LKKAuto)
Subject: RE: Your Ref: LB1117-2351_ACCIDENT INVOLVING XE 2944C & PLU 1588 ON 18/11/2017

WITHOUT PREJUDICE

Dear Karen,

We refer to your email below.

For a quick and amicable settlement, we revised our offer to settle global sum at S\$ 8,880.00 (all in)

Note: Your client's vehicle is a foreign vehicle.

Kindly confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Karen [<mailto:karen@leebrothers.com.sg>]
Sent: Tuesday, 6 February 2018 11:38 AM
To: Zaini (LKK Auto) <Zaini@lkkauto.com>
Cc: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: RE: Your Ref: LB1117-2351_ACCIDENT INVOLVING XE 2944C & PLU 1588 ON 18/11/2017

Dear Zaini,

We would like to counter propose as below.

COR	\$ 8399.50
LOU	\$ 550.00 (11 days)
TOWING	\$120.00
LTA/EFILE	\$ 34.35

Please revert soon.

Thanks & Best Regards

Ms Karen
Lee Brothers Automotive Pte Ltd
1 Kaki Bukit Ave 6
#02-47 Autobay
Singapore 417883
Tel: 6509 5521
Fax: 6509 5523

From: Zaini (LKK Auto) [<mailto:Zaini@lkkauto.com>]
Sent: Monday, 5 February, 2018 3:56 PM
To: Karen
Cc: Hsiao Tong (LKKAuto)
Subject: Your Ref: LB1117-2351_ACCIDENT INVOLVING XE 2944C & PLU 1588 ON 18/11/2017

WITHOUT PREJUDICE

Your Ref: LB1117-2351
Our Ref: CC6/CTI17022172/Ukb3s2

Dear Karen,

ACCIDENT INVOLVING XE 2944C & PLU 1588 ON 18/11/2017

We refer to the above matter

For a quick and amicable settlement, we offer to settle global sum at **S\$ 8,850.00 (all in)**

Kindly confirm acceptance.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Best Regards,

Zaini Kusaini | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2132 | email: Zaini@lkkauto.com | fax: 6741-4108

Blk 51, PayaUbi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI17022172/Ukb3s2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 06-03-2018



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 2944C	Veh. Inspected	PLU 1588
Policy No.	DMCVSN1734181700	Coverage (\$)	0.00
Claim No.	SNM17D06693C02/4	Excess (\$)	0.00
Assign From		Assign Date	21/11/2017

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI ATTRAGE (A)	c.c	1193
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	MMBSTA13AEH011781	Colour	GREY
Odometer	17234	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/60R15	BRIDGESTONE	6 mm
L/H Front Tyre	185/60R15	BRIDGESTONE	6 mm
R/H Rear Tyre	185/60R15	BRIDGESTONE	6 mm
L/H Rear Tyre	185/60R15	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	18/11/2017	Inspection Date	21/11/2017
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PLU 1588

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DEEP CUT	659.00	659.00
2	REAR BUMPER SIDE RETAINER RH/LH !@ \$32.00	O/S BENT	64.00	32.00
1	REAR FENDER RH	BADLY DENTED / BENT	725.00	725.00
1	REAR FENDER LOWER SHIELD RH	NOT NECESSARY	46.00	-
1	REAR SHOCK ABSORBER RH	TWISTED	225.00	225.00
1	REAR AXLE	NOT NECESSARY	939.00	-
1	REAR AXLE WHEEL BEARING RH	DAMAGED	110.00	110.00
1	REAR DOOR RH	BADLY DENTED / CRACKED	845.00	845.00
1	REAR DOOR TOP HINGE RH	BENT	49.00	49.00
1	REAR DOOR BOTTOM HINGE RH	BENT	49.00	49.00
1	REAR DOOR CHECKER RH	TWISTED	52.00	52.00
1	REAR DOOR RUBBER RH	TORN	129.00	129.00
1	REAR DOOR LOCK RH	TWISTED / SHORTED	290.00	290.00
1	REAR DOOR INNER SPEAKER RH	CRACKED	155.00	155.00
1	REAR DOOR INNER TRIM BOARD RH	DEFORMED / CRACKED	472.00	472.00
1	REAR DOOR GLASS CHANNEL RH	NOT NECESSARY	101.00	-
1	REAR DOOR GLASS REGULATOR RH	BENT	119.00	119.00
1	REAR DOOR GLASS REGULATOR MOTOR RH	SHORTED	352.00	352.00
1	REAR DOOR BLACK TAPE RH	NECESSARY	27.00	27.00
1	REAR DOOR OUTER HANDLE RH	TO REPAIR SEE LABOUR	92.00	-
1	DOOR CENTRE PILLAR RH	TO REPAIR SEE LABOUR	982.00	-
1	FRONT DOOR RH	DENTED / BENT	752.00	752.00
1	FRONT DOOR RUBBER RH	NECESSARY	168.00	168.00
1	FRONT DOOR INNER SPEAKER RH	NOT NECESSARY	155.00	-
1	FRONT DOOR LOCK RH	TWISTED	290.00	290.00
1	FRONT DOOR INNER TRIM BOARD RH	DEFORMED / CRACKED	495.00	495.00

Report Ref No. CC6/CT117022172/Ukb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT DOOR GLASS RH	NOT NECESSARY	375.00	-
1	FRONT DOOR GLASS CHANNEL RH	NOT NECESSARY	113.00	-
1	FRONT DOOR GLASS REGULATOR RH	BENT	125.00	125.00
1	FRONT DOOR GLASS REGULATOR MOTOR RH	SHORTED	352.00	352.00
1	FRONT DOOR BLACK TAPE RH	NECESSARY	27.00	27.00
1	FRONT DOOR OUTER HANDLE RH	CUT	92.00	92.00
1	FRONT DOOR VIEW MIRROR RH	BROKEN	604.00	604.00
1	FRONT DOOR VIEW MIRROR COVER RH	CUT	103.00	103.00
1	FRONT DOOR VIEW MIRROR SIGNAL LAMP RH	NOT NECESSARY	151.00	-
1	FRONT FENDER QUARTER GARNISH RH	GRAZED	32.00	32.00
	LESS 10% DISCOUNT		-1,031.60	-733.00
			9,284.40	6,597.00
1	REAR SPORT RIM RH (SN)	CUT	645.00	300.00
	LESS 10% DISCOUNT		-64.50	-
			580.50	300.00
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SPONGE TAPE (SN)	NECESSARY	20.00	20.00
1	SET FRT WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR BOOT INNER TRIM CLIPS (SN)	NOT NECESSARY	45.00	-
1	SET REAR BUMPER CLIP (SN)	NECESSARY	35.00	35.00
1	REAR TYRE RH (60%) (SN)	GRAZED	200.00	120.00
1	FRONT FENDER EMBLEM RH (SN)	NECESSARY	50.00	50.00
			430.00	265.00
	<u>LABOUR</u>			
	TO KNOCK OUT DENT, CUT / WELD REAR FENDER RH AND REPAIR FENDER INNER PANEL AND REPLACE ACCIDENT PARTS. INCLUSIVE OF THE REPAIR OF REAR DOOR OUTER HANDLE RH AND DOOR CENTRE PILLAR RH.		1,200.00	1,000.00
	TO SPRAY PAINTING ON ACCIDENT PARTS.		1,200.00	1,000.00
	TO REMOVE, REFIX REAR WINDSCREEN.		120.00	120.00
	TO REMOVE, REFIX CUSHION AND INNER TRIM.		120.00	80.00

Report Ref No. CC6/CT117022172/Ukb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE, REPLACE REVERSE SENSOR.		80.00	50.00
	TO REMOVE, REPLACE REAR UNDERCARRIAGE.		300.00	120.00
	4 WHEEL ALIGNMENT.		80.00	60.00
	TO TRANSFER 2 DOOR PARTS.		160.00	120.00
	TO TUFF KOTE.		100.00	100.00
	TOWING.		60.00	60.00
			3,420.00	2,710.00
	GRAND TOTAL		13,714.90	9,872.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,850.00

Report Ref No. CC6/CT117022172/Ukb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.