

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883
TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg
GST:200712509E RCB NO:200712509E

not Ardent
nu
1/5 a
6 Lg.

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET
#04-#05 IOB BUILDING
SINGAPORE 049711

TEL: 6347 6100

FAX: 6224 4174

ATTN: Motor Claim Department

Your Ref No: SLE1158D

Claim Type: Third Party

Accident Date: 18-11-2017

TP Veh Reg No: SHD4604R

Estimate No: EST0000521

Date: 21 Nov 2017

Policy No: 5090133686

Veh Reg No: SLE1158D

Make/Model: HONDA VEZEL

Chassis No: RU11115101

Engine No: L15B4035107

Reg. Date: 08-07-2016

Estimate Repair Cost to Vehicle No :SLE1158D

Description	U/Price	Quantity	List Price S\$	Amount S\$
HONDA VEZEL 1.5x				
List Price				
1 Front Fender RH	558.70	1 PC	558.70	
2 Front Fender Dust Cover RH	130.00	1 PC	130.00	
3 Front Fender Dust Cover Clipse RH	5.50	6 PC	33.00	
4 Front Fender Protector RH	153.00	1 PC	153.00	
5 Front Head Lamp RH	1,780.60	1 PC	1,780.60	
6 Front Bumper	801.70	1 PC	801.70	
7 Front Bumper Side Retainer RH	16.00	1 PC	16.00	
8 Front Bumper Lower Skirt	351.00	1 PC	351.00	
9 Front Bumper Fog Lamp Cover RH	40.60	1 PC	40.60	
10 Front Wheel Housing RH Member	400.60	1 PC	400.60	
11 Front Sport Rim	903.20	2 PC	1,806.40	700% w
12 Front Steering Rack & Pinion	1,750.60	1 PC	1,750.60	
13 Front Steering Ball Joint	80.00	2 PC	160.00	
14 Front Shock Absorber	480.70	2 PC	961.40	
15 Front Shock Absorber Top Mounting	80.50	2 PC	161.00	
16 Front Cross Member	950.20	1 PC	950.20	
17 Front Knuckle Arm	390.10	2 PC	780.20	
18 Front Hub Bearing	191.40	2 PC	382.80	
19 Front Lower Arm	350.60	2 PC	701.20	
20 Front Rod Link RH	110.40	1 PC	110.40	
21 Front Drive Shaft RH	1,054.10	1 PC	1,054.10	
22 Rear Shock Absorber LH	362.20	1 PC	362.20	x
23 Rear Hub Bearing LH	286.40	1 PC	286.40	
			13,732.10	
		Less 20%	2,746.42	10,985.68
Special Net				
24 Front Tyre LP200	350.00	2 PC	700.00	70%
25 Rear Tyre LH LP200	350.00	1 PC	350.00	70%
			1,050.00	1,050.00
Labour				
26 Towing	50.00	1 PC	50.00	✓
27 Panel Beating	1,400.00	1 PC	1,400.00	600
28 Check Wiring	80.00	1 PC	80.00	20
29 Alignment	50.00	1 PC	50.00	✓
30 To Remove & Replace Front & Rear Under Carriage	520.00	1 PC	520.00	350

PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S : INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET
#04-#05 IOB BUILDING
SINGAPORE 049711

TEL: 6347 6100

FAX: 6224 4174

ATTN: Motor Claim Department

Your Ref No: SLE1158D

Claim Type: Third Party

Accident Date: 18-11-2017

TP Veh Reg No: SHD4604R

Estimate No: EST0000521

Date: 21 Nov 2017

Policy No: 5090133686

Veh Reg No: SLE1158D

Make/Model: HONDA VEZEL

Chassis No: RU11115101

Engine No: L15B4035107

Reg. Date: 08-07-2016

Estimate Repair Cost to Vehicle No :SLE1158D

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
31 To Spray Painting	980.00	1 PC	980.00	800
32 To Spray Rust Proofing	80.00	1 PC	80.00	60
			3,160.00	
		Less 20%	632.00	2,528.00
			Total	S\$ 14,563.68

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND FIVE HUNDRED SIXTY THREE AND CENTS SIXTY EIGHT ONLY

For PROGRESSIVE AUTO PTE LTD

Progressive Auto Pte Ltd

No 1 Kaki Bukit Ave 6 Autobay

#02-48/50 Singapore 417883

Tel: 68444620 Fax: 68444625

AUTHORISED SIGNATURE

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: