


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5020D
Ref. No : TAX/11/17/2108
Reg. Date : 01/04/2016
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : ONG CHEE WAN
Type of Accident : HEAD TO SIDE
Date / Time of Accident : 17/11/2017 09:54:00 AM
Accident Reported Date / Time : 17/11/2017 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 17/11/2017
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024093140
Special Instruction to ARC, if any :
TOWED \$40 *1A14/Repair by paint*
Prepared Date : 17/11/2017 12:05:48 PM



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U205767678

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	0.00
Total Spray Painting Charges :	1,116.00	0.00
Total Material Charges :	5,350.94	5,350.94
Other Charges :	580.00	0.00
TOTAL :	8,060.94	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	6.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sing Off Date :	17/11/2017 03:00:11 PM	01/01/1900 12:00:00 AM

5 days - P/P



Ref 20/11/17 e1400

Prepared / Adjusted Date :

Remarks :

Prepared Date : 17/11/2017 02:59:32 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 11/17/2017 2:59:34 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable.
TO REPAIR LH FRONT PORTION	1,014.00	0.00 500
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable.
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 100
TO RESPRAY RIM	180.00	0.00 X
Total Spray Painting & Panel Beating	1,116.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable.
TOWING CHARGE	80.00	0.00 7.
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 40
Total Other Costs	580.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>DE</i>	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace <i>?</i>	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace <i>?</i>	No
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace <i>?</i>	No
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace <i>ne</i>	No
81529-47060			BRACKET, FR TURN CENTER LH	1	58.20	25.00	43.65	Replace	Replace <i>ms</i>	No
81529-47050			BRACKET, FR TURN LOWER LH	1	26.00	25.00	19.50	Replace	Replace <i>ms</i>	No
81529-47040			BRACKET, FR TURN UPPER LH	1	24.40	25.00	18.30	Replace	Replace <i>ms</i>	No
81521-47050			LENS & BODY, FR TURN LH	1	511.80	10.00	460.62	Replace	Replace <i>ms</i>	No
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace <i>sc</i>	No
81170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace <i>R</i>	No
53802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace <i>sp</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>bu</i>	No
53876-47030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace <i>ne</i>	No
42611-47140 (Frt)		6505658	WHEEL DISC. FRONT	1	1,484.20	25.00	1,113.15	Replace	Replace <i>DE</i>	No
TOTAL MATERIALS								5,350.95	5,350.94	
TOTAL MATERIALS(Discounted)								5,350.94	5,350.94	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									