

**COMFORTDELGRO ENGINEERING PTE LTD**

**REPAIR ESTIMATE\***

VEHICLE NO : SHB 4089M

MAKE :

MODEL : HYUNDAI i40

DATE 11/18/2017 9:55

*Lee/Kalvin* *PbyP*  
*Like* *AIG*

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 1,052.20
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) ?			\$ 24.60
	Front Bumper Retainer (LH) ?			\$ 9.20
	Headlamp (LH) ?			\$ 1,388.00
	Front Fender (LH) ✓			\$ 619.00
	Front Fender Shield (LH) X			\$ 169.80
	Front Fender Retainer (LH) X			\$ 9.20
	Front Wheel Hub Cap (LH) ✓			\$ 150.70
	<b>SUB TOTAL</b>			<b>\$ 3,445.10</b>
	<b>LESS 20%</b>			<b>\$ 689.02</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 2,756.08</b>
	Front Fender Advertisement Logo (LH) ✓			\$ 100.00 <b>Nett</b>
				<b>\$ 100.00</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ <del>560.00</del> <i>400</i>
	Spray Painting Charge			\$ <del>400.00</del> <i>360</i>
	Wiring Charge			\$ <del>30.00</del> <i>X</i>
	Tuff Kote			\$ <del>50.00</del> <i>20</i>
	Transfer of Door		\$ 120.00	\$ 240.00 <i>X</i>
	FRT Wheel Alignment			\$ <del>80.00</del> <i>X</i>
	<b>TOTAL LABOUR</b>			<b>\$ 1,360.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 4,216.08</b>

*Kalvin 10/11/17*  
*20/11/17 0950h*  
*2 Pys.*  
*Pip*  
*Before Paint photo*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.