


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : TIB1120M
 Ref. No : BUS/11/17/7025
 Reg. Date : 17/11/2017
 Vehicle Type : BUS -17M
 Make : MB0405G 17M (MERCEDES)
 Model : BENDY
 Name of Driver : MERCEDES 0405G
 Name of Driver : Qi Chenglin
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 10/11/2017 01:07:00 PM
 Accident Reported Date / Time : 16/11/2017 12:00:00 AM
 Surveyor is Required? : Yes
 Surveyor by : China Tai Ping
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No :
 Special Instruction to ARC, if any :
 TIB1120M - REAR DENTED
 GT7184T (TP) - INSURED WITH CHINA
 Prepared Date : 17/11/2017 04:29:41 PM



LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Chassis No : Mileage : 0
Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,325.00	0.00
Total Spray Painting Charges	: 786.00	0.00
Total Material Charges	: 1,102.65	1,102.65
Other Charges	: 45.00	0.00
TOTAL	: 3,258.65	0.00
Lum Sum Total	: 3,250.00	0.00

No. of Repair Days : 3.00 *2 days - Lump sum*

Prepared / Adjusted By :

Arc / Surveyor Sing Off Date : 20/11/2017 10:58:38 AM

01/01/1900 12:00:00 AM



*Per 20/11/17
1330 hrs*

Prepared / Adjusted Date :

Remarks :

Prepared Date : 20/11/2017 09:24:15 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No :
Quotation Date : Invoice Date :
Invoice Amount : Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	1,325.00	0.00
Total Labour	1,325.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	786.00	0.00
Total Spray Painting & Panel Beating	786.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
License Plate	45.00	0.00
Total Other Costs	45.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
40098510	REAR	6008173	REAR BUMPER CENTER	1	1,041.83	10.00	937.65	Replace	Replace <i>CR</i>	No
	COMMO	4005301	SMRT STICKER (S)	1	75.00	0.00	75.00	Replace	Replace <i>RC</i>	No
		4	60KM/H STICKER	1	15.00	0.00	15.00	Replace	Replace <i>RC</i>	No
	COMMO	5	REFLECTOR STICKER REAR BUMPER CENTER	1	75.00	0.00	75.00	Replace	Replace <i>CR</i>	No
TOTAL MATERIALS								1,102.65	1,102.65	
TOTAL MATERIALS(Discounted)								1,102.65	1,102.65	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									