STUTTGART AL*TO NO:12 SUNGEI KADUT AVE (S) 729648 (FAX NO. 63602899)

ESTIMATED COST OF REPAIRS

AXA INSURANCE PTE LTD NAME: Mr Ariun Gupta WIP: 29405 8 SHENTON WAY ADDRESS: 11 Evelyn Road #24-01 AXA TOWER #15-01 DATE: 20.11.2017 SINGAPORE 068811 Singapore 309304 MOTOR CLAIM DEPT ATTN. TEL: FAX: 68804838 / 68804739 VEH NO: SLM2668A DATE IN: CONTACT PERSON: RICK 63602445 CHASSIS NO WP1ZZZ95ZHLB24686 MILEAGE TYPE OF CLAIM: do DATE REG. POLICY NO. : MODEL 23.03.2017 Macan S NATURE OF WORKS S/NO Parts Description (NETT) QTY PART NO PRICES DC/ 1 LINING 1 P95B-807-221-A -G2X \$ 785.10 DG / 2 **GRILLE** 1 P95B-807-683-K -1E0 \$ 293.10 <u>H / </u> 3 P95B-823-031-CY-GRV/LID 1 P95B-823-031-JY-GRV \$ 2,974.90 me -**GASKET** 2 P95B-823-739- -\$ 14.00 5 AIR DUCT 1 \$ P95B-121-710- -1E0 136.70 6 SOUND ABSORBER 1 \$ 215.90 P95B-863-831-C -P7PP-010-714-R -/(WB35) WARNING SIGN 1 P7PP-010-006-A -\$ 6.10 X 8 (WE72) START/STOP WARNING SIGNSTICKER \$ 1 P7PP-010-786-T -6.50 DE 1 9 LICENSE PLATE BRACKET 1 \$ P95B-807-287- -1E0 71.60 **SUB TOTAL** 4,503.90 \$ **LESS 20%** 900.78 **Total Parts** \$ 3.603.12 Labour Description 2800 TO REMOVE / REPLACE FRONT DAMAGED 3,500.00 BUMPER, BONNET & OTHER AFFECTED BODY PARTS INCLUDING PANEL BEAT / STRAIGTHEN BODY PANELS & FITTINGS WHICHEVER NECESSARY INCLUDING ALIGNMENT OF BODY STRUCTURE 2200 TO SPRAY PAINT FRONT BUMPER & BONNET. \$ 2,400.00 3 TO CHECK ELECTRICAL WIRING SYSTEM FOR PROPER NETT 250.00 \$ FUNCTION ABILITY INCLUDING PARKING ASSIST SENSORS. TO CONDUCT CALIBRATION ON IN-BULIT CAMERA **NETT** \$ 1,400.00 & WHEEL ALIGNMENT ACCORDING TO SPECIFICATIONS 5 TO SUPPLY 1 PC CHASSIS STICKER. **NETT** \$ 150.00 6 TO RE-PROGRAMMED SYSTEM & ERASE FAULT CODES **NETT** \$ 600.00 AFTER ACCIDENT REPAIR MA 7 TO SUPPLY 1 PC NO PLATE \$70.00 EA **NETT** \$ 70.00 50 8 SUNDRIES. \$ 100.00

-		
	TOTAL LABOUR	\$ 8,470.00
	TOTAL PARTS	\$ 3,603.12
	GRAND TOTAL	\$ 12,073.12

Please note that this is only an estimate, base on our visual inspection. However should there be any additional work be found necessary in the course of repair and thus additional parts, materials and labor cost will be deem necessary, you will be inform accordingly prior to any action taken. In view of this, expected delays will be indivertible and therefore additional working days will be required. As such the loss of use and other incidentals will be adjusted accordingly.

Prepared By

Acknowledge By

Hp 90010068 22/11/17@1345

EXCESS: 3000 REVERT Removely 64 paid

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- · Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: