

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB 9530Y - III**AAD1709-199***Not Authored
i/Bp &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB 9530Y - CANDY**KL1LA69RJBB123960****CHEVROLET****CHEVROLET EPICA 2.0****18.09.2017****III****PART****LIST**

1	1	Front Bumper	\$	Sn	1,202.00	} X
2	1	Front Bumper Lower Absorber	\$	Sn	180.00	
3	1	Front Bumper Reinforcement	\$	R	356.00	
4	1	Front Bumper Retainer LH	\$	Sn	102.00	
5	1	Bumper Fog Lamp Cover LH	\$	Sn	32.40	
6	1	Front Fender LH	\$	R	837.60	
7	1	Front Fender Liner LH	\$	Sn	47.00	
8	1	Front Door LH	\$	R	1,133.00	
9	1	Front Door Outer Handle LH	\$	Sn	125.00	
10	1	Front Door Hinge Upper LH	\$	R	65.00	
11	1	Front Door Hinge Lower LH	\$	R	65.00	
12	1	Front Side View Mirror LH	\$	Sn	939.00	
13	1	Side Rocker Panel Garnish LH	\$	Sn	236.40	
14	1	Rear Door LH	\$	R	1,133.00	
15	1	Rear Door Guide LH Chrome Moulding	\$	Sn	60.00	
16	1	Rear Door Outer Handle LH	\$	Sn	125.00	
17	1	Rear Door Weatherstrip LH	\$	Sn	138.79	
18	1	Rear Fender LH	\$	R	1,145.00	
19	1	Rear Fender Inner Cowling LH	\$	Sn	298.00	

TOTAL	\$	8,220.19
10%	\$	822.02
	\$	7,398.17

Specical Nett

1	1 Set	Front Fender Liner Clip LH	\$	nn	30.00	X
2	1	Door Sticker "Trans-cab" LH	\$	nn	80.00	born
3	1	Door Sticker "6555-3333" LH	\$	nn	80.00	X
4	1set	Side Rocker Panel Garnish Clip LH	\$	nn	60.00	X
5	1	Rear Tyre LH	\$	Sn	360.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1709-199**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB 9530Y - III

6	1	Rear Wheel Rim LH	\$	<i>Ph</i>	254.00	X
7	2	Rear Windscreen Sealant	\$	<i>nn</i>	80.00	X
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>nn</i>	100.00	X

TOTAL	\$	1,044.00
TOTAL PARTS	\$	8,442.17

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,700.00 *2001*

To Rust-Proofing Of The Affected Areas.

\$ *nn* 220.00 X

Putty and Spray Painting Of The Affected
Portion.

\$ 2,800.00 *4001*

To Check Electrical Lighting Concerned.

\$ *nn* 170.00 X

To check steering geometry and computer wheel
alignment

\$ *nn* 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

Towing Fees

\$ *nn* 120.00 X

To transfer of door fittings, attachment and
perform water seepage test.

\$ *nn* 170.00 X

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$ *nn* 170.00 X

To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.

\$ *nn* 170.00 X

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged items for confirmation • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company REPAIR DAYS Acknowledged by Repairer Signature: Date:	TOTAL	\$	6,910.00
	Over All Total	\$	15,352.17
	10 DAYS <i>2 days</i>		