

Not about
her
the whole of the rep
1 day.
23/11/17
P/P 300

Third Party Insurer : III
Insured's Veh No : SHC8862R
Date of accident : 13.11.2017

Messrs Grab Rentals Pte Ltd

Estimate To Repair : Toyota Prius-1.8 Hybrid
Vehicle No : SLS4728R
Chassis No : JTDKB3FU903571161

Date : 18.11.2017

23/11/17
req: LKK - marcus

Pages : 1 of 1

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	front bumper <i>See R</i>	\$ 495.50	\$ 495.50
2	1 pc	front bumper lower centre air grille <i>17</i>	\$ 165.00	\$ 165.00
3	1 pc	front bumper upper centre air grille <i>17</i>	\$ 335.60	\$ 335.60
4	10 ps	front bumper clips <i>17</i>	\$ 4.30	\$ 43.00
5	2 ps	front bumper side retainers <i>17</i>	\$ 76.90	\$ 153.80
6	1 pc	front bumper lower beam <i>17</i>	\$ 238.50	\$ 238.50
7	1 pc	front bumper lower beam garnish <i>17</i>	\$ 65.00	\$ 65.00
8	2 ps	front bumper air guide <i>17</i>	\$ 70.00	\$ 140.00
				\$ 1,636.40
Less 25%				\$ 409.10
				\$ 1,227.30
LABOUR & MISC. CHARGES				
1		To check electrical lighting concerned. <i>17</i>	\$	60.00
2		Panel beating, knocking and straighten the necessary portion,		
3		remove and renewal of parts, adjust and realign the same. <i>300</i>	\$	400.00
		Putty and spray painting of the affected portion.	\$	550.00
				\$ 1,010.00
Grand Total				\$ 2,237.30
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				