

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 27 Nov 2017

Preliminary Advice

Insured Vehicle No	: XE2096A		
TP Vehicle No	: SGP9938T	Accident Date	: 15/11/2017
Make	: FORD MONDEO	Assignment Date	: 20/11/2017
Date of Inspection	: 24/11/2017	Est. Duration of Repair	: 0.00
Inspection At	: SENG KIN MOTOR WORKS (HQ)		
	BLOCK 1, SIN MING INDUSTRIAL ESTATE #01-131 SINGAPORE 575636		
	SINGAPORE 575636		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,279.30
Revised Amount	:S\$	6,683.05
Check Items (Estimated)	:S\$	4,908.30
Total	:S\$	11,591.35

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.