

23/03/2002

ASS. REC. BY:

REF:

CS/FCU7022205/Ugbn

Special Instruction:

Surveyor:

ASSIGNMENT (Office) ↓

From (Person):

W9 Joanne Yong

of

FCL

Date/Time: 21.11.2017 220pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLL 8442A

Insured:

SHA 677C

at Workshop m/s

Pegasus

Tel:

6858 1846

of

51 Defu Lane 10

Policy No:

D-1507270/MFSH

Claim No:

D17010737 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

16.11.2017

CA / REV / REP. / REV 24 HRS 'wp'

H.O.D. Endorsement:

Date/Time:

21.11.2017 247pm

Person Contacted:

Alvin

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SLL 8442A - X

SHA 677C - NS/INC11019595 / Hlgp

DUA: 23092011



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI17022205/Uqb

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 21-11-2017



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 6777C	Veh. Inspected	SLL 8442A
Policy No.		Coverage (\$)	0.00
Claim No.	D17010737MFSH	Excess (\$)	0.00
Assign From	CWS (JOANNE YONG)	Assign Date	21/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	16/11/2017	Inspection Date
Survey held at	51 DEFU LANE 10	
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Survey Department Check List (Case Handler)

Reference No.: 92/FCI/70005/496
Policy Type: OD / TP / TP RES / TL / EVA

SL 8442A

Case Handler

Typist

Admin (Cathy): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Navan): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity, (C.C)
- N Colour
- C Odometer, (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Cathy 23/11/17
Case Handler Date

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	17-11-2017	Our Ref No. D17010737MFSH
Accident Date	16-11-2017	Claim Type. Third Party
Insured Vehicle	SHA6777C	Third Party Vehicle. SLL8442A
Survey Location	51 DEFU LANE 10	
Contact Person.	RICHARD ANG	
Contact No.	68581846/ 68581846	Fax No. 64876070
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	PEGASUS ENGINEERING & TRADING PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	JOANNEY	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/230463)



PRI Documents



Close



PRI Header Details

Claim No	D17010737MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & PE TRADING
Workshop Name	PEGASUS ENGINEERING & TRADING PTE LTD (Contact Person : RICHARD ANG)	Survey Location & Contact Details	51 DEFU LANE 10 Mobile: 68581846 , Phone: 68581846 , Fax: EmailId: CLAIMS@PEGASUSENGRG.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA6777C	TP Vehicle No	SLL844
PRI Recieved Date	21-11-2017 03:54:35 PM	Surveyor Appointed Date	21-11-2017 02:20:39 PM	Surveyor Accept Date	21-11-

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	21-11-2017	Upload Survey Report *:	
------------------------------------	--	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents

File Name

Action

Surveyor Job Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 23 November, 2017 2:03 PM
To: 'Claim Workflow System'; assignments
Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17010737MFSH/1
Attachments: CSFCI17022205Uqb.pdf

Dear Joanne,

Enclosed herewith preliminary advice of SLL 8442A.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Tuesday, 21 November, 2017 2:48 PM

To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>

Cc: JOANNEYONG@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D17010737MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]

Sent: Tuesday, 21 November, 2017 2:20 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; JOANNEYONG@FIRST-INSURANCE.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D17010737MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17010737MFSH

Date: 22 November 2017

Our Ref: CS/FCI17022205/Uqb

The Motor Claims Department
First Capital Insurance Ltd


Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SLL 8442A

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/11/2017 at the premises of M/s PEGASUS, and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 3,359.12</u>
Revised Estimate Amount	: <u>S\$ 2,100.00 (Lump Sum)</u>
"Check" Items Amount	: <u>S\$ -</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

Description of Damage:
The vehicle sustained damages
at the rear o/s portion.



Yours faithfully

CHUA KANG SENG
Licensed Appraiser

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	7200G
Vehicle Details	
Vehicle No.	SLL8442A
Vehicle to be Exported	Yes
Intended De-registration Date	17 Nov 2017
Vehicle Make	HONDA
Vehicle Model	VEZEL HYBRID 1.5X AUTO
Primary Colour	Silver
Manufacturing Year	2016
Engine No.	LEB5920303
Chassis No.	RU31220293
Maximum Power Output	112.0 kW (150 bhp)
Open Market Value	\$25,457.00
Original Registration Date	13 Mar 2017
First Registration Date	13 Mar 2017
Transfer Count	0
Actual ARF Paid	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	12 Mar 2027
PARF Rebate Amount	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date	12 Mar 2027
COE Category	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$46,229.00
COE Rebate Amount	\$36,983.00
Total Rebate Amount	\$40,733.00

The information contained herein is correct as at 17 Nov 2017

OK

Messrs Grab Rentals Pte Ltd

Estimate To Repair Honda Vezel 1.5 Hybrid X (A)
Vehicle No : SLL8442A
Chassis No : RU31220293

Third Party Insurer : First Capital
Insured's Veh No : SHA6777C
Date of accident : 16.11.2017

Date : 17.11.2017

Pages : 1 of 1

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	tailgate lid <i>DD/3rd</i>	\$ 953.30	\$ 953.30
2	1 pc	tailgate lid hybrid badge <i>neu</i>	\$ 62.70	\$ 62.70
3	1 pc	tailgate lid vezel badge <i>neu</i>	\$ 56.30	\$ 56.30
4	1 pc	o/s tailgate lid reflector <i>SCA</i>	\$ 141.10	\$ 141.10
5	1 pc	rear windshield glass weatherstrip <i>neu</i>	\$ 88.00	\$ 88.00
	1 pc	rear bumper center <i>DD/DE</i>	\$ 762.70	\$ 762.70
7	1 pc	o/s rear bumper reflector <i>AT</i>	\$ 141.00	\$ 141.00
8	1 pc	o/s rear bumper side <i>CU7/DE</i>	\$ 95.00	\$ 95.00
9	1 pc	o/s rear bumper side retainer <i>AT</i>	\$ 23.00	\$ 23.00
10	6 pc	rear bumper clip <i>neu</i>	\$ 4.30	\$ 25.80
				\$ 2,348.90
Less 20%				\$ 469.78
				\$ 1,879.12
SPECIAL NETT ITEMS				
11	1 pc	rear windshield glass sealant <i>neu</i>	\$ 120.00	\$ 120.00
12	1 pc	rear windshield inner sponge <i>neu</i>	\$ 80.00	\$ 80.00
				\$ 200.00
LABOUR & MISC. CHARGES				
1		To check electrical lighting concerned.	20	\$ 60.00
2		To reinstall of rear bumper parking sensor.	50	\$ 120.00
3		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	300	\$ 500.00
4		Putty and spray painting of the affected portion.	480	\$ 600.00
				\$ 1,280.00
				\$ 3,359.12
Grand Total				

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17022205/Uqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 24-11-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 6777C	Veh. Inspected	SLL 8442A	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17010737MFSH	Excess (\$)	0.00	
Assign From	JOANNE YONG	Assign Date	21/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL HYBRID (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	RU31220293	Colour	SILVER	
Odometer	59125	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	16/11/2017	Inspection Date	22/11/2017	
Survey held at	51 DEFU LANE 10			
Repairer	PEGASUS ENGINEERING & TRADING PTE LTD			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 8442A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE LID	DENTED / BENT	953.30	953.30
1	TAILGATE LID HYBRID BADGE	NECESSARY	62.70	62.70
1	TAILGATE LID VEZEL BADGE	NECESSARY	56.30	56.30
1	O/S TAILGATE LID REFLECTOR	SCRATCHED	141.10	141.10
1	REAR WINDSHIELD GLASS WEATHERSTRIP	NECESSARY	88.00	88.00
1	REAR BUMPER CENTER	DENTED / DEFORMED	762.70	762.70
1	O/S REAR BUMPER REFLECTOR	NOT NECESSARY	141.00	-
1	O/S REAR BUMPER SIDE	CUT / DEFORMED	95.00	95.00
1	O/S REAR BUMPER SIDE RETAINER	NOT NECESSARY	23.00	-
6	REAR BUMPER CLIP @\$4.30	NECESSARY	25.80	25.80
	LESS 20% DISCOUNT		-469.78	-436.98
			1,879.12	1,747.92
SPECIAL NETT ITEMS				
1	REAR WINDSHIELD GLASS SEALANT (SN)	NECESSARY	120.00	40.00
1	REAR WINDSHIELD INNER SPONGE (SN)	NECESSARY	80.00	30.00
			200.00	70.00
LABOUR				
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR.		120.00	50.00
	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL PARTS, ADJUST AND REALIGN THE SAME.		500.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		600.00	480.00
	-		-	-
	-		-	-
	-		-	-
			1,280.00	850.00
GRAND TOTAL			3,359.12	2,667.92

Report Ref No. CS/FCI17022205/Uqbn2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,100.00
---	--	--	----------

Report Ref No. CS/FCI17022205/Uqbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.