



5

1

BUMPER RETAINER RH REAR

Serviceable

0

10

0

Reviewing



6

1

-

2

1

BUMPER LOWER REAR

Damaged

768.84

10

691.96

Reviewing



3

1

BUMPER BRACKET CTR REAR

Handbrake (Serviceable)

Engine Modification

Pre-accident condition

Excellent

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

Driver License #

License Type

1 ▼

License Issue Date

License Expiration Date

Address

BLK 780F WOODLANDS CRESCENT, 736780,
Singapore

Address type

Personal Correspondence

Business Correspondence ▼



Type

Listed on policy ▼

Type of Paint

Chassis No

Engine No

Engine Capacity

Sum Insured

Model
LATITUDE-2.0 L (A)

Service Address

BLK 5A UPPER BOON KENG ROAD, , 381005

Primary Contact/Insured

SIM HENG LEONG
BLK 5A UPPER BOON KENG ROAD, 381005, Singapore

ADMIN@CHESSA.COM.SG

Claim Handler

NG Stacey
6568804351
stacey.ng@axa.com.sg

Additional Instructions
ARC. NO TP Xs

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Add

User Portal

2/13/18 1:54 PM

\$6,750.00

\$6,750.00

Open

Share

Clone

3/8/2018

Claim Portal

Menu

Policy Schedule / Covernote / Certificate of
insurance

TEO Kitty

November 21, 2017

February 22, 2018

LTA SEARCH.pdf

Forms / Claim Documents

Others

LKK AUTO CONSULTANTS PTE LTD (TP)

February 22, 2018

LETTER TO OI.pdf

Letters and Correspondence

Policy Holders / Insured

LKK AUTO CONSULTANTS PTE LTD (TP)

February 13, 2018

SHB9965B - TP GIA Report.PDF

Reports & Statement

GIA Report

TAN Wancong

November 24, 2017

Preliminary Advice.pdf

Forms / Claim Documents

Others

LKK AUTO CONSULTANTS PTE LTD (TP)

Model

LATITUDE-2.0 L (A)

Service Address

BLK 5A UPPER BOON KENG ROAD, , , 381005

Primary Contact/Insured

SIM HENG LEONG

BLK 5A UPPER BOON KENG ROAD, 381005, Singapore

ADMIN@CHESSA.COM.SG

Claim Handler

NG Stacey

6568804351

stacey.ng@axa.com.sg

Additional Instructions

ARC. NO TP Xs

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

Document Type

Document SubType

--	--

Upload Documents

WORKSHOP INVOICE.pdf

Invoice

Repairer

LKK AUTO CONSULTANTS PTE LTD (TP)

March 8, 2018

DISCHARGE VOUCHER.pdf