

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB 9965B -**AAD1711-195***Not Authored
L/Sing &*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHB 9965B - CANDY
VF1ABL15AUC273441
RENAULT
LATITUDE
17.11.2017

*AAA***PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bz</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>Bz</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i> 135.97	X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i> 44.99	X
6	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
7	1	BUMEPR RETAINER LH REAR	\$	<i>D11</i> 44.99	✓
8	1	BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61	✓
9	1	BUMPER BEAM REAR	\$	<i>Bz</i> 777.52	✓
10	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	✓
11	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
12	1	BOOT REAR	\$	<i>R</i> 2,872.68	} X
13	1	BOOT FINISHER	\$	<i>Sn</i> 470.06	
14	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	
15	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	
16	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	
17	1	BOOT BADGE 'RENAULT'	\$	<i>Sn</i> 225.36	
18	1	BOOT BADGE	\$	<i>Sn</i> 225.36	
19	1	BOOT STRUT LH	\$	<i>Sn</i> 276.08	
20	1	BOOT HINGE LH	\$	<i>R</i> 367.84	
21	1	BOOT INNER TRIM	\$	<i>Sn</i> 586.45	
22	1	BOOT SWITCH	\$	<i>Sn</i> 168.13	
23	1	BOOT LOCK	\$	<i>R</i> 202.67	
24	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40	
25	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	
26	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	
27	1	FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45	
28	1	FENDER PANEL REAR LH	\$	<i>Bu</i> 3,299.13	✓
29	1	WHEELARCH REAR LH	\$	<i>Sn</i> 543.47	X
30	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	X
31	1	TAILLAMP LH	\$	<i>CM</i> 552.55	✓
32	1	TAILLAMP PANEL LH	\$	<i>R</i> 986.70	X
33	1	OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77	X
34	1	OUTER PANEL REAR (End Panel)TRIM	\$	<i>Sn</i> 404.56	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB 9965B -**AAD1711-195**

TOTAL	\$	21,905.60
10%	\$	2,190.56
	\$	19,715.04

Specical Nett

1	1SET	PARKING AID	\$	Short	700.00	✓
2	1SET	REAR BUMPER CLIP	\$	na	66.00	✓
3	1SET	BUMPER BRACKET CTR CLIP	\$	na	33.00	✓
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	na	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	na	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10	1SET	BOOT FINISHER CLIP	\$	na	24.20	X
11	1	BOOT STICKER "Trans-cab"	\$	na	30.00	X
12	1	BOOT STICKER "6555-3333"	\$	na	30.00	Y
13	1	BOOT INNER TRIM CLIP	\$	na	45.00	X
14	1SET	FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
15	1	FENDER INNER TRIM CLIP LH	\$	na	28.00	X
16	1	TAILLAMP CLIP LH	\$	na	5.00	X
17	2	REAR WINDSCREEN SELANT	\$	na	80.00	405m
18	1	WINDSCREEN MOULDING	\$	na	100.00	305m
19	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	X
20	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na	385.00	X
21	1	SPARE TYRE	\$	na	330.00	X

TOTAL	\$	2,139.20
TOTAL PARTS	\$	21,854.24

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00	660
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	600
To Rust-Proofing Of The Affected Areas.	\$	170.00	300
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB 9965B -**AAD1711-195**

To reinstall rear bumper parking sensor.	\$	170.00	601
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 100
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00	
Towing Fees	\$	120.00	120.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	120
To check steering geometry and computer wheel alignment	\$	220.00	220.00 X

TOTAL	\$	10,270.00
Over All Total	\$	32,124.24

(PARTS BY PARTS)**Repair Days****15 Days***5 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: