



ComfortDelGro Engineering

205 Braddell Road S(579701)

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP

Vehicle No. : SJY9857K

Make & Model : KIA SPORTAGE 2.0

Year of Manufacture : 2010

Chassis No. : KNAPC811MB7024918

Ins Company : AIG VS

Engine No. : _____

Excess : _____

Policy No. : _____

Date of Accident : 11/11/2017

Time of Accident : _____

Suggested Days of Repair : _____

In-house Vehicle Assessor

Repair Estimates

Case Owner : ROHANI

Signature : _____

Parts (a) Cost / List Price Items \$4,042.00

Contact No

Plus/Less 10% \$404.20

63837466 – Patrick
patricktia@sparkcarcare.com

Total of Cost / List \$3,637.80

63837890 – Eric
ericppg@sparkcarcare.com

63838115 – WILLIAM

(b) Nett Price Items \$-

63837362 – EZEL

63837656 - Ngo
nqotw@cdge.com.sg

Less _____

Total of Nett Item _____

63837730 – Brenda Ng

(c) Special Nett Items \$-

Total Parts Cost (Appendix A) \$3,637.80

Labour (Appendix B) \$1,990.00

Total Repair Cost \$5,627.80

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	_____
Company	:	_____
Survey conducted on	:	_____ at _____
Remarks By Surveyor		
(a) The repair of this vehicle is authorized / is not authorized until further notice.		
(b) Recommended Days of Repair	:	_____ day(s)
(c) Resurvey	:	Required / Not Required
(d) Excess	:	:\$ _____
(e) Signature of surveyor	:	_____ Date: _____

Spark Car Care

ComfortDelGro Engineering Pte Ltd
205 Braddell Road S (579701)
Tel: 63837168 / 63837466 Fax:62815767

Spare Parts

Vehicle No : SJY9857K Case Owner : ROHANI

Make & Model : KIA SPORTAGE 2.0 Year Manufacture : 2010

Chassis No : KNAPC811MB7024918 Engine No : 0

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	FRT BUMPER	1		\$538.00		
2	FRT BUMPER SIDE RETAINER RH	1		\$28.00		
3	FRT BUMPER SIDE RETAINER LH	1		\$28.00		
4	FRT BUMPER LOWER GARNISH	1		\$224.00		
5	FRT BUMPER LOWER GARNISH CLIP	15		\$60.00		
6	FRT BUMPER CENTRAL GRILLE	1		\$107.00		
7	FRT BUMPER CENTRAL GRILLE LOGO	1		\$58.00		
8	FRT LH FOG LAMP	1		\$158.00		
9	FRT LH FOG LAMP BRACKET	1		TBA		
10	FRT BUMPER CHROME LH	1		\$75.00		
11	FRT BUMPER CHROME RH	1		\$75.00		
12	LH HEADLAMP	1		\$1,483.00		
13	LH HEADLAMP TOP RUBBER SEAL	1		\$15.00		
14	FRT BUMPER REINFORCEMENT	1		\$524.00		
15	FRT BUMPER SPONGE	1		\$70.00		
16	LH HEADLAMP PANEL	1		\$564.00		
17	FRT BUMPER CLIP	10		\$35.00		
18	0	0				
19	0	1				
20	0	0				
21	0	4				
22	0	1				
23	0	1				
24	0	1				
25	0	6				
26	0	0				
27	0	0				
28	0	0				
29		0				
30		0				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

