

REF:

CS/TP172022211/Anb22

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 07 days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLN2415H. Page: 2017 April
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Opel Mokka. cc 1598
 Colour: Grey. A/C Insured / Std / NI / NA
 Sp. Reading: 33782 T. Radio Insured / Std / NI / NA
 Eng No: _____
 C/No: WOLJD7E66H B08 2061
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Jammed / Leaked / Burnt or
 Brake: Order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 215/55R18
 R: 215/55R18
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Continental
 Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 21/11/17.
 Survey held at 1st Autowork.
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP Great American Independent.

31/1/2018 P/P \$19,715 (Red 21,809.90 - 52%)

RECEIVED 11 JAN 2018

Date/Time: File Pass to?



Preli. Report



Final Report

Date/Time: File Return to?

31/1/2018 - typist

Days Of Repair: 7 days

Resurvey No. of Trip: _____

Survey Fee

Transportation

S - P - S

Phone

Other

Add Fee: ☐ Site Insp \$☐ Interview \$☐ Tech. Insp \$☐ Weekend \$

Report Format:

Lump Sum / I.B.I. (\$) _____

31X15

170+465

50

50+50

80

80

465

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 15/11/2017

Reference: SLN2415H

Make: OPEL MOKKA X

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLN2415H
CHASSIS NO.W0LJD7EC6HB082061
ENGINE NO.:A2162685GU7X0324

Name of insured :National Car Rental
Date of accident.: 04/11/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	LHF Headlamp	\$ 2,600.00
2	1	RHF Headlamp	\$ 2,600.00
3	1	Front Radiator Grille Moulding, Base	\$ 248.00
4	1	Front Radiator Grille Chrome Moulding	\$ 472.00
5	1	Front Bumper - Upper	\$ 1,362.00
6	1	Front Bumper - Lower	\$ 448.00
7	1	Front Bumper Lower Grille	\$ 238.00
8	1	Front Bumper Lower Sill Plate	\$ 188.00
9	1	Front Bumper Towing Cover	\$ 90.00
10	1	Front License Plate Bracket	\$ 100.00
12	1	LHF Foglamp Cover	\$ 120.00
13	1	LHF Foglamp	\$ 424.00
14	1	RHF Foglamp Cover	\$ 120.00
15	1	RHF Foglamp	\$ 424.00
16	1	Bar, Limiter Impact Absorber,	\$ 784.00
17	1	Crash Limiter, Frt End Lower	\$ 486.00
18	1	Front Bumper Absorber - Upper	\$ 92.00
19	1	Front Bumper Absorber - Lower	\$ 72.00
20	1	Front Support Panel Assy	\$ 968.00
21	1	LHF Bumper Bracket - Guide	\$ 65.00
22	1	RHF Bumper Bracket - Guide	\$ 65.00
23	1	LHF Fender	\$ 584.00
24	1	LHF Fender Protector	\$ 125.00
25	1	Rear Tailgate	\$ 1,840.00
26	1	Rear Tailgate Top Moulding (incl rr view camera)	\$ 2,302.00
27	1	Rear Tailgate Outer Handle	\$ 270.00
28	1	Rear Tailgate Opel Logo	\$ 216.00
29	1	Lettering Mokka X	\$ 146.00

30	1	Lettering CDTI <i>Ren</i>	\$ 110.00	✓
31	1	Rear Windscreen With Moulding <i>Ren</i>	\$ 1,258.00	✓
32	1	Tailgate Inner Trim Board ?	\$ 314.00	?
33	1	LHR Taillamp <i>Ren</i>	\$ 564.00	+
34	1	RHR Taillamp <i>Ren</i>	\$ 564.00	+
35	1	Rear Bumper <i>Del d</i>	\$ 1,800.00	✓
36	1	Rear Bumper Lower <i>Del d</i>	\$ 1,390.00	✓
37	1	Rear Bumper Towing Cover <i>Del d</i>	\$ 90.00	✓
38	1	Rear Bumper Sill Plate <i>Del d</i>	\$ 344.00	✓
39	1	LHF Bumper Reflector ?	\$ 150.00	?
40	1	RHF Bumper Reflector ?	\$ 150.00	?
42	1	Rear Exhaust <i>Ren</i>	\$ 1,643.00	+
43	1	Rear Bumper Reinforcement Bar ?	\$ 671.00	?
44	1	Rear Bumper Absorber - RH ?	\$ 82.00	?
45	1	Rear Bumper Absorber - LH ?	\$ 82.00	?
46	1	LHR Bumper Bracket, Guide ?	\$ 70.00	?
47	1	RHR Bumper Bracket, Guide ?	\$ 70.00	?
48	1	LHR Bumper Bracket ?	\$ 65.00	?
49	1	RHR Bumper Bracket ?	\$ 65.00	?
50	1	Rear End Panel ?	\$ 1,241.00	?
51	1	Rear End Panel Trim ?	\$ 164.00	?
52	2	Rear Bumper Air Ventilator ?	\$ 80.00	?

Parts Total: \$ 28,416.00
Less 10%: \$ 2,841.60
Total : \$ 25,574.40

Labour

Labour Description

No.

Price (SGD)

Front portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 PER DAY)	\$ 2,600.00	650
2	Carry out spray painting on accident affected area (\$500 PER PANEL)	\$ 2,500.00	500
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 350.00	+
5	To remove and refix radiator and conduct pressure test	\$ 50.00	+
6	To refocus headlamp	\$ 80.00	+
7	To remove and refit front sensor	\$ 80.00	50

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 PER DAY)	\$ 3,900.00	?
2	Carry out spray painting on accident affected area (\$500 PER PANEL)	\$ 3,000.00	1500
3	To remove and refix reverse sensor and conduct test	\$ 80.00	50
4	To remove and refix reverse camera and conduct test	\$ 80.00	50
5	To conduct transfer of parts from old tailgate to new tailgate	\$ 160.00	100
6	To conduct water leakage test after repairs of vehicle	\$ 80.00	+
7	To apply door sealant to rear tailgate	\$ 80.00	+
8	To remove and refix rear tail gate windscreen	\$ 180.00	120

Labour Total : \$ 13,250.00

Others

Other Description

No. Qty

Price (SGD)

Front portion

1	1	Number plate with casement <i>cancel</i>	\$ 45.00	✓
2	10	Front bumper clip <i>new</i>	\$ 65.00	✓ 30
3	8	Front support panel top garnish clip <i>new</i>	\$ 52.00	+
4	8	Front Radiator Grille Clip <i>new</i>	\$ 52.00	20
5	1	Front sensor 1 set <i>new</i>	\$ 640.00	x.

Rear portion

1	1	Rear number plate <i>new</i>	\$ 45.00	+
2	10	Rear bumper clip <i>new</i>	\$ 65.00	30
3	6	Rear fender liner clips <i>new</i>	\$ 39.00	+
4	5	Rear end panel trim clip ?	\$ 32.50	?
5	1	Reverse sensor 1 set ?	\$ 640.00	?
6	1	Rear reverse camera <i>new</i>	\$ 230.00	7.
7	1	Rear end panel insulation seal ?	\$ 90.00	?
8	1	Rear floor panel insulation seal <i>new</i>	\$ 180.00	+
9	10	Tail gate inner trim board clip <i>new</i>	\$ 65.00	30
10	1	Tailgate windscreen sealant <i>new</i>	\$ 120.00	60
11	1	Tailgate windscreen solar film <i>new</i>	\$ 220.00	-
12	1	Rear Spoiler Sealant <i>new</i>	\$ 120.00	80

Other Total: \$ 2,700.50

GRAND TOTAL: \$ 41,524.90

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Service Executive

Suhaimi Ong

HP : 8298 8933 Fax:6844 5185

Adrian Lg
P/P 21/11/17.

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	/			
C	Customer Code	/			
N	Assign From	/			
C	Assign Date	/			
C	Veh No (Inspected)	/			
C	Veh No (Insured)	/			
C	D.O.A	/			
C	Policy No	/			
C	Claim No	/			
C	Insurance Authorisation (CA /REV/REP)	/			
C	Report Type	/			
C	Weekend Charges	/			
N	Survey held at/Repairer	/			
C	Excess	/			

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	/			
C	Regn Month/Year	/			
N	Vehicle Type	/			
N	Make & Model	/			
C	Engine Capacity. (C.C)	/			
N	Colour	/			
C	Odometer. (Sp.Reading)	/			
C	Chassis No	/			
N	General Condition	/			
N	Steering	/			
N	Brake	/			
N	Modification (Modi)	/			
C	Tyre Size	/			
N	Tyre Make	/			
C	Tyre Balance	/			
C	Date of Inspection	/			
N	Survey held	/			
N	Des.of Damages	/			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded				
---	--------------------------------------	--	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition				
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair				
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded				
---	-------------------------	--	--	--	--

Check By: Rita 31/1/2018
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2018

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/11/2017 13:23
Date Of Accident	04/11/2017 13:30
Exact Location Of Accident	ALONG AMK AVE 3 . NEXT TO BUS STOP NEFORE CTE (PIE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN2415H
Insured/Policyholder	
Name Of Registered Owner	NATIONAL CAR RENTAL PTE LTD
Co Reg No	1960100157E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-65113043

Vehicle Particulars

Manufacturer	OPEL
Model	MOKKA-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	RENTAL
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5089517881
Cover Note Number	

Driver

Name of Driver	MUHAMMAD FADHLI BIN MOHAMED NOOR
NRIC No	S9134510B
Date Of Birth	30/09/1991
Occupation	OUTDOOR
Date Of Driving Pass	14/08/2013
Driving Experience	4 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94899794
Fax Number	
Contact Number	
Email Address	MUHDFADHLT@LIVE.COM.SG

Address
 Postcode
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident CHAIN COLLISION
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Was any body injured in the Accident? YES
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name HONG KAH NORTH NEIGHBOURHOOD POLICE POST
 Police Station Address ROAD: BLK 370 BUKIT BATOK STREET 31 , POSTCODE: 650370 ,
 COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-5679999 - FAX NO: 65652508
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO REPORT ATTACHED .

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GX5483Y
 Vehicle Make/Model/Colour MIT VAN
 Details Of Properties
 Name of Driver WANG YUBO
 NRIC/Passport Number G8123303P
 Contact Number 86539396
 Address
 Postcode
 Insurance Company Name
 Nature Of Damage
 No. Of Passenger (Including Driver)

Details of Witness

Name
 Phone Number

Email Address

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLN2754D
Vehicle Make/Model/Colour HONDA VEZEL
Details Of Properties
Name of Driver HUANG HUANCONG , ANDY
NRIC/Passport Number S8827333H
Contact Number 81634027
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF INJURED PERSON 1

Name MUHAMMAD FADHLI BIN MOHAMED NOOR
Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn?
Was injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

06/11/17 1210

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



INSURANCE CERT



Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA)

Certificate Number: S089517821

Cover : drive PREMIUM

1. Index mark and Registration Number of Vehicle
Chassis Number

: SLN7415H
: W0LD7EC6H0R2061

2. Name of Policyholder

: NATIONAL CAR RENTALS (PRIVATE) LIMITED

3. Effective Date of Insurance

: 27 Apr 2017

4. Expiry Date of Insurance

: 26 Apr 2018

5. Persons or Classes of Persons entitled to drive#

(a) The Policyholder.

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to Use#

(A) Use for social domestic and pleasure purposes and in connection with the Policyholder's or Hirer's business.

This Policy does not cover

(c) Use for racing, pace-making, reliability trial or speed-testing

(d) Use for the carriage of goods (other than samples) in connection with any trade or business.

(e) Use for any purpose in connection with the Motor Trade.

Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION 1)	: S\$2,000
EXCESS (SECTION 2)	: S\$2,000
WINDSCREEN EXCESS	: S\$100
ADDITIONAL EXCESS	: N/A
UNNAMED DRIVER EXCESS	: PLEASE REFER OVERLEAF
REPAIR AT OWNER'S PREFERRED WORKSHOP	: YES
INSURE WITH COE	: YES
NCD PROTECTION	: NO
TRANSPORT ALLOWANCE	: NO
EXCESS WAIVER	: NO
PRIMARY DRIVER	: N/A
NAMED DRIVER (1)	: N/A
NAMED DRIVER (2)	: N/A
HIRE PURCHASE COMPANY	: SUMITOMO MITSUI FINANCE AND LEASING (SINGAPORE) PTE LTD
SUM INSURED	: MARKET VALUE OF INSURED VEHICLE AT TIME OF LOSS

(We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia))

Agency : AON SINGAPORE PTE LTD (00000690339)

Date of Issue : 11 Apr 2017 18:10 hrs

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:

Authorised Officer

Chief Executive

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 15/11/2017

Reference: SLN2415H

Make: OPEL MOKKA X

To Whom It May Concern

Dear Sir,

RE: VEHICLE :SLN2415H
CHASSIS NO.W0LJD7EC6HB082061
ENGINE NO.:A2162685GU7X0324

Name of insured :National Car Rental

Date of accident: 04/11/2017

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	LHF Headlamp ? <i>cracked</i>	\$ 2,600.00
2	1	RHF Headlamp? <i>cracked</i>	\$ 2,600.00
3	1	Front Radiator Grille Moulding, <i>cracked</i> Base	\$ 248.00
4	1	Front Radiator Grille Chrome Moulding <i>cut</i>	\$ 472.00
5	1	Front Bumper - Upper <i>del</i>	\$ 1,362.00
6	1	Front Bumper - Lower <i>new</i>	\$ 448.00
7	1	Front Bumper Lower Grille <i>new</i>	\$ 238.00
8	1	Front Bumper Lower Sill Plate <i>new</i>	\$ 188.00
9	1	Front Bumper Towing Cover <i>new</i>	\$ 90.00
10	1	Front License Plate Bracket <i>del</i>	\$ 100.00
12	1	LHF Foglamp Cover ?	\$ 120.00
13	1	LHF Foglamp <i>for</i>	\$ 424.00
14	1	RHF Foglamp Cover <i>for</i>	\$ 120.00
15	1	RHF Foglamp	\$ 424.00
16	1	Bar, Limiter Impact Absorber, <i>new</i>	\$ 784.00
17	1	Crash Limiter, Frt End Lower <i>new</i>	\$ 486.00
18	1	Front Bumper Absorber - Upper <i>del</i>	\$ 92.00
19	1	Front Bumper Absorber - Lower <i>del</i>	\$ 72.00
20	1	Front Support Panel Assy <i>new</i>	\$ 968.00
21	1	LHF Bumper Bracket - Guide <i>new</i>	\$ 65.00
22	1	RHF Bumper Bracket - Guide <i>new</i>	\$ 65.00
23	1	LHF Fender <i>new</i>	\$ 584.00
24	1	LHF Fender Protector <i>new</i>	\$ 125.00
25	1	Rear Tailgate <i>del</i>	\$ 1,840.00
26	1	Rear Tailgate Top Moulding (incl rr view camera) <i>new</i>	\$ 2,302.00
27	1	Rear Tailgate Outer Handle <i>del</i>	\$ 270.00
28	1	Rear Tailgate Opel Logo <i>new</i>	\$ 216.00
29	1	Lettering Mokka X	\$ 146.00

30	1	Lettering CDTI <i>Ren</i>	\$ 110.00	✓
31	1	Rear Windscreen With Moulding <i>Ren</i>	\$ 1,258.00	✓
32	1	Tailgate Inner Trim Board <i>Ren</i>	\$ 314.00	2 ✓
33	1	LHR Taillamp <i>Ren</i>	\$ 564.00	+
34	1	RHR Taillamp <i>Ren</i>	\$ 564.00	+
35	1	Rear Bumper <i>Ren</i>	\$ 1,800.00	✓
36	1	Rear Bumper Lower <i>Ren</i>	\$ 1,390.00	✓
37	1	Rear Bumper Towing Cover <i>Ren</i>	\$ 90.00	✓
38	1	Rear Bumper Sill Plate <i>Ren</i>	\$ 344.00	✓
39	1	LHF Bumper Reflector <i>Ren</i>	\$ 150.00	2 ✓
40	1	RHF Bumper Reflector <i>Ren</i>	\$ 150.00	2 ✓
42	1	Rear Exhaust <i>Ren</i>	\$ 1,643.00	+
43	1	Rear Bumper Reinforcement Bar <i>Ren</i>	\$ 671.00	+
44	1	Rear Bumper Absorber - RH <i>Ren</i>	\$ 82.00	+
45	1	Rear Bumper Absorber - LH <i>Ren</i>	\$ 82.00	+
46	1	LHR Bumper Bracket, Guide <i>Ren</i>	\$ 70.00	2 ✓
47	1	RHR Bumper Bracket, Guide <i>Ren</i>	\$ 70.00	2 ✓
48	1	LHR Bumper Bracket <i>Ren</i>	\$ 65.00	+
49	1	RHR Bumper Bracket <i>Ren</i>	\$ 65.00	2 ✓
50	1	Rear End Panel <i>Ren</i>	\$ 1,241.00	+
51	1	Rear End Panel Trim <i>Ren</i>	\$ 164.00	+
52	2	Rear Bumper Air Ventilator <i>Ren</i>	\$ 80.00	+

16500
14850

Parts Total: \$ 28,416.00
Less 10%: \$ 2,841.60
Total : \$ 25,574.40

Labour

No.	Labour Description	Price (SGD)
Front portion		

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 PER DAY)	\$ 2,600.00	650
2	Carry out spray painting on accident affected area (\$500 PER PANEL)	\$ 2,500.00	500
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00	✓
4	To remove and refit aircon condensor, vacuum, refill and check air con gas system	\$ 350.00	+
5	To remove and refix radiator and conduct pressure test	\$ 50.00	+
6	To refocus headlamp	\$ 80.00	+
7	To remove and refit front sensor	\$ 80.00	50

Rear portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 PER DAY)	\$ 3,900.00	1300
2	Carry out spray painting on accident affected area (\$500 PER PANEL)	\$ 3,000.00	1500
3	To remove and refix reverse sensor and conduct test	\$ 80.00	50
4	To remove and refix reverse camera and conduct test	\$ 80.00	50
5	To conduct transfer of parts from old tailgate to new tailgate	\$ 160.00	100
6	To conduct water leakage test after repairs of vehicle	\$ 80.00	+
7	To apply door sealant to rear tailgate	\$ 80.00	+
8	To remove and refix rear tail gate windscreen	\$ 180.00	120

4350

Labour Total : \$ 13,250.00

Others

Other Description

No. Qty

Price (SGD)

Front portion

1	1	Number plate with casement <i>cancel</i>	\$ 45.00	✓
2	10	Front bumper clip <i>in</i>	\$ 65.00	✓ 30
3	8	Front support panel top garnish clip <i>new</i>	\$ 52.00	+
4	8	Front Radiator Grille Clip <i>new</i>	\$ 52.00	20
5	1	Front sensor 1 set <i>new</i>	\$ 640.00	x.

Rear portion

1	1	Rear number plate <i>new</i>	\$ 45.00	+
2	10	Rear bumper clip <i>in</i>	\$ 65.00	30
3	6	Rear fender liner clips <i>new</i>	\$ 39.00	+
4	5	Rear end panel trim clip <i>new</i>	\$ 32.50	+
5	1	Reverse sensor 1 set <i>new</i>	\$ 640.00	+
6	1	Rear reverse camera <i>new</i>	\$ 230.00	+
7	1	Rear end panel insulation seal <i>new</i>	\$ 90.00	x
8	1	Rear floor panel insulation seal <i>new</i>	\$ 180.00	+
9	10	Tail gate inner trim board clip <i>new</i>	\$ 65.00	30
10	1	Tailgate windscreen sealant <i>new</i>	\$ 120.00	60
11	1	Tailgate windscreen solar film <i>new</i>	\$ 220.00	-
12	1	Rear Spoiler Sealant <i>new</i>	\$ 120.00	80

Other Total: \$ 2,700.50

GRAND TOTAL: \$ 41,524.90

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully

Suhaimi Ong

Service Executive
Suhaimi Ong

HP : 8298 8933 Fax: 6844 5185

UKK Auto Consultants hence notify the Repairer of the following:

- To resurvey and re-spray painting
- Parts price subject to confirmation
- Third party survey on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
P/P 21/11/17.

total: 19715 /
CP/P /
07 Days /

Findlater - Advice

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

TAX INVOICE

GREAT AMERICAN INSURANCE

GST Ref. No: 20-0000274-Z

Vehicle No: SLN2415H

Invoice No:

Chasis No : W0LJD7EC6HB082061

Engine No: A2162685GU7X0324

Invoice Date:

DESCRIPTION	AMOUNT	SGD
-------------	--------	-----

Parts

No.	Qty.	Description	Price (SGD)
1	1	LHF Headlamp	\$ 2,600.00
2	1	RHF Headlamp	\$ 2,600.00
3	1	Front Radiator Grille Moulding, Base	\$ 248.00
4	1	Front Radiator Grille Chrome Moulding	\$ 472.00
5	1	Front Bumper - Upper	\$ 1,362.00
6	1	Front License Plate Bracket	\$ 100.00
7	1	Front Bumper Absorber - Upper	\$ 92.00
8	1	Front Bumper Absorber - Lower	\$ 72.00
9	1	Rear Tailgate	\$ 1,840.00
10	1	Rear Tailgate Outer Handle	\$ 270.00
11	1	Rear Tailgate Opel Logo	\$ 216.00
12	1	Lettering Mokka X	\$ 146.00
13	1	Lettering CDTI	\$ 110.00
14	1	Rear Windscreen With Moulding	\$ 1,258.00
15	1	Tailgate Inner Trim Board	\$ 314.00
16	1	Rear Bumper	\$ 1,800.00
17	1	Rear Bumper Lower	\$ 1,390.00
18	1	Rear Bumper Towing Cover	\$ 90.00
19	1	Rear Bumper Sill Plate	\$ 344.00
20	1	LHF Bumper Reflector	\$ 150.00
21	1	RHF Bumper Reflector	\$ 150.00
22	1	Rear Bumper Reinforcement Bar	\$ 671.00
23	1	LHR Bumper Bracket, Guide	\$ 70.00
24	1	RHR Bumper Bracket, Guide	\$ 70.00
25	1	RHR Bumper Bracket	\$ 65.00

Total: \$ 16,500.00

Less 10%: \$ 1,650.00

Parts Total : \$ 14,850.00

Labour

No.	Description	Price (SGD)
Front portion		
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 PER DAY)	\$ 650.00
2	Carry out spray painting on accident affected area (\$500 PER PANEL)	\$ 500.00

<u>3</u>	To disconnect wire harness of electrical component to facilitate	\$ 30.00
<u>4</u>	To remove and refit front sensor	\$ 50.00

Rear portion

<u>1</u>	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$650 PER DAY)	\$ 1,300.00
<u>2</u>	Carry out spray painting on accident affected area (\$500 PER PANEL)	\$ 1,500.00
<u>3</u>	To remove and refix reverse sensor and conduct test	\$ 50.00
<u>4</u>	To remove and refix reverse camera and conduct test	\$ 50.00
<u>5</u>	To conduct transfer of parts from old tailgate to new tailgate	\$ 100.00
<u>6</u>	To remove and refix rear tail gate windscreen	\$ 120.00

Labour Total : \$ 4,350.00

Other

<u>No.</u>		<u>Other Description</u>	<u>Price (SGD)</u>
<u>Front portion</u>			
1	1	Number plate with casement	\$ 45.00
2	10	Front bumper clip	\$ 30.00
3	8	Front Radiator Grille Clip	\$ 20.00
<u>Rear portion</u>			
1	10	Rear bumper clip	\$ 30.00
2	10	Tail gate inner trim board clip	\$ 30.00
3	1	Tailgate windscreen sealant	\$ 60.00
4	1	Tailgate windscreen solar film	\$ 220.00
5	1	Rear Spoiler Sealant	\$ 80.00


Other Total : \$ 515.00

Total : \$ 19,715.00

GST (7%) \$ 1,380.05

Grand Total: \$ 21,095.05

Yours Faithfully,



Suhaimi Ong

Service Advisor

Tel: 68441985 Fax: 68445185

E & O E

- ALL CHEQUE PAYMENTS SHOULD BE CROSSED AND MADE PAYABLE TO "1ST Autoworks Pte Ltd".
- PLEASE INDICATE THE INVOICE NO. ON THE REVERSE SIDE.

Please check and finalize with me this invoice




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
1ST AUTOWORKS PTE LTD		Ref : CS/TP17022211/Anbe2		
23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933		Date : 06-02-2018		
ON BEHALF OF NATIONAL CAR RENTAL PTE LTD Code : TP480				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SLN 2415H	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		21/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	OPEL MOKKA	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	W0LJD7EC6HB082061	Colour	GREY	
Odometer	33982	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R18	CONTINENTAL	6 mm	
L/H Front Tyre	215/55 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	215/55 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	215/55 R18	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/11/2017	Inspection Date	21/11/2017	
Survey held at	1ST AUTOWORKS PTE LTD 23 KAKI BUKIT AVE 4 #04-01 (SOUNTH WING) SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLN 2415H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	LHF HEADLAMP	CRACKED	2,600.00	2,600.00
1	RHF HEADLAMP	CRACKED	2,600.00	2,600.00
1	FRONT RADIATOR GRILLE MOULDING BASE	CRACKED	248.00	248.00
1	FRONT RADIATOR GRILLE CHROME MOULDING	CUT	472.00	472.00
1	FRONT BUMPER - UPPER	DEFORMED	1,362.00	1,362.00
1	FRONT BUMPER - LOWER	NOT NECESSARY	448.00	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	238.00	-
1	FRONT BUMPER LOWER SILL PLATE	NOT NECESSARY	188.00	-
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	90.00	-
1	FRONT LICENSE PLATE BRACKET	DEFORMED	100.00	100.00
1	LHF FOGLAMP COVER	NOT NECESSARY	120.00	-
1	LHF FOGLAMP	NOT NECESSARY	424.00	-
1	RHF FOGLAMP COVER	NOT NECESSARY	120.00	-
1	RHF FOGLAMP	NOT NECESSARY	424.00	-
1	BAR, LIMITER IMPACT ABSORBER,	NOT NECESSARY	784.00	-
1	CRASH LIMITER, FRT END LOWER	NOT NECESSARY	486.00	-
1	FRONT BUMPER ABSORBER- UPPER	DEFORMED	92.00	92.00
1	FRONT BUMPER ABSORBER - LOWER	DEFORMED	72.00	72.00
1	FRONT SUPPORT PANEL ASSY	TO REPAIR SEE LABOUR	968.00	-
1	LHF BUMPER BRACKET - GUIDE	NOT NECESSARY	65.00	-
1	RHF BUMPER BRACKET - GUIDE	NOT NECESSARY	65.00	-
1	LHF FENDER	NOT NECESSARY	584.00	-
1	LHF FENDER PROTECTOR	NOT NECESSARY	125.00	-
1	REAR TAILGATE	DENTED	1,840.00	1,840.00
1	REAR TAILGATE TOP MOULDING (INCL RR VIEW CAMERA)	NOT NECESSARY	2,302.00	-
1	REAR TAILGATE OUTER HANDLE	DEFORMED	270.00	270.00
1	REAR TAILGATE OPEL LOGO	NECESSARY	216.00	216.00
1	LETTERING MOKKA X	NECESSARY	146.00	146.00
1	LETTERING CDTI	NECESSARY	110.00	110.00
1	REAR WINDSCREEN WITH MOULDING	NECESSARY	1,258.00	1,258.00
1	TAILGATE INNER TRIM BOARD	CRACKED	314.00	314.00
1	LHR TAILLAMP	NOT NECESSARY	564.00	-

Report Ref No. CS/TP17022211/Anbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RHR TAILLAMP	NOT NECESSARY	564.00	-
1	REAR BUMPER	DEFORMED	1,800.00	1,800.00
1	REAR BUMPER LOWER	DEFORMED	1,390.00	1,390.00
1	REAR BUMPER TOWING COVER	DEFORMED	90.00	90.00
1	REAR BUMPER SILL PLATE	DEFORMED	344.00	344.00
1	LHF BUMPER REFLECTOR	CRACKED	150.00	150.00
1	RHF BUMPER REFLECTOR	CRACKED	150.00	150.00
1	REAR EXHAUST	NOT NECESSARY	1,643.00	-
1	REAR BUMPER REINFORCEMENT BAR	BENT	671.00	671.00
1	REAR BUMPER ABSORBER - RH	NOT NECESSARY	82.00	-
1	REAR BUMPER ABSORBER - LH	NOT NECESSARY	82.00	-
1	LHR BUMPER BRACKET, GUIDE	NECESSARY	70.00	70.00
1	RHR BUMPER BRACKET, GUIDE	NECESSARY	70.00	70.00
1	LHR BUMPER BRACKET	NOT NECESSARY	65.00	-
1	RHR BUMPER BRACKET	CRACKED	65.00	65.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,241.00	-
1	REAR END PANEL TRIM	NOT NECESSARY	164.00	-
2	REAR BUMPER AIR VENTILATOR	NOT NECESSARY	80.00	-
	LESS 10% DISCOUNT		-2,841.60	-1,650.00
			25,574.40	14,850.00
	SPECIAL NETT ITEMS			
1	NUMBER PLATE WITH CASEMENT (SN)	CRACKED	45.00	45.00
10	FRONT BUMPER CLIP (SN)	NECESSARY	65.00	30.00
8	FRONT SUPPORT PANEL TOP GARNISH CLIP (SN)	NOT NECESSARY	52.00	-
8	FRONT RADIATOR GRILLE CLIP (SN)	NECESSARY	52.00	20.00
1	SET FRONT SENSOR (SN)	NOT NECESSARY	640.00	-
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	45.00	-
10	REAR BUMPER CLIP (SN)	NECESSARY	65.00	30.00
6	REAR FENDER LINER CLIPS (SN)	NOT NECESSARY	39.00	-
5	REAR END PANEL TRIM CLIP (SN)	NOT NECESSARY	32.50	-
1	SET REVERSE SENSOR (SN)	NOT NECESSARY	640.00	-
1	REAR REVERSE CAMERA (SN)	NOT NECESSARY	230.00	-
1	REAR END PANEL INSULATION SEAL (SN)	NOT NECESSARY	90.00	-
1	REAR FLOOR PANEL INSULATION SEAL (SN)	NOT NECESSARY	180.00	-
10	TAIL GATE INNER TRIM BOARD CLIP (SN)	NECESSARY	65.00	30.00

Report Ref No. CS/TP17022211/Anbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE WINDSCREEN SEALANT (SN)	NECESSARY	120.00	60.00
1	TAILGATE WINDSCREEB SOLAR FILM (SN)	NECESSARY	220.00	220.00
1	REAR SPOILER SEALANT (SN)	NECESSARY	120.00	80.00
			2,700.50	515.00
	LABOUR			
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS (\$650 PER DAY)		2,600.00	650.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (\$500 PER PANEL)		2,500.00	500.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR.		30.00	30.00
	TO REMOVE AND REFIT AIRCON CONDENSOR, VACUUM, REFILL AND CHECK AIR CON GAS SYSTEM.	NOT NECESSARY	350.00	-
	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.	NOT NECESSARY	50.00	-
	TO REFOCUS HEADLAMP.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIT FRONT SENSOR.		80.00	50.00
	TO DISMANTLE/ RENEW THE ACCIDENT DAMAGED PORTION, TO PANEL BEATING, RESHAPE, STRAIGHTEN, ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS (\$650 PER DAY)		3,900.00	1,300.00
	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA (\$500 PER PANEL)		3,000.00	1,500.00
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		80.00	50.00
	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST.		80.00	50.00
	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE.		160.00	100.00
	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE.	NOT NECESSARY	80.00	-
	TO APPLY DOOR SEALANT TO REAR TAILGATE.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN.		180.00	120.00
			-	-
			-	-
			13,250.00	4,350.00
GRAND TOTAL			41,524.90	19,715.00

Report Ref No. CS/TP17022211/Anbe2



RECOMMENDED COST OF REPAIRS

19,715.00

Report Ref No. CS/TP17022211/Anbe2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever in contract or tort is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.