Surveyor:	Foul	ASSIGN	MENT (Office)	-			
Munhan From (Person)	- Ikni Tun	of	mala	Date	Time:	EIOC·11·De	
Estimated Cos			Bill to:				
OD / TO / WS	TP RES / OD RES	S/EVA/INV/MY	V / CS				
To Inspect Ve	hicle No:	966 5356	Η	Insured:	9T(1832B	
at Workshop r	n/s	SAT Motors	3	Tel:	9126 9	987	
of		24 Defu Lar	N 12				
Policy No:	MSD /YPCP/	16-001051	Claim No:	msc/v	/16-001	646	
Sum Insured:	The mitter of the second secon		Excess:			ALMAND KOART PURDUNGSHIN	
Make of Veh:				D.O.	. 71	11.2016	
	And the second s				A	11.2010	-
(Client's Record CA / REV /	And the second s	RS /Wp) 1 Person Contact	30-11-2016 @ ed: Shou n	after 12pm	O.D. Endorse	ment:	
(Client's Record CA / REV /	1) REP. / REV 24 H 25-11-2016 9-19900	Person Contact	ed: Shown	after 12pm H.O. Vehicl	O.D. Endorse	ment:	
(Client's Record CA / REV / Date/Time;	REP. / REV 24 H	1 Person Contact	ed: Shown	after 12pm	O.D. Endorse	ment:	
(Client's Record CA / REV / Date/Time;	REP. / REV 24 H 25-11-2016 9-19-cm	1 Person Contact	ed: Shown	after 12pm H.O. Vehicl	O.D. Endorse	ment:	
(Client's Record CA / REV / Date/Time;	REP. / REV 24 H 25 11-2016 9-1990 Action/Instruction	Person Contact	ed: Shoun ate	after 12pm H.C. Vehicl	O.D. Endorse	ment:	
(Client's Record CA / REV / Date/Time; Date/Time	REP. / REV 24 H 25-11-2016 9-19-cm	Person Contact	ed: Shown	after 12pm H.C. Vehicl	O.D. Endorse	ment:	
(Client's Record CA / REV / Date/Time; Date/Time	Action/Instruction Son + PRS P	Person Contaction (×) Estim	ed: Shoun ate Vang Hrough	after 12pm H.C. Vehicl	O.D. Endorse	ment:	
(Client's Record CA / REV / Date/Time; Date/Time	Action/Instruction Son + PRS P	Person Contaction (X) Estim	ed: Shoun ate Vang Hrough	after 12pm H.C. Vehicl	O.D. Endorse	ment:	

REF: MSth				
AS	SIGNMENT			2
Estimated Cost: OD TP / WS / TP RES / OD RES / EVA / INV / MV		M.Cycle / Bus / Va	Yr Regn: 03	1
To Inspect Vehicle No: 965 5356H	Make:	Zoyota Kus	HIXA C.C	1495
at Workshop m/s SAT Muturs	Colour	BLACK		td / NI / NA
of 24 Defu lune 12	Sp.Reading	265287	T/Radio: Insured / S	
Insured:	Eng/No:		352166450X	
Policy No.	C/No:		TE00 8 0007546	
Claims No.	Gen. Cond: Go	od / Fair / Poor / B		
Sum Insured: Excess:	Steering: Inord	er / Jammed / Lea	ked / Burnt or	
(Client's Record)		er / Jammed / Lea		
Make of Veh:	1000	/Rim / STD A/Rin		-
after 12pm	Tyre Size:		15/65.876	
(Policy Condition)	7	R:	//	
Remark: The veh had commenced its N/S O/S	BS / DUN / EXN	OVA/GY/FS/LI	ZA / MIC / OHTSU / PIR / SU	IMI /
repair at the time of inspection.	тоуо / уоко			, mil /
Bal. or Market Value:	Front		Rear	
IDAC Accident Rport: Consistent? : Yes or No	R/Bal.	mm	R/Bal.	mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal.	mm	L/Bal. 7	mm
Est. Repairs: days Res.: Yes or No	D.O.A. 21111		D.O.I. 19/190/1	
Lum Sum: % 3 Val.: Yes or No	Survey held at	SHT	Notal	- CANHAL
CA / REV / REP. / 24 HRS WD	Special Control of the Control of th	: Frt / Rear / O	S / N/S / U/C / Rooftop	
Vehicle: IN / OUT			o / mo / o/o / Roottop	OI:
Date: Person Contacted: Date / Time Action / Instruction	The U/C / Cf	nassis frame / Bo	ody Structure affected due t	to collision.
REPAIR DEPUEL . \$5,500 fo \$6,500	m	ALP.		
After hullater	Days Of Repair: Resurvey No. of	V	Survey Fee:	
1) Object Muss : Final Report R	Resurvey No. of	V	Transportation	
1) Coff Musy : Final Report R	Resurvey No. of	Trip:	Transportation:)S+RSSI	
Prefix Report Date/Time, File Return 10? Add Fee: Report Format:	Resurvey No. of	Trip; (\$ (\$	Transportation	
Date/Time, File Return to? Add Fee:	Resurvey No. of Site Insp	Trip: (\$ (\$ (\$	Transportation: S + RSSI Photos	

(08/11/13) *



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation				
MSIC	SINSURANCE (SI	NGAPORE) PTE LTD	Ref : CS3/MSG160	22477/qb-1		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		BLDG SINGAPORE 048581	Date: 21-11-2017 Code: MSG			
1.	MET NO PER NO	Policy Particulars	:- THIRD PARTY CLA	AIM		
	Insured Veh. SLC 1832B		Veh. Inspected	SGS 5356H		
	Policy No.	MSD/VPCP/16-001051	Coverage (\$)	0.00		
	Claim No.	MSC/V/16-001646	Excess (\$)	0.00		
	Assign From	MERIMEN (IRENE TAN)	Assign Date	20/11/2017		
2.		Vehicle Parti	iculars & Condition			
	Make & Model		c.c	0		
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
-	Odometer -		Steering			
	Brakes		Modification			
	General					
3.		Condit	tions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre			mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre			mm		
	L/H Rear Tyre			mm		
4.		Descript	tion of Damages	- 1000000000000000000000000000000000000		
-		Gener	al Information			
5.	Accident Date	21/11/2016	Inspection Date	21/11/2017		
	Survey held at	SAT MOTORS	opconon pano			
	Survey neid at	24 DEFU LANE 12 SINGAPORE 539131				
			Remarks	- The state of the		

Catherine Chong (LKK Auto)

From:

Keny Ong <Keny_Ong@sg.msig-asia.com>

Sent:

Monday, 20 November, 2017 11:38 AM

To:

Catherine Chong (LKK Auto); SUR

Subject:

Your ref: CS3/MSG16022477/PQBS2FW Our ref: 516017 Paper reinspection for

SGS5356H

Dear Catherine

We have appointed your firm to carry out a PRI for SGS5356H recently.

Please do a paper reinspection of SGS5356H and let us have the report soon.

The survey report and photos of SGS5356H can be found in Merimen.

Have a great day!

Keny Ong

Senior Executive, Claims Services (Motor) Direct line +65 6643 1309 | Direct fax +65 6225 7402 | keny_ong@sg.msig-asia.com





Insurer Claims Team of the Year

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220

9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | msig.com.sg



A Member of MS&AD INSURANCE GROUP

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	22 Nov 2016		25 Nov 2016 08:41 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Cancel Cas	r Survey Report
	Main	Re	ference	Claim	Details	Docume	nts	Show All
CLAIM S	UBFOLDER DET	TAILS				[Created by	/ insurer]	
Insured:		HITACHI CAP	ITAL ASIA PACI	FIC PTE LTD, C	o. Reg. No.: 199400	399N		
Main Clai	imant:	SAT MOTORS,	Co. Reg. No.:					
Vehicle R	teg. No.:	SGS5356H		Date	of Loss:	21/11/2016		
Claim Ty	pe:	TP / MSC/V/	16-001646	Polic	y/Cover Note No.:		6-001051 (Cor 2/04/2016 - 21	
Vehicle R		SLC1832B		Polic	y No. (Claimant):			
(ansureu	7-			Exce	ss:	5\$1,500.00		
Repairer	:			12, 539131 Defu				
Handling	Insurer:	2541]			Tel: +65 6827 7888			
Adjuster	1	22/11/2017]		(HQ) - Tel: 6256	5-3561 [Handled b	by Paul Chan Ch	in Ming] [l	Final Rpt due
Driver/C (Insured	ustodian i):	AW WAI MENG	(), NRIC: S137	1704D, Tel; +6	590229832			
ASSOCIA	ATED MAIL REC	CEIVED				View A	II Compo	se Case Mail
 MSIG_ 	SG (20/11/2017)	: Report Send B	ack Alerts - SGS	5356H (TP)				
E ALL ASS	OCIATED TASE	cs			View All Search	Tasks Cre	ate New Task	Complete
Due Da		Type Task 0	Group Subject	ct Handler	Assigned By	Completed On	Created	On Done?

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation,
- This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Δ.	\sim 1	DER	NT S	ТΔТ	13 A	IΞN	
	-				_		

 Date Of Report
 22/11/2016 16:44

 Date Of Accident
 21/11/2016 21:35

Exact Location Of Accident JUNCTION OF SIMS WAY & GUILLEMARD

Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SGS5356H

Insured/Policyholder

Name Of Registered Owner SAT MOTORS
Co Reg No 53164690D

Email Address wee@satmotors.com

Mobile Phone No

Alternative Phone No Office-67481141

Vehicle Particulars

Manufacturer TOYOTA Model RUSH

Exact Purpose for which vehicle was being used

at time of accident

Are you claiming under your own insurance policy

for repair to your vehicle?

No

If No, Please state action to be taken Third Party
Vehicle Category Private Car

Insurance Company

Name of Insurance Company NTUC Income Insurance Co-operative Ltd

Type Of Coverage Third Party
Fleet Policy No

Policy Number 5077054048

Cover Note Number

Driver

Name of Driver ZULKARNAN BIN SUBARI

 NRIC No
 S7738169D

 Date Of Birth
 25/12/1977

 Occupation
 Outdoor

 Date Of Driving Pass
 25/11/2004

Driving Experience 11 Years And 11 Months

Gender Male

Mobile Number (Local) +65-91641585

Fax Number Contact Number

EMail Address NOEMAIL

Address

APT BLK 203A COMPASSVALE ROAD #04-07 S541203

Postcode

Was driver an employee of the Insured's Company

If No. Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

Collision- Head to Rear (TP Hit Insured)

Other - HIRE & REWARD

Weather Conditions

Clear

Road Surface

Dry

Other Information

Was any foreign vehicle involved in this accident?

Yes Was any body injured in the Accident?

Was any other material or property damaged?

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

Number of Passengers (Including Driver)

Yes No

No

2

Details of Police Action

Was the accident reported to the police?

Yes

If Yes, Please state which Police Station

Police Station Name

Punggol N.p.c

Police Station Address Police Station Contact

ROAD: 21A TEBING LANE, POSTCODE: 828837, COUNTRY: Singapore

TEL NO: - FAX NO:

Was notice of intended Prosecution given?

If Yes, against whom?

No

Circumstances of Accident

REFER TO THE ATTACHED.

Attachment(s)

Are accident photos available for attachment?

Yes

Was there any video captured by Car Camera?

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SLC1832B

Vehicle Make/Model/Colour

NIL

Details Of Properties

NIL

Name of Driver

AW WAI MENG

NRIC/Passport Number

S1371704D

Contact Number

90229832

Address

NIL

NIL

Postcode

NIL

Insurance Company Name

Nature Of Damage

NIL

No. Of Passenger (Including Driver)

Details of Witness

Name

Phone Number

Email Address

NIL

NIL NIL

DETAILS OF INJURED PERSON 1

Name

ZULKARNAIN BIN SUBARI

Approximate Age

Injuries Sustain

NIL

Injured person in which vehicle?

SGS5356H

Were seat belts worn?

Yes

Was injured conveyed to hospital by ambulance?

No

Address

203A COMPASSVALE ROAD

#04-07

Postcode

541203

DETAILS OF INJURED PERSON 2

Name

CHERYL LEE

Approximate Age

Injuries Sustain

NIL

Injured person in which vehicle?

SGS5356H

Were seat belts worn?

Yes

Was injured conveyed to hospital by ambulance?

No

NIL

Address

NIL

Postcode

NIL

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore (*GIA*) may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of ;
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

1600hrs. 22/11/2016 Witnessed by Reporting Centre Driver's Signature (If driver is not the policyholder) / Date Date & Policyholder* & Tirre Sketch Plan - 5655856H 56618321 Sims Way TE

Accident Sketch Plan Pg.1

scribe Circumstances of the Accident	us were fifteeing to quillement void . I was
At about 2135hvs, I was driving along sin	is despitation
ading to Geylang Lor 30, sending a passenger to	her destination.
As I was turning left to filtering left to	guillemand road 1 saw a vehicle coming from
e right and therefore stop behind the line. The	vehicle, a dark groy toyoth airis, section
t my car from the rear.	
	The Hall Control of the Control of t
	147147 120/12/09
	Insurance Co. NEW MOME
	Vehicle Ho. 400 / John Sale of Accident
	Reporting Only
	Own Damage Claim
	Third Party Claim
- III	Other Workshop
Declaration	120
to a consect	
WWe declare the foregoing particulars are true in every respect.	0199 1000
	(\$\times \) \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\
TORS	(3)
/00	STAN STAN
< as do 1 22	11 2016 1600hrs.
	not the policyholder) / Date Witnessed by Reporting Centre
8 Time	Personnel
Time & Tipe	



THE PROPERTY OF STREET

Police Station Of Origin Plunggel N.P.C 21A Teoing Lane SINGAPORE 828937 Tet No. 1800-6049909 Report No: 1/20161124/2005

REPORT OF A TRAFFIG ACCIDENT Date/Time Report Made 24/11/2018 01:08			Vide Report No.	Station Diary No. 19	
Name of	informant NAIN BIN		Address APT BLK 203A COMPASSVAI 541203	LE ROAD #14-97 SINGAPORE	
ID Type	ID Type / ID No. NEIC NO / 57738169D		Contact No.	Mobile 91841585	
National		EN	Email		
Sex	Age 38	Date of Birth 25/12/1977	Type of informant Driver	Institution / School Name	
Race			Language English		
Occupat	tions		Orwing Licence Information Class 28.3	Date of Expiry	

iccioral infor	nation of the Accide	Drink	Date/Time of	Type of Location
Type of Accident	Injury Others	Drive No.	Accident 21/11/2016 21:35	Bend
Along Road SIMS WAY GUILLEMAR	D ROAD E JUCTION OF SIM	S WAY / CUILLEMAR!	ROAD (TOWARDS)	JUT (EMARD ROAD)
Weather Clear		Dry		Road Speed Limit. Traffic Volume
Weather		The second second		

Details of V	Marie Street Committee of the Committee	Make	Model	Color	Condition No of
Verscie No.	Туре	CONTRACTOR OF THE PROPERTY OF	RUSH 15A	Black	Slightly 1
SG55358H	Car	TOYOTA	HUSH 127		Damaged
	A CONTRACTOR OF THE PARTY OF TH	TOYOTA	COROLLA	Grey	Slightly 1
SLC1832B	Car	TOTO!	ALTIS CLASSIC 1.6 CVT		Damaged



Police Station Of Origin Punggol N P C 21A Tebing Lane SINGAPORE 828837. Tel No. 1630-6049999



2014

Report No. 1/20101124/2005

CONTINUATION OF REPORT

Details of Person Any Pedesthan In No. of Pedestren	volved No	Use of Ped	ustrian Cross	
Oriver			ID No.	\$77381890
Name	ZULKARNAIN BIN SUBARI		to a Ma	91641585
Related Versicle	SGS5355H (CH)		Contact No	
Hospital/Clinic	POLYCI NIC		Crass of Driving Licence & Expiry Date	Class 28.3 Date of Expry Nit.
		Due Discharge 22/11/2016		
Date Treatment	22/11/2016 ted Medical Leave 03	Degree 9	injury Sligh	
Driver	aW wAI mENG		ID No.	\$1371704D
Name	AV W		Dontact No	90229832
Related Vehicle	NIL	The STAPLE OF		Class NiL
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Dat	Date of Expiry, NIL
Date Treatment	1000	Date D	scharge Nil	

On 21/11/2016 at about 2135hrs, I am driving Grab car and was travelling on my vehicle SGS5356H towards the filter lene, junction of Sims Wey / Guillemand Road (towards Guillemand Road) after I picked up one passenger namely Cheryl Lee at 403 Jalan Besar to her destination to 38 Geylang Lorong 30.

When I was approaching the filter tane I slowed down my vehicle to give way to the oncoming vehicle that was from Nicoli Highway towards Guillemard Road. I saw one vehicle from Nicoli Highway towards that was from Nicoli Highway towards the Nicoli Highway towards the Nicoli Highway towards the Nicoli Highway towards the Nicoli Highway towards

He claims that he saw my vehicle was moving out from the filter rane, hence he checked out for the blind spot on his right from Nicoll Highway and did not realised that my vehicle had stopped at the filter lane as one vehicle was approaching from Nicoll Highway Idwards Guillemard Road. He could not stopped his vehicle on time hence hit the back of my vehicle.

Both parties exchanged particulars, photos was taken at scene. The next day on 22/11/2015 I went to Sengkang Polyclinio to make a check as I suffered pain at the back of my neck, my back body as well as my leg. No ambulance at scene. No one was being conveyed to hospital. I was given 03 days MC.

Police report




Police Station Of Origin

Punggol N.P.C.
21A Tebing Lane SINGAPORE \$28837

Tel No. 1800-6049899 CQNTNUATION OF REPORT

Hisport No. 1/20/161124/2006

Police report



Constant Appraiser Services

Qualified Automobile Accident Damage Appraisers/Loss Adjusters Blk 2 Rivervale Link, #09-02 Singapore 545040 Tel/Fax: 6886 1106 Mobile: 9007 5234 Email: constant as@yahoo.com.sg

RCB No. 53138015K

Automobile Inspection Report

To: SAT Motors

24 Defu Lane 12

Singapore 539131

Date

: 12/12/2016

Reference No : CAS/16-12/036

General Information

Registration No. Accident Date

SGS 5356H

21/11/2016

Particulars of Damaged Vehicle

Colour

Black

Make & Model

Toyota Rush 1.5 A

Engine Capacity

: 1495 cc

Pre-Accident Condition Engine No.

Good : 3SZ1664504

Mileage (KM) Chassis No.

263281 J200E0007546

Steering

: In Order

Registration Date : 17/03/2007

Brake

: In Order

Tyre Condition

Size

Make

Balance

R/H Front Tyre

215/65R16

BRIDGESTONE

50%

L/H Front Tyre R/H Rear Tyre

215/65R16 215/65R16 BRIDGESTONE

50%

L/H Rear Tyre

215/65R16

BRIDGESTONE BRIDGESTONE

50% 50%

Inspection

Repairer

: Auto Mega Mall Pte Ltd

24 Defu Lane 12, Singapore 539131

Adjustment And Recommendation Cost Of Repair

Repairer's Estimate : \$11,152.05

Revised Amount

: \$6,950.00

Less Excess

Nett Total

: \$6,950.00

Remarks

- (A) Survey was done on 30/11/2016
- (B) Re-survey was done on 01/12/2016
- (C) Re-survey after repair was done on 07/12/2016
- (D) The survey was conducted entirely on WITHOUT PREJUDICE basis.
- (E) We have NOT given any instruction to authorize the repair of the vehicle.

NOTE: The revised estimate was made from a visual inspection. Should there be any discrepancy or unseen damage/item in this survey, kindly notified the company within 7 (seven) days from the date hereof. Otherwise, the revised amount shall be deem to be valid.

Vehicle No : SGS 5356H

Our ref: CAS/16-12/036

Adjustment On Repair Costs And Replacement Of Parts:

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		PARTS REPLACEMENT - LIST ITEMS			
1	1pc	Rear spare wheel cover inner	Broken	509.63	509.63
2	lpc	Rear spare wheel cover outer	Broken	1,507.15	S), 0254254574
3	lpc	Rear spare wheel carrier	Bent	355.30	1,507.15
4	1pc	Rear tailgate	Dented	200000000	355.30
5	1pc	Rear tailgate outer handle	Serviceable	1,602.41	1,602.41
6	1pc	Rear tailgate inner lock	Bent/Jammed	189.62 422.95	422.05
7	1pc	Rear tailgate inner trim board	Serviceable	362.80	422,95
8	1pc	Rear tailgate weatherstrip	Distorted	239.96	220.00
9	1pc	Rear tailgate checker	Bent	50000079837511	239.96
10	2pcs	Rear tailgate hinge @ \$148.96	Bent	162.05 297.92	162.05
1	1pc	Rear tailgate side stopper	Bent	25,555,50	297.92)
12	lpc	Rear tailgate side stopper striker	Bent	68.50	68.50
13	2pcs	Rear taillamp @ \$518.30	O/S Broken	42.20	42.20
4	1pc	Rear bumper	Dented Dented	1,036.60	518.30
5	2pcs	Rear bumper reflector @ \$86.55	N/S Grazed	968.64	968.64
16	lpc	Rear bumper tow hook cover	Serviceable	173.10	86.55
17	lpc	Rear bumper licence lamp	Serviceable	48,95 106,25	1.5
8	1pc	Rear bumper side retainer RH	Bent/Broken	S-200902	50.00
9	lpc	Rear bumper side retainer LH		59.90	59.90
0	1pc	Rear end panel	Bent/Broken	44.07	44.07
1	lpc	Rear end panel inner member	Dented Dented	513.50	513.50
2	lpc	Rear end panel top garnish	Deformed	489.70	489.70
3	1pc	Rear exhaust silencer	Repair	239.13	239.13
4	lpc	Rear exhaust mounting	Serviceable	834.05	1511
		and the same and t	Sciviceable	56.35	
		Less 25%		10,330.73	8,127.86
		1003 23 70		(2,582.68)	(2,031.96)
		PARTS REPLACEMENT - SPECIAL NETT ITEMS	Sub total	7,748.05	6,095.90
1	1set	Rear windscreen sealant set	Necessary	80.00	60.00
2	1set	Rear windscreen inner foam tape	Necessary	65,00	65.00
3	lpc	Rear no plate	Bent	50.00	45.00

Vehicle No: SGS 5356H

Our ref: CAS/16-12/036

S/No	Qty	Descriptions	Assessed Condition	Estimate by Workshop (\$)	Revised Amount (\$)
		PARTS REPLACEMENT – SPECIAL NETT ITEMS (CONT'D)			
4	lset	Rear bumper center clip	Necessary	19.50	19.50
-5	1set	Rear bumper center clip holder	Necessary	19.50	19.50
6	4pcs	Rear spare wheel cover rubber stopper @ \$25.00	Necessary	100.00	100.00
	355		Sub total	8,082.05	6,404.90
		LABOUR & MISC. CHARGES			
1		To remove, refix rear windscreen glass		180.00	140.00
2		To checkup rear electrical wiring		40.00	20.00
3		To remove, refix rear exhaust silencer	Not Necessary	80.00	-
4		To remove, refix rear interior upholstery to assist repair		120.00	80.00
5		To respray undercoating		150.00	90.00
6		To respray painting & etc		1,300.00	1,000.00
7		Panel beating, remove & replacing		1,200.00	950.00
			Grand total	11,152.05	8,684.90
		ost of lump sum repair ent condition)			6,950.00

6 glass

Adjustment/Recommendations

We have thoroughly inspected each and every item on the estimate against the physical damage found on the vehicle and we have listed the breakdown of our finding and our recommendation.

The repairer has agreed to undertake the job at a lump sum of \$6,950.00 on a contractual basis. Under normal circumstances, the repair period would be about 7 (Seven) working days.

Yours faithfully,


Constant Appraiser Services


Lim Yong Tian (Sebastian)


Licensed Appraiser
Adv. Dip. In Mechanical Engineering (AUS)

MSAAA









...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	22 Nov 2016		25 Nov 2016 08:41 Edit Adj Rpt	S\$5,400.00 Edit Estimates	\$\$5,400.00 View Rpt		Pending for Survey Report Cancel Case	
	Main	Refer	ence	Claim Deta	ils \	Documents	Show All	
CLAIM S	UBFOLDER DET	AILS				[Created by i	nsurer]	
Insured:		HITACHI CAP	ITAL ASIA PACI	FIC PTE LTD, Co	. Reg. No.: 19940	00399N		
Main Clai	imant:	SAT MOTORS,	Co. Reg. No.: 5	3164690D			- Side of the Side	
Vehicle F	Reg. No.:	SGS5356H		Date of L	Date of Loss:		:00 - :59	
Claim Type:		TP / MSC/V/	16-001646	Policy/Co	Policy/Cover Note No.:		MSD/VPCP/16-001051 (Comprehensive) Coverage: 22/04/2016 - 21/04/2017	
Vehicle Reg. No. (Insured):		SLC1832B		Policy No	Policy No. (Claimant):			
				Excess:	Excess:		S\$1,500.00	
Repairer	1	Sat Motors (H	Q) 24 Defu Lane	12, 539131 Defu L	ane - Tel:			
Handling	Insurer:	6594 2541]	3 50				Irene Tan Gek Ing -	
Adjuster	:	Rpt due 22/	sultants Pte Ltd 11/2017]	(HQ) - Tel: 6256-	-3561 [Handled	by Paul Chan C	hin Ming] [Final	
Driver/C (Insured	ustodian I):	AW WAI MENG	(), NRIC: S137	1704D, Tel: +65	90229832			
ASSOCI	ATED MAIL REC	EIVED				View All	Compose Case Mail	
MSIG_	SG (20/11/2017)	: Report Send B	ack Alerts - SGS	5356H (TP)				
E ALL ASS	OCIATED TASK	cs		View All	Search Tasks	Create Ne	w Task Complete	
Due Da		Type Task Gro	oup Subject	Handler Ass	igned By Co	impleted On	Created On Done?	

Claim Documents

*SGS5356H (MSC/V/16-001646) [SLC1832B] TP SAT MOTORS Nov 21 2016 9:00PM [HITACHI CAPITAL ASIA PACIFIC PTE LTD] Sat Motors

Ass	essment Reports		1 per p	page 🔻	1
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	24/11/16 17:08	Accident Statement From:OD - Reg. No: SLC18328, Claimant: HITACHI CAPITAL ASIA PACIFIC PTE LTD	0	Load HTM	
ho	otos/Images		3 per j	page 🔻	V
No	The second secon	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Prin
1	30/11/16 19:06	General View	0	Load JPG	1
2	30/11/16 19:06	General View	0	Load JPG	V
3	30/11/16 19:06	General View	0	Load JPG	V
4	30/11/16 19:06	General View	0	Load JPG	V
5	30/11/16 19:06	General View	0	Load JPG	J
6	30/11/16 19:06	General View	0	Load JPG	V
7	30/11/16 19:06	General View	0	Load JPG	V
8	30/11/16 19:06	General View	0	Load JPG	V
9	30/11/16 19:06	General View	0	Load JPG	V
10	30/11/16 19:06	General View	0	Load JPG	V
11	30/11/16 19:06	General View	0	Load JPG	V
12	30/11/16 19:06	General View	0	Load JPG	V
13	30/11/16 19:06	General View	0	Load JPG	V
14	NAME OF THE PARTY	General View	0	Load JPG	V
15		General View	0	Load JPG	V
16	V (1000)	General View	0	Load JPG	V
17	n distribution consume	General View	0	Load JPG	V
18	30/11/16 19:06	General View	0	Load JPG	V
19	30/11/16 19:06	General View	0	Load JPG	V
20		General View	0	Load JPG	V
21	30/11/16 19:06	General View	0	Load JPG	V
22		General View	0	Load JPG	V
23		General View	0	Load JPG	V
24		General View	0	Load JPG	U
25		General View	0	Load JPG	V
26		General View	0	Load JPG	V
27		General View	0	Load JPG	V
28	20111112222	General View	0	Load JPG	V
29		General View	0	Load JPG	V
30	C Construction of the cons	General View	0	Load JPG	V
31		General View	0	Load JPG	7
y202		General View	0	Load JPG	V
32		General View	0	Load JPG	V
33		General View	0	Load JPG	V
35		General View	0	Load JPG	V

2	28/11/17 11:41	РНОТО	0	Load PDF	
1	28/11/17 11:14	Invoice	0	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
4	20/11/17 15:09	\SGS5356H complete survey report	0	Load PDF	
3	20/11/17 11:30	Survey Report	0	Load PDF	
2	24/11/16 17:11	PRI	0	Load PDF	
No 1	Finalized On 24/11/16 17:10	MSIG Insurance (Singapore) Pte. Ltd. (HQ) SGS5356H GIA Rpt	-	Thumbnail	Prin
	umentation		1 per	7.7	V
	1 2 2	Name pecasis Filoto	0	Load JPG	V
53	01/12/16 17:40	Reinspection Photo		Load JPG	
52	01/12/16 17:40	Reinspection Photo	8	Load JPG	7
51	01/12/16 17:40	Reinspection Photo	0	00.033008.000	V
50	01/12/16 17:40	Reinspection Photo	0	Load JPG	7
49	01/12/16 17:40	Reinspection Photo	0	Load JPG	V
48	01/12/16 17:40	Reinspection Photo	0	Load JPG	V
47	01/12/16 17:40	Reinspection Photo	0	Load JPG	~
46	01/12/16 17:40	Reinspection Photo	0	Load JPG	V
45	01/12/16 17:40	Reinspection Photo	0	Load JPG	V
44	01/12/16 17:40	Reinspection Photo	0	Load JPG	V
43	01/12/16 17:40	Reinspection Photo	0	Load JPG	J
42	01/12/16 17:40	Reinspection Photo	0	Load JPG	V
41	01/12/16 17:40	Reinspection Photo	0	Load JPG	V
40	01/12/16 17:40	Reinspection Photo	0	Load JPG	V
39	01/12/16 17:40	Reinspection Photo	0	Load JPG	J
38	30/11/16 19:06	General View	0	Load JPG	V
37	30/11/16 19:06	General View	0	Load JPG	1
36	30/11/16 19:06	General View	6	Load JPG	V

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
	•			
	-			
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co.Reg. No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS3/MSG16022477/GQBE2-

Date:

28/11/2017

REFERENCE

Handling

MSIG Insurance (Singapore) Pte. Policy No:

MSD/VPCP/16-001051

Insurer: Ltd.

Insured Vehicle

SLC1832B

Claimant Vehicle No:

SGS5356H

No:

Claim MSC/V/16-

Date of Loss:

21/11/2016

Nature of Claim: TP

No:

001646

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SGS5356H

Make & Model:

TOYOTA RUSH, 1.5 (A) 17/03/2007 (Man. Year: 2006) Engine No: Chassis No:

Odometer:

3SZ1664504 J200E0007546

263281 km

Reg. Date: Colour:

Black 1495 cc

Engine Capacity: Market Value/New Car Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Good

Engine Modification:

Yes Footbrake (Serviceable): No Pre-accident Condition:

Yes

Handbrake (Serviceable): CONDITION OF TYRES

Front Tyre Size:

215/65 R16

Yes

Rear Tyre Size:

215/65 R16

Front Left Side: Front Right Side: Bridgestone 6 mm Bridgestone 6 mm Rear Left Side: Rear Right Side: Bridgestone 7 mm Bridgestone 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,082.05	4,823.88	3,258.17	40.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,070.00	1,960.00	1,110.00	36.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,152.05	6,783.88	4,368.17	39.17
Approved Total (Overridden) (S\$)		5,400.00		
(S\$)	11,152.05	5,400.00	5,752.05	51.58
+ GST 7.00/7.00% (S\$)	780.64	378.00	402.64	51.58
Nett Amount (S\$)	11,932.69	5,778.00	6,154.69	51.58

INSPECTION

Date of Assignment:

Date Inspected:

25/11/2016

30/11/2016

Inspected At:

Sat Motors

24 Defu Lane 12 Singapore 539131

Estimated Period of Repair:

6.0 days

Adjuster: Paul Chan Chin Ming

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REGISTRATION DATE UNABLE TO TRADE: DUE TO VEHICLE DE-REGISTER

Adjuster Report Page 4 of 5

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 28 Nov 2017) Parts: M1-SUV

TOYOTA RUSH 1.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SGS5356H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	. Particulars	Condition	Repairer's	Amount
1	1		*REAR SPARE WHEEL COVER INNER	Bent	509.63 FL	*367.00 FL
2	1		*REAR SPARE WHEEL COVER OUTER	Broken	1,507.15 FL	*1,507.15 FL
3	1		*REAR SPARE WHEEL CARRIER *REAR TAILGATE	Not Necessary Dented	355.30 FL	*- FL *1,400.00 FL
5	1		*REAR TAILGATE OUTER HANDLE	Serviceable	189.62 FL	
6	1		*REAR TAILGATE INNER LOCK	Bent / Jammed	422.95 FL	
7	1		*REAR TAILGATE INNER TRIM BOARD	Serviceable	362.80 FL	
8	1		*REAR TAILGATE WEATHERSTRIP	Distorted	239.96 FL	*166.00 FL
9	1		*REAR TAILGATE CHECKER	Not Necessary	162.05 FL	*-FL
10	2		*REAR TAILGATE HINGE	Not Necessary	297.92 FL	*-FL
11	1		*REAR TAILGATE SIDE STOPPER	Bent	68.50 FL	*68.50 FL
12	1		*REAR TAILGATE SIDE STOPPER STRIKER	Bent	42.20 FL	*42.20 FL
13	1		*REAR TAILLAMP	O/S Broken	1,036.60 FL	
14	1		*REAR BUMPER	Dented	968.64 FL	*881.00 FL
15	1		*REAR BUMPER REFLECTOR	N/S Grazed	173.10 FL	*86.55 FL
16	1		*REAR BUMPER TOW HOOK COVER	Serviceable	48.95 FL	*- FL
17	1		*REAR BUMPER LICENCE LAMP	Serviceable	106.25 FL	*-FL
18	1		*REAR BUMPER SIDE RETAINER RH	Bent / Broken	59.90 FL	*59.90 FL
19	1		*REAR BUMPER SIDE RETAINER LH	Bent / Broken	44.07 FL	*44.07 FL
20	1		*REAR END PANEL	Dented	513.50 FL	*513.50 FL
21	1		*REAR END PANEL INNER MEMBER	Repair	489.70 FL	*-FL
22	1		*REAR END PANEL TOP GARNISH	Deformed	239.13 FL	*199.00 FL
23	1		*REAR EXHAUST SILENCER	Repair	834.05 FL	
24	1		*REAR EXHAUST MOUNTING	Serviceable	56.35 FL	*-FL
25	1		*SET REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
26	1		*SET REAR WINDSCREEN INNER FOAM TAPE	Necessary	65.00 FS	*65.00 FS
27	1		*REAR NO PLATE	Bent	50.00 FS	*45.00 FS
28	1		*SET REAR BUMPER CENTER CLIP	Necessary	19.50 FS	*19.50 FS
29	1		*SET REAR BUMPER CENTER CLIP HOLDER	Necessary	19.50 FS	*19.50 FS
30	4		*REAR SPARE WHEEL COVER RUBBER STOPPER	Necessary	100.00 FS	*60.00 FS
F=Fra	nchise	part. S=SpcI	Nett. L=ListItemDisc.	Sub Total (S\$)	10.664.73	6,342.17

- List Item Discount on L Items 25.00/25.00% (S\$) 1,518.29 2,582.68

> 4,823.88 Total Parts (S\$) 8,082.05

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1 2	TO REMOVE, REFIX REAR WINDSCREEN GLASS TO CHECKUP REAR ELECTRICAL WIRING	New New	180.00 40.00	120.00
3 4	TO REMOVE, REFIX REAR EXHAUST SILENCER TO REMOVE, REFIX REAR INTERIOR UPHOLSTERY TO ASSIST REPAIR	New	80.00 120.00	20.00 0.00 60.00
5 6	TO RESPRAY UNDERCOATING TO RESPRAY PAINTING & ETC	New New	150.00 1,300.00	60.00
7	PANEL BEATING, REMOVE & REPLACING	New	1,200.00	900.00 800.00
	Gross Labou	r Cost (S\$)	3,070.00	1,960.00
	Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >