

**CITY CAB PTE LTD**  
**VEHICLE NO : SHC 400T**

ACG

DATE 20/11/2017 13:14

MAKE :  
 MODEL : HYUNDAI SONATA

DOA: 20.11.17

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>x repair</i>			\$ 578.40
	Rear Bumper Clip <i>x</i>			\$ 22.00
	Rear Bumper Protector (RH) <i>x repair</i>			\$ 38.00
	Rear Door Protector (RH) <i>x repair</i>			\$ 54.50
	Rear Wheel Hup-Cap (RH) <i>✓</i>			\$ 145.00
	<i>Rear Fender (RH) x repair</i>			
	<i>Rear Door (RH) x repair</i>			
	<b>SUB TOTAL</b>			<b>\$ 837.90</b>
	<b>LESS 20%</b>			<b>\$ 167.58</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 670.32</b>
	Rear Door Tel No. Sticker (RH) <i>✓</i>			\$ 10.00
				<b>Nett</b>
	<b>Labour Charge</b>			
	Panel Beating- Rear Fender			\$ <del>850.00</del> 400
	Spray Painting Charge			\$ <del>600.00</del> 540
	Wiring Charge			\$ <del>50.00</del> x
	Tuff Kote			\$ <del>50.00</del> x
	Remove/Refix Reverse Sensor			\$ <del>120.00</del> x
	Rear Wheel Alignment			\$ <del>120.00</del> x
	<b>TOTAL LABOUR</b>			<b>\$ 1,790.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,470.32</b>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledge by Repairer  
 Signature:  
 Date:

Larry Ng

Kalvin (LKK)  
 20/11/17 1500 hrs.  
 2 Days  
 c/s  
 After Repair photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.