

Surveyor XBD

REF: Independent

OS/TP17022219/Gab

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at Workshop m/s Performance Motors
of _____
Insured: _____
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

N/S	O/S

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 3 days Res.: Yes or No
Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____
Vehicle: IN / OUT

Veh No: W31265 Yr Regn: 28 Nov 2016
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: BMW X5 cc 1997
Colour: white A/C: Insured / Std / NI / NA
Sp. Reading: 43423 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: PMIKT08040LA06175
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 285/45 R19
R: 11
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front: _____ Rear: _____
R/Bal. 7 mm R/Bal. 7 mm
L/Bal. 7 mm L/Bal. 7 mm
D.O.A. _____ D.O.I. 20-11-17
Survey held at W/S 4pm
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
02/01/18 @ 2.41pm	W31265 - X Confirmed with Caroline Fraser fig to \$153.35, 3 days. Cred to \$217.75, 5% no resurvey photo
RECEIVED 0.3 JAN 2018	

Date/Time, File Pass to? <u>03/01/18</u> <u>mm</u>	☐ : Preli. Report	Days Of Repair: <u>3</u>	Survey Fee: <u>135</u>
Date/Time, File Return to?	☐ : Final Report	Resurvey No. of Trip: _____	Transportation: <u>50</u>
Report Format: <u>TP</u>	Add Fee: ☐ : Site Insp. (\$)	☐ : S + RS (\$)	<u>11</u>
Lump Sum / I.B.I. (\$): <u>4153.35</u>	☐ : Interview (\$)	☐ : Photos	<u>20</u>
	☐ : Tech. Invs (\$)	☐ : Others	<u>276</u>
	☐ : Weekend (\$)		
		TOTAL	

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (*Cathy*): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		
☒	☒		

Surveyor (*Guo Ming*): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			
☒			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

☒		
-------------------------------------	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

☒		
☒		

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--

Check By:

Cathy
Case Handler

20/1/18
Date



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

PERFORMANCE MOTORS LTD

Ref : CS/TP17022219/Gqb

303 ALEXANDRA RD #01-01 PERFORMANCE
CENTRE SINGAPORE 159941

Date : 21-11-2017



Code : TP196

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	W 3126S
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	20/11/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/11/2017	Inspection Date	20/11/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 2 January, 2018 2:41 PM
To: 'PBSP'; Guo Qiang (LKKAUTO); SUR
Subject: RE: FINAL REPORT / W3126S

Dear Caroline,

Confirm final fig \$4,153.35 before GST and 3 repair days.

Wishes you a Happy New Year 2018

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25
| S(408933)

-----Original Message-----

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]

Sent: Wednesday, 27 December, 2017 11:25 AM

To: Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>

Subject: FINAL REPORT / W3126S

Dear Guo Qiang

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 1,283.55

Total Parts : 2,869.80

Total Labour & Parts : 4,153.35

Repair days: 3

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all



SINGAPORE POLICE FORCE



T/20171107/2157

1 of 3

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

Report No. T/20171107/2157

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 07/11/2017 19:21		Vide Report No.:		Station Diary No.: 26	
Informant's Particulars					
Name of Informant: LIM ALEK			Address: APT BLK 139 LORONG AH SOO #06-189 LHK BUILDING SINGAPORE 530139		
ID Type / ID No.: FIN NO / F7798527K			Contact No.: Home/Office: Mobile: 96697797		
Nationality: MALAYSIAN			Email:		
Sex: Male	Age: 62	Date of Birth: 13/01/1955	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: CONSTRUCTION WORKER			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident

Type of Accident:	Non-Injury Foreign Vehicle	Drink Drive: No	Date/Time of Accident: 07/11/2017 10:00	Type of Location:
Location: Along Road 1 TAMPINES STREET 85 *Along Tampines St 86 (Cannot be found in the search location)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume:
Type of Collision: Between Moving Vehicles - Head To Side				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
W3126S	Car				Slightly Damaged	0



**SINGAPORE
POLICE FORCE**



T/20171107/2157

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

2 of 3

Report No. T/20171107/2157

CONTINUATION OF REPORT

Brief Details.

On the above mentioned time and date, I parked my vehicle with registration plate number W3126S along the above mentioned road. After which I proceeded out of the vehicle and walked about 10 meters away from my parked car when suddenly a lorry drove out from the construction site and hit (Brush) the side the rear of my vehicle. I went back to my car as quickly as I could and wanted to give a chase however the lorry was nowhere to be seen.

There is a slight damages. However I then realized that the lorry was from China Jingye Engineering Corp Ltd. I tried to give a call however to no avail.

I have a video recorded pertaining to the incident. I did not manage to capture the plate number of the lorry. No one was injured.

There is no in-cam CCTV in my car.



**SINGAPORE
POLICE FORCE**



T/20171107/2157

3 of 3

Report No. T/20171107/2157

Police Station Of Origin:
Paya Lebar NPP
114 Hougang Avenue 1 #01-1270
SINGAPORE 530114
Tel No: 1800-2899999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the **report number** as reference.

Signature Of Officer Recording The Report:

F /

Sgt 2 MOHAMMAD AZRUL BIN AZMI

Signature Of Informant: X

Signature Of Interpreter:

Not applicable

Date/Time:

07/11/2017 19:21

Officer In Charge Of Case:

TP / AEIT /

Sr Staff Sgt LEE SOON LYE

Contact No.: 65476239

Classification Of Case:

Authentication Stamp

NP168



SIJIL PEMILIKAN KENDERAAN

JABATAN PENGANGKUTAN JALAN

4EGLQNKX

No. Pendaftaran : **W3126S**
No. ID : 550113015409
Nama Pemunya Berdaftar : LIM ALEK
Alamat : NO. 115 JALAN HAJI YACOB LENGA
84040 MUAR JOHOR

No. Chasis/No. Enjin : PMIKT08040LA06175 / A7261522
Buatan>Nama Model : BMW / BMW X5 XDRIVE40E
Keupayaan Enjin : 1997
Bahan Bakar : PETROL
Status Asal : PEMASANGAN TEMPATAN
Kelas Kegunaan : PSDN-JIP/VAN/BAS/KVN IND
Jenis Badan/Tahun Dibuat : JIP / 2016
Tarikh Pendaftaran : 28/11/2016
B. D. M/B. G. K/BTM : -
Syarat Pendaftaran 1 : -
Syarat Pendaftaran 2 : -
Syarat Pendaftaran 3 : -

ADDLINE



LESEN KENDERAAN MOTOR

AKTA PENGANGKUTAN JALAN 1987 KAEDAH KENDERAAN MOTOR (PENDAFTARAN DAN PELESENAN) 1959

Sila baca maklumat di muka sebelah sebelum
melekatkan LKM ini di cermin kenderaan anda

2017

W3126S

27 NOV

0110011 HeAMqMK
VELO2006 MASTURAH
SEMENANJUNG

28112016 27112017
1997SP AD RM438.80
PERSENDIRIAN

37599359



LESEN KENDERAAN MOTOR
AKTA PENGANGKUTAN JALAN 1987 KAEDAH KENDERAAN
MOTOR (PENDAFTARAN DAN PELESENAN) 1959



HeAMqMK


**BORANG PENGESAHAN PEMBELIAN INSURANS /
CONFIRMATION OF INSURANCE PURCHASE SLIP**

Cover Note No.: 4649134

IPJ Status: PENDING REPLY

PERATURAN CBC / CBC REGULATION

Mengikut Seksyen 84 Akta Perkhidmatan Kewangan 2013, tiada perlindungan akan diberi sehingga premium telah dibayar kepada kami dengan cara yang kami tentukan atau seperti yang ditentukan oleh Bank Negara Malaysia. Di mana premium dibayar melalui cek, kiriman wang, kiriman pos, draf bank atau arahan kasyier, bayaran hendaklah dibuat atas nama AIG Malaysia Insurance Berhad (795492-W) dan dipalang "Akaun Penerima Sahaja".

According to Section 84 of the Financial Services Act 2013, no cover can be granted until the premium has been paid to us in the manner we may prescribe or as may be prescribed by Bank Negara Malaysia. Where payment of the premium is made by cheque, money order, postal order, bank draft or cashier order, the payment must be made in favour of AIG Malaysia Insurance Berhad (795492-W) and crossed "Account Payee Only".

Tarikh dikeluarkan/Date issued 28-11-2016

Nama / Name: LIM ALEK

No. K.P./Pendaftaran Perniagaan/I.C./Business Regn. No.: 550113-01-5409

Alamat/Address NO. 115 JALAN HAJI YACOB LENGA 84040 MUAR JOHOR DARUL TAKZIM

Yang telah memohon untuk insurans dan membayar premium sebanyak / Having proposed for insurance and paid the sum of RM 8,165.79	
Cukai Barangan dan Perkhidmatan/ Goods and Services Tax	RM 489.95
Duti Setem/ Stamp Duty	RM 10.00
Jumlah Premium / Total Premium RM 8,665.74	
Untuk kenderaan bermotor yang dinyatakan dalam jadual di bawah, risiko yang berikutnya dilindungi tertakluk kepada terma -terma perlindungan AIG Malaysia Insurance Berhad (Syarikat) / In respect of the motor vehicle described in the schedule below the risk is hereby covered subject to AIG Malaysia Insurance Berhad (Company) terms of coverage.	
Yang dapat diterima pakai bagi tempoh dari/ applicable thereto for the period from	
sehingga tengah malam pada / till midnight on	
Kecuali jika perlindungan ini ditamatkan oleh Syarikat secara bertulis di mana insurans ini akan dihentikan dan Syarikat akan memulangkan secara bersekadar premium yang telah diterima untuk insurans tersebut selepas mengambil kira tempoh Syarikat telah menanggung risiko.	
/ Unless the cover is terminated by the Company in writing, in which case the insurance will thereupon cease and the Company will return a proportionate part of the premium received for such insurance after due allowance for the period the Company has been on risk.	

NCD	55.00	Jenis Insurans / Insurance Type	NEW INSURANCE	Kegunaan Kenderaan / Used only for the following purpose	PRIVATE USE
Buatan / Make		BMW		Lebihan / Excess	RM 0.00
Model / Model of Vehicle		X5 (JAA16F) X5 xDRIVE40c M SPORT (CKD) 8 SP AUTOMATIC STEPTRONIC		No. Enjin / Engine No.	A7261522
No Pendaftaran / Registration No.				No. Chasis / Chassis No.	PM1KT08040LA06175
Keupayaan Enjin/Muatan Cubic Capacity/Tonnage		1997		Tahun Di Perbuat / Year of Manufacture	2016
Bilangan Tempat Duduk / Seating Capacity		5		Nilai diinsuranskan / Value insured	RM 388,000.00 (Agreed Value)

TERMASUK PERLINDUNGAN TAMBAHAN / EXTRA COVERAGE INCLUDED	LIMIT	TERMASUK PERLINDUNGAN TAMBAHAN / EXTRA COVERAGE INCLUDED	LIMIT
Auto-LEGAL LIABILITY TO PASSENGER	RM 0.00	Auto-LLP ACT OF NEGLIGENCE	RM 0.00
Auto-SPECIAL PERILS	RM 0.00	Auto-WINDSCREEN	RM 10,000.00

SIJIL INSURANS / CERTIFICATE OF INSURANCE

Saya/Kami dengan ini mengesahkan bahawa insurans perlindungan ini dikeluarkan adalah selaras dengan peruntukan Bahagian IV Akta Pengangkutan Jalan, 1987 (Malaysia) dan Akta Kenderaan Bermotor (Risiko dan Ganti rugi Pihak Ketiga) (Republik Singapura), Akta Insurans Kenderaan Bermotor (Risiko Pihak Ketiga) (Bah 90) Negara Brunei Darussalam.

I/We hereby certify that this insurance coverage is issued in accordance with the provisions of Part IV of the Road Transport Act, 1987 (Malaysia), the Motor Vehicles (Third Party Risks and Compensation) Act (Republic of Singapore) and the Motor Vehicles Insurance (Third Party Risks) Act (Cap 90) Negara Brunei Darussalam.

Sewa beli / Pajakan Hire Purchase/Leasing with	AFFIN ISLAMIC BANK BERHAD
Nama Agen / Producer Name	SIME DARBY AUTO CONNEXION S/B - AB GLENMARIE
Kod Agen / Producer Code	0501269020
Alamat Agen / Producer Address	NO. 3A PERSIARAN KERJAYA SEKSYEN U1, GLENMARIE 41050 SHAH ALAM
No. Tel. Agen / Producer Contact No.	03-5566 3800, NA, NA, NA, NA

 Bagi dan untuk pihak/For and on behalf of
AIG Malaysia Insurance Berhad

Note:

In the event of ambiguity, the English version of this form prevails.
Jika terdapatnya kekeliruan, versi Bahasa Inggeris akan mengatasi.

 Tandatangan Sah & Cop Syarikat /
Authorised Signature & Company Stamp

RoadRanger - Preferred Segment - Free 24-hrs Vehicle Breakdown Assistance Service. Dedicated Line : 1 300 883 933

By paying the premium hereby quoted, you agree to be bound by the Company's motor policy standard terms and conditions which adheres to the Malaysian Motor Policy Tariff. For your immediate reference, you may refer to the policy wordings at our website www.aig.my or obtain a copy from any of our branch office.



LESEN MEMANDU
DRIVING LICENCE



MALAYSIA

LIM ALEK

Warganegara / Nationality No. Pengenalan / Identity No.
MALAYSIA 550113015409

Kelas / Class

B2 D

Tempoh / Validity

28/08/2016 - 13/01/2022

Alamat / Address

NP 115 JL HJ YACOB
LENGA

84000 MUAR
JOHOR



KAD PENGENALAN
MALAYSIA
IDENTITY CARD

MyKad



550113-01-5409



LIM ALEK

NO 115
JALAN HAJI YACOB
LENGA
84040 MUAR
JOHOR

WARGANEGARA
LELAKI

N31268

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X

307, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159941
Tel. 63190528
63190533/5300 (Motorcycles)
64706501 (AfterSales)
64796526 (Motorcycles)
is subject to final approval from Insurance Company



LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• To subject to confirmation
• Survey is on a "Without Prejudice" basis
• Repairer is allowed
• (Motorcycles) must be resurveyed and
is subject to final approval from Insurance Company

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 44842
Date Estimated : 14/11/2017
Prepared By : Han Kwan Yong

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -
Cash Sales - Service
Singapore

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
W3126S	LA06175		X5 XDRIVE40E	0

DESCRIPTION

To replace rear bumper & attachments, rear right fender tail light including to knock out dented area caused by the accident (\$425.00) (less 15%)

VALUE

361.25

To respray rear bumper (\$1038.00) (less 15%)

882.30

Sundries. n/c

40.00

Total Labour 1: 1,283.55

DESCRIPTION

BODY NUT X ABC
MOUNT BUMPER RR RH X
REAR BUMPER PANEL PRIMED (M PDC)
RH TAIL LIGHT FINISHER TRUNK X NN TN
REAR LIGHT IN THE SIDE PANEL RH - CWA

QTY	PRIC
10	0.90
1	197.45
1	2,254.20
1	29.80
1	597.10

VALUE

9.00

197.45

2,254.20

29.80

597.10

Total Parts : 3,087.55

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date & Time 20/11/17 Excess \$

Surveyor's Name Guo Qiang Sign

82880282 Yes/No

Authorised Date Time

RESURVEY PAINT REQUIRED BY SURVEYOR? Yes/No PML Yes/No

Surveyor's E-mail Guo.Qiang@lkkauto.com

No. of Working Days Remitted 3 Days.

3 Days.
before paint photos.

23/11/17

Labour 1	:	1,283.55
Parts	:	3,087.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	305.98
Grand Total	:	4,677.08

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

4371.10

4384.60

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 44842
Date Estimated : 14/11/2017
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Cash Sales - Service
Singapore

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE	
W3126S	LA06175		X5 XDRIVE40E	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, rear RH light in side panel include knocking out dents caused by the accident			361.25		361.25
To spray paint rear bumper			882.30		882.30
Sundries			40.00		40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET WHITE *	1.85	10.00		18.50
REAR BUMPER PANEL PRIMED (M PDC)	2,254.20	1.00		2,254.20
REAR LIGHT IN THE SIDE PANEL RH	597.10	1.00		597.10

SUPPLEMENTARY ITEMS

Total Labour :	1,283.55
Total Parts :	2,869.80
Total Labour & Parts :	4,153.35
Deduction for Excess :	0.00
Total Repair Costs less Excess:	4,153.35
GST @7%:	290.73
Grand Total :	4,444.08

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 44842
Date Estimated : 14/11/2017
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Cash Sales - Service
Singapore

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN NO	CHASSIS NO	REGN DATE	MODEL	M
W3126S	LA06175		X5 XDRIVE40E	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET WHITE * / McL.	1.85	10.00		18.50

Total Labour :	0.00
Total Parts :	18.50
Total Labour & Parts :	18.50

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
PERFORMANCE MOTORS LTD		Ref : CS/TP17022219/Gqbs2		
303 ALEXANDRA RD #01-01 PERFORMANCE CENTRE SINGAPORE 159941		Date : 08-01-2018		
ON BEHALF OF LIM ALEK		Code : TP196		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		W 3126S	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		20/11/2017	
2. Vehicle Particulars & Condition				
Make & Model	BMW X5	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	PM1KT08040LA06175	Colour	WHITE	
Odometer	43423	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	285/45R19	PIRELLI	7 mm	
L/H Front Tyre	285/45R19	PIRELLI	7 mm	
R/H Rear Tyre	285/45R19	PIRELLI	7 mm	
L/H Rear Tyre	285/45R19	PIRELLI	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	07/11/2017	Inspection Date	20/11/2017	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. W 3126S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
10	BODY NUT (SN)	NOT NECESSARY	9.00	-
1	MOUNT BUMPER RR RH (SN)	NOT NECESSARY	197.45	-
1	REAR BUMPER PANEL PRIMED (M PDC) (SN)	TORN	2,254.20	2,254.20
1	RH TAIL LIGHT FINISHER TRUNK (SN)	NOT NECESSARY	29.80	-
1	REAR LIGHT IN THE SIDE PANEL RH (SN)	CRACKED	597.10	597.10
1	SUNDRISE (SN)	NECESSARY	40.00	40.00
1	EXPANDING RIVET WHITE (SN)	NECESSARY	18.50	18.50
			3,146.05	2,909.80
LABOUR				
	TO REPLACE REAR BUMPER & ATTACHMENTS, REAR RIGHT FENDER TAIL LIGHT INCLUDING TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT. (@ \$425.00 DISCOUNT 15%)		361.25	361.25
	TO RESPRAY REAR BUMPER. (@ \$1038.00 DISCOUNT 15%)		882.30	882.30
			1,243.55	1,243.55
GRAND TOTAL			4,389.60	4,153.35
RECOMMENDED COST OF REPAIRS				4,153.35

Report Ref No. CS/TP17022219/Gqbs2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.