

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE*

VEHICLE NO : SHB3545U
 MAKE : HYUNDAI
 MODEL : i40

Date: 20.11.2017

Qty	Type	Unit Price	Amount
1	Left Rear Door		\$ 1,403.00
1	Rocker Cover Garnish - LH <i>x repair</i>		\$ 483.60
1	Rear Wheel Cover - LH		\$ 150.70
SUB TOTAL			\$ 2,037.30
LESS 20%			407.46
DISCOUNTED TOTAL			\$ 1,629.84
1	Rear Door Tel No Sticker		\$ 10.00 Nett
			\$ 10.00
1	Labour Charge		
1	Panel Beating		\$ 400.00 200
1	Spray Painting Charge		\$ 600.00 540
1	Wiring Charge		\$ 50.00 x
1	Tuff Kote		\$ 50.00 20
TOTAL LABOUR			\$ 1,100.00
ESTIMATE TOTAL			\$ 2,739.84

Larry Ng

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Kalvin LKK
 20/11/17 1438 hrs.
 3 P.Y.S
 L/S
 After Repair photo.

Page 1 of 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Damaged parts during resurvey
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: