

EQ - LKK

**COMFORTDELGRO ENGINEERING PTE LTD**

VEHICLE NO : SHD 3896X

DATE 20/11/2017 10:37

Ja

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Door Outer Handle (RH) ✓			\$ 39.60
	Rear Fender (RH) x repair			
	Rear Door (RH) x repair			
	<b>SUB TOTAL</b>			\$ 39.60
	<b>LESS 20%</b>			\$ 7.92
	<b>DISCOUNTED TOTAL</b>			\$ 31.68
	Rear Door Tel No. Sticker (RH) ✓			\$ 10.00
	<b>Labour Charge</b>			
	Panel Beating- Repair Rear Fender			\$ <del>560.00</del> 400
	Spray Painting Charge			\$ <del>400.00</del> 360
	<b>TOTAL LABOUR</b>			\$ 960.00
	<b>ESTIMATE TOTAL</b>			\$ 1,001.68
	<p>Kalvin LKK</p> <p>20/11/17 1040hrs</p> <p>2 Days</p> <p>L/S</p> <p>After Repair photo</p>			
	<p>LKK Auto Consultants hence notify the Repairer using following:</p> <ul style="list-style-type: none"> <li>To resurvey and spray painting</li> <li>To disassemble and install and resurvey</li> <li>Parts to be replaced to the satisfaction</li> <li>Third party surveyors on a "without prejudice" basis</li> <li>No legal proceedings is allowed</li> <li>Supplies and materials must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			