

BODYFIX

NO 10 ANG MO KIO INDUSTRIAL PARK 2A #04-06
 AMK AUTOPOINT SINGAPORE 568047
 Tel No. : 62571289 Fax No. : 64837432
 Tax Reg. No. : 53010635C Buss. Reg. No. : 53010635C

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY #27-01
 AXA TOWER SINGAPORE 068811

Attention : Motor Claim Department
 Contact : 3387288 Fax No. : 8804838

Estimate : ES171122

Date : 22/11/2017
 Vehicle Num. : SJM 4304 K
 Make/Model : HONDA FIT-2008
 Chassis/Eng# : GE61138275
 Accident Date : 18/11/2017
 Claim No. :
 Reference :
 Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

- | | | | | |
|----|--------|---------------------------|--|--|
| 1. | 1 PC | REAR BUMPER | | |
| 2. | 10 PCS | REAR BUMPER CLIPS | | |
| 3. | 2 PCS | REAR BUMPER SIDE RETAINER | | |
| 4. | 1 PC | REAR BUMPER LOWER LIP | | |
| 5. | 1 PC | REAR END PANEL | | |
| 6. | 1 PC | BOOTLID LOGO | | |
| 7. | 1 PC | EMBLEM 'FIT' | | |
| 8. | REPAIR | REAR BOOTLID | | |

LIST ITEMS :

List Total S\$:

- | | | | | |
|----|-------|--|--|--|
| 1. | 1 SET | SPECIAL NETT ITEMS :
REVERSE SENSOR | | |
|----|-------|--|--|--|

Special Nett Total S\$:

LABOUR :

RUST-PROOFING ON THE REAR ACCIDENT AFFECTED PORTIONS
 TO CHECK, TEST LIGHTING & REVERSE SENSOR WIRING
 LABOUR TO REPLACE ABOVE PARTS, PANEL BEAT, REPAIR &
 RE-ALIGN DAMAGE PARTS

TO SPRAY PAINT REAR BUMPER, REAR END PANEL & REAR BOOT

Labour Total S\$:

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

3.90
 16.50
 474.50
 39.00
 33.00
 958.00
 390.00
 25.00
 35.00

1,954.50

280.00

280.00

60.00
 80.00

1,000.00

900.00

2,040.00

SingDollars : Four Thousand Two Hundred Seventy-Four & Cents Fifty Only

E. & O.E.

Total S\$: 4,274.50

=====


 for BODYFIX

Not Author.
 PIP Repair.
 Before taking photo
 LKB AUTOMOB

28/11/2017
 S.W. Jay S

\$1,550 confirmed
