

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Number Plate <i>x</i>			\$ 25.00	Nett
	Front No Plate Trim Cover <i>x</i>			\$ 30.00	Nett
	Front Fender Advertisement Logo (LH) <i>/</i>			\$ 100.00	Nett
	Front Door Comfort Logo (LH) <i>/</i>			\$ 75.00	Nett
	Front Door Advertisement Logo (LH) <i>/</i>			\$ 100.00	Nett
	Front Windscreen Sealant <i>/</i>			\$ 46.00	Nett
	Front ERP Sticker <i>/</i>			\$ 26.00	Nett
	Front Tyre (LH) <i>/ 50%</i>			\$ 216.00	Nett
				\$ 618.00	
	Labour Charge			<i>1000</i>	
	Panel Beating			\$ 2,400.00	
	Spray Painting Charge			\$ 1,600.00	<i>900</i>
	Wiring Charge			\$ 100.00	<i>20</i>
	Tuff Kote			\$ 150.00	<i>50</i>
	Towing Charge			\$ 50.00	<i>/</i>
	Remove/Refix Undercarriage (FRT)			\$ 400.00	<i>200</i>
	FRT Wheel Alignment			\$ 120.00	<i>60</i>
	Remove/Refix Aircon & Refill Gas			\$ 150.00	<i>60</i>
	Remove/Refix Dashboard			\$ 450.00	<i>150</i>
	Remove/Refix Fuse Box			\$ 180.00	<i>50</i>
	Remove/Refix Front Windscreen Glass			\$ 120.00	<i>100</i>
	Remove/Refix Cushion & Upholstery Front			\$ 90.00	<i>50</i>
	TOTAL LABOUR			\$ 5,810.00	
	ESTIMATE TOTAL			\$ 23,744.84	
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>					

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3555E

DATE 17/11/2017 16:00

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Bracket, LH ?			\$ 49.00
	Rear Bumper Clips 10 pcs ✓			\$ 22.00
	Rear Fender (LH) ✗ repair			\$ 2,020.10
	Rear Fender Inner Lining (LH) ?			\$ 164.40
	Rear Windscreen Moulding ✗			\$ 60.00
	Rear Wheel Hup-Cap (LH) ✓			\$ 150.70
	SUB TOTAL			\$ 3,069.80
	LESS 20% DISCOUNTED TOTAL			\$ 2,455.84
	Rear Bumper Rubber Mat ✓			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00
	Rear Windscreen Sealant ✗			\$ 46.00
				\$ 296.00
	Labour Charge			
	Panel Beating			\$ 1,200.00
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00
	Remove/Refix Rear Windscreen Glass			\$ 120.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 2,090.00
	ESTIMATE TOTAL			\$ 4,841.84

Nett
Nett
Nett

400
360
x
20
x
20

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary items must be surveyed and is subject to the approval from Insurance Company

Acknowledged by Repairer
 Date:

Kalan 16/11/17
 20/11/17 10:10 hrs.
 6 Repair Qty.
 PIP
 Before Paint p Lho.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.