

Signature

Tang

REF:

AXIA

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLC 4445R Yr Regt: 2016 / mig

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel

C.C. 1496

Colour: White

A/C: Insured / Std / NI / NA

Sp. Reading: 145375

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RU1106841

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 21/11/17

Survey held at Vermagen Bens.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

45: 41.700 (RSD: 46,213.21 79%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip: _____

Survey Fee:

Transportation

) \$ + RS \$

) Photo

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)



SLC4445R

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 18/11/2017

Vehicle Reg. No. : SLC4445R
Vehicle Reg. Date: 13-May-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4026844
Chassis No. : RU11106841

COST OF CLAIMS

Parts Cost / List Items : \$ 5,152.00
Plus/Less 20% \$ 1,030.40
Total Cost / List : \$ 4,121.60
Special Nett Items : \$ -
Total Parts Amount : \$ 4,121.60
Total Labour Amount : \$ 3,330.00
Gross Total : \$ 7,451.60
GST % : 7% \$ 521.61
Nett Amount : \$ 7,973.21

Surveyor Name and Company :

Taufik 97495749-44
Date of survey : 21/11/17 @ 1630
Part by Part / Lump Sum : 3 days
Resurvey Before Paint / After Paint 7
Authorize/Not Authorize/Without Prejudice 7
Email : zur@lkkauto.com
Fax No : _____
HP No : _____

This claim is handled by : EDMOND

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC4445R**
 Vehicle Reg. Date: **13/5/2016**
 Make / Model : **H. VEZEL 1.5X CVT**
 Engine No. : **L15B4026844**
 Chassis No. : **RU11106841**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear rim LHS	cut ✓	\$ 950.00		\$ 450
2	1	Rear fender arc garnish LH	cut ✓	\$ 165.00		✓
3	1	Rear fender arc garnish clips	use ✓	\$ 40.00		✓
4	1	Rear rim LHS	X repeated	\$ 950.00		
5	1	Rear shock absorber LH	X	\$ 625.00		
6	1	Rear shock absorber mounting LH	X	\$ 40.00		
7	1	Rear shock mounting bearing LH	X	\$ 40.00		
8	1	Rear shock absorber dust cover LH	X	\$ 50.00		
9	1	Rear shock stopper LH	X	\$ 40.00		
10	1	Rear lower arm LH	X	\$ 437.00		
11	1	Rear lower arm ball joint LH	X	\$ 113.00		
12	1	Rear wheel cover LH (honda)	X	\$ 110.00		
13	1	Rear bumper cover LH	cut ✓	\$ 210.00		✓
14	1	Rear bumper	cut ✓	\$ 885.00		\$ 800
15	1set	Rear bumper clips	use ✓	\$ 50.00		✓
16	1	Rear bumper retainer LH	use ✓	\$ 72.00		\$ 24.80
17	1	Rear bumper bracket LH	use ✓	\$ 116.00		
18	1	Rear bumper reflector LH	X	\$ 167.00		
19	1set	Rear bumper cover clips	use ✓	\$ 50.00		✓
20	1	Rear bumper cover retainer LH	X	\$ 42.00		
21	1	0				
22	1	0	parts	5132		
23	1	0				
24	0	0				
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29	0	0				
30	0	0				
31	1	0				
32	1	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	1	0				
38	0	0				
39	0	0				
40	0	0				

Tel : 6904 4596 | Fax No : 6694 4929

PAGE 1

[illegible]

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Flossie Ang

Date: 27 Nov 2017

Preliminary Advice

Insured Vehicle No	: SKK1938A	Accident Date	: 18/11/2017
TP Vehicle No	: SLC4445R	Assignment Date	: 21/11/2017
Make	: HONDA VEZEL 1.5X CVT	Est. Duration of Repair	: 3 days
Date of Inspection	: 21/11/2017		
Inspection At	: Vermogen Ace Pte Ltd (HQ) 1 Bukit Batok Crescent, #04-54/55 WCEGA Plaza Singapore 658064		

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesN/S rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,451.60
Revised Amount	:S\$	2,677.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,677.60

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : We have not authorized repairs.

« MANDATE REQUEST FOR S7M004RA

Type

🔗 Question

Message

Liability: Insured exit from the slip road and collided with third party vehicle. Spoken to insured and he aware that his NCD is affected and AXA to settle at best. Settlement: Repair Cost : \$1,819.00 (w/GST) Loss of Use: \$400 (5days x \$80) - UBER DRIVER LTA: \$17.00 Total: \$2,236.00 Revised Immediate Advice with Mandate uploaded for your easy reference. Please kindly let us have your approval / instruction if any. Thank you -
Asher Sng (12/06/2018)

Reply



Re:MANDATE REQUEST FOR S7M004RA

Type

 Information

Message

Hi Pls proceed. However, for LOU and earning, please offer \$70/ per day, tks Vale

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKK 1938A (Insd veh)	Model:	HONDA
	SLC 4445R (TP veh)		VEZEL 1.5X CVT
Date of Accident:	18/11/2017		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	9,075.74
Final Repair Cost	:	\$	1,819.00
Loss of Use	:	\$	350.00
Rental (if any)	:	\$	5 days at \$70.00 per day
LTA / GIA Search Fee	:	\$	17.00

Others:	:	\$	
---------	---	----	--

	:	\$	
Final Settlement Sum	:	\$	2,186.00

Is Third Party Workshop GIA Registered?		☐ YES	☒ NO	(Kindly indicate below)
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____		
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)		
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	VERMOGEN ACE PTE LTD	:	\$ 2,186.00

NUR SHAQILAH BTE ABDOL
WAHAB

12/07/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

SERVICE REQUESTS

MESSAGES

CLAIMS

<< Service Request Details

Claim	S7M004RA	Vehicle Information	
Reference		Incident Vehicle	SLC4445R
CC4/ASM17022226/11es3 		Registration #	TPVD SLC4445R 9
November 18, 2017 Request Date		Make	HONDA
December 18, 2017 Due Date		Model	VEZEL
July 31, 2018 Vendor Name			GRAY LANE # 04-01, , ,
LKK AUTO Type of			438951
CONSULTANTS PTE Loss		Primary Contact/Insured	
LTD (TP)		HUANG XIAO YU	
Third Party Vehicle Services		9 GRAY LANE, 438951, Singapore	
Damage		86668669	
		HUANG_SHERRIE@HOTMAIL.COM	

Actions

Next Step

Finish the work

Complete Work

More

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
Immediate Advice with Mandate.pdf	Reports & Statement	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	June 12, 2018
GA138254-Policy Schedule.pdf	Forms / Claim Documents	Claim memo / Summary	ANG Flossie	December 5, 2017
GA138254- Certificate of Insurance.pdf	Forms / Claim Documents	Policy Schedule / Covernote / Certificate of insurance	ANG Flossie	December 5, 2017
SLC4445R MARKED EST.pdf	Forms / Claim Documents	Estimate / Quotation	ANG Flossie	December 5, 2017
SLC4445R TP GIA RPT.PDF	Reports & Statement	GIA Report	ANG Flossie	December 5, 2017
LTR TO INSD (NON REPORTING).pdf	Letters and Correspondence	Policy Holders / Insured	ANG Flossie	December 5, 2017
SKK1938A -INSD GIA RPT.PDF	Reports & Statement	GIA Report	ANG Flossie	December 5, 2017
IA- LKK.pdf	Letters and Correspondence	Intermediaries	ANG Flossie	December 5, 2017
EMAIL_ABS REQ SURVEY.pdf	Letters and Correspondence	Third Party	ANG Flossie	December 5, 2017

SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	S7M004RA	Vehicle Information	
Reference		Incident Vehicle	SLC4445R
CC4/ASM17022226/Title3 		Registration #	TPVD SLC4445R 9
November 18, 2017		Make	HONDA
Request Date		Model	VEZEL
December 18, 2017			GRAY LANE # 04-01, , ,
Due Date			438951
July 31, 2018		Primary Contact/Insured	
Vendor Name		HUANG XIAO YU	
LKK AUTO		9 GRAY LANE, 438951, Singapore	
Type of CONSULTANTS PTE Loss LTD (TP)		86668669	
Third Party Vehicle		HUANG_SHERRIE@HOTMAIL.COM	
Services Damage			

Actions

Next Step

Finish the work

Complete Work

More



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#

SLC4445R

Purchase Date

mm/dd/yyyy 

Registration State

SINGAPORE

Registration Date *

05/13/2016 

Mileage

145675

Age of Vehicle

1

Driver Details

Manufacturing Year

CATEGORY

Driver Name

POLICY INFORMAT...

ASSESSMENT INFO...

2015

FNOL INFORMATI...

ADRIAN GOH NGAT CHOON (ADRIAN WU YUECHUN)

CATEGORY

Make

CATEGORY

Engine No

POLICY INFORMAT...

ASSESSMENT INFO...

L15B4026844

CATEGORY

Engine Capacity

POLICY INFORMAT...

ASSESSMENT INFO...

1496 cc

CATEGORY

Sum Insured

POLICY INFORMAT...

ASSESSMENT INFO...

0

CATEGORY

Market Value

POLICY INFORMAT...

ASSESSMENT INFO...

0

FNOL INFORMATI... 0

POST SURVEY INF...

CATEGORY

Driver License #

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Type

FNOL INFORMATI...

POST SURVEY INF...

CATEGORY

License Issue Date

FNOL INFORMATI...

POST SURVEY INF...

mm/dd/yyyy

CATEGORY

License Expiration Date

FNOL INFORMATI...

POST SURVEY INF...

mm/dd/yyyy

CATEGORY

Address



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Front left side

ACHILLES 6mm

Rear left side

ACHILLES 6mm

Front right side

ACHILLES 6mm

Rear right side

ACHILLES 6mm

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts

EDIT	SR NO	QUANTITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTR%	DISC QUNT%	SALV AGE%	PART PRICE(NET)	ACT (PA)
	1	1			REAR RIM LHS			Cut	450		20		360	Rev
	2	1			REAR FENDER ARC GARNISH LH			Cut	165		20		132	Rev
	3	1			REAR FENDER ARC GARNISH CLIPS			Necessary	40		20		32	Rev
	4	1			REAR RIMS LHS			Serviceable	0		20		0	Rev
	5	1			REAR SHOCK ABSORBER LH			Serviceable	0		20		0	Rev
	6	1			REAR SHOCK ABSORBER MOUNTING LH			Serviceable	0		20		0	Rev
	7	1			REAR SHOCK MOUNTING BEARING LH			Serviceable	0		20		0	Rev

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTTR%	DISC.OUNT%	SALV AGE%	PART PRICE(NET)	ACT (PA
☐	19	1			SET REAR BUMPER COVER CLIPS			Necessary	50		20		40	Rev
☐	20	1			REAR BUMPER COVER RETAINER LH			Serviceable	0		20		0	Rev

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT
☐	1		TO STRAIGHTEN AND PANEL BEATING ACCIDENT AREA.	300	0	0	Reviewing	
☐	2		TO PUTTY, RESPRAY PAINTING AND POLISH ACCIDENT AREA.	300	0	0	Reviewing	
☐	3		TO CHECK AND RECTIFY WIRING AND AFTER DISCONNECT AND CONNECT.	30	0	0	Reviewing	
☐	4		TO RUST PROOF AFFECTED AREAS.	0	0	0	Reviewing	
☐	5		TO CONDUCT COMPUTER WHEEL ALIGNMENT.	80	0	0	Reviewing	
☐	6		TO REMOVE AND REPLACE REAR SHOCK ABSORBER, MOUNTING, BEARING, DUST COVER STOPPER RHS.	0	0	0	Reviewing	
☐	7		TO REMOVE AND REPLACE TYRE & RIM, TYRE BALANCING.	30	0	0	Reviewing	

SERVICE REQUESTS MESSAGES CLAIMS

<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary EDIT SR NO NAME ACTION AMOUNT COMMENT REMOVE

☐		1	DAYS OF REPAIR	Reviewing	3	
--------------------------	--	---	----------------	-----------	---	--

- SERVICE REQUESTS
- MESSAGES
- CLAIMS

<< Assessment Details

General & Workshop Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary	Claim Amount	\$2,171.84	Claim Amount	\$2,171.84	

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$740.00	\$740.00

Submit for Review

SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Add

Approve

Deny

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
------	-------	------	--------	--------	---------	--------

		1	FINAL LUMP SUM	Reviewing	1700	
--	--	---	----------------	-----------	------	--