



SLC4445R

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)
6 Benoi Sector, Singapore (629904)
Tel : 6904 4596 | Fax No : 6694 4929

ACCIDENT REPAIR ESTIMATE

TP INSURER : AXA
OWN INSURER : AIG
CLAIM TYPE : TP
Date of Accident : 18/11/2017

Vehicle Reg. No. : SLC4445R
Vehicle Reg. Date: 13-May-2016
Make / Model : H. VEZEL 1.5X CVT
Engine No. : L15B4026844
Chassis No. : RU11106841

COST OF CLAIMS

Parts Cost / List Items :	\$	5,152.00
Plus/Less 20%	\$	1,030.40
Total Cost / List :	\$	4,121.60
Special Nett Items :	\$	-
Total Parts Amount :	\$	4,121.60
Total Labour Amount :	\$	3,330.00
Gross Total :	\$	7,451.60
GST % : 7%	\$	521.61
Nett Amount :	\$	7,973.21

Surveyor Name and Company :

Taufik 97495749-46
Date of survey : 21/11/17 @ 1630
Part by Part / Lump Sum : 3 days
Resurvey Before Paint / After Paint
Authorize/Not Authorize/Without Prejudice
Email : zur@kkanfo.com
Fax No :
HP No :

This claim is handled by : EDMOND

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Vermogen Ace Pte Ltd (Co.Reg. No: 20160623C)

6 Benoi Sector, Singapore (629904)

Tel : 6904 4596 | Fax No : 6694 4929

Vehicle Reg. No. : **SLC4445R**

Vehicle Reg. Date: **13/5/2016**

Make / Model : **H. VEZEL 1.5X CVT**

Engine No. : **L15B4026844**

Chassis No. : **RU11106841**

PAGE 1

Estimates on Parts

No	Qty	PARTICULARS	CONDITION	AMOUNT	S/N	ADJUSTED AMOUNT
1	1	Rear rim LHS	<i>cut ✓</i>	\$ 950.00		
2	1	Rear fender arc garnish LH	<i>cut ✓</i>	\$ 165.00		
3	1	Rear fender arc garnish clips	<i>new ✓</i>	\$ 40.00		
4	1	Rear rim LHS	<i>x repeated</i>	\$ 950.00		
5	1	Rear shock absorber LH	<i>x</i>	\$ 625.00		
6	1	Rear shock absorber mounting LH	<i>x</i>	\$ 40.00		
7	1	Rear shock mounting bearing LH	<i>x</i>	\$ 40.00		
8	1	Rear shock absorber dust cover LH	<i>x</i>	\$ 50.00		
9	1	Rear shock stopper LH	<i>x</i>	\$ 40.00		
10	1	Rear lower arm LH	<i>x</i>	\$ 437.00		
11	1	Rear lower arm ball joint LH	<i>x</i>	\$ 113.00		
12	1	Rear wheel cover LH (honda)	<i>x</i>	\$ 110.00		
13	1	Rear bumper cover LH	<i>cut ✓</i>	\$ 210.00		
14	1	Rear bumper	<i>cut ✓</i>	\$ 885.00		
15	1set	Rear bumper clips	<i>new ✓</i>	\$ 50.00		
16	1	Rear bumper retainer LH	<i>new ✓</i>	\$ 72.00		
17	1	Rear bumper bracket LH	<i>new ✓</i>	\$ 116.00		
18	1	Rear bumper reflector LH	<i>x</i>	\$ 167.00		
19	1set	Rear bumper cover clips	<i>new ✓</i>	\$ 50.00		
20	1	Rear bumper cover retainer LH	<i>x</i>	\$ 42.00		
21	1	0				
22	1	0				
23	1	0				
24	0	0				
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29	0	0				
30	0	0				
31	1	0				
32	1	0				
33	0	0				
34	0	0				
35	0	0				
36	0	0				
37	1	0				
38	0	0				
39	0	0				
40	0	0				

Tel : 6904 4596 | Fax No : 6694 4929

PAGE 1

[illegible]