

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/1143/2017/JT
Date : 18-Nov-17

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle number : SLN 8117 D

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Kuan Wooi Ping
Address : 71 Pasir Ris Grove
#13-22
Singapore 518205
Telephone : HP +65 9236 6656
Type of Claim : Third Party Claim
Policy No. : 5092379395
Vehicle No : **SLJ 9201 H**
Model Code : Audi A4 Sedan 1.4 TFSI S-tronic
Model / Year : Dec-16
Engine No : CVN 018132
Chassis No : WAUZZZF40HA030615
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 11-Nov-17
Place of Accident : PIE(Tuas) before Kallan exit lane 1

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLJ 9201 H.

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid. Check function.	S/N \$ 280.00 ✓	
2	To dismantle and renew rear bumper. Re-organise rear crash management components. Reinstall all parts removed.	\$ 900.00 500.	
3	To respray rear bumper.	\$ 800.00 550	
4	To carry out diagnostic checks.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 2,172.00	

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

S/N are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLJ 9201 H.

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	REAR BUMPER <i>sel</i>	\$ 1,844.00	✓
2	REAR BUMPER SECURING STRIP <i>green</i>	\$ 182.00	+
3	REAR BUMPER LOWER SPOILER	\$ 203.00	+
4	REAR BUMPER LIGHT REFLECTOR - LHS/RHS <i>nea</i>	\$ 66.00	+
5	REAR REINFORCEMENT BEAM <i>nea</i>	\$ 756.00	+
6	REAR PARKING AID <i>A</i>	\$ 415.00	?
7	SUNDRIES <i>?</i>	\$ 300.00	?
TOTAL SPARE PARTS		\$ 3,766.00	
TOTAL LABOUR CHARGES		\$ 2,172.00	
GRAND TOTAL		\$ 5,938.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ly
Surveyed Date : 22/11/17.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant